

ASS REC BY:

REF: CS / MSG1702285 / 1167

Special Instruction: range

Survivor:

Taufik

ASSIGNMENT (Office)

From (Person):

Katharine Wong

of

MSEI

Date/Time: 21-11-2017 240pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFN 560E

Insured:

SJV 2763J

at Workshop m/s

B's Performance

Tel:

9776 5722

of

No. 7 Soon Lee St #01-38

Policy No:

MSD/VPLP/17-000802-00

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 110pm

H.O.D. Endorsement:

Date/Time:

22.11.2017 9.12am

Person Contacted:

Elson

Vehicle IN OUT

Date/Time

Action/Instruction ( X ) Estimate

SFN 560E - X

SJV 2763J - X

Dismantle Part: 24.11.2017

After repair: 29.11.2017

02/12/17 1.38pm Email to Katharine Wong thru Mesimen.

Simone Tappin

## TOTAL

RECEIVED 11 APR 2018

## Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

**(3) Workshop Estimate/Assignment Form**

N	ALL Parts condition				
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

**(4) System - (Views/Merimen)**

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By:

Case Handler

Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17022285/T1b

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 22-11-2017



Code : MSG

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJV 2763J	Veh. Inspected	SFN 560E
Policy No.	MSD/VPCP/17-000802-00	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	21/11/2017

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	19/11/2017	Inspection Date	22/11/2017
Survey held at	B'S PERFORMANCE PTE LTD 7 SOON LEE STREET ISPACE #01-38 SINGAPORE 627668		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Nov 2017		21 Nov 2017 14:40 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

<b>Insured:</b>	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
<b>Main Claimant:</b>	Lim Ming Kwang James, ID: S77122861		
<b>Vehicle Reg. No.:</b>	SFN560E	<b>Date of Loss:</b>	19/11/2017 11:00 - :59
<b>Claim Type:</b>	TP	<b>Policy/Cover Note No.:</b>	MSD/VPCP/17-000802-00 Coverage: 08/04/2017 - 07/04/2018
<b>Vehicle Reg. No. (Insured):</b>	SJV2763J	<b>Policy No. (Claimant):</b>	
		<b>Excess:</b>	
<b>Repairer:</b>	Bs Performance Pte Ltd (HQ) NO. 7 SOON LEE STREET, #01-38 I SPACE SINGAPORE 627608, 627608 Pioneer - Tel:		
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/11/2017]		

**ASSOCIATED MAIL RECEIVED** View All Compose Case Mail

There are no mail for this case.

**ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/11/2017 10:47
Date Of Accident	19/11/2017 12:00
Exact Location Of Accident	ALONG AYE AFTER CLEMENTI FLOYVER
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFN560E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM MING KWANG JAMES
NRIC No	S7712286I
Email Address	JAMESLIMMK@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90278278
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250-1.8 CGI (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA269341
Cover Note Number	

### Driver

Name of Driver	LIM MING KWANG JAMES
NRIC No	S7712286I
Date Of Birth	02/05/1977
Occupation	INDOOR
Date Of Driving Pass	07/11/1996
Driving Experience	21 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90278278
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	JAMESLIMMK@GMAIL.COM

Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? YES  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 4

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name CLEMENTI POLICE DIVISIONAL HQ (D DIVISION )  
 Police Station Address ROAD: 20 CLEMENTI AVENUE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-7740000 - FAX NO: 67741705  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT D/20171119/7010

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJV2763J  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver SIEW JUN JIE ELROY  
 NRIC/Passport Number G3531232W  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

#### Details of Witness

Name  
 Phone Number



Email Address

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGE3535U  
Vehicle Make/Model/Colour  
Details Of Properties  
Name of Driver GOH KAR TUCK  
NRIC/Passport Number S7621706H  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### Details of Witness

Name  
Phone Number  
Email Address

#### DETAILS OF INJURED PERSON 1

Name LOH JUN JIA  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SFN560E  
Were seat belts worn?  
Was injured conveyed to hospital by ambulance?  
Address  
Postcode

#### DETAILS OF INJURED PERSON 2

Name LIM ZHI EN JALYN  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SFN560E  
Were seat belts worn?  
Was injured conveyed to hospital by ambulance?  
Address  
Postcode

#### DETAILS OF INJURED PERSON 3

Name LIM ZHI HENG  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SFN560E  
Were seat belts worn?  
Was injured conveyed to hospital by ambulance?  
Address  
Postcode

#### DETAILS OF INJURED PERSON 4

Name LIM MING KWANG JAMES  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SFN560E



Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode


## Sketch Plan Pg. 1

### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of thereport being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that :
  - (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

I AM AWARED THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.




Policyholder's Signature / Date &

  
Driver's Signature (If driver is not the policyholder) / Date

  
Witnessed by Reporting Centre

#### Sketch Plan

	<p>A - SFNS60E B - SJV2763J C - SFE3535U D - unknown</p> <p>AYE After Clementi Flyover (towards city)</p>
---	---

## Sketch Plan Pg. 2

Describe Circumstances of the Accident

Describe Circumstances of the Accident

Refer to Police Report D/2017/119/7010

### Declaration

I/We declare the foregoing particulars are true in every respect.

☐ Claim own policy  
☐ Claim third party  
☒ Claim OD TP at other workshop B5 Performance  
☐ For record purpose

Policy No. VAT/GA260341  
Insurer AXA Veh. No. SFN560E

Policyholder's Signature / Date &amp; Time

Driver's Signature (If driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel



redefining / insurance

AXA Insurance Pte Ltd

1800 880 4888 (Within Singapore)  
(65) 6880 4888 (International)  
(65) 6880 4740  
customer.care@axa.com.sg  
www.axa.com.sg

## Certificate of Insurance

account number  
11055

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)  
-Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

### Policy details

Policyholder name	LIM MING KWANG JAMES	Certificate number	GA269341 / 1
Cover	Comprehensive	Chassis number	WDD2120472A182795
Plan name	Essential	Engine number	27186030043605
NCD applicable	50%		
Vehicle registration number	SFN560E		
Period of Insurance	from 21/09/2017 to 24/12/2018 (both dates inclusive)		
Finance loan company	MAYBANK		

### Persons or classes of persons entitled to drive\*

- (a) The Policyholder  
(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

### Limitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

#### EXCESS

Windscreen Excess

Not Applicable

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

### Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

### Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7712286I



Name

LIM MING KWANG JAMES  
(LIN MINGGUANG)

林 明 光

Race

CHINESE

Date of birth

02-05-1977

Sex

M

Country of birth

SINGAPORE



4041339



NRIC No S7712286I

Date of issue

11-05-2002

APT BLK 322A JURONG EAST STREET 31 #04-264  
SINGAPORE 601322

NRIC No: S7712286I

Date: 30/06/2009

No: 6139623

REPUBLIC OF SINGAPORE DRIVING LICENCE



577422861

TIN DING KWANG JAMES  
(LIN BING GUANG JAMES)

02 May 1977

15 Oct 2003



1000925302E

YOU ARE LICENSED TO DRIVE VEHICLES AS FOLLOWS:

- |          |  |             |
|----------|--|-------------|
| Class 2B | Motorcycles not exceeding 200 cc   | 07 Jan 1998 |
| Class 2A | Motorcycles between 201 cc and 400 cc  | 18 Jan 1999 |
| Class 3  | Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms | 07 Nov 1996 |

NP 428A



License No. 577422861



# SINGAPORE POLICE FORCE



D/20171119/7010

1 of 2

**POLICE REPORT (NP299)**

Report No. D/20171119/7010

Police Station Of Origin  
Clementi Police Divisional HQ  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No:1800-7740000

Date/Time Report Made 19/11/2017 18:15	Vide Report No.	Station Diary No.
Name Of Informant LIM MING KWANG JAMES	Address APT BLK 322A JURONG EAST STREET 31 #04-264 SINGAPORE 601322	
ID Type / ID No. NRIC NO / S7712286I	Contact No. Home/Office:                      Mobile: 90278278	
Nationality SINGAPORE CITIZEN	Email Address jameslimmk@gmail.com	
Occupation SALES AND MARKETING MANAGER	Sex Male	Age 40
Institution/School Name	Date of Birth 02/05/1977	Race Chinese
Date/Time Of Incident 19/11/2017 11:45 - 19/11/2017 12:00	Language English	
	Location Of Incident AYER RAJAH EXPRESSWAY	

**Brief details.**

I am the driver of vehicle number , sfn560e. we were travelling on aye towards city. the accident happened after clementi flyover. Because of road works ahead, alot of cars were filtering from the right and caused cars infront of me to brake to a stop. i managed to brake but unfortunately, the cars behind me hit my car from the back. there were 3 cars, mine being the first, the second was sjv2763j, and third sge3535u.

the impact caused the 4 passengers, me , my wife and my 2 kids , felt discomfort and pain. we went to

Signature Of Officer Recording The Report:  Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 19/11/2017 18:15
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp





# SINGAPORE POLICE FORCE



D/20171119/7010

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. D/20171119/7010

hospital to follow with a check at 2:30pm.

passenger details

1. Loh Jun Jia S8214893J
2. Lim Zhi En Jalyn T0621359B
3. Lim Zhi Heng Jarvis T0830334C

Person Name	LIM MING KWANG JAMES		
ID Type	NRIC NO	ID No	S7712286I
Gender	Male	Age	40
Race	Chinese	Language	English
Occupation	SALES AND MARKETING MANAGER	Address Type	
Address	APT BLK 322A JURONG EAST STREET 31 #04-264 SINGAPORE 601322	Mobile No	90278278
Is Informant A Victim?	Yes		
Person Name	LIM MING KWANG JAMES (Informant)		

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this  
report has been authenticated by  
SingPass. No signature is required.

Date/Time:

19/11/2017 18:15

Classification Of Case:

## View Sent Message

This mail is associated with :

**\*SFN560E (MSC/V/17-001809)  
[SJV2763J]**

TP  
Lim Ming Kwang James  
Nov 19 2017 11:00AM  
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]  
Bs Performance Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **02/12/2017 13:38 PM**.  
**To** MSI\_WCS  
**Subject** Pre-repair Inspection

Dear Katherine,

Refer to your assignment on 21.11.2017 at 2.40PM.

Please be informed that we have inspected the vehicle SFN 560E on 22.11.2017 at 5.15PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,  
Catherine Chong | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Nov 2017		21 Nov 2017 14:40 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>HITACHI CAPITAL ASIA PACIFIC PTE LTD</b> , Co. Reg. No.: 199400399N		
Main Claimant:	<b>Lim Ming Kwang James</b> , ID: S7712286I		
Vehicle Reg. No.:	<b>SFN560E</b>	Date of Loss:	19/11/2017 11:00 - :59 [88 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / MSC/V/17-001809</b>	Policy/Cover Note No.:	MSD/VPCP/17-000802-00 (Comprehensive) Coverage: 08/04/2017 - 07/04/2018
Vehicle Reg. No. (Insured):	<b>SJV2763J</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Bs Performance Pte Ltd (HQ)</b> NO. 7 SOON LEE STREET, #01-38 I SPACE SINGAPORE 627608, 627608 Pioneer - Tel:		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Katherine Wong Chew Shong</b> - 6594 2544]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Imm.Advice due 22/11/2017]		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SFN560E (MSC/V/17-001809)  
[SJV2763J]**

**TP**

**Lim Ming Kwang James**




































**Nov 19 2017 11:00AM**

**[HITACHI CAPITAL ASIA PACIFIC PTE LTD]**

**Bs Performance Pte Ltd**

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/04/18 09:29	Odometer Reading	 Load JPG	✓
2	06/04/18 09:29	Chassis Number	 Load JPG	✓
3	06/04/18 09:29	General View	 Load JPG	✓
4	06/04/18 09:29	General View	 Load JPG	✓
5	06/04/18 09:29	General View	 Load JPG	✓
6	06/04/18 09:29	General View	 Load JPG	✓
7	06/04/18 09:29	General View	 Load JPG	✓
8	06/04/18 09:29	General View	 Load JPG	✓
9	06/04/18 09:29	General View	 Load JPG	✓
10	06/04/18 09:29	General View	 Load JPG	✓
11	06/04/18 09:29	General View	 Load JPG	✓
12	06/04/18 09:29	General View	 Load JPG	✓
13	06/04/18 09:29	General View	 Load JPG	✓
14	06/04/18 09:29	General View	 Load JPG	✓
15	06/04/18 09:29	General View	 Load JPG	✓
16	06/04/18 09:29	General View	 Load JPG	✓
17	06/04/18 09:29	General View	 Load JPG	✓
18	06/04/18 09:29	General View	 Load JPG	✓
19	06/04/18 09:29	General View	 Load JPG	✓
20	06/04/18 09:29	General View	 Load JPG	✓
21	06/04/18 09:29	General View	 Load JPG	✓
22	06/04/18 09:29	General View	 Load JPG	✓
23	06/04/18 09:29	General View	 Load JPG	✓
24	06/04/18 09:29	General View	 Load JPG	✓
25	06/04/18 09:29	General View	 Load JPG	✓
26	06/04/18 09:29	General View	 Load JPG	✓
27	06/04/18 09:29	General View	 Load JPG	✓
28	06/04/18 09:29	General View	 Load JPG	✓
29	10/04/18 16:08	Private Photo	 Load JPG	✓
30	10/04/18 16:08	Private Photo	 Load JPG	✓
31	10/04/18 16:08	Private Photo	 Load JPG	✓
32	10/04/18 16:08	Private Photo	 Load JPG	✓
33	10/04/18 16:08	Private Photo	 Load JPG	✓
34	10/04/18 16:08	Private Photo	 Load JPG	✓
35	10/04/18 16:08	Private Photo	 Load JPG	✓

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	10/04/18 16:08	Private Photo	1 Load JPG	✓
37	10/04/18 16:08	Private Photo	1 Load JPG	✓
38	10/04/18 16:08	Private Photo	1 Load JPG	✓
39	10/04/18 16:08	Private Photo	1 Load JPG	✓
40	10/04/18 16:08	Private Photo	1 Load JPG	✓
41	10/04/18 16:08	Private Photo	1 Load JPG	✓
42	10/04/18 16:08	Private Photo	1 Load JPG	✓
43	10/04/18 16:08	Private Photo	1 Load JPG	✓
44	10/04/18 16:08	Private Photo	1 Load JPG	✓
45	10/04/18 16:08	Private Photo	1 Load JPG	✓
46	10/04/18 16:08	Private Photo	1 Load JPG	✓
47	10/04/18 16:08	Private Photo	1 Load JPG	✓
48	10/04/18 16:09	Private Photo	1 Load JPG	✓
49	10/04/18 16:09	Private Photo	1 Load JPG	✓
50	10/04/18 16:09	Private Photo	1 Load JPG	✓
51	10/04/18 16:09	Private Photo	1 Load JPG	✓
52	10/04/18 16:09	Private Photo	1 Load JPG	✓
53	10/04/18 16:09	Private Photo	1 Load JPG	✓
54	10/04/18 16:09	Private Photo	1 Load JPG	✓
55	10/04/18 16:14	Photographs of Damaged Parts	1 Load JPG	✓
56	10/04/18 16:14	Photographs of Damaged Parts	1 Load JPG	✓
57	10/04/18 16:14	Photographs of Damaged Parts	1 Load JPG	✓
58	10/04/18 16:14	Photographs of Damaged Parts	1 Load JPG	✓
59	10/04/18 16:14	Photographs of Damaged Parts	1 Load JPG	✓
60	10/04/18 16:14	Photographs of Damaged Parts	1 Load JPG	✓
61	10/04/18 16:14	Photographs of Damaged Parts	1 Load JPG	✓
62	10/04/18 16:14	Photographs of Damaged Parts	1 Load JPG	✓
63	10/04/18 16:14	Photographs of Damaged Parts	1 Load JPG	✓
64	10/04/18 16:14	Photographs of Damaged Parts	1 Load JPG	✓
65	10/04/18 16:14	Photographs of Damaged Parts	1 Load JPG	✓
66	10/04/18 16:14	Photographs of Damaged Parts	1 Load JPG	✓
67	10/04/18 16:14	Photographs of Damaged Parts	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/11/17 11:19	(1/3) SFN560E E FILE REPORT	1 Load PDF	
2	21/11/17 14:37	TP disagree on SJE & PRI Details	1 Load PDF	
3	24/01/18 10:15	TP police Report	1 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17022285/T1BS2

Date: 13/04/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VPCP/17-000802-00  
 Claimant Vehicle No: SFN560E Insured Vehicle No: SJV2763J  
 Date of Loss: 19/11/2017 Nature of Claim: TP Claim No: MSC/V/17-001809

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SFN560E  
 Make & Model: MERCEDES-BENZ E250, 1.8 CGI (A) Engine No: 27186030043605  
 Reg. Date: 25/06/2010 (Man. Year: 2010) Chassis No: WDD2120472A182795  
 Colour: Black Odometer: 124552 km  
 Engine Capacity: 1796 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 245/45R17 Rear Tyre Size: 245/45R17  
 Front Left Side: Achilles 6 mm Rear Left Side: Achilles 6 mm  
 Front Right Side: Achilles 6 mm Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 21/11/2017

Date Inspected: 22/11/2017 Inspected At:

Bs Performance Pte Ltd (HQ)  
 NO. 7 SOON LEE STREET, #01-38 I SPACE  
 SINGAPORE 627608  
 Singapore 627608

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



4/13/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,500.00 - \$6,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Apr 2018)
Parts:	143	MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFN560E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >