

22/03/2012

ASS REC. BY:

REF: CS3/EQ217022286/T1022

Special Instruction:

range & days

claim

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Bazim Ahmad

of

EQ1

Date/Time: 22.11.2017 8:56am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBB 6369M

Insured:

SGN 6085J

at Workshop m/s

Han Car Repairs

Tel:

6371 0275.

of

Blk 1001 Bukit Meriah Lane 3 # 01-49

Policy No:

Claim No:

DM17H002629/FN

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20.11.2017

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

22.11.2017 9:35am

Person Contacted:

David

Vehicle (IN) OUT

Date/Time	Action/Instruction (X) Estimate	
	GBB 6369M - CT4/A2616012960/Aeb3	DA: 080716
	SGN 6085J - CS/TP08009398/002	DA: 01039008
	Demantle Part: 23.11.2017	

GIRVANT

Tanjah

REF:

EQ1

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

PRS

Veh No:

G5B6369M Yr Regn: 2009, itary

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

c.c 2482

Colour:

S/ new

A/C: Insured / Std / NI / NA

Sp. Reading

311743

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02P-100046058

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

22/11/17 @ 12:45pm

Survey held at

Han Car Repairs BM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/5

Submit PRS report.

A 6000 - A 7000, Bde 9 days.

RECEIVED 08 MAY 2018

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

9

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format:

PRS

Lump Sum / I.B.I: (\$

100

100

Survey Department Check List (Case Handler)

Reference No.: CS3/EQ11703386/T1b
Policy Type: OD / TP / TP RES / TL / EVA PRS

Case Handler

Typist

Admin (Catherine): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Surveyor (Raufish): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Alina 2/5/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CS3/EQ117022286/T1b	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 22-11-2017	
		Code : EQ1	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SGN 6085J	Veh. Inspected	GBB 6369M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	BAZLIN AHMAD	Assign Date	22/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/11/2017	Inspection Date	22/11/2017
Survey held at	HAN CAR REPAIRS BLK 1001 #01-49 BUKIT MERAH LANE 3 ALEXANDRA VILLAGE SINGAPORE 159718		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Catherine Chong (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Wednesday, 22 November, 2017 8:57 AM
To: assignments
Subject: FW: 2nd Notice to Conduct Pre-Repair Survey - Accident involving GBB6369M & SGN6085J along Dunman Road towards Haig Road on 20.11.2017 EQ ref: SGN6085J
Our ref: GBB6369M/HC/sy/ch
Attachments: 2nd PRS.PDF; 1st PRS.PDF

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Bazlin Ahmad [mailto:bazlin.ahmad@eqinsurance.com.sg]
Sent: Wednesday, 22 November, 2017 8:56 AM
To: accident@kscgp.com; Admin A <admin-a@lkkauto.com>
Cc: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>; motor@kscgp.com
Subject: RE: 2nd Notice to Conduct Pre-Repair Survey - Accident involving GBB6369M & SGN6085J along Dunman Road towards Haig Road on 20.11.2017 EQ ref: SGN6085J Our ref: GBB6369M/HC/sy/ch

Dear Sirs,

We object to all the surveyors as proposed. We shall be appointing our surveyor, **LKK AUTO CONSULTANT**, to attend to the pre-repair survey of your client's vehicle.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Aside to LKK,
Please arrange to attend to the said Pre-repair survey.

Thank You.

Regards,

Bazlin Ahmad
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate



From: accident@kscgp.com [<mailto:accident@kscgp.com>]

Sent: Tuesday, November 21, 2017 2:42 PM

To: Bazlin Ahmad

Cc: Elaine Cheong; motor@kscgp.com

Subject: 2nd Notice to Conduct Pre-Repair Survey - Accident involving GBB6369M& SGN6085J along Dunman Road towards Haig Road on 20.11.2017 EQ ref: SGN6085J Our ref: GBB6369M/HC/sy/ch

Dear Bazlin,

Please find enclosed the 2nd Notice to Conduct Pre-Repair Survey.

Thank you.

Regards,

Chit Yee

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Bazlin Ahmad [<mailto:bazlin.ahmad@eqinsurance.com.sg>]

To: accident@kscgp.com

Cc: elaine.cheong@eqinsurance.com.sg

Sent: Tue, 21 Nov 2017 06:30:19 +0000

Subject:

Without Prejudice

Dear Sir,

We refer to your Notice of Accident of even date.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155 Contact person : Joey/Joseh	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon Kho
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Ricky Teng	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328 Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Thank You.

Regards,

Bazlin Ahmad

Executive | Claims



EQ Insurance Company Limited


5 Maxwell Road #17-00 Tower Block MND

Complex Singapore 069110

did 65 6496 9881 | tel 65 6223 9433 ext 881 |

fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: accident@kscgp.com [<mailto:accident@kscgp.com>]

Sent: Monday, November 20, 2017 12:52 PM

To: Elaine Cheong

Cc: motor@kscgp.com

Subject: Notice to Conduct Pre-Repair Survey - Accident involving GBB 6369M & SGN 6085J along Dunman Road towards Haig Road on 20.11.2017 Your ref: SGN 6085J Our ref: GBB 6369M/HC/sy/ch

Dear Elaine,

Please find enclosed the Notice to Conduct Pre-Repair Survey.

Thank you.

Regards,

Chit Yee

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9472N
Vehicle Details	
Vehicle No.:	GBB6369M
Vehicle to be Exported:	No
Intended De-registration Date:	08 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1KD1943120
Chassis No.:	JTFHT02P100046058
Maximum Power Output:	-
Open Market Value:	\$25,387.00
Original Registration Date:	26 Aug 2009
First Registration Date:	26 Aug 2009
Transfer Count:	0
Actual ARF Paid:	\$1,270.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Aug 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$18,801.00
COE Rebate Amount:	\$2,436.00
Total Rebate Amount:	\$2,436.00

The information contained herein is correct as at 08 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/11/2017 14:45
Date Of Accident	19/11/2017 10:20
Exact Location Of Accident	DUNMAN ROAD TOWARD HAIG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB6369M
Insured/Policyholder	
Name Of Registered Owner	AEON ENVIRONMENTAL SERVICE PTE LTD
Co Reg No	199409472N
Email Address	HANCARREPAIRS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98310120
Alternative Phone No	OFFICE-98310120

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VCA/P1972049
Cover Note Number	

Driver

Name of Driver	MUNIANDY A/L WAI OON @ PAH WAI ONN
Passport No/FIN	G7195448Q
Date Of Birth	12/05/1981
Occupation	OUTDOOR
Date Of Driving Pass	11/11/2013
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGN6085J

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver QUEK YEOK CHAI, WINSTON

NRIC/Passport Number S8435257H

Contact Number 87423295

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan Pg. 1

SKETCH PLAN

VEHICLE NO: 908 6369M

DOA: 19/11/2017

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

PLEASE NOTE YOUR INSURER MAY HAVE A 14DAY-TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY.




Policy holder's Signature / Date & Time

Driver's Signature (if driver is not the policy holder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan Pg. 2

Describe Circumstances of the Accident

I was travelling along ~~Dunman~~ Dunman Road towards Maig Road. My vehicle (A) was stationary at the traffic junction waiting for traffic light to turn green. A few seconds later, vehicle (B) came from behind & hit my vehicle (A). The impact caused my neck to hurt.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

☐ OWN DAMAGE



Driver's Signature (If driver is not the policyholder) / Date & Time

☒ THIRD PARTY CLAIM

Witnessed by Reporting Centre Personnel

☐ REPORTING ONLY



PRE-REPAIR INSPECTION REPORT				
EQ INSURANCE COMPANY LTD		Ref: CS3/EQ117022286/T1be2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110		Date: 18-05-2018		
Code: EQ1				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SGN 6085J	Veh. Inspected	GBB 6369M	
Policy No.		Coverage (\$)	0.00	
Claim No.	DM17HO02629/FN	Excess (\$)	0.00	
Assign From	BAZLIN AHMAD	Assign Date	22/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTFHT02P100046058	Colour	SILVER	
Odometer	311743 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
5. General Information				
Accident Date	19/11/2017	Inspect Date / Time	22/11/2017 (12:21 PM)	
Survey held at	HAN CAR REPAIRS BLK 1001 #01-49 BUKIT MERAH LANE 3 ALEXANDRA VILLAGE SINGAPORE 159718			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	

Report Ref No. CS3/EQ117022286/T1be2

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.