

03/2002

SS REC. BY:

REF: CS/M6617022293 / Arb Special Instruction:

Survivor: Adrian

ASSIGNMENT (Office)

From (Person): Jasmine Tok of MSLH Date/Time: 22-11-2017 1020am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJK 7947X Insured: SKR 6984X

at Workshop m/s Yi Heng Tel: 6509 0052

of Blk 1 Kakt Bukit Ave 6 #02-19

Policy No: 80427PDSQMY Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 20-11-2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 22-11-2017 12.01pm Person Contacted: Wan Ping Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJK 7947X - CS / INCD9011002 / Uvh DCA: 230209
	SKR 6984X - X
	Sent pending estimate email to Jasmine through Menmen
	Confirm with Wan Ping L/S \$3500 @ 6 days (Red: \$8945.60, 72%)

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 5JK 2947X Yr Regn: 2008 NovType: M.Cal M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit c.c. 1339Colour: Red. A/C: Insured / Std / NI / NASp. Reading: 178506 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GE61109887Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/55R15R: 195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Crucero

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. D.O.I. 22/11/17.Survey held at Yi Henry.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MS16.

MV: 14K

PV: 7.5K

Nett: 6.5K

RECEIVED 20 SEP 2018

RECEIVED 24 NOV 2017

Date/Time, File Pass to?

☐ : Preli. Report1) Final☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 6Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photos

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)Report Format : TPLump Sum / L.R. (\$ 3500)

TOTAL

300
10
310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17022293/Arb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 22-11-2017		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKR 6984X	Veh. Inspected	SJK 7947X	
Policy No.	80429723QMY	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (JASMINE LOK)	Assign Date	22/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/11/2017	Inspection Date	22/11/2017	
Survey held at	YI HENG MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-19 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Nov 2017		22 Nov 2017 10:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	IRANTAFFY SAID BIN ROHANI, ID: S7318035Z								
Main Claimant:	ST RENT & DRIVE PTE LTD, Co. Reg. No.: 201615374C								
Vehicle Reg. No.:	SJK7947X	Date of Loss:	20/11/2017 11:00 - :59						
Claim Type:	TP	Policy/Cover Note No.:	80429723QMY (Comprehensive) Coverage: 11/04/2017 - 10/04/2018						
Vehicle Reg. No. (Insured):	SKR6984X	Policy No. (Claimant):							
		Excess:							
Repairer:	YI Heng Motor Workshop (HQ) Blk 1 Kaki Bt Ave 6 #02-19, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/11/2017]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Print Sent Message

This mail is associated with :

***SJK7947X (537363)**

[SKR6984X]

TP

ST RENT & DRIVE PTE LTD

Nov 20 2017 11:00AM

[IRANTAFFY SAID BIN ROHANI]

Yi Heng Motor Workshop

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 29/11/2017 12:20 PM.
To jasmine_lok@sg.msig-asia.com
Subject SJK7947X (537363)

Dear Jasmine,

Please be informed that we have inspected the vehicle **SJK 7947X** on 22/11/2017.

We are pending estimate from repairer.

Thank you.

Regards,
Janice

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/11/2017 16:49
Date Of Accident	20/11/2017 11:05
Exact Location Of Accident	JURONG WEST ST 42 (BLK 404 CARPARK)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK7947X
Insured/Policyholder	
Name Of Registered Owner	ST RENT & DRIVE PTE LTD
Co Reg No	201615374C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64631770

Vehicle Particulars

Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5081178524-01
Cover Note Number	

Driver

Name of Driver	NG PETER
NRIC No	S8622656A
Date Of Birth	26/07/1986
Occupation	INDOOR
Date Of Driving Pass	18/02/2005
Driving Experience	12 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97341250
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 406 JURONG WEST ST 42 #06-585
Postcode	640406
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 20/11/2017 AT 11.05AM, (SKJ7947X) WAS TRAVELLING STRAIGHT TOWARDS THE MAIN ROAD OF JURONG WEST STREET 42. VEHICLE B (SKR6984X) CAME OUT FROM THE SIDE OF BLK 404 CARPARK AND KNOCK ONTO THE RIGHT SIDE OF MY CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR6984X
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Name of Driver	IRANTAFFY BIN SAID ROHANI
NRIC/Passport Number	S7318035Z
Contact Number	98574636
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 20 NOV 2017 at 11:05am, I (SKJ 7947X) was travelling straight towards the main road of Jurong West Street 42. Vehicle BC SKR 6984X came out from the side of Block 404 carpark and knock onto the right side of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

YI HENGA

Full Servicing Will Be Done Upon Confirmation.

Posted: 16-Oct-2017 Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit, Honda Fit, Honda, Fit, Fit, Used Honda

Details

**Honda Fit 1.3A GF****\$13,800****\$8,030 /yr****10-Nov-2008****1,339 cc****138,121 km****Hatchback****Available**

Low Depreciation Of \$650 Per Month Yet Slightly Negotiable, Best For Uber/Grab Use! New Road Tax. Low Mileage Clocked Of 15800km Annually. No Repairs Needed. Fussy Owner. 100% Accident Free. Call Now!

Lake View Credit Pte Ltd

Posted: 17-Nov-2017 Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit, Honda Fit, Honda, Fit, Fit, Used Honda

Details

PREMIUM AD**Honda Fit 1.3A G****\$14,500****\$8,870 /yr****11-Nov-2008****1,339 cc****148,956 km****Hatchback****Available**

1 Owner With Well Maintain Condition, Original Paint, Upholstery And Grooming Interior, Fuel Efficient, Worth Value For Short Term Ride And COE Extension, Price Negotiable.

Posted: 16-Nov-2017 Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit, Honda Fit, Honda, Fit, Fit, Used Honda

Details

**Honda Fit 1.5A RS Skyroof****\$19,800****\$9,950 /yr****13-Nov-2008****1,496 cc****107,000 km****Hatchback****Available**

Highest OMV, Sporty White RS. Very Well Kept And Maintained By Previous Owner, Superb Interior And Exterior Condition. Come With LTA Approve Kakimoto Exhaust System, High Loan/In House Loan Available....

Lay Auto Pte Ltd

Posted: 17-Nov-2017 Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit, Honda Fit, Honda, Fit, Fit, Used Honda

Details

PREMIUM AD**Honda Fit 1.3A G****\$14,900****\$9,490 /yr****14-Nov-2008****1,339 cc****-****Hatchback****Available**

Just Renew 6 Months Road Tax. Regularly Serviced And Maintained And Excellent Condition, Sports Edition Package With Mugen Bodykit.

Posted: 18-Nov-2017 Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit, Honda Fit, Honda, Fit, Fit, Used Honda

Details

DIRECT OWNER**Honda Fit 1.3A G****\$15,500****\$9,800 /yr****21-Nov-2008****1,339 cc****110,000 km****Hatchback****Available**

Well Maintained And Excellent Condition, Owner Upgrading, Sports Edition Package With Mugen Bodykit, Leather Seat In Excellent Condition With Yellow Stitching.

Allmotoring.sg

Posted: 18-Nov-2017 Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit, Honda Fit, Honda, Fit, Fit, Used Honda

Details

PREMIUM AD**Honda Fit 1.3A G****\$14,800****\$8,860 /yr****28-Nov-2008****1,339 cc****-****Hatchback****Available**

Very Well Maintained By The Owner. Low Maintain And Low Fuel Consumption! Top Choices For Easy Transportation From A To B. Cheap Road Tax And Insurance. Call Now And Come Down To View This Wonderful M...

Cycle & Carriage.Fulco Motor Dealer

Posted: 17-Nov-2017 Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit, Honda Fit, Honda, Fit, Fit, Used Honda

Details

**Honda Fit 1.5A RS****\$19,800****\$10,930 /yr****05-Dec-2008****1,496 cc****-****Hatchback****Available**

\$0 Down Payment! Low Monthly Installment! 1 Owner Only, Extended Warranty Available, Wear And Tear Parts Replaced, Excellent Condition, View To Believe Before Its Gone! High Trade-In.

Posted: 20-Nov-2017 Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit, Honda Fit, Honda, Fit, Fit, Used Honda

Details

PREMIUM AD**Honda Fit 1.3A GF****\$13,888****\$7,830 /yr****06-Dec-2008****1,339 cc****109,038 km****Hatchback****Available**

HIGH Loan And High Trade In Available! Lowest Int At 1.99%! \$0 DriveAway! Immediate Loan Approval From Our In House Finance Officers! 100% Accident Free! No Salesman Means No Commision Or Misc Fees Ne...

Posted: 21-Nov-2017 Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit, Honda Fit, Honda, Fit, Fit, Used Honda

Details

PREMIUM AD**Honda Fit 1.3A G****\$17,500****\$9,340 /yr****22-Dec-2008****1,339 cc****125,010 km****Hatchback****Available**

Most Worthy Deal In Town. Highest OMV Of \$14.8K Assuring You Lowest Depreciation. Best Condition Assured. New Paintwork. New Tires. New Roadtax. Meticulously Maintained By Ex-Teacher Owner. No Modific...

Posted: 19-Nov-2017 Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit, Honda Fit, Honda, Fit, Fit, Used Honda

Details

**Honda Fit 1.3A GF****\$16,800****\$8,540 /yr****22-Dec-2008****1,339 cc****110,000 km****Hatchback****Available**

1 Owner Unit, New Paintwork, No Repair Needed, Very Well Maintained By Owner, Perfect For Short Term Use Or Coe Renewal, Popular All Time Favorite Hatchback, Call Us Today!

Posted: 12-Nov-2017 Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit, Honda Fit, Honda, Fit, Fit, Used Honda

Details

**Honda Fit 1.3A G****\$18,000****\$10,600 /yr****26-Dec-2008****1,339 cc****109,700 km****Hatchback****Available**

Reliable And Best Fuel Efficient, Low Mileage, Well Kept By Owner! Renewed Road Tax Till Dec 2017!

Posted: 30-Sep-2017 Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit, Honda Fit, Honda, Fit, Fit, Used Honda

Details

DIRECT OWNER[Compare](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	5374C

Vehicle Details

Vehicle No.	SJK7947X
Vehicle to be Exported	Yes
Intended De-registration Date	21 Nov 2017
Vehicle Make	HONDA
Vehicle Model	FIT 1.3G A
Primary Colour	Red
Manufacturing Year	2008
Engine No.	L13A4121838
Chassis No.	GE61109887
Maximum Power Output	73.0 kW (97 bhp)
Open Market Value	\$13,314.00
Original Registration Date	03 Nov 2008
First Registration Date	03 Nov 2008
Transfer Count	1
Actual ARF Paid	\$13,314.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	02 Nov 2018
PARF Rebate Amount	\$6,657.00

Intended COE Rebate Details

COE Expiry Date	02 Nov 2018
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$10,989.00
COE Rebate Amount	\$1,042.00
Total Rebate Amount	\$7,699.00

The information contained herein is correct as at 21 Nov 2017

OK

Nett 6.5K

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

22-11-17

OUR REF NO. SJK 7947X

ST RENT & DRIVE PTE LTD
THE GRANDSTAND CARMALL
210, TURFCLUB ROAD
LOT A12/A27
SINGAPORE 287995

TP MS16-
Janice

GE61109887

ESTIMATE BILL FOR VEHICLE NO. SJK 7947X MODEL : HONDA FIT 1.3G

LIST ITEM

1) REAR BUMPER	<i>torn</i>		588.20 474.40
2) REAR BUMPER CLIP	<i>new</i>	8 PCS @ \$ 5.00	40.00 30
3) REAR BUMPER SIDE ATTACHMENT		2 PCS @ \$ 47.20 <i>RH new</i>	94.40 225 24.10
4) REAR BUMPER SPLASH SHIELD (RH)	<i>new</i>		117.00 +
5) REAR BUMPER SPLASH SHIELD CLIP (RH)	<i>new</i>	5 PCS @ \$ 5.00	25.00 +
6) REAR FENDER QUARTER GLASS W/MOULDING (RH)	<i>new</i>		348.20 85
7) REAR DOOR STOPPER (RH)	<i>new</i>	2 PCS @ \$ 21.10	42.20 +
8) REAR DOOR MOULDING (RH)	<i>new</i>		128.00 +
9) REAR DOOR (RH)	<i>dent</i>		885.20 765
10) REAR DOOR WEATHERSTRIPE (RH)	<i>new</i>		211.00 123
11) REAR DOOR TRIM BOARD (RH)	<i>new</i>		483.00 ? X
12) REAR DOOR LOCK (RH)	<i>new</i>		286.50 231
13) REAR DOOR STRIKER (RH)	<i>new</i>		34.00 +
14) ROCKER PANEL (RH)	<i>new</i>		658.00 +
15) REAR WHEEL BEARING (RH)	<i>new</i>		437.00 X
16) REAR AXLE BEAM	<i>new</i>		983.00 X
17) REAR AXLE BUSH	<i>new</i>	2 PCS @ \$ 223.00	446.00 +
18) REAR SHOCK ABSORBER (RH)	<i>new</i>		286.00 X
19) REAR WHEEL HOUSING PANEL (RH)	<i>new</i>		586.00 +
20) REAR FENDER (RH)	<i>dent</i>		780.00 652

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

21) REAR FENDER INNER BOARD (RH) <i>new</i>	387.10 <i>X</i>
22) REAR FENDER INNER BOARD CLIP (RH) 5 PCS @ \$ 5.00 <i>n</i>	25.00 ✓
23) REAR FENDER INNER FLAME WEATHERSTRIPE (RH) <i>n</i>	247.00 <i>X</i>
24) TAIL LAMP ASSY (RH) <i>n</i>	481.20 <i>X</i>

	8597.00
<i>2409.50</i> <i>1927.60</i>	LESS DISCOUNT - 20% 1719.40
	6,877.60

SPECIAL NETT ITEM

1) REAR FENDER QUARTER GLASS INNERSEAL <i>n</i>	60.00 <i>20</i>
2) REAR FENDER QUARTER GLSSS GUM <i>n</i>	60.00 <i>20</i>
3) DOOR VISIOR (ACCESSORIES) <i>n</i>	280.00 <i>60</i>
4) FRONT DOOR PROTECTOR (LONG) <i>n</i>	180.00 <i>60</i>
5) FRONT DOOR PROTECTOR (SMALL) <i>n</i>	28.00 ✓
6) FRONT SPORT RIM (RH) <i>lot</i>	660.00 <i>480</i>
	1,258.00

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM	50.00 <i>30</i>
2) TO APPLY UNDER SEALING ON AFFECTED AREAS	120.00 <i>40</i>
3) TO CONDUCT 4 WHEEL ALIGNMENT (BEFORE AND AFTER)	120.00 <i>80</i>
4) TO REMOVE AND REFIX REAR UNDERCARRIAGE	480.00 <i>? X</i>
5) TO REMOVE AND REFIX REAR FENDER QAURTER GLASS (RH)	120.00 <i>60</i>
6) TO REMOVE AND REFIX CUSHION, FLOOR BOARD, ROOF LINNING, TRIM, GARNISH, UPHOLSTERY ETC	220.00 <i>60</i>
7) TO REMOVE AND REFIX BOOT LID FIXING AND REALIGNMENT	220.00 <i>X</i>
8) TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT	120.00 <i>? 40</i>

LKK Auto Consultants hence notify

the Repairer of the following:

9) TO REMOVE AND REFIX REAR DOOR FIXING AND REALIGNMENT

• To resurvey before and after survey painting

• To display damaged parts during resurvey

• Parts prices to be displayed

• Third party survey is on a "Without Prejudice" basis

• Not to be used for insurance claim

10) TO RESPRAY ON AFFECTED AREAS
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4385.60
1/3: 3.5K
2/3: 22/11/17
06 days

1540.00 *800*
1100.00 *600*
4,310.00
12,445.60

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Nov 2017		22 Nov 2017 10:20 Edit Adj Rpt	S\$3,500.00 Edit Estimates	S\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	IRANTAFFY SAID BIN ROHANI , ID: S7318035Z								
Main Claimant:	ST RENT & DRIVE PTE LTD , Co. Reg. No.: 201615374C								
Vehicle Reg. No.:	SJK7947X	Date of Loss:	20/11/2017 11:00 - :59 [108 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 537363	Policy/Cover Note No.:	A80429723QMY (Comprehensive) Coverage: 11/04/2017 - 10/04/2018						
Vehicle Reg. No. (Insured):	SKR6984X	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Yi Heng Motor Workshop (HQ) Blk 1 Kaki Bt Ave 6 #02-19, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Imm.Advice due 23/11/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJK7947X (537363)
[SKR6984X]
TP
ST RENT & DRIVE PTE LTD
Nov 20 2017 11:00AM
[IRANTAFFY SAID BIN ROHANI]
Yi Heng Motor Workshop

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
2	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
3	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
4	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
5	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
6	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
7	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
8	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
9	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
10	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
11	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
12	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
13	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
14	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
15	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
16	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
17	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
18	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
19	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
20	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
21	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
22	30/08/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>					
23	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
24	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
25	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
26	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
27	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
28	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
29	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
30	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
31	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
32	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
33	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
34	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
35	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
36	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
37	30/08/18 17:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	30/08/18 17:56	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/11/17 17:23	Fax From Third Party	Load PDF	
2	21/11/17 17:23	TP GIA Rep - SJK7947X	Load PDF	
3	22/11/17 10:18	Agree on SJE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022293/ARBE2

Date: 01/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80429723QMY

Claimant Vehicle No : SJK7947X

Insured Vehicle No : SKR6984X

Date of Loss: 20/11/2017

Nature of Claim: TP

Claim No: 537363

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJK7947X

Make & Model: HONDA FIT, 1.3 G (A)

Engine No: L13A4121838

Reg. Date: 03/11/2008 (Man. Year: 2008)

Chassis No: GE61109887

Colour: Red

Odometer: 178506 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size:

195/55 R15

Front Left Side: Crucero 6 mm

Rear Left Side:

Crucero 6 mm

Front Right Side: Crucero 6 mm

Rear Right Side:

Crucero 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,135.60	2,595.60	5,540.00	68.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,310.00	1,790.00	2,520.00	58.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,445.60	4,385.60	8,060.00	64.76
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	12,445.60	3,500.00	8,945.60	71.88

INSPECTION

Date of Assignment: 22/11/2017

Date Inspected: 22/11/2017 Inspected At:

Yi Heng Motor Workshop (HQ)
Blk 1 Kaki Bt Ave 6 #02-19
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2018)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK7947X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Top casing broken	586.20 FL	*474.40 FL
2	8		*REAR BUMPER CLIP	Necessary	40.00 FL	*30.00 FL
3	1		*REAR BUMPER SIDE ATTACHMENT	O/S Necessary	94.40 FL	*24.10 FL
4	1		*REAR BUMPER SPLASH SHIELD (RH)	Not Necessary	117.00 FL	*- FL
5	5		*REAR BUMPER SPLASH SHIELD CLIP (RH)	Not Necessary	25.00 FL	*- FL
6	1		*REAR FENDER QUARTER GLASS W/MOULDING (RH)	Necessary	348.20 FL	*85.00 FL
7	2		*REAR DOOR STOPPER (RH)	Not Necessary	42.20 FL	*- FL
8	1		*REAR DOOR MOULDING (RH)	Not Necessary	128.00 FL	*- FL
9	1		*REAR DOOR (RH)	Dented	885.20 FL	*765.00 FL
10	1		*REAR DOOR WEATHERSTRIPE (RH)	Cut	211.00 FL	*123.00 FL
11	1		*REAR DOOR TRIM BOARD (RH)	Not Necessary	483.00 FL	*- FL
12	1		*REAR DOOR LOCK (RH)	Damaged	286.50 FL	*231.00 FL
13	1		*REAR DOOR STRIKER (RH)	Not Necessary	34.00 FL	*- FL
14	1		*ROCKER PANEL (RH)	Not Necessary	658.00 FL	*- FL
15	1		*REAR WHEEL BEARING (RH)	Not Necessary	437.00 FL	*- FL
16	1		*REAR AXLE BEAM	Not Necessary	983.00 FL	*- FL
17	2		*REAR AXLE BUSH	Not Necessary	446.00 FL	*- FL
18	1		*REAR SHOCK ABSORBER (RH)	Not Necessary	286.00 FL	*- FL
19	1		*REAR WHEEL HOUSING PANEL (RH)	Repair	586.00 FL	*- FL
20	1		*REAR FENDER (RH)	Dented	780.00 FL	*652.00 FL
21	1		*REAR FENDER INNER BOARD (RH)	Not Necessary	387.10 FL	*- FL
22	5		*REAR FENDER INNER BOARD CLIP (RH)	Necessary	25.00 FL	*25.00 FL
23	1		*REAR FENDER INNER FLAME WEATHERSTRIPE (RH)	Not Necessary	247.00 FL	*- FL
24	1		*TAIL LAMP ASSY (RH)	Not Necessary	481.20 FL	*- FL
25	1		*REAR FENDER QUARTER GLASS INNERSEAL	Necessary	60.00 FS	*20.00 FS
26	1		*REAR FENDER QUARTER GLASS GUM	Necessary	60.00 FS	*20.00 FS
27	1		*DOOR VISOR (ACCESSORIES)	Necessary	280.00 FS	*60.00 FS
28	1		*REAR DOOR PROTECTOR (LONG)	Necessary	180.00 FS	*60.00 FS
29	1		*REAR DOOR PROTECTOR (SMALL)	Necessary	28.00 FS	*28.00 FS
30	1		*REAR SPORT RIM (RH)	Cut	650.00 FS	*480.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,855.00	3,077.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,719.40	481.90
Total Parts (\$\$)	8,135.60	2,595.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	50.00	30.00
2	TO APPLY UNDER SEALING ON AFFECTED AREAS	New	120.00	40.00
3	TO CONDUCT 4 WHEEL ALIGNMENT (BEFORE AND AFTER)	New	120.00	80.00
4	TO REMOVE AND REFIX REAR UNDERCARRIAGE	New	480.00	0.00
5	TO REMOVE AND REFIX REAR FENDER QUARTER GLASS (RH)	New	120.00	60.00
6	TO REMOVE AND REFIX CUSHION, FLOOR BOARD, ROOF LINNING, TRIM, GARNISH, UPHOLSTERY ETC	New	220.00	60.00
7	TO REMOVE AND REFIX BOOT LID FIXING AND REALIGNMENT	New	220.00	0.00
8	TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT	New	120.00	40.00
9	TO REMOVE AND REFIX REAR DOOR FIXING AND REALIGNMENT	New	220.00	80.00
10	TO REPLACE NEW PARTS, CUT, WELD, KNOCK AND ETC	New	1,540.00	800.00
11	TO RESPRAY ON AFFECTED AREAS	New	1,100.00	600.00
Gross Labour Cost (S\$)			4,310.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >