

ASS. REC. BY:

REF:

CS/CTL7022310 / Ctd 342

Special Instruction:

Survivor
Main

GQ

ASSIGNMENT (Office)

From (Person):

Joel Fion

of

CTL

Date/Time: 22-11-2017 3:02pm

Estimated Cost:

Bill to:

~~OD~~ / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDY 2747L

Insured:

EM 9399M

at Workshop m/s

Allswell Motor

Tel:

9147 8545

of

25 Dehu Lane 9

Policy No:

DMPCSN1660791701

Claim No:

SNM17D06661002/9

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16-11-2017

CA / REV / REP. / REV 24 HRS

Wp

23-11-2017 @ after 11am - 12pm

H.O.D. Endorsement:

Date/Time:

22/11/2017 4:27pm

Person Contacted:

Ben.

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SDY 2747L - CS3 / MS 617020865 / Wb	DA: 28/10/2017
	EM 9399M - CC3 / CTL700 8238 / Kwb302	DA: 24/04/2017

13/11/17

REF: C12

Surrey
Muller

ASSIGNMENT

From: _____ Date: 23.11.2017

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDY 2747L

at Workshop m/s Allwell Motor

of 25 Deft Lane 9

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

11am - 12pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDY 2747L Yr Regn: 25 Jun 2008

Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Corolla AH15 C.C. 1598

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 157077 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0538EE10.6111282

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD/A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 23-11-17

Survey held at w/s 12pm

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2/10 Finalized \$ 324.86 with Ben. (Red. 96.29, 22%)

RECEIVED 03 OCT 2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 1

1)

☐ : Final Report

Resurvey No. of Trip: 1

Survey Fee: 270

Date/Time, File Return to?

Transportation:

2)

Add Fee: ☐ : Site Insp (\$) S+RS, SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

Report Format: TP

Lump Sum / ☒ B (\$ 324.86)

TOTAL

270



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17022310/Grb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 22-11-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EM 9399M	Veh. Inspected	SDY 2747L
Policy No.	DMPCSN1660791701	Coverage (\$)	0.00
Claim No.	SNM17D06661C02/9	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	22/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/11/2017	Inspection Date	23/11/2017
Survey held at	25 DEFU LANE 9		
Repairer	ALLSWELL MOTOR TRADERS		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Nov 2017		22 Nov 2017 15:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		KOH MELVIN KENNY, ID: S8010648C							
Main Claimant:		ALLSWELL LEASING & LIMOUSINE PTE LTD, Co. Reg. No.: 201432541Z							
Vehicle Reg. No.:		SDY2747L	Date of Loss:	16/11/2017 18:00 - :59					
Claim Type:		TP / SNM17D06661C02/9	Policy/Cover Note No.:	DMPCSN1660791701 (Comprehensive)					
Vehicle Reg. No. (Insured):		EM9399M	Policy No. (Claimant):	5095581315					
			Excess:	S\$0.00					
Repairer:		Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]							
Claimant's Insurer:		NTUC Income Insurance Co-operative Ltd (HQ) - Tel:							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/12/2017]							
Driver/Custodian (Insured):		KOH MELVIN KENNY (37 / Male), NRIC: S8010648C							
Adj Asg. Remarks:		NO ESTIMATES. GUO QIANG SELECTED AS SJE FOR WP PRS							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	2541Z
Vehicle Details	
Vehicle No.	SDY2747L
Vehicle to be Exported	No
Intended De-registration Date	24 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	COROLLA ALTIS 1.6 AUTO
Primary Colour	Silver
Manufacturing Year	2008
Engine No.	3ZZ4776498
Chassis No.	MR053ZEE106111282
Maximum Power Output	80.0 kW (107 bhp)
Open Market Value	\$16,777.00
Original Registration Date	25 Jun 2008
First Registration Date	25 Jun 2008
Transfer Count	1
Actual ARF Paid	\$16,777.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	24 Jun 2018
PARF Rebate Amount	\$8,388.00
Intended COE Rebate Details	
COE Expiry Date	24 Jun 2018
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$14,101.00
COE Rebate Amount	\$822.00
Total Rebate Amount	\$9,210.00

The information contained herein is correct as at 24 Nov 2017

OK

SINGAPORE ACCIDENT STATEMENT**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/11/2017 10:11
Date Of Accident	16/11/2017 18:55
Exact Location Of Accident	KPE TUNNELAFTER THE EXIT OF UPPER PAYA LEBAR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDY2747L
Insured/Policyholder	
Name Of Registered Owner	ALLSWELL LEASING & LIMOUSINE PTE LTD
Co Reg No	201432541Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-64625405

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5095581315
Cover Note Number	

Driver

Name of Driver	YAP SIEW HONG
NRIC No	S1749376J
Date Of Birth	05/06/1966
Occupation	OUTDOOR
Date Of Driving Pass	20/05/1994
Driving Experience	23 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94311275

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER & LEASEE

Vehicle Registration Number of Driver's Own Vehicle -

-

-

Insurance Company of Driver's Own Vehicle -

-

-

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 4

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] SEE POLICE REPORT ATTACHED

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

On 16/11/2017, 18:55 when my car travelling along KPE tunnel on the second lane, that is after the exit of upper paya lebar, i heard the bang and saw there was a white car turning out from first lane. My right mirror, casing and signed light were damaged. We moved to the shoulder, took photos but he didn't bring NRIC and LICENSE.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number EM9399M

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

17/11/17

Driver's Signature

(If driver is not the policyholder)

Date & Time: 17/11/17


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/11/17, 6.55pm when my car travelling along KPE tunnel on the second lane, that is after the exit of Upper Paya Lebar. I heard the bang and saw there was a white car turning out from first lane. My right mirror, casing and signal light were damaged.

We moved to the shoulder took photos but he said he didn't bring NRIC and licence.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: *Beli*
 Date & Time: 17/11/17



Driver's Signature: *Jimmy*
 (If driver is not the policyholder)
 Date & Time: 17/11/17

Reporting Centre Personnel's Signature: *Beli*
 Name:
 NRIC/FIN No.:

Wilson

For your endorsement:

(3rd party claim} against China Tariff EU19399M)

Vehicle No. : SDY274TL
 Make & Model : Corolla Altis 1.6A
 Chassis No. : _____
 Date of survey : _____

Submitted by : Bun
Year Manufacture : 2008
Engine No. : _____

[illegible]

12.5

$$385.15$$

$$- 25\% : 288.86$$

Total	\$42.15
-------	---------

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

Total : 324.86

1 Day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Additional labor cost**
- No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Nov 2017		22 Nov 2017 15:02 Edit Adj Rpt	S\$324.86 Edit Estimates	S\$324.86 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: KOH MELVIN KENNY , ID: S8010648C									
Main Claimant: ALLSWELL LEASING & LIMOUSINE PTE LTD , Co. Reg. No.: 201432541Z									
Vehicle Reg. No.: SDY2747L		Date of Loss: 16/11/2017 18:00 - :59 [112 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM17D06661C02/9		Policy/Cover Note No.: DMPCSN1660791701 (Comprehensive)							
Vehicle Reg. No. (Insured): EM9399M		Policy No. (Claimant): 5095581315							
		Excess: S\$0.00							
Repairer: Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 01/12/2017]									
Driver/Custodian (Insured): KOH MELVIN KENNY (37 / Female) , NRIC: S8010648C Email:									
Adj Asg. Remarks: NO ESTIMATES. GUO QIANG SELECTED AS SJE FOR WP PRS									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDY2747L (SNM17D06661C02/9)
[EM9399M]

TP

ALLSWELL LEASING & LIMOUSINE PTE LTD



















Nov 16 2017 6:00PM

[KOH MELVIN KENNY]

Allswell Motor Traders







Upload Documents | Upload Photos | Compose New Letter



View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
1	18/11/17 12:10	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
1	18/11/17 11:43	Identification Card [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	18/11/17 11:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	18/11/17 11:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	18/11/17 11:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	18/11/17 12:10	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/10/19 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
2	02/10/19 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
3	02/10/19 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
4	02/10/19 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
5	02/10/19 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
6	02/10/19 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
7	02/10/19 17:52	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
8	02/10/19 17:52	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
9	02/10/19 17:52	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/11/17 15:02	OI GIA REPORT	 Load PDF	
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
1	18/11/17 11:58	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	18/11/17 11:58	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
1	18/11/17 12:10	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
1	18/11/17 11:43	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
2	18/11/17 11:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	18/11/17 11:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	18/11/17 11:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	18/11/17 12:10	Police Report	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Allswell Motor Traders (HQ)		Thumbnail	Print
No	Finalized On	Allswell Motor Traders (HQ)		Thumbnail	Print
1	18/11/17 11:58	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	18/11/17 11:58	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17022310/GCD3E2

Date: 04/10/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1660791701

Claimant
Vehicle No : SDY2747LInsured
Vehicle No : EM9399M

Date of Loss: 16/11/2017

Nature of Claim: TP

Claim
No: SNM17D06661C02/9

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDY2747L

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4776498

Reg. Date: 25/06/2008 (Man. Year: 2008)

Chassis No: MR053ZEE106111282

Colour: Silver

Odometer: 157077 km

Engine Capacity: 1598 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	385.15	288.86	96.29	25.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	36.00	36.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	421.15	324.86	96.29	22.86
+ GST 7.00/7.00% (S\$)	29.48	22.74	6.74	22.86
Nett Amount (S\$)	450.63	347.60	103.03	22.86

INSPECTION

Date of Assignment: 22/11/2017

Date Inspected: 23/11/2017 Inspected At:

Allswell Motor Traders (HQ)
25 Defu Lane 9
Singapore 539266

Estimated Period of Repair: 1.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDY2747L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT SIDE MIRROR	Distorted	385.15 F	*385.15 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	385.15
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00
					Total Parts (\$\$)	385.15
						288.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING	New	36.00	36.00
Gross Labour Cost (S\$)			36.00	36.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >