

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : KL1LA69RJBB128019

Mileage :

0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,690.00	0.00
Total Spray Painting Charges	: 2,970.00	0.00
Total Material Charges	: 13,347.58	13,347.58
Other Charges	: 1,750.00	0.00
<b>TOTAL</b>	<b>: 19,757.58</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 19,750.00</b>	<b>0.00</b>
No. of Repair Days	: 10.00	0.00 10 days - Lumper
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 21/11/2017 11:37:53 AM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/11/2017 11:37:53 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date: