

Signature: *R. Rouse*

REF: NS/INC17022325 / R116n2

536K

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: FY 8785M  
 Policy No. 5064505474-03 040317-030318  
 Claims No. MT/097621-001  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. of Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHB 5261A Yr Regn: 2017 / 04  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Prius Hybrid 1798  
 Colour: MAKOWN A/C: Insured / Std / NI / NA  
 Sp. Reading: 18834 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: 3T0KB 3Fu8035 72673  
 Gen. Cond: Good / ☒ Fair / Poor / Burnt  
 Steering: ☒ Order / Jammed / Leaked / Burnt or  
 Brake: ☒ Order / Jammed / Leaked / Burnt or  
 Modi: ☒ Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/65R15  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / ☒ YOKO or \_\_\_\_\_

Front		Rear	
R/Bal. <u>5</u> mm		R/Bal. <u>5</u> mm	
L/Bal. <u>5</u> mm		L/Bal. <u>5</u> mm	
D.O.A. <u>20/11/17</u>		D.O.I. <u>21/11/17</u>	

Survey held at SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
b/d Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHB 5261A - 043 MTH 16010745 / Klyb3g2  
FY 8785M - X

DOT: 070016

11/17/2126

NRCL

Part by Part \$2556.91 (Red: 2755.92: 151%)

FY 8785M

RECEIVED 25 NOV 2017

Date/Time, File Pass to?

29/11 Typst

Date/Time, File Return to?

2)

☐ Preli. Report  
☒ Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$ )  
☐ Interview (\$ )  
☐ Tech. Invs (\$ )  
☐ Weekend (\$ )

\$ + RS \$

Photos

Others

TOTAL

Report Format: TP

Lum Sum / I.B.I: (\$ 2556.91)

160
35
195



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17022325/R1tb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 22-11-2017

189556



Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FY 8785M	Veh. Inspected	SHB 5261A
Policy No.	5064505474-03	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/11/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	20/11/2017	Inspection Date	21/11/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident

Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5064505474-03	AB HASAN BIN AHMAD IDRIS	S0248366A	GMC	Third Party	FY8785M	FY8785M	04/03/2017	03/03/2018

## Denise Tay (LKKAUTO)

---

**From:** mtreg <mtreg@income.com.sg>  
**Sent:** Wednesday, 29 November, 2017 12:43 PM  
**To:** Denise Tay (LKKAUTO)  
**Subject:** REQUEST CLAIM NUMBER

Hi,

All claims created.

**Samsia**  
Senior Admin Assistant, Motor Insurance  
[www.income.com.sg](http://www.income.com.sg)



---

**From:** Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]  
**Sent:** Wednesday, November 29, 2017 10:51 AM  
**To:** mtreg <mtreg@income.com.sg>  
**Subject:** REQUEST CLAIM NUMBER

Dear Sir,

### TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date
1	MT/0971613-001	SMRT TAXIS PTE LTD	SHB 535T	FBG 907Z	
2	MT/0971616-001	SMRT TAXIS PTE LTD	SHC 4736Z	SJA 2764S	
3	MT/0969589-002	SMRT TAXIS PTE LTD	SHB 736E	FY 4059C	
4	MT/0971621-001	SMRT TAXIS PTE LTD	SHB 5261A	FY 8785M	
5	MT/0965908-003	SMRT TAXIS PTE LTD	SHF 210J	SJQ 586T	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/11/2017 08:59
Date Of Accident	20/11/2017 14:50
Exact Location Of Accident	CLEMENTI ROAD JUNCTION CLEMENTI AVE 2
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5261A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

### Driver

Name of Driver	TAN NORMAN
NRIC No	S0490084G
Date Of Birth	07/11/1948
Occupation	OUTDOOR
Date Of Driving Pass	14/03/1979
Driving Experience	38 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? YES  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 3

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name TECK GHEE NEIGHBOURHOOD POLICE POST  
 Police Station Address ROAD: BLK 321 ANG MO KIO STREET 31, POSTCODE: 560321, COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-4599999 - FAX NO: 64574478  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20171120/2120 On 20/11/2017 at about 2.45pm, I was driving (SHB5261A) along Clementi Road (towards Woodlands) and approaching to junction with Clementi Avenue 2. I was driving on the 2nd lane from the right (total 4 lanes). The traffic light was green to my favour and I saw a few vehicles stopping at the opposite direction inside the pocket to wait to turn right. As I was nearing the junction, suddenly a motorcycle FY8785M, from the opposite direction made a right turn and was in my path. As such, I took evasive actions and swerve my car to the left. However, the motorcycle hit my rear right passenger door. Traffic police and ambulance came to the scene. I was then advised by the Traffic Police officer to lodge an accident report. There is an in-cam footage in my taxi which was handed over to the traffic Police officer. I suffered pain on my neck due to the accident.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FY8785M  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

**DETAILS OF INJURED PERSON 1**

Name UNKNOWN RIDER

Approximate Age

Injuries Sustain

Injured person in which vehicle? FY8785M

Were seat belts worn?

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

**DETAILS OF INJURED PERSON 2**

Name TAN NORMAN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHB5261A

Were seat belts worn? YES

Was injured conveyed to hospital by ambulance? NO

Address

Postcode



SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:







**SINGAPORE  
POLICE FORCE**



T/20171120/2120

1 of 3

Report No. T/20171120/2120

Police Station Of Origin:  
Teck Ghee NPP  
321 Ang Mo Kio Street 31 SINGAPORE  
560321  
Tel No: 1800-4599999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 20/11/2017 17:16		Vide Report No.: D/20171120/0069	Station Diary No.: 25
<b>Informant's Particulars</b>			
Name of Informant: TAN NORMAN		Address: APT BLK 406B FERNVALE ROAD #02-47 SINGAPORE 792406	
ID Type / ID No.: NRIC NO / S0490084G		Contact No.: Home/Office:	Mobile: 81540218
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 69	Date of Birth: 07/11/1948	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 2B,2A,2,3	
		Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 20/11/2017 14:50	Type of Location: X-Junction
Location: Along Road 1 Traveling Toward Road 2 CLEMENTI ROAD CLEMENTI AVENUE 2				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FY8785M	Motorcycle				Slightly Damaged	0
SHB5261A	Car				Slightly Damaged	2

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20171120/2120

2 of 3

Police Station Of Origin:  
Teck Ghee NPP  
321 Ang Mo Kio Street 31 SINGAPORE  
560321  
Tel No: 1800-4599999

Report No. T/20171120/2120

## CONTINUATION OF REPORT

Name	Unknown		ID No.	NIL
Related Vehicle	FY8785M (Motorcycle)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious	
<b>Driver</b>				
Name	TAN NORMAN		ID No.	S0490084G
Related Vehicle	SHB5261A (Car)		Contact No.	81540218
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

**Brief Details.**

On 20/11/2017 at about 2.45pm, I was driving (SHB5261A) along Clementi Road (towards Woodlands) and approaching to junction with Clementi Avenue 2. I was driving on the 2nd lane from the right (total 4 lanes). The traffic light was green to my favour and I saw a few vehicles stopping at the opposite direction inside the pocket to wait to turn right. As I was nearing the junction, suddenly a motorcycle FY8785M, from the opposite direction made a right turn and was in my path. As such, I took evasive actions and swerve my car to the left. However, the motorcycle hit my rear right passenger door.

Traffic police and ambulance came to the scene. I was then advised by the Traffic Police officer to lodge an accident report. There is an in-cam footage in my taxi which was handed over to the Traffic Police officer. I suffered pain on my neck due to the accident.



**SINGAPORE  
POLICE FORCE**



T/20171120/2120

Police Station Of Origin:  
Teck Ghee NPP  
321 Ang Mo Kio Street 31 SINGAPORE  
560321  
Tel No: 1800-4599999

3 of 3

Report No. T/20171120/2120

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sr Staff Sgt NORSHAFIK BIN AB HAMID	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 20/11/2017 17:16
Officer In Charge Of Case: TP / GIT / SI YEO CHUN JIAN Contact No.: 65476213	Classification Of Case: SN 005
Authentication Stamp NP168	Signature

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type	Company
Owner ID	5369K
<b>Vehicle Details</b>	
Vehicle No.	SHB5261A
Vehicle to be Exported	No
Intended De-registration Date	29 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	PRIUS HYBRID 1.8 CVT
Primary Colour	Maroon
Manufacturing Year	2017
Engine No.	2ZRS096813
Chassis No.	JTDKB3FU803572673
Maximum Power Output	90.0 kW (120 bhp)
Open Market Value	\$29,007.00
Original Registration Date	10 Oct 2017
First Registration Date	10 Oct 2017
Transfer Count	0
Actual ARF Paid	\$5,000.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	09 Oct 2025
PARF Rebate Amount	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date	09 Oct 2025
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$34,052.00
COE Rebate Amount	\$33,457.00
<b>Total Rebate Amount</b>	<b>\$37,207.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Nov 2017

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5261A  
 Ref. No : TAX/11/17/2126  
 Reg. Date : 10/10/2017  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS4  
 Name of Driver : TAN NORMAN  
 Type of Accident : HEAD TO SIDE  
 Date / Time of Accident : 20/11/2017 02:50:00 PM  
 Accident Reported Date / Time : 21/11/2017 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024093196  
 Special Instruction to ARC, if any :  
 FY8785M / NTRC / Recovery by 4 point  
 Prepared Date : 21/11/2017 09:18:25 AM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKB3FU803572673


Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 918.00	0.00
Total Material Charges	: 2,849.83	2,849.83
Other Charges	: 700.00	0.00
<b>TOTAL</b>	<b>: 5,312.83</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 5.00	0.00 3 days - p/p
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 21/11/2017 03:54:29 PM	01/01/1900 12:00:00 AM

  
21/11/17  
@ 1630

Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/11/2017 03:54:29 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :



## Section D - Details of Repair Estimates

### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	845.00	0.00 <del>200</del> 150
<b>Total Labour</b>	<b>845.00</b>	<b>0.00</b>

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR RH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
RESPRAY WHEEL CAP	180.00	0.00 X
TO RESPRAY RIM	180.00	0.00 <del>150</del> 50
<b>Total Spray Painting &amp; Panel Beating</b>	<b>918.00</b>	<b>0.00</b>

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 20
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 <del>80</del> 30
TO REMOVE AND REFIT TYRE	120.00	0.00 <del>100</del> 30
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 40
TO TRANSFER DOOR MECHANISM	120.00	0.00 X
<b>Total Other Costs</b>	<b>700.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6700347210			PANEL SUB-ASSY, REAR DOOR, RH	1	1,243.90	25.00	932.92	Replace	Replace <i>Repair</i>	No
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace <i>Re</i>	No
7585047910			MOULDING ASSY, BODY ROCKER PANEL, RH	1	576.00	25.00	432.00	Replace	Replace <i>DE</i>	No
4260247180			CAP SUB-ASSY, WHEEL	1	175.80	25.00	131.85	Replace	Replace <i>cut</i>	No
4261147450			WHEEL, DISC	1	1,555.10	25.00	1,166.32	Replace	Replace <i>cut</i>	No
			TYRE	1	126.74	0.00	126.74	Replace	Replace <i>cut</i>	No
<b>TOTAL MATERIALS</b>							<b>2,849.84</b>	<b>2,849.83</b>		
<b>TOTAL MATERIALS(Discounted)</b>							<b>2,849.83</b>	<b>2,849.83</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592


Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

## SMRT Accident Vehicle Repair Estimates

## Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5261A  
Ref. No : TAX/11/17/2126  
Reg. Date : 10/10/2017  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS4  
Name of Driver : TAN NORMAN  
Type of Accident : HEAD TO SIDE  
Date / Time of Accident : 20/11/2017 02:50:00 PM  
Accident Reported Date / Time : 21/11/2017 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : Rasul  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024093196  
Special Instruction to ARC, if any :  
FY8785M NTUC PIP  
Before paint photo, After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL  
/ HP : 9001 0068. email: rasul@lkkauto.com  
Prepared Date : 21/11/2017 09:18:25 AM



Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date

2nd witness

Date

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

Vehicle Return Time:

SMRT staff sign:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKB3FU803572673

Mileage


0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	150.00
Total Spray Painting Charges	: 918.00	350.00
Total Material Charges	: 1,916.91	1,916.91
Other Charges	: 700.00	140.00
<b>TOTAL</b>	<b>: 4,379.91</b>	<b>2,556.91</b>
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	3.00
Prepared / Adjusted By	:	RASUL (LKK)
Arc / Surveyor Sing Off Date	: 21/11/2017 03:54:29 PM	21/11/2017 04:55:26 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/11/2017 03:54:29 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No

QN-1711-0683

Invoice No :

Quotation Date

27/11

Invoice Date :

Invoice Amount :

Prepared Date :

# Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	845.00 ✓	150.00
<b>Total Labour</b>	<b>845.00</b>	<b>150.00</b>

## Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR RH	378.00 ✓	200.00
TO RESPRAY ROCKER PANEL MOULDING	180.00 ✓	100.00
RESPRAY WHEEL CAP	180.00 ✗	0.00 <i>na x</i>
TO RESPRAY RIM	180.00 ✓	50.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>918.00</b>	<b>350.00</b>

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 <i>na</i>
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30.00
TO REMOVE AND REFIT TYRE	120.00	30.00
TO REPLACE SUNDRY PARTS	100.00	20.00
TO WASH AND VACUUM	60.00	40.00
TO TRANSFER DOOR MECHANISM	120.00	0.00 <i>na</i>
<b>Total Other Costs</b>	<b>700.00</b>	<b>140.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
6700347210			PANEL SUB-ASSY, REAR DOOR, RH	1	1,243.90	100.00	0.00	Replace	Repair	No
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace	No
7585047910			MOULDING ASSY, BODY ROCKER PANEL, RH	1	576.00	25.00	432.00	Replace	Replace	No
4260247180			CAP SUB-ASSY, WHEEL	1	175.80	25.00	131.85	Replace	Replace	No
4261147450			WHEEL, DISC	1	1,555.10	25.00	1,166.32	Replace	Replace	No
			TYRE	1	126.74	0.00	126.74	Replace	Replace	No
TOTAL MATERIALS							1,916.92	1,916.91		
TOTAL MATERIALS(Discounted)							1,916.91	1,916.91		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

1916.91  
+ 150.00  
+ 490.00

2556.91

3 days

6,000.54





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Thatcham escribe

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17022325/R1tbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 04-12-2017

189556



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FY 8785M	Veh. Inspected	SHB 5261A
Policy No.	5064505474-03	Coverage (\$)	0.00
Claim No.	MT/0971621-001	Excess (\$)	0.00
Assign From		Assign Date	21/11/2017

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS HYBRID 1.8	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU803572673	Colour	MAROON
Odometer	18834	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	5 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	5 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	20/11/2017	Inspection Date	21/11/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5261A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	MOULDING ASSY,BODY ROCKER PANEL,RH (DISC 25%)	DEFORMED	576.00	432.00
1	CAP SUB-ASSY,WHEEL (DISC 25%)	CUT	175.80	131.85
1	WHEEL,DISC (DISC 25%)	CUT	1,555.10	1,166.32
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	TYRE (SN)	CUT	126.74	126.74
1	PANEL SUB-ASSY,REAR DOOR,RH	TO REPAIR	1,243.90	-
			3,737.54	1,916.91
<b>LABOUR</b>				
THATCHAM STANDARD REPAIR TIME ON BODY WORKS.			1,285.00	210.00
THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.			1,018.00	370.00
TO REPLACE SUNDRY PARTS.			100.00	20.00
TO WASH AND VACUUM.			60.00	40.00
			2,463.00	640.00
<b>GRAND TOTAL</b>			<b>6,200.54</b>	<b>2,556.91</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>2,556.91</b>

Report Ref No. NS/INC17022325/R1tbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.