

REC. BY:

REF:

CS3 / LCR 17022368 / R162

Special Instruction:

DAR &amp; days

Supervisor:

Rasul

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

LCR

Date/Time:

22.11.2017 2.01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJZ 90106

Insured:

SLG 7132C

at Workshop m/s

Tel:

9117 0086

of

71 Woodlands Ave 10 # 02-07

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A. 11/11/2017

CA / REV / REP. / REV 24 HRS Wp1

H.O.D. Endorsement:

Date/Time:

23-11-2017 9.22am

Person Contacted:

Ah Xiang

Vehicle IN / OUT

Date/Time

Action/Instruction ( X ) Estimate

SJZ 90106 - CS3 / ALG 14005138 / Any3w2

DA: 131314

SLG 7132C - X

Dismantle Part: 27.11.2017





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/LCR17022368/R1b	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 23-11-2017	
		Code : LCR	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SLG 7132G	Veh. Inspected	SJZ 9010G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	22/11/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	11/11/2017	Inspection Date	23/11/2017
Survey held at	71 WOODLANDS AVE 10 #02-09		
Repairer	-		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLG7132C AND SJZ9010G  
ON 11/11/2017

From: Chin, Lee-Ying  
To: 'assignments', 'Admin A'  
Cc: Fong, Andy-SY  
Sent: Wednesday, 22 November, 2017 2:00:11 PM  
Attachments: 0889\_001.pdf 0910\_001.pdf

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

From: [teamsiti@visionlawllc.com](mailto:teamsiti@visionlawllc.com)  
To: [Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com)  
Subject: PRI on SJZ 9010 G  
Date: Wed, 22 Nov 2017 04:54:33 +0000  
Dear Lee Ying

As spoken just, we were informed that our client's vehicle can be inspected at:

71 Woodlands Ave 10  
#02-09 Woodlands Industrial Xchange  
Singapore 737743

Please contact Ah Xiang at 9117 0086 for the arrangement.

Tks n Rgds  
Siti Aminah  
(Secretary)  
VISION LAW LLC  
133 New Bridge Road  
#18-01 Chinatown Point  
Singapore 059413  
Tel: 6534 2811  
Fax: 6535 6802

---

**DISCLAIMER:**

This message (and its attachment(s), if any) is intended solely for the recipient(s) addressed above and may contain privileged/confidential information. If you are not the intended recipient of this e-mail, we would be grateful if you could kindly notify us and delete this message (and its attachment(s), if any) from your computer. You should not read, copy, use or disseminate this message (or its attachment(s), if any) in any form or manner.

---

VISION LAW LLC  
Advocates & Solicitors  
(Incorporated with limited liability)  
Unique Entity No. 200721148H  
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413  
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

**DISCLAIMER:**

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

# Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin ( )**: Case handler to make sure all information created by the assignment team are ACCURATE.

## (1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**Surveyor ( )**: Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

## (2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

## (3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RS), TMI, MSIG
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days


## (4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

\*C: Critical \*N: Non-Critical

21/05/2014

*From Peruvian*

Battery Bracket

MOTOR CAR (STD)

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor	✓BR		
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel	✓DO		
1098	995147	Frt LH Fender <del>Emblem</del>	✓DO		
1099	995148	Frt LH Fender Protector	✓TN		
1100	991740	Frt LH Fender Inner Shield	✓TN		
1101	995179	Frt LH Mudflap	✓DM		
1102	995170	Frt LH Wheel Rim	✓SCR		
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992093	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt FH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

9/4/2018



Condition (CDN)

(0) Bent (1) Bent (2) Bent (3) Bent (4) Cracked (5) Cracked (6) Scratched  
(7) Deformed (8) Stuffed (9) Buckled (10) Broken (11) Accidental (12) Missing  
(13) Torn (14) Unconscious (15) Not Working

## MOTOR CAR (LH)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Back (7)  
(4) Not Consistent (NC)

Aug 2003

## Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	✓	00	
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator	BT	✓	
1264	991596	Frt LH Door Glass Regulator Motor	BT	✓	
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock	BT	✓	
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			

Vehicle No: SJZ 9010 G

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door	✓	scr R	
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1143	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker			

No of Items: \_\_\_\_\_

Assessor: \_\_\_\_\_

\* 2 days

# MOTOR CAR (UC)

## Undercarriage

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber		2	
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm	BT	2	
1376	995199	Frt LH Knuckle Arm Bearing	BT	2	
1377	995178	Frt LH Lower Arm	BT	2	
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

Vehicle No: SJZ 9010 G

NAC	INC	Item	CON	AC	Qty
1428	991935	Frt RH Shock Absorber			
1429	991944	Frt RH Shock Absorber Mounting			
1430	990632	Frt RH Coil Spring			
1431	991844	Frt RH Knuckle Arm			
1432	991845	Frt RH Knuckle Arm Bearing			
1433	991851	Frt RH Lower Arm			
1434	992064	Frt RH Upper Arm			
1435	992040	Frt RH Tie Rod			
1436	991692	Frt RH Drive Shaft			
1437	990661	Frt RH Control Arm			
1438	992062	Frt RH Trailing Arm			
1439	991848	Frt RH Leaf Spring			
1440	991293	Frt RH Brake Disc Rotor			
1441	991281	Frt RH Brake Caliper			
1442	991292	Frt RH Brake Pipe			
1443	991287	Frt RH Brake Hose			
1444	991295	Frt RH Brake Sensor Wire			
1445	993720	Rear RH Shock Absorber			
1446	993723	Rear RH Shock Absorber Mounting			
1447	993173	Rear RH Coil Spring			
1448	993550	Rear RH Knuckle Arm			
1449	993551	Rear RH Knuckle Arm Bearing			
1450	993601	Rear RH Lower Arm			
1451	993885	Rear RH Upper Arm			
1452	993322	Rear RH Drive Shaft			
1453	993178	Rear RH Control Arm			
1454	995117	Rear RH Trailing Arm			
1455	995110	Rear RH Leaf Spring			
1456	992942	Rear RH Brake Disc Rotor			
1457	992938	Rear RH Brake Caliper Assy			
1458	990434	Rear RH Brake Pipe			
1459	992947	Rear RH Brake Hose			

*John*  
9/10/2018

No of Items:

Assessor:



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/11/2017 15:55
Date Of Accident	11/11/2017 14:45
Exact Location Of Accident	FROM ORCHARD LINK TOWARDS ORCHARD ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ9010G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN KIM GUAN (CHEN JINYUAN)
NRIC No	S7313758F
Email Address	MTAN0901@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81889010
Alternative Phone No	OFFICE-81889010

### Vehicle Particulars

Manufacturer	AUDI
Model	A4 1.8
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10544024
Cover Note Number	N.A

### Driver Particulars

Name of Driver	TAN KIM GUAN (CHEN JINYUAN)
NRIC No	S7313758F
Date Of Birth	27/03/1973
Occupation	INDOOR
Date Of Driving Pass	17/07/1992
Driving Experience	25 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81889010
Fax Number	
Contact Number	OFFICE-81889010
Email Address	MTAN0901@GMAIL.COM

Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident SIDE SWIPE  
 Weather Conditions DRIZZLING  
 Road Surface WET

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

Refer to attached statement.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: WILL FORWARD TO INSURANCE TEAM ONCE INSURED SEND  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLG7132C  
 Vehicle Make/Model/Colour MAZDA3  
 Details Of Properties  
 Name of Driver VINOTH DANIEL MATHIALAGAN  
 NRIC/Passport Number S9021956A  
 Contact Number 97665149  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver) 1

#### Details of Witness

Name  
 Phone Number  
 Email Address



## ACCIDENT STATEMENT (2000 characters)

On 11/11/17 around 245pm and weather is drizzling, I SJZ9010G was approaching from Orchard link towards Orchard Road. Before the red light turns into green, I had checked that there is no pedestrian crossing before I start moving off. As move off from the traffic junction after the traffic light turn into green, I was keeping to my lane towards Orchard road. Moving off less than 30m , out of sudden, a vehicle from the left side crash into my passenger side of the vehicle. Fortunately ,no one was hurt during the accident.

Taxi Voucher No.:

## DECLARATION

I/We declare that the above particulars &amp; information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MUHAMMAD SUMARDI BIN MOHD AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

13 November 2017 12:41 pm

Date/Time:

13 November 2017 12:41 pm

**Boey**

---

**From:** Marcus Tan <mtan0901@gmail.com>  
**Sent:** Thursday, 16 November, 2017 2:12 PM  
**To:** Boey  
**Cc:** group@ajaxmars.com  
**Subject:** Re: GIA Report - SJZ9010G  
**Attachments:** GIA statement V2.docx; Untitled attachment 00482.txt; image1.jpeg; Untitled attachment 00485.txt

Hi Boey,

Please find attached the revised statement for your filing to proceed with the third party claim against the other party.

Attached is the mutual settlement form which was signed off by the other party as part of the accident documents.

Kindly acknowledge upon the receipt of the files and send me a copy of the final GIA report once it's available.

Thanks in advance.



# Mutual Settlement Form

## MUTUAL SETTLEMENT FORM FOR MOTOR ACCIDENT

AIG

### 1. WE, THE UNDERSIGNED HEREBY AGREE TO MUTUALLY SETTLE AMONG OURSELVES A MOTOR ACCIDENT AS FOLLOWS:



Date / Time:	11 NOV 2017 / 1500hr
Along:	Orchard Road
Involving Vehicle Number(s):	SJZ 9010 G & SLG 7132 C

### 2. BOTH PARTIES HAVE AGREED TO SETTLE THIS MATTER AMICABLY AS FOLLOWS:

\*Delete (A) and (B) as applicable.

(A) Neither party shall be liable to compensate the party for any loss or damages (direct or indirect) incurred or to be incurred as a result of the accident.

(B) Without admission of liability, Vineth Daniel S9021956A (Name) (Party paying compensation) has paid a sum of S\$ \_\_\_\_\_ (Amount) which Tan Kim Guan SJ313758P (Owner of vehicle receiving compensation) herewith acknowledge receipt in full and final settlement of damages and costs incurred as a result of this accident. \* Amount to be advised on Monday 13/11/17.

Signature: 	Signature: 
Name: Tan Kim Guan	Name: Vineth Daniel
I/C No: SJ313758P	I/C No: S9021956A
Address: 52 Hume Avenue, #04-14 Singapore 596230	Address: 121 Rivervale Drive #10-414 5540121
Vehicle No.: SJZ 9010 G	Vehicle No.: SLG 7132 C
Contact No.: 81889010	Contact No.: 97665149
Date: 11/11/17	Date: 11/11/17

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building 78 Shenton Way #07-16 Singapore 079120  
Tel: 6419 3000  
Co. Reg. No. 201009404M

Copyright © 2015 AIG Asia Pacific Insurance Pte. Ltd. All rights reserved.

## Statement

On 11/11/17, approximately 1500hrs, I, Mr Tan Kim Guan, driver of vehicle no. SJZ9010G was traveling along Orchard link towards the Orchard Road heading in the direction towards Istana. The traffic was heavy and congested for both Orchard Link and Orchard Road. I was the first car at the traffic light. When the traffic light turns green, I start to drive off cautiously, ensuring no pedestrians are crossing the road. While I slowly approaching the junction, I noticed many cars along Orchard Road not able to move and was stationary at the yellow box due to the traffic congestion flow along Orchard Road. Although it was a green light indicating I have the right of way to proceed towards Orchard Road, I did note that there was a car that could not move and stopped at the traffic junction. With caution, I slowly drove towards the 1<sup>st</sup> stationery car. When approaching traffic junction just about passing the stationery car, I also did a quick check on my right side of the traffic for any blind spot as I was at the outer left lane turning and approaching to Orchard Road. When I was slowly driving by the 1<sup>st</sup> stationery car, the vehicle SLG7132C suddenly appeared abruptly and crashed into the front left side of my car. The car was switching lane from back of the stationery car to the outer left lane at the major junction, when my traffic flow is in a green light indicating the right of way. I tried to do an emergency brake to prevent the accident but he was too fast to avoid this accident. We came down to check our car damages and agree to move to another location to exchange details, as the traffic was bad and there was no injury during the accident.

After stopping our vehicle at a safe location, we had a short discussion and eventually the driver of SLG7132C, Mr. Vinoth Daniel Mathialagan asking for my agreement to proceed with the mutual settlement, agreeing that he is willing to compensate the damage of my car, as part of his negligence. As it was a weekend, we could not submit any accident report on that day. We eventually agree to meet at my regular workshop on Monday to assess the cost of the damages that he will take liability to pay the damages. We sign off the mutual settlement form on that day and pending the advice of the cost of the repair for my car.

On Monday, 13/11/2017 around 1015 hrs, we met at my regular workshop and upon assessing the cost of my damages, he decided that the repair cost was too high for him and advice me to go ahead to submit an insurance claim against his insurance company, AIG.

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	18 Nov 2017 <a href="#">Edit Reg</a>		22 Nov 2017 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>	
						<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

**CLAIM SUBFOLDER DETAILS**

[Created by adjuster]

Insured: **LCRF PTE LTD**, Co. Reg. No.: 201624597K

Main Claimant: **TAN KIM GUAN (CHEN JINYUAN)**, ID: S7313758F

Vehicle Reg. No.: <b>SJZ9010G</b>	Date of Loss: 11/11/2017 00:00 - :59 [83 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type: <b>TP / 6670212675SG</b>	Policy/Cover Note No.: 0999995030 (Comprehensive)
Vehicle Reg. No. (Insured): <b>SLG7132C</b>	Policy No. (Claimant):
	Excess:

Repairer: **- Not Applicable - (-)**

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (Express)** - Tel: 65-6419-3000 ... [Handled by **Chew, Mavis**] Chew.Mavis@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **MOHD RASUL**] ... [Final Rpt due 26/12/2017]

**ASSOCIATED MAIL RECEIVED**

View All | Compose Case Mail

- AIG\_SG (15/12/2017): TP GIA REPORT

**ALL ASSOCIATED TASKS**














View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJZ9010G (6670212675SG)  
[SLG7132C]  
TP  
TAN KIM GUAN (CHEN JINYUAN)  
Nov 11 2017 12:00AM  
[LCRF PTE LTD]

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Assessment Reports															1 per page		<input checked="" type="checkbox"/>	
No.	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print	
1	15/12/17 10:48		Accident Statement From: SC - Reg. No: SLG7132C, Claimant: LCRF PTE LTD												1	Load HTM		
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print	
1	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
2	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
3	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
4	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
5	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
6	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
7	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
8	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
9	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
10	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
11	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
12	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
13	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
14	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
15	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
16	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
17	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
18	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
19	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
20	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
21	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
22	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
23	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
24	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
25	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
26	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
27	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
28	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
29	09/04/18 17:05		General View												1	Load JPG		<input checked="" type="checkbox"/>
30	09/04/18 17:05		Photographs of Damaged Parts												1	Load JPG		<input checked="" type="checkbox"/>
31	09/04/18 17:05		Photographs of Damaged Parts												1	Load JPG		<input checked="" type="checkbox"/>
32	09/04/18 17:05		Photographs of Damaged Parts												1	Load JPG		<input checked="" type="checkbox"/>
33	09/04/18 17:05		Photographs of Damaged Parts												1	Load JPG		<input checked="" type="checkbox"/>
34	09/04/18 17:05		Photographs of Damaged Parts												1	Load JPG		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
35	09/04/18 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	09/04/18 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	09/04/18 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	09/04/18 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	09/04/18 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	09/04/18 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	09/04/18 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	09/04/18 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	09/04/18 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>



## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/LCR17022368/R1BE2

Date: 10/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995030  
 Claimant Vehicle No: SJZ9010G Insured Vehicle No: SLG7132C  
 Date of Loss: 11/11/2017 Nature of Claim: TP Claim No: 6670212675SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ9010G**  
 Make & Model: AUDI A4, 1.8 TFSI (A) Engine No: CDH099736  
 Reg. Date: 24/11/2010 (Man. Year: 2010) Chassis No: WAUZZZ8K0BA011260  
 Colour: Black Odometer: 154474 km  
 Engine Capacity: 1798 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/55 R19 Rear Tyre Size: 245/55 R19  
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 22/11/2017  
 Date Inspected: 23/11/2017 Inspected At: 71 WOODLANDS AVE 10 #02-09  
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WIPER WASHER TANK	Broken	0.00 F	*- F
2	1		*FRT LH FENDER	Dented	0.00 F	*- F
3	1		*FRT LH FENDER EMBLEM	Necessary	0.00 F	*- F
4	1		*FRT LH FENDER PROTECTOR	Torn	0.00 F	*- F
5	1		*FRT LH FENDER INNER SHIELD	Torn	0.00 F	*- F
6	1		*FRT LH MUDFLAP	Damaged	0.00 F	*- F
7	1		*FRT LH WHEEL RIM	Scratched	0.00 F	*- F
8	1		*FRT LH DOOR	Dented	0.00 F	*- F
9	1		*FRT LH DOOR GLASS REGULATOR	Bent	0.00 F	*- F
10	1		*FRT LH DOOR GLASS REGULATOR MOTOR	* Check	0.00 F	*- F
11	1		*FRT LH DOOR RUBBER	Bent	0.00 F	*- F
12	1		*FRT LH DOOR LOCK	Bent	0.00 F	*- F
13	1		*REAR LH DOOR	Repair	0.00 F	*- F
14	1		*FRT LH SHOCK ABSORBER	* Check	0.00 F	*- F
15	1		*FRT LH KNUCKLE ARM	Bent	0.00 F	*- F
16	1		*FRT LH KNUCKLE ARM BEARING	Bent	0.00 F	*- F
17	1		*FRT LH LOWER ARM	Bent	0.00 F	*- F
18	1		*FRT LH UPPER ARM	* Check	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >