

22/03/2012

ASS. REC. BY:

REF: CB / AL117022370 / T110521

Special Instruction:

Survivor: Taufik.

ASSIGNMENT (Office)

Insured:

From (Person): Auto - Assignment of AL11

Date/Time: 22/11/2017 5:02pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YN 4105K

Insured:

at Workshop m/s

Goldbell

Tel: 97557336

of

J9 Tanjung Perahu

Policy No: 1700045623

Claim No: 4675879577SG

Sum Insured:

Excess: TBA \$1000

Make of Veh:

D.O.A. 20.10.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 23.11.2017 9:31am

Person Contacted: William

Vehicle IN/OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	YN 4105K - X
27/11/17	Received file from assignment team.

merimen

Tanjung

REF. ALH

ASSIGNMENT

From: Date 23-11-2017

Estimated Cost:

① OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: YN 4105K

at Workshop no: Goldbell

of 29 Tanjung Perungu

Insured:

Policy No:

Claims No:


Sum Insured: Excess TBA

(Client's Record)

Make of Vehicle: William

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$70K.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repair: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

YN4105K

Yr Regn 2013 Sep

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Mitsubishi Canter FEC91 2998

Colour: White A/C Insured / Std / NI / NA

Sp Reading: T T/Radio Insured / Std / NI / NA

Eng No:

C No: FEC91HA00003

Gen: Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: W / S/Rim / STD A/Rim or

Tyre Size: F: 210/75 R17.5

R: 4 4(12)

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 7 mm R/Bal: 7/7 mm

L/Bal: 2 mm L/Bal: 7/7 mm

D/OA: D/OA: 23/11/17 @ 16:15

Survey held at: Goldbell Tg Perungu

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time Action/ Instruction

27/11/17 REV in merimen.

28/11/17 Victor ALH call informed - policy does not cover the cargo box. to reject OD claim as per instructed by UNW.

28/11/17 email to William, ALH reject OD claim.

30/11/17 received addendum GIA report from William.

1/12/17 Submit preliminary report.

RECEIVED 1 DEC 2017

Date/Time File Pass to:



: Preli. Report



: Final Report

Date/Time File Return to:

Days Of Repair: 12

Resurvey No. of Trip:

Survey Fee:

Transportation:

Lump Sum:

Depos:

Lump Sum:

Lump Sum:

Lump Sum:

Lump Sum:

Add Fee:



Site Insp: \$



Interview: \$



Tech Insp: \$



Witness: \$

Report Format:

Lump Sum (M.B.): \$

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG17022370/T1gb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 23-11-2017



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	YN 4105K
Policy No.	1700045623	Coverage (\$)	0.00
Claim No.	4675879577SG	Excess (\$)	0.00
Assign From	MERIMEN (AUTO-ASSIGNMENT)	Assign Date	22/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	20/10/2017	Inspection Date	23/11/2017
Survey held at	GOLDBELL ENGINEERING PTE LTD 29 TANJONG PENJURU SINGAPORE 609026		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Oct 2017 Sendback Est	22 Nov 2017 17:02 S\$22,760.00	22 Nov 2017 17:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	C K DEPARTMENT STORE, Co. Reg. No.: 52844511A, Tel: +6594492526		
Vehicle Reg. No.:	YN4105K	Date of Loss:	20/10/2017 18:00 - :59
Claim Type:	OD / 4675879577SG	Policy/Cover Note No.:	1700045623 (Comprehensive)
	Excess:		
Repairer:	Goldbell Engineering Pte Ltd (Tuas) 29, Tanjong Penjuru, 609026 West Coast - Tel: 6864 0695		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/12/2017]		
Driver/Custodian:	SHI JIANGUO (37 / Male), NRIC: G8467218T, Tel: +6594492526		
Adj Asg. Remarks:	Auto-assignment		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Ai Phing (LKKAUTO)

From: William Go Shaw Chan <WilliamGoSC@goldbell.com.sg>
Sent: Thursday, 30 November, 2017 5:54 PM
To: Ai Phing (LKKAUTO)
Cc: SUR; Ashlyn Chng
Subject: RE: YN 4105K AIG-OD (DOA 20-10-2017)

Dear Ai Phing,


Please be informed that my client has decided to drop this OD claim.

Thanks & Best Regards,



William Go Shaw Chan | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Tanjong Penjuru)
29 Tanjong Penjuru Singapore 609026



From: Ai Phing (LKKAUTO) [mailto:aiphing@lkkauto.com]
Sent: Tuesday, November 28, 2017 12:14 PM
To: William Go Shaw Chan <WilliamGoSC@goldbell.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: YN 4105K AIG-OD (DOA 20-10-2017)

Dear William,

As spoken, according to AIG policy does not cover the cargo box. To reject OD claim as per instructed by UW.

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Tuesday, 28 November, 2017 12:14 PM
To: WilliamGoSC@goldbell.com.sg
Cc: SUR
Subject: YN 4105K AIG-OD (DOA 20-10-2017)

Dear William,

As spoken, according to AIG policy does not cover the cargo box. To reject OD claim as per instructed by UW.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	21 Oct 2017 11:30	Cim Veh Model Changed		[] Merimen Administrator
2	21 Oct 2017 11:30	Cim Created	Reg No: YN4105K. Policy No: 1700045623. Acct Date: 2017/10/20. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA217139386	[I] Merimen Administrator
3	22 Nov 2017 16:37	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] WILLIAM GO SHAN CHAN
4	22 Nov 2017 16:37	Cim Veh Model Changed	(205014) MITSUBISHI CANTER 3.0 D FEB71ER4SDEC (CBU) (M).	[R] WILLIAM GO SHAN CHAN
5	22 Nov 2017 17:02	Cim Submitted	22760.00.	[R] WILLIAM GO SHAN CHAN
6	22 Nov 2017 17:02	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Auto-assignment	[A] Merimen Administrator
7	22 Nov 2017 17:02	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/01	[A] Merimen Administrator
8	22 Nov 2017 17:02	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Merimen Administrator
9	22 Nov 2017 18:22	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
10	23 Nov 2017 11:47	Cim Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 1000.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Chan, Kian Meng
11	23 Nov 2017 11:47	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
12	23 Nov 2017 15:19	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH	[A] CATHERINE CHONG KAI LING
13	27 Nov 2017 14:06	Adj Rpt Initiated		[A] LOW AI PHING
14	27 Nov 2017 14:09	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/12/01	[A] LOW AI PHING
15	27 Nov 2017 14:10	Adj Mandate Request	Cur.Reg:21790.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	[A] LOW AI PHING
16	28 Nov 2017 12:00	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/01. Mandate Remarks: As spoken, policy does not cover the cargo box. To reject OD claim as per instructed by UW.	[I] Koh, Victor-CK
17	28 Nov 2017 12:00	Adj Mandate Set	Maintained:As spoken, policy does not cover the cargo box. To reject OD claim as per instructed by UW.	[I] Koh, Victor-CK

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1647058	22/11/2017 16:37	Motor	Goldbell Engineering Pte Ltd (Tuas)	Goldbell Engineering Pte Ltd (Tuas)	YN4105K		xx.xx
1650400	27/11/2017 14:06	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	YN4105K		10.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chan, Kian Meng

Date: 27 Nov 2017

Preliminary Advice

Vehicle No	: YN4105K	Accident Date	: 20/10/2017
Make	: MITSUBISHI CANTER	Policy No.	: 1700045623
Assignment Date	: 22/11/2017	Excess	: S\$1,000.00
Date of Inspection	: 23/11/2017	Est. Duration of Repair	: 12.00
Inspection At	: GOLDBELL ENGINEERING PTE LTD (TUAS) 29, TANJONG PENJURU SINGAPORE 609026		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rooftop portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,760.00
Revised Amount	:S\$	17,990.00
Check Items (Estimated)	:S\$	3,800.00
Total	:S\$	21,790.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	41,314.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,686.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/10/2017 11:22
Date Of Accident	20/10/2017 18:20
Exact Location Of Accident	CLEMENTI AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN4105K
Insured/Policyholder	
Name Of Registered Owner	C K DEPARTMENT STORE
Co Reg No	52844511A
Email Address	HUILING@CKDEPT.SG
Mobile Phone No	
Alternative Phone No	OFFICE-67437411

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FEC91HA00003
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700045623
Cover Note Number	

Driver

Name of Driver	SHI JIANGUO
NRIC No	G8467218T
Date Of Birth	18/09/1980
Occupation	OUTDOOR
Date Of Driving Pass	24/11/2010
Driving Experience	6 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94492526
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address C/O 6 CHANGI SOUTH ST 2 #10-01 XILIN DISTRICT CENTRE SINGAPORE
 Postcode 486349
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident HIT BY FALLEN TREE / OTHER OBJECTS
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

HIT BY LORRY CRANE REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: VIDEO WITH OWNER
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XB9936X
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: PERWAN
NRIC/FIN No.:

21/10/17
10:40am


Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20 October 2017, Around 6:20pm. I was driving along Clementi Ave 6. There was 2 lane at there and my lorry at extremely right lane. Beside have construction work at left lane. While my lorry pass by a construction lorry, the crane of the lorry hit my lorry roof top.



DECLARATION

I/We declare the foregoing particulars are true in every respect.
Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated time frame from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 10:15

Reporting Centre Personnel's Signature
Name: Peterson
NAIC/FIN No.:

© 2004 Blackwell Publishing Ltd *Journal of Internal Medicine* 255: 103–110

10:40 AM
21/10/17

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MPA 217139386 Vehicle Registration No: YN 41051K
Name(as shown in NRIC): CK Department Store
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No: _____
Address: _____
Contact (Tel): _____ (H/P): 67437411
(Email): _____
Date of Accident: 20/10/17 Time of Accident: 1820hrs.
Place of Accident: Clementi Arab
Insurance Company: Atch Ins.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Process for third party claim.

Signature of Vehicle Owner / Driver

Date:



29/11/17



CERTIFICATE OF INSURANCE

COMMERCIAL AUTOPLAN COMMERCIAL VEHICLE

Name of Policyholder : C K Department Store
 Period of Insurance : 19 Sep 2017 To 18 Sep 2018
 Engine No. : 4P10A14604
 Chassis No. : FFC91HA00003

Vehicle No. : YN4105K
 Policy No. : 1700045823
 Endorsement No. :
 Issued Date : 28 Aug 2017

ABOUT THE COVER

Make/Model	MITSUBISHI CANTER 4.5 ton [Lorry]				
Engine Capacity/Tonnage	4.2 Tonnage	Sum Insured	Market Value	First Year of Registration	2013
Driver Restriction	NA	Off Peak Car	No	Insuring with COE/PAF	Yes

Person or Classes of Persons Entitled to Drive*

* The policyholder is responsible for ensuring that the insured vehicle is driven only by persons who are licensed to drive in Malaysia and are not under the influence of alcohol or drugs.

* The policyholder is responsible for ensuring that the insured vehicle is not used for any purpose other than the purpose stated in the policy.

Age Condition All Age Condition

Limitation as to use*

* The policyholder is responsible for ensuring that the insured vehicle is not used for any purpose other than the purpose stated in the policy.

* The policyholder is responsible for ensuring that the insured vehicle is not used for any purpose other than the purpose stated in the policy.

EXCESS

Section 1

Fire & Theft Damage - \$5000. Theft - \$0. Flood Damage - \$0.

Section 2

Third Party Damage - \$0.

Windscreen - \$500.

Named Driver and Excess (see policy schedule)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

* The policyholder is responsible for ensuring that the insured vehicle is not used for any purpose other than the purpose stated in the policy.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan - NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 120) Part IV of the Road Transport Act 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules 1989 (Malaysia).

0503647000

TAY HONGDA

51 SCOTTS ROAD #03-01 PRUDENTIAL @ SCOTTS
 SINGAPORE 220241

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Signature

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORIZED REPRESENTATIVE

HONGDA TAY

78 Selegie Road #07-18 AIG Building 5078120 | T: 65 6419 3000 | F: 65 6415 3723 | www.aig.com.sg

AIG Asia Pacific Insurance Pte. Ltd.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Business
Owner ID	4511A

Vehicle Details

Vehicle No.	YN4105K
Vehicle to be Exported	No
Intended De-registration Date	24 Nov 2017
Vehicle Make	MITSUBISHI
Vehicle Model	CANTER FEC91HR4SDED
Primary Colour	White
Manufacturing Year	2012
Engine No.	4P10A14604
Chassis No.	FEC91HA00003
Maximum Power Output	-
Open Market Value	\$45,030.00
Original Registration Date	19 Sep 2013
First Registration Date	19 Sep 2013
Transfer Count	0
Actual ARF Paid	\$2,252.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	18 Sep 2023
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
QP Paid	\$71,001.00
COE Rebate Amount	\$41,314.00
Total Rebate Amount	\$41,314.00

The information contained herein is correct as at 24 Nov 2017

OK

DRIVER NRIC & LICENSE Pg. 1

WORK PERMIT		REPUBLIC OF SINGAPORE DRIVING LICENCE	
Employment of Foreign Manpower Act (Chapter 91A) Republic of Singapore		Name: SHI JIANGUO	
Employer: C K DEPARTMENT STORE	Work Permit No.: 8 T01Y664	Date of Birth: 18 Sep 1980	
Gender: SERVICE	Name: SHI JIANGUO	Date of Issue: 25 May 2016	
Occupation: DRIVER	Date of Application: 06-11-2015	Valid till: 05 May 2019	
Date of Issue: 06-12-2015	Date of Expiry: 07-12-2018	Licence No: G5467216T	
L744T692			

VISIT PASS		YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES	
Immigration Regulations <td colspan="2">EFFECTIVE DATE </td>		EFFECTIVE DATE	
Name: SHI JIANGUO	Date of Birth: 18-09-1980	Class 3: Motor Cars ≤ 3000kg with ≤ 4 passengers, exclusive of the driver; and other motor vehicles ≤ 2500kg	06 May 2009
Sex: M	Transparency: CHINESE	Class 4: Motor vehicles which are constructed to carry load or passengers and the unladen weight > 2500kg	24 Nov 2010
File: G5467216T	Date of Issue: 06-12-2015	*Motor vehicles which are not constructed to carry load and the unladen weight < 7250kg	
Date of Expiry: 07-12-2018	MULTIPLE JOURNEY VISA ISSUED		
YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.		Licence No: G5467216T	
		NP 420A	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/10/2017 11:22
Date Of Accident	20/10/2017 18:20
Exact Location Of Accident	CLEMENTI AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN4105K
Insured/Policyholder	
Name Of Registered Owner	C K DEPARTMENT STORE
Co Reg No	52844511A
Email Address	HUILING@CKDEPT.SG
Mobile Phone No	
Alternative Phone No	OFFICE-67437411

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FEC91HA00003

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700045623
Cover Note Number	

Driver

Name of Driver	SHI JIANGUO
NRIC No	G8467218T
Date Of Birth	18/09/1980
Occupation	OUTDOOR
Date Of Driving Pass	24/11/2010
Driving Experience	6 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94492526
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address C/O 6 CHANGI SOUTH ST 2 #10-01 XILIN DISTRICT CENTRE
SINGAPORE
Postcode 486349
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident HIT BY FALLEN TREE / OTHER OBJECTS
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

HIT BY LORRY CRANE REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: VIDEO WITH OWNER
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD9936X
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address


GOLDBELL
ENGINEERING

 Industrial Vehicles.
 20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 10 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 196003963B

INSURER: AIG Asia Pacific Insurance Pte. Ltd. (SG)
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	GBE/SVC/SALES-4473/171101
Policy No:	1700045623	Date of Loss:	20/10/2017
Vehicle Reg. No.:	YN4105K	Driveable?	
Driver Age/Info:	37 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	C K DEPARTMENT STORE	Contact No:	+6594492526
Driver:	SHI JIANGUO		
Make/Model:	MITSUBISHI CANTER, 3.0 D FEB71ER4SDEC (CBU) (M)	Vehicle Reg. Date:	19/09/2013
Vehicle Colour:	WHITE	Chassis No:	FEC91HA00003
Engine No:	4P10A14604		
Odometer:	0 KM		
Paint Type:			
List Item	25.00 %		
Discount:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	HIT BY LORRY CRANE REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336		

Tanpin 97495749
Ex: to be advise.
**Resurvey new parts*
23/11/17 @ 1615
12 days. 'Revert'

Remarks: VEHICLE AT 29 TANJONG PENJURU (S) 609026
Present Location: GOLDBELL ENGINEERING PTE LTD (TUAS)
COST OF CLAIMS

	Amount
Parts	16,350.00
Miscellaneous Items	10.00
Labour	6,400.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (\$\$)	22,760.00
- Excess (\$\$)	1,000.00
Nett Amount (\$\$)	21,760.00

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This claim is handled by: WILLIAM GO SHAN CHAN - 97557336

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 22 Nov 2017)
Parts: N/A MITSUBISHI CANTER 3.0 D FEB71ER4SDEC (CBU) (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Goldbell Engineering Pte Ltd/YN4105K/22/11/2017 17:02
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*CARGOBOX FRONT PANEL <i>bt</i>	0	0.00	*800.00 FS
2	1		*CARGOBOX FRONT PANEL SIDE PILLAR LHS <i>bt</i>	0	0.00	*850.00 FS
3	1		*CARGOBOX ROOF PANEL <i>huc</i>	0	0.00	*2,800.00 FS
4	5		*CARGOBOX ROOF RAILING HORIZONTAL BAR <i>bt</i>	0	0.00	*3,250.00 FS
5	4		*CARGOBOX ROOF RAILING VERTICAL BAR <i>?</i>	0	0.00	*1,800.00 FS
6	1		*CARGOBOX ROOF SIDE RAILING <i>bt</i>	0	0.00	*900.00 FS
7	1		*CARGOBOX ROOF SIDE J-BAR <i>bt</i>	0	0.00	*650.00 FS
8	1		*CARGOBOX ROOF FRONT J-BAR <i>bt</i>	0	0.00	*500.00 FS
9	1		*CARGOBOX SLIDING DOOR LHS <i>?</i>	0	0.00	*2,000.00 FS
10	1		*CARGOBOX SIDE PANEL LHS <i>bt</i>	0	0.00	*2,000.00 FS
11	1		*COMPANY STICKER <i>rel</i>	0	0.00	*800.00 FS
Total Parts (S\$)						16,350.00

F=Franchise part. S=SpcNett.

Goldbell Engineering Pte Ltd/YN4105K/22/11/2017 17:02. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE, REFIX & REALIGN REAR CARGOBOX ASSY. TO REPLACE ALL DAMAGED PARTS	New	4,200.00
2	TO PUTTY, CLEAN SPRAY PAINT & POLISH, ETC.	New	2,100.00
3	SUNDRIES	New	100.00
Gross Labour Cost (S\$)			6,400.00

Goldbell Engineering Pte Ltd/YN4105K/22/11/2017 17:02. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Oct 2017 Sendback Est	22 Nov 2017 17:02 S\$22,760.00	22 Nov 2017 17:02 Edit Adj Rpt	S\$17,990.00 Edit Estimates	S\$17,990.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: C K DEPARTMENT STORE, Co. Reg. No.: 52844511A, Tel: +6594492526									
Vehicle Reg. No.: YN4105K		Date of Loss: 20/10/2017 18:00 - :59							
Claim Type: OD / 4675879577SG		Policy/Cover Note No.: 1700045623 (Comprehensive)							
		Excess: S\$1,000.00							
Repairer: Goldbell Engineering Pte Ltd (Tuas) 29, Tanjong Penjuru, 609026 West Coast - Tel: 6864 0695									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH] ... [Final Rpt due 01/12/2017]									
Driver/Custodian: SHI JIANGUO (37 / Male), NRIC: G8467218T, Tel: +6594492526									
Adj Asg. Remarks: Auto-assignment									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (28/11/2017): Alert - Adj Mandate Maintained - YN4105K - Claim Handler: Chan, Kian Meng									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

YN4105K (4675879577SG)

OD

Oct 20 2017 6:20PM

[C K DEPARTMENT STORE]

Goldbell Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View Use Viewer		
Assessment Reports												1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	Goldbell Engineering Pte Ltd (Tuas)										Thumbnail		Print			
1	22/11/17 17:02	Repairer Estimates										Load HTM					
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	27/11/17 14:09	Adjuster Immediate Advice										Load HTM					
Photos/Images												3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
2	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
3	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
4	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
5	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
6	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
7	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
8	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
9	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
10	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
11	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
12	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
13	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
14	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
15	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
16	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
17	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
18	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
19	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
20	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
21	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
22	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
23	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
24	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
25	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
26	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
27	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
28	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
29	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
30	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
31	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
32	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
33	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
34	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
35	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
36	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
37	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			
38	27/11/17 12:52	General View										Load JPG		<input checked="" type="checkbox"/>			

39	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
40	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
41	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
42	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
43	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
44	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
45	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
46	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
47	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
48	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
49	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
50	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
51	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
52	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
53	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
54	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
55	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
56	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
57	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
58	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
59	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
60	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
61	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
62	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
63	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
64	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
65	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
66	27/11/17 12:52	General View		Load JPG	<input checked="" type="checkbox"/>
				1 per page	<input checked="" type="checkbox"/>
Documentation					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/11/17 13:56	Certificate of Insurance		Load PDF	
2	27/11/17 13:56	Drivers Driving License		Load PDF	
3	27/11/17 13:56	ESTIMATE		Load PDF	
4	27/11/17 13:56	Singapore Accident Statement		Load PDF	
5	01/12/17 10:49	Addendum of Singapore Accident Statement		Load PDF	

Linked Accident Report Documents

			View Use Viewer	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	21/10/17 11:30	Accident Statement	Load HTM	<input type="checkbox"/>
2	31/10/17 17:51	Addendum Sheet	Load JPG	<input checked="" type="checkbox"/>
3	31/10/17 17:51	Accident Statement Addm. #1	Load HTM	<input type="checkbox"/>
4	22/11/17 10:15	Addendum Sheet	Load JPG	<input checked="" type="checkbox"/>
5	22/11/17 10:15	Accident Statement Addm. #2	Load HTM	<input type="checkbox"/>
6	29/11/17 14:02	Addendum Sheet	Load JPG	<input checked="" type="checkbox"/>
7	29/11/17 14:02	Accident Statement Addm. #3	Load HTM	<input type="checkbox"/>
			3 per page	<input checked="" type="checkbox"/>
Photos/Images			Thumbnail	Print
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		
1	21/10/17 11:27	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	21/10/17 11:27	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	21/10/17 11:27	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	21/10/17 11:27	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	21/10/17 11:27	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	21/10/17 11:27	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

7	21/10/17 11:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	21/10/17 11:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	21/10/17 11:28	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	21/10/17 11:28	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>
3	21/10/17 11:28	CI		Load TIF	
4	21/10/17 11:28	DRIVER NRIC & LICENSE		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid gray; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG17022370/T1GBS2

Date: 05/12/2017

REFERENCE

Insured/Claimant: C K DEPARTMENT STORE
Date of Loss: 20/10/2017

Policy No: 1700045623
Nature of Claim: OD

Claim No: 4675879577SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YN4105K
Make & Model: MITSUBISHI CANTER, 3.0 D FEB71ER4SDEC (CBU) (M) Engine No: 4P10A14604
Reg. Date: 19/09/2013 (Man. Year: 2012) Chassis No: FEC91HA00003
Colour: White Odometer: 0 km
Engine Capacity: 2998 cc
Market Value/New Car Price: S\$70,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/75 R17.5 Rear Tyre Size: 215/75 R17.5 (D)
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7/7 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	16,350.00	12,550.00	3,800.00	23.24
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	6,400.00	5,430.00	970.00	15.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,760.00	17,990.00	4,770.00	20.96
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	21,760.00	16,990.00	4,770.00	21.92
+ GST 0.00/7.00% (S\$)	0.00	1,189.30	-1,189.30	
Nett Amount (S\$)	21,760.00	18,179.30	3,580.70	16.46

INSPECTION

Date of Assignment: 22/11/2017 Present Location:
Date Inspected: 23/11/2017 Inspected At:

Goldbell Engineering Pte Ltd (Tuas)
Goldbell Engineering Pte Ltd (Tuas)
29, Tanjong Penjuru
Singapore 609026

Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

According to AIG policy does not cover the cargo box. To reject OD claim as per instructed by UW.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$3,800.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CARGOBOX FRONT PANEL	Bent	800.00 FS	*800.00 FS
2	1		*CARGOBOX FRONT PANEL SIDE PILLAR LHS	Bent	850.00 FS	*850.00 FS
3	1		*CARGOBOX ROOF PANEL	Buckled	2,800.00 FS	*2,800.00 FS
4	5		*CARGOBOX ROOF RAILING HORIZONTAL BAR	Bent	3,250.00 FS	*3,250.00 FS
5	4		*CARGOBOX ROOF RAILING VERTICAL BAR	*Check	1,800.00 FS	*- FS
6	1		*CARGOBOX ROOF SIDE RAILING	Bent	900.00 FS	*900.00 FS
7	1		*CARGOBOX ROOF SIDE J-BAR	Bent	650.00 FS	*650.00 FS
8	1		*CARGOBOX ROOF FRONT J-BAR	Bent	500.00 FS	*500.00 FS
9	1		*CARGOBOX SLIDING DOOR LHS	*Check	2,000.00 FS	*- FS
10	1		*CARGOBOX SIDE PANEL LHS	Bent	2,000.00 FS	*2,000.00 FS
11	1		*COMPANY STICKER	Necessary	800.00 FS	*800.00 FS
				Total Parts (S\$)	16,350.00	12,550.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (\$\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, REFIX & REALIGN REAR CARGOBOX ASSY. TO REPLACE ALL DAMAGED PARTS	New	4,200.00	3,600.00
2	TO PUTTY, CLEAN SPRAY PAINT & POLISH, ETC.	New	2,100.00	1,750.00
3	SUNDRIES	New	100.00	80.00
Gross Labour Cost (\$\$)			6,400.00	5,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >