

22/03/2012

ASS. REC. BY:

REF: CS/CT17022375 Ng

Special Instruction:

Survivor:

MARMS.

ASSIGNMENT (Office)

From (Person):

Joel Guh

of

CT1

Date/Time:

22-11-2017 4:07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

STD 4772P

Insured:

YN 5909B

at Workshop m/s

Hock Wah

Tel:

6785 3933

of

Blk 3011 Bedok Ind Park E #01-2008

Policy No:

DMCVSN306651700

Claim No:

SM17D06723C02/9

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21-11-2017

CA / REV / REP. / REV 24 HRS Wp

27-11-2017 @ 11:30am

H.O.D. Endorsement:

Date/Time:

23-11-2017 9:08am

Person Contacted:

De Han

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

STD 4772P - x

YN 5909B - x

SIRVILL, MARY

REF:

CT1/

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

24/3/18

Vehicle: IN / OUT

Veh No:

570 4772P

Yr Regn:

24/3/08

Type:

M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CAI

Make:

ma 7da 3

sp

c.c

1588

Colour:

Black

A/C

Insured / Std / NI / NA

Sp. Reading

134840

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM6BK106280368371

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Modi:

NI / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

KumHO

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

21/11/17

D.O.I.

27/10/17

Survey held at

Des. of Damages:

Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4 veh

27A 8527-

nett 4073

resurvey 2-12-17

27/11/17

confirmed 2/s & 4000 with han
(Ref to 729740, 65%)

RECEIVED 21

Date/Time, File Pass to?

☐

: Preli. Report

1) 21/12 2017

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Report Format :

MEP-TP

Lump Sum / I.B.A. (\$

4000

200

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17022375/Uqb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 23-11-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 5909B	Veh. Inspected	SJD 4772P
Policy No.	DMCVSN3065651700	Coverage (\$)	0.00
Claim No.	SNM17D06723C02/9	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	22/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/11/2017	Inspection Date	27/11/2017
Survey held at	HOCK WAH MOTOR WORKSHOP **Terminated** BLK 9002 TAMPINES ST 93 #01-70 SINGAPORE 528836		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Nov 2017		22 Nov 2017 16:07 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		UNITED PLUMBING PTE LTD, Co. Reg. No.: 201201749W							
Main Claimant:		THRILLER EVENTS, Co. Reg. No.: 53282154L							
Vehicle Reg. No.:		SJD4772P	Date of Loss:	21/11/2017 07:00 - :59					
Claim Type:		TP / SNM17D06723C02/9	Policy/Cover Note No.:	DMCVSN3065651700 (Comprehensive)					
Vehicle Reg. No. (Insured):		YN5909B	Policy No. (Claimant):	5087353389					
		Excess:	S\$0.00						
Repairer:		Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E,, #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]							
Claimant's Insurer:		NTUC Income Insurance Co-operative Ltd (HQ) - Tel:							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/12/2017]							
Driver/Custodian (Insured):		NATARAJAN VELMURUGAN (37 / Male), NRIC: G2188601M, Tel: +6594825337							
Adj Asg. Remarks:		NO ESTIMATES. MARCUS CHUA SELECTED AS SJE FOR WP PRS							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Reference No. : 03/11/1072375 Ugr
Policy Type: OD / TP / TP RES / TL / EVA

SJD 4772P

Typist

Admin (Catherine): Case handler to make sure all Information created by the assignment team are **ACCURATE**

[illegible]

Surveyor (Mawa): Case handler to make sure the surveyor completed all required information.

[illegible]

✓	
---	--

✓	
✓	
✓	

--	--	--	--

Check By: [Signature] 28/11/17
Case Handler Date

[†]C: Critical *N: Non-Critical

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Business
Owner ID	2154L
Vehicle Details	
Vehicle No.	SJD4772P
Vehicle to be Exported	No
Intended De-registration Date	27 Nov 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA3 SP
Primary Colour	Black
Manufacturing Year	2007
Engine No.	Z6595238
Chassis No.	JM6BK106280368371
Maximum Power Output	79.0 kW (105 bhp)
Open Market Value	\$14,762.00
Original Registration Date	25 Mar 2008
First Registration Date	25 Mar 2008
Transfer Count	3
Actual ARF Paid	\$16,239.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	24 Mar 2018
PARF Rebate Amount	\$8,119.00
Intended COE Rebate Details	
COE Expiry Date	24 Mar 2018
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$12,856.00
COE Rebate Amount	\$408.00
Total Rebate Amount	\$8,527.00

The information contained herein is correct as at 27 Nov 2017

OK



Mazda 3 1.6A SP **\$15,500** **\$8,780 /yr** **16-Oct-2008** **1,598 cc** **131,299 km** **Sedan** **Available**

Very Well Maintained. Low Mileage Done Only 131,229km, Road Tax Till 15/04/2018. Please Call For More Information And Viewing.

Posted: 04-Nov-2017 Tags: 2008 Mazda 3, 2008 Mazda 3, Mazda 3, Mazda 3, Mazda 3, 3, 3, Used Mazda

[Details](#)



Mazda 3 1.6A SP **\$12,800** **\$8,140 /yr** **27-Aug-2008** **1,598 cc** **125,000 km** **Sedan** **Available**

Asking Low! Well Maintained Interior/Exterior. Low Mileage With No Repairs Required. Act Fast! Please Call For Appointment Viewing.

Posted: 02-Nov-2017 Tags: 2008 Mazda 3, 2008 Mazda 3, Mazda 3, Mazda 3, Mazda 3, 3, 3, Used Mazda

[Details](#)



Mazda 3 1.6A SP (New 5-yr COE) **\$35,800** **\$7,160 /yr** **11-Feb-2008** **1,598 cc** **-** **Sedan** **Available**

Up To 90% Loan. Well Maintained, Excellent Condition, In House Loan Available.

Posted: 27-Oct-2017 Tags: 2008 Mazda 3, 2008 Mazda 3, Mazda 3, Mazda 3, Mazda 3, 3, 3, Used Mazda

[Details](#)



Mazda 3 1.6A SP Luxury **\$15,800** **\$7,410 /yr** **23-Dec-2008** **1,598 cc** **-** **Sedan** **Available**

10-20% Must View, Very Low Usage, New Paint, Well Maintained, Almost New Tyre. Please Call/SMS For More Details And Viewing Now. Thank You.

Posted: 26-Oct-2017 Tags: 2008 Mazda 3, 2008 Mazda 3, Mazda 3, Mazda 3, Mazda 3, 3, 3, Used Mazda

[Details](#)



Mazda 3 1.6A SP **\$13,800** **\$8,060 /yr** **10-Sep-2008** **1,598 cc** **-** **Sedan** **Available**

1 Owner Only! Excellent Condition! Extended Warranty Available! A Stylish Sedan Engineered To Give You Superb Handling And Stability. Buy It From Us With A Peace Of Mind, A Company Accredited With Out...

Dickson Automobile

Posted: 20-Oct-2017 Tags: 2008 Mazda 3, 2008 Mazda 3, Mazda 3, Mazda 3, Mazda 3, 3, 3, Used Mazda

[Details](#)



Mazda 3 1.6A Luxury **\$13,800** **\$8,340 /yr** **14-Aug-2008** **1,598 cc** **178,000 km** **Sedan** **Available**

6 Months Road Tax, High Loan Available. Trade In Welcome. As It Is Condition.

Posted: 18-Oct-2017 Tags: 2008 Mazda 3, 2008 Mazda 3, Mazda 3, Mazda 3, Mazda 3, 3, 3, Used Mazda

[Details](#)



Mazda 3 1.6A SP **\$15,800** **\$8,760 /yr** **10-Nov-2008** **1,598 cc** **-** **Sedan** **Available**

Very Affordable! Warranty Till Scrap! STA Evaluated Cars! Be Fascinated By This One Of Its Kind, Well Maintained Sedan That Comes With Stylish Body-kit! Buy It From Us With A Peace Of Mind, A Company ...

Dickson Automobile

Posted: 08-Oct-2017 Tags: 2008 Mazda 3, 2008 Mazda 3, Mazda 3, Mazda 3, Mazda 3, 3, 3, Used Mazda

[Details](#)

Save this search criteria, to get email alerts whenever a match is found.

Make: Model: Price: Depreciation: Reg Date: Eng Cap: Mileage: Veh Type: Status:

For old advertisements, view Expired ads.

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mazda 3, Mazda 3 Singapore, used Mazda 3 Singapore, used Mazda 3, used vehicles Singapore or even buy used Mazda 3 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/11/2017 15:57
Date Of Accident	21/11/2017 07:50
Exact Location Of Accident	ALONG PIE>CHANGI BEFORE UPPER CHANGI ROAD NORTH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJD4772P
Insured/Policyholder	
Name Of Registered Owner	THRILLER EVENTS
Co Reg No	53282154L
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94554542
Alternative Phone No	OFFICE-94554542

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	PERSONAL PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087353389
Cover Note Number	07/01/2017-25/03/2018

Driver

Name of Driver	GANDHI S/O VELLASAMY
NRIC No	S7339680H
Date Of Birth	05/10/1973
Occupation	INDOOR
Date Of Driving Pass	07/07/2003
Driving Experience	14 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94554542
Fax Number	
Contact Number	
Email Address	NOEMAIL

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number YN5909B

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name GANDHI S/O VELLASAMY

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name SARATHA D/O RAMACHANDRAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?


Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT

T/2017/121/2048

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 21/11/17
16:15 hr

WOCK WAI MOTOR VEHICLE PRT LTD
88-9000, Singapore, S. 01-401-224
Singapore 01-401-224
Tel: 6785 9988 (China) Fax: 6785 9988

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20171121/2048

2 of 4

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

Report No. T/20171121/2048

CONTINUATION OF REPORT

Passenger			
Name	Saratha D/O Ramachandran	ID No.	S7345794G
Related Vehicle	SJD4772P (Car)	Contact No.	93832157
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	21/11/2017	Date Discharge	21/11/2017
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Driver			
Name	GANDHI S/O VELLASAMY	ID No.	S7339680H
Related Vehicle	SJD4772P (Car)	Contact No.	94554542
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	21/11/2017	Date Discharge	21/11/2017
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Driver			
Name	NATARAJAN VULMURUGAN	ID No.	G2188601M
Related Vehicle	YN5909B (Lorry)	Contact No.	94825337
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 21/11/2017 at 0750hrs, I was travelling along PIE towards Changi Airport and was nearing the Upp Changi Rd North exit when the accident happened. I was driving on the most left lane and traffic most slow. Suddenly, I felt an impact at the back of my vehicle. I realized the lorry (YN5909B) had collided onto the back of my car. The impact resulted in my vehicle colliding with the vehicle (SBR236T) which was in front of me.

My wife was inside the vehicle together with me and we both suffered minor injuries. We took photos of the accident and left the scene after it happened.

Individual Statement



SINGAPORE
POLICE FORCE



T/20171121/2048

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

4 of 4

Report No. T/20171121/2048

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Staff Sgt NUR MUHAMMAD ISKANDAR BIN
REINDIO

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Sgt 2 YEO KIA HUAT
Contact No.: 65476325

Authentication Stamp
NR158

Signature Of Informant:

Date/Time:
21/11/2017 12:11

Classification Of Case:

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL : 67853933 FAX: 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : 53282154L
THRILLER EVENTS
BLK 87 87 PASIR RIS GROVE
06-14
SINGAPORE 518213
TEL: FAX:
PH: 94554542
ATTN:

ESTIMATE BILL

Number : EBK0000225
Date : 22/11/2017
Case No : ADK0000297
Vehicle No : SJD4772P
Chassis:
Year of Mfr
Policy No
Model : MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRT BUMPER	1.0	862.70	20	690.16
2	FRT BUMPER SIDE RETAINER LH RH	2.0	28.20	20	45.12
3	FRT BUMPER BRACKET LH RH	2.0	47.20	20	75.52
4	FRT BUMPER CLIPS	12.0	3.50	20	33.60
5	FRT BUMPER REINFORCEMENT W BRACKET LH RH	1.0	590.60	20	472.48
6	FRT GRILLE ASSY W EMBLEM	1.0	292.20	20	233.76
7	FRT HEADLAMP LH RH	2.0	875.90	20	1,401.44
8	FRT SUPPORT PANEL ASSY	1.0	406.00	20	324.80
9	FRT NOPLATE GARNISH	1.0	75.20	20	60.16
10	FRT BUMPER LOWER GRILLE	1.0	120.60	20	96.48
11	RR BUMPER	1.0	862.20	20	689.76
12	RR BUMPER SIDE RETAINER LH RH	2.0	32.40	20	51.84
13	RR BUMPER BRACKET LH RH	2.0	40.50	20	64.80
14	RR BUMPER CLIPS	12.0	4.50	20	43.20
15	RR BUMPER REINFORCEMENT W BRACKET LH RH	1.0	403.40	20	322.72
16	RR BOOTLID	1.0	1,046.80	20	837.44
17	RR BOOTLID HINGE LH RH	2.0	151.20	20	241.92
18	RR BOOTLID LOGO MAZDA 3	1.0	48.40	20	38.72
19	RR BOOTLID LOCK TOP	1.0	238.90	20	191.12
20	RR BOOTLID LOCK BOTTOM	1.0	67.50	20	54.00
21	RR BOOTLID INSULATOR	1.0	175.30	20	140.24
22	RR BOOTLID INSULATOR CLIPS	10.0	4.80	20	38.40
23	RR BOOTLID LOCK SENSOR	1.0	287.20	20	229.76
24	RR BUMPER SIDE SKIRT LH RH	2.0	275.10	20	440.16
25	RR EMBLEM	1.0	78.20	20	62.56
26	RR END PANEL ASSY	1.0	384.80	20	307.84
27	RR END PANEL TOP GARNISH	1.0	213.20	20	170.56
28	RR END PANEL TOP GARNISH CLIPS	6.0	4.80	20	23.04
29	RR BOOTLID INNER RUBBER	1.0	105.30	20	84.24
30	RR BOOTLID SPOILER	1.0	395.70	20	316.56
31	RR BOOTLID LOGO SP	1.0	45.00	0	45.00
32	FRT NOPLATE	1.0	40.00	0	40.00
List Price - Parts Sub Total					7,782.40
Nett Price - Parts Sub Total					45.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528849
TEL : 67853933 FAX: 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : 53282154L
THRILLER EVENTS
BLK 87 87 PASIR RIS GROVE
06-14
SINGAPORE 518213
TEL : FAX :
PH : 94554542
ATTN :

ESTIMATE BILL

Number : EBK0000225
Date : 22/11/2017
Case No : ADK0000297
Vehicle No : SJD4772P
Chassis :
Year of Mfr :
Policy No :
Model : MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
33	FRT NOPLATE HOLDER <i>NT</i>	1.0			
34	RR NOPLATE <i>ner</i>	1.0	40.00	0	40.00
35	RR BUMPER REVERSE SENSOR <i>shuh</i>	1.0	40.00	0	40.00
	Special Nett Price - Parts Sub Total	1.0	250.00	0	250.00
	Parts Total				370.00
36	FRT BONNET REPAIR <i>2x</i>	1.0			8,197.40
37	FRT FENDER LH RH REPAIR <i>2x</i>	1.0			
38	RR FENDER LH RH REPAIR <i>2x</i>	1.0			
39	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0			
40	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,200.00	0	1,200.00
41	WIRING	1.0	1,500.00	0	1,500.00
42	ANTI RUST COATING	2.0	40.00	0	80.00
43	LABOUR TO INSTALL REVERSE SENSOR	1.0	200.00	0	200.00
	Labour 1 Sub Total	1.0	120.00	0	120.00
					3,100.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature:					
SINGAPORE DOLLARS : TWELVE THOUSAND EIGHTY-EIGHT AND CENTS TWENTY-TWO ONLY					
Less Excess					0.00
SUBTOTAL					11,297.40
GST 7.00%					790.82
TOTAL					12,088.22

Date of accident : 21/11/2017 07:50 AM. Place : ALONG PIE>CHANGI BEFORE UPPER CHANGI ROAD NORTH

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Nov 2017		22 Nov 2017 16:07 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	UNITED PLUMBING PTE LTD , Co. Reg. No.: 201201749W		[Created by insurer]
Main Claimant:	THRILLER EVENTS , Co. Reg. No.: 53282154L		
Vehicle Reg. No.:	SJD4772P	Date of Loss:	21/11/2017 07:00 - :59
Claim Type:	TP / SNM17D06723C02/9	Policy/Cover Note No.:	DMCVSN3065651700 (Comprehensive)
Vehicle Reg. No. (Insured):	YN5909B	Policy No. (Claimant):	5087353389
		Excess:	S\$0.00
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E,, #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 01/12/2017]		
Driver/Custodian (Insured):	NATARAJAN VELMURUGAN (37 / Male), NRIC: G2188601M, Tel: +6594825337		
Adj Asg. Remarks:	NO ESTIMATES. MARCUS CHUA SELECTED AS SJE FOR WP PRS		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJD4772P (SNM17D06723C02/9)
[YN5909B]
TP
THRILLER EVENTS
Nov 21 2017 7:00AM
[UNITED PLUMBING PTE LTD]
Hock Wah Motor Workshop Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		Use Viewer	
Assessment Reports						1 per page		☒	
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)				Thumbnail		Print	
1	21/11/17 16:41	Accident Statement				Load HTM			
Photos/Images						3 per page		☒	
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)				Thumbnail		Print	
1	21/11/17 16:41	Accident Photo [Linked Accident Report Documents]				Load JPG		☒	
2	21/11/17 16:41	Accident Photo [Linked Accident Report Documents]				Load JPG		☒	
3	21/11/17 16:41	Accident Photo [Linked Accident Report Documents]				Load JPG		☒	
4	21/11/17 16:41	Accident Photo [Linked Accident Report Documents]				Load JPG		☒	
5	21/11/17 16:41	Accident Photo [Linked Accident Report Documents]				Load JPG		☒	
6	21/11/17 16:41	Accident Photo [Linked Accident Report Documents]				Load JPG		☒	
7	21/11/17 16:41	Accident Photo [Linked Accident Report Documents]				Load JPG		☒	
8	21/11/17 16:41	Accident Photo [Linked Accident Report Documents]				Load JPG		☒	
9	21/11/17 16:41	Accident Photo [Linked Accident Report Documents]				Load JPG		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	27/11/17 14:16	Chassis Number				Load JPG		☒	
2	27/11/17 14:16	Odometer Reading				Load JPG		☒	
3	27/11/17 14:16	General View				Load JPG		☒	
4	27/11/17 14:16	General View				Load JPG		☒	
5	27/11/17 14:16	General View				Load JPG		☒	
6	27/11/17 14:16	General View				Load JPG		☒	
7	27/11/17 14:16	General View				Load JPG		☒	
8	27/11/17 14:16	General View				Load JPG		☒	
9	27/11/17 14:16	General View				Load JPG		☒	
10	27/11/17 14:16	General View				Load JPG		☒	
11	27/11/17 14:16	General View				Load JPG		☒	
12	27/11/17 14:16	General View				Load JPG		☒	
13	27/11/17 14:16	General View				Load JPG		☒	
14	27/11/17 14:16	General View				Load JPG		☒	
15	27/11/17 14:16	General View				Load JPG		☒	
16	27/11/17 14:16	General View				Load JPG		☒	
17	27/11/17 14:16	General View				Load JPG		☒	
18	27/11/17 14:16	General View				Load JPG		☒	
19	27/11/17 14:16	General View				Load JPG		☒	
20	27/11/17 14:16	General View				Load JPG		☒	
21	27/11/17 14:16	General View				Load JPG		☒	
22	27/11/17 14:16	General View				Load JPG		☒	
23	27/11/17 14:16	General View				Load JPG			

					☒
24	27/11/17 14:16	General View		Load JPG	☒
25	27/11/17 14:16	General View		Load JPG	☒
26	27/11/17 14:16	General View		Load JPG	☒
27	27/11/17 14:16	General View		Load JPG	☒
28	27/11/17 14:16	General View		Load JPG	☒
29	27/11/17 14:16	General View		Load JPG	☒
30	27/11/17 14:16	General View		Load JPG	☒
31	27/11/17 14:16	General View		Load JPG	☒
32	27/11/17 14:16	General View		Load JPG	☒
33	27/11/17 14:16	General View		Load JPG	☒
34	27/11/17 14:16	General View		Load JPG	☒
35	27/11/17 14:16	General View		Load JPG	☒
36	27/11/17 14:16	General View		Load JPG	☒
37	27/11/17 14:16	General View		Load JPG	☒
38	27/11/17 14:16	General View		Load JPG	☒
39	27/11/17 14:16	General View		Load JPG	☒
40	27/11/17 14:16	General View		Load JPG	☒
41	27/11/17 14:16	General View		Load JPG	☒
42	27/11/17 14:16	General View		Load JPG	☒
43	27/11/17 14:16	General View		Load JPG	☒
44	27/11/17 14:16	General View		Load JPG	☒
45	27/11/17 14:16	General View		Load JPG	☒
46	27/11/17 14:16	General View		Load JPG	☒
47	27/11/17 14:16	General View		Load JPG	☒
48	27/11/17 14:16	General View		Load JPG	☒
49	27/11/17 14:16	General View		Load JPG	☒
50	27/11/17 14:16	General View		Load JPG	☒
51	27/11/17 14:16	General View		Load JPG	☒
52	27/11/17 14:16	General View		Load JPG	☒
53	27/11/17 14:16	General View		Load JPG	☒
54	27/11/17 14:16	General View		Load JPG	☒
55	27/11/17 14:16	General View		Load JPG	☒
56	27/11/17 14:16	General View		Load JPG	☒
57	27/11/17 14:16	General View		Load JPG	☒
58	27/11/17 14:16	General View		Load JPG	☒
59	27/11/17 14:16	General View		Load JPG	☒
60	27/11/17 14:16	General View		Load JPG	☒
61	27/11/17 14:16	General View		Load JPG	☒
62	27/11/17 14:16	General View		Load JPG	☒
63	27/11/17 14:16	General View		Load JPG	☒
64	27/11/17 14:16	General View		Load JPG	☒
65	27/11/17 14:16	General View		Load JPG	☒
66	27/11/17 14:16	General View		Load JPG	☒
67	21/12/17 11:27	Reinspection Photo		Load JPG	☒
68	21/12/17 11:27	Reinspection Photo		Load JPG	☒
69	21/12/17 11:27	Reinspection Photo		Load JPG	☒
70	21/12/17 11:27	Reinspection Photo		Load JPG	☒
71	21/12/17 11:27	Reinspection Photo		Load JPG	☒
Documentation				1 per page ▾	☒

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/11/17 16:08	OI GIA REPORT		Load PDF	
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)		Thumbnail	Print
1	21/11/17 16:10	Individual Statement [Linked Accident Report Documents]		Load JPG	☒
2	21/11/17 16:10	Individual Statement [Linked Accident Report Documents]		Load JPG	☒
3	21/11/17 16:10	Individual Statement [Linked Accident Report Documents]		Load JPG	☒
4	21/11/17 16:10	Individual Statement [Linked Accident Report Documents]		Load JPG	☒
5	21/11/17 16:18	Sketch Plan [Linked Accident Report Documents]		Load JPG	☒
6	21/11/17 16:18	Sketch Plan #2 [Linked Accident Report Documents]		Load JPG	☒

Linked Accident Report Documents

Assessment Reports				View	Use Viewer
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)	1 per page		☒
1	21/11/17 16:41	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)	Thumbnail	Print	
1	21/11/17 16:41	Accident Photo		Load JPG	☒
2	21/11/17 16:41	Accident Photo		Load JPG	☒
3	21/11/17 16:41	Accident Photo		Load JPG	☒
4	21/11/17 16:41	Accident Photo		Load JPG	☒
5	21/11/17 16:41	Accident Photo		Load JPG	☒
6	21/11/17 16:41	Accident Photo		Load JPG	☒
7	21/11/17 16:41	Accident Photo		Load JPG	☒
8	21/11/17 16:41	Accident Photo		Load JPG	☒
9	21/11/17 16:41	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)	Thumbnail	Print	
1	21/11/17 16:10	Individual Statement		Load JPG	☒
2	21/11/17 16:10	Individual Statement		Load JPG	☒
3	21/11/17 16:10	Individual Statement		Load JPG	☒
4	21/11/17 16:10	Individual Statement		Load JPG	☒
5	21/11/17 16:18	Sketch Plan		Load JPG	☒
6	21/11/17 16:18	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117022375/UQBE2

Date: 28/12/2017

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3065651700
Claimant Vehicle No :	SJD4772P	Insured Vehicle No :	YN5909B
Date of Loss:	21/11/2017	Nature of Claim:	TP
		Claim No:	SNM17D06723C02/9

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD4772P	Engine No:	Z6595238
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BK106280368371
Reg. Date:	25/03/2008 (Man. Year: 2007)	Odometer:	134840 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,197.40	3,487.00	4,710.40	57.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	1,880.00	1,220.00	39.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,297.40	5,367.00	5,930.40	52.49
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	11,297.40	4,000.00	7,297.40	64.59
+ GST 7.00/7.00% (\$\$)	790.82	280.00	510.82	64.59
Nett Amount (\$\$)	12,088.22	4,280.00	7,808.22	64.59

INSPECTION

Date of Assignment: 22/11/2017

Date Inspected: 27/11/2017 Inspected At:

Hock Wah Motor Workshop Pte Ltd
(Bedok)
Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2017)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD4772P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented / Deformed	862.70 FL	*862.70 FL
2	2		*FRT BUMPER SIDE RETAINER LH RH	Bent	56.40 FL	*56.40 FL
3	2		*FRT BUMPER BRACKET LH RH	Bent	94.40 FL	*94.40 FL
4	12		*FRT BUMPER CLIPS	Necessary	42.00 FL	*42.00 FL
5	1		*FRT BUMPER REINFORCEMENT W BRACKET LH RH	Repair	590.60 FL	*- FL
6	1		*FRT GRILLE ASSY W EMBLEM	Cracked	292.20 FL	*292.20 FL
7	2		*FRT HEADLAMP LH RH	Not Necessary	1,751.80 FL	*- FL
8	1		*FRT SUPPORT PANEL ASSY	Not Necessary	406.00 FL	*- FL
9	1		*FRT NO PLATE GARNISH	Cut	75.20 FL	*75.20 FL
10	1		*FRT BUMPER LOWER GRILLE	Repair	120.60 FL	*- FL
11	1		*RR BUMPER	Dented / Deformed	862.20 FL	*862.20 FL
12	2		*RR BUMPER SIDE RETAINER LH RH	Bent	64.80 FL	*64.80 FL
13	2		*RR BUMPER BRACKET LH RH	Bent	81.00 FL	*81.00 FL
14	12		*RR BUMPER CLIPS	Necessary	54.00 FL	*54.00 FL
15	1		*RR BUMPER REINFORCEMENT W BRACKET LH RH	Repair	403.40 FL	*- FL
16	1		*RR BOOTLID	Dented / Buckled	1,046.80 FL	*1,046.80 FL
17	2		*RR BOOTLID HINGE LH RH	Repair	302.40 FL	*- FL
18	1		*RR BOOTLID LOGO MAZDA 3	Necessary	48.40 FL	*48.40 FL
19	1		*RR BOOTLID LOGO TOP	Twisted	238.90 FL	*238.90 FL
20	1		*RR BOOTLID LOCK BOTTOM	Not Necessary	67.50 FL	*- FL
21	1		*RR BOOTLID INSULATOR	Not Necessary	175.30 FL	*- FL
22	10		*RR BOOTLID INSULATOR CLIPS	Not Necessary	48.00 FL	*- FL
23	1		*RR BOOTLID LOCK SENSOR	Not Necessary	287.20 FL	*- FL
24	2		*RR BUMPER SIDE SKIRT LH RH	Repair	550.20 FL	*- FL
25	1		*RR EMBLEM	Necessary	78.20 FL	*78.20 FL
26	1		*RR END PANEL ASSY	Repair	384.80 FL	*- FL
27	1		*RR END PANEL TOP GARNISH	Not Necessary	213.20 FL	*- FL
28	6		*RR END PANEL TOP GARNISH CLIPS	Not Necessary	28.80 FL	*- FL
29	1		*RR BOOTLID INNER RUBBER	Twisted	105.30 FL	*105.30 FL
30	1		*RR BOOTLID SPOILER	Repair	395.70 FL	*- FL
31	1		*RR BOOTLID LOGO SP	Necessary	45.00 FS	*45.00 FS
32	1		*FRT NO PLATE	Cracked	40.00 FS	*20.00 FS
33	1		*FRT NO PLATE HOLDER	Not fitted	40.00 FS	*- FS
34	1		*RR NO PLATE	Necessary	40.00 FS	*20.00 FS
35	1		*RR BUMPER REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
36	1		*FRT BONNET (NPA)	Repair	0.00 FS	*- FS
37	1		*FRONT FENDER LH RH (NPA)	Repair	0.00 FS	*- FS
38	1		*RR FENDER LH RH (NPA)	Repair	0.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$) 10,143.00 4,287.50

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					1,945.60	800.50
Total Parts (S\$)					8,197.40	3,487.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	New	1,200.00	650.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,500.00	1,100.00
3	WIRING	New	80.00	30.00
4	ANTI RUST COATING	New	200.00	50.00
5	LABOUR TO INSTALL REVERSE SENSOR	New	120.00	50.00
Gross Labour Cost (S\$)			3,100.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >