

ASS. REC. BY:

REF: CS/AU1702376/Gtb

Special Instruction

Supervisor:

613

ASSIGNMENT (Office)

From (Person):

Ashley Chen

of

ALH

Date/Time: 22.11.2017 7:40am

Estimated Cost:

Bill for

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8JE 3627

Insured:

SKT 9442M

at Workshop m/z

m-Tech motor

Tel:

9735 4567

of

Blk 9005 Tampines St 93 # 01-252

Policy No.

Claim No:

733 8607 1949(1003

Sum Insured:

Excess:

Make of Veh:

D.O.A.

20.112017

(Client's Record)

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time: _____

23.11.2017 9.16Gm

Person Contacted:

Mr. Chyn

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJE 3621T -x
	SKT 9442M -x

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG17022376/Gtb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 23-11-2017



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKT 9442M	Veh. Inspected	SJE 3621T
Policy No.		Coverage (\$)	0.00
Claim No.	7338607194SG003	Excess (\$)	0.00
Assign From	ASHLEY CHAN	Assign Date	23/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/11/2017	Inspection Date
Survey held at	M-TECH MOTOR SERVICES BLK 9005 TAMPINES STREET 93 #01-252, TAMPINES INDUSTRIAL PARK A SINGAPORE 528839	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

- Pre repair inspection request - SJE3621T VS SKT9442M (OI) DOA 20/11/2017

From: Chan, Yoke Shi
To: assignments@lkkauto.com, Admin A
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Loo, Kar Yong
Sent: Thursday, 23 November, 2017 7:40:14 AM
Attachments:  22112017152325.pdf

Hi,

Please refer to the enclosed request from **Kuru & Co.**

Claim no : 7338607194SG003
Case Owner : LEE MING YAO

If you have any queries/concerns, please let us know.
Kindly assist to assign Xing Guo Qiang as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com www.aig.com

From: Kuru & Co [<mailto:kurulegal@yahoo.com.sg>]

Sent: Wednesday, November 22, 2017 5:02 PM

To: Chan, Yoke Shi

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Loo, Kar Yong

Subject: Re: Our Ref: L.17.1809.AT//PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKT9442M AND SJE3621T ON 20/11/2017

Dear Sirs

Our client is agreeable to the following surveyor(s) as the SJE: **LKK Auto Consultants Pte Ltd/Xing Guo Qiang**

Please arrange for your surveyor to survey our client's vehicle at the following address:

M-TECH MOTOR SERVICES
Blk 9005 Tampines St 93
#01-252
Singapore 528839
Tel: 97354567/Mr Chan

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey(s).

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards
Anne
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building

Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

From: "Chan, Yoke Shi" <yokeshi.chan@aig.com>
To: Kuru & Co <kuru.legal@yahoo.com.sg>
Cc: "Tan, Lily (AIG)" <Lily.Tan@aig.com>; "Fong, Andy-SY" <Andy-SY.Fong@aig.com>; "Kaur, Baljit" <Baljit.Kaur@aig.com>; "Chin, Lee-Ying" <Lee-Ying.Chin@aig.com>; "Abu Kassim, Noor Mariesa" <NoorMariesa.AbuKassim@aig.com>; "Md Ishak, Mohd Imran" <imran.ishak@aig.com>; "Lim, Sheng Yang" <ShengYang.Lim@aig.com>; "Loo, Kar Yong" <KarYong.Loo@aig.com>
Sent: Wednesday, 22 November 2017, 16:00
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKT9442M AND SJE3621T ON 20/11/2017

Without Prejudice

Your Reference : L17.1809.AT
Our Reference : 7338607194SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel: +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 21/11/2017 11:09
Date Of Accident 20/11/2017 19:40
Exact Location Of Accident TPE EXIT TOWARDS BUANGKOK DR
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJE3621T
Insured/Policyholder
Name Of Registered Owner TAN SENG KOK
NRIC No S6822789E
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-90999619
Alternative Phone No OFFICE-90999619

Vehicle Particulars

Manufacturer HONDA
Model STREAM-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5095318035
Cover Note Number

Driver

Name of Driver TAN SENG KOK
NRIC No S6822789E
Date Of Birth 10/06/1968
Occupation OUTDOOR
Date Of Driving Pass 23/08/1988
Driving Experience 29 YEARS AND 2 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-90999619
Fax Number
Contact Number OFFICE-90999619
Email Address NOEMAIL

Address	BLK 470C FERNVALE LINK #22-418
Postcode	793470
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT9442M
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	YEO AIK GUAN
NRIC/Passport Number	S68082108
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN



A - SSE 3621T

B - SKT9442M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

我的车在 Buangkok Dr TPE 的出口靠近红绿灯处车前
当我在等红绿灯时一辆车从后边 HIT 我的车后

B 对方车号 SKT 9442 M

A SSE 3621 T

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GI Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	2789E
Vehicle Details	
Vehicle No.	SJE3621T
Vehicle to be Exported	No
Intended De-registration Date	28 Nov 2017
Vehicle Make	HONDA
Vehicle Model	STREAM 1.8L A
Primary Colour	Grey
Manufacturing Year	2008
Engine No.	R18A12802748
Chassis No.	JHMRN68408S202752
Maximum Power Output	103.0 kW (138 bhp)
Open Market Value	\$20,486.00
Original Registration Date	23 Apr 2008
First Registration Date	23 Apr 2008
Transfer Count	1
Actual ARF Paid	\$20,486.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	22 Apr 2018
PARF Rebate Amount	\$10,243.00
Intended COE Rebate Details	
COE Expiry Date	22 Apr 2018
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$19,001.00
COE Rebate Amount	\$764.00
Total Rebate Amount	\$11,007.00

The information contained herein is correct as at 28 Nov 2017

OK

M-TECH MOTOR SERVICES

Blk 9005 Tampines St.93, #01-252 Tampines Industrial Park A, Singapore 528839
Tel: 6784 0077 Fax: 6788 3025
(Registration No. 269252/00B)

Tan Seng Kok
Blk 470 C Fernvale Link #22-418
Singapore 793470

Attention : Motor Claim Department

Estimate : T1030164

Date : 27/11/2017
Vehicle Num. : SJE 3621 T
Make/Model : Honda Stream
Chassis/Eng#:
Accident Date : 27/11/2017
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS : Rear bumper <i>/ Cnt</i>		588.90
2.	1	Taillamp assy - n/s <i>/ Cnt</i>		390.20

List Total S\$:

LABOUR :

Replace rear bumper & taillamp
Respray rear bumper & boot cover

Labour Total S\$:

969.10
20%: 775.28
200 250.00
300 400.00
650.00

3 Days .
Lumpsum Repair .
After repair photos.
Guo Qiang - 82680282
27/11/17

1275.28

20%: 1000

SingDollars : One Thousand Six Hundred Nineteen & Cents Ten Only

for M-TECH MOTOR SERVICES

F & O E
LX Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total S\$: 1,619.10

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Nov 2017 Edit Reg		22 Nov 2017 00:00 Edit Adj Rpt	S\$1,000.00 Edit Estimates	S\$1,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by adjuster]		
Insured:	YEO AIK GUAN, ID: S68082108					
Main Claimant:	TAN SENG KOK, ID: S6822789E					
Vehicle Reg. No.:	SJE3621T	Date of Loss:	20/11/2017 19:00 - :59 [114 Months and 28 Days From LTA Reg Date (Man Yr)]			
Claim Type:	TP / 7338607194SG	Policy/Cover Note No.:	2100419038 (Comprehensive) Coverage: 26/06/2017 - 25/06/2018			
Vehicle Reg. No. (Insured):	SKT9442H	Policy No. (Claimant):				
		Excess:				
Repairer:	M-tech Motor Services (HQ) BLK 9005 TAMPINES ST 93, #01-252 TAMPINES INDUSTRIAL PARK A, 528839 Tampines - Tel:					
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/12/2017]					
Claimant's Solicitor:	KURU & CO - Tel: 65322009					

ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (29/11/2017): Request To Upload TP GIA Report 				

ALL ASSOCIATED TASKS					View All	Search Tasks	Create New Task	Complete	
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJE3621T (7338607194SG)
[SKT9442M]
TP
TAN SENG KOK
Nov 20 2017 7:00PM
[YEO AIK GUAN]
M-tech Motor Services

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
------------------	---------------	--------------------	--------------	--------------	--

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	29/11/17 11:14	AIG Asia Pacific Insurance Pte. Ltd. (SG) Accident Statement <small>From: OD - Reg. No: SKT9442M, Claimant: YEO AIK GUAN</small>		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
1	21/06/18 14:20	LKK Auto Consultants Pte Ltd (HQ) General View		Load JPG	<input checked="" type="checkbox"/>
2	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
3	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
4	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
5	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
6	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
7	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
8	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
9	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
10	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
11	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
12	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
13	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
14	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
15	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
16	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>
17	21/06/18 14:20	General View		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
1	21/06/18 14:31	LKK Auto Consultants Pte Ltd (HQ) TP Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG17022376/GTBQ2

Date: 29/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100419038
Claimant SJE3621T **Insured Vehicle No :** SKT9442M
Vehicle No : SJE3621T
Date of Loss: 20/11/2017 **Nature of Claim:** TP **Claim No:** 7338607194SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJE3621T**
 Make & Model: HONDA STREAM, 1.8 (A) Engine No: R18A12802748
 Reg. Date: 23/04/2008 (Man. Year: 2008) Chassis No: JHMRN68408S202752
 Colour: Grey Odometer: 178688 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65R15 Rear Tyre Size: 205/65R15
 Front Left Side: Katana 6 mm Rear Left Side: KAPSEN 6 mm
 Front Right Side: Katana 6 mm Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	969.10	775.28	193.82	20.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	500.00	150.00	23.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,619.10	1,275.28	343.82	21.24
Approved Total (Overridden) (S\$)		1,000.00		
Nett Amount (S\$)	1,619.10	1,000.00	619.10	38.24

INSPECTION

Date of Assignment: 22/11/2017
 Date Inspected: 22/11/2017 Inspected At: M-tech Motor Services (HQ)
 BLK 9005 TAMPINES ST 93, #01-252
 TAMPINES INDUSTRIAL PARK A
 Singapore 528839
 Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	588.90 F	*588.90 FL
2	1		*TAILLAMP ASSY -N/S	Cracked	380.20 F	*380.20 FL
					Sub Total (\$\$)	969.10
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00
					Total Parts (\$\$)	969.10
						775.28

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER & TAILLAMP	New	250.00	200.00
2	RESPRAY REAR BUMPER & BOOT COVER	New	400.00	300.00
Gross Labour Cost (\$\$)			650.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >