

ASS. REC. BY:

REF: CS/FCL11020377/Kg6m2

Special Instruction:

Surveyor:

ASSIGNMENT (Office) ✓

From (Person): CWS Sithara

of

FCL

Date/Time: 23-11-2017 1035am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKM 7786X

Insured:

SHC 7042Y

at Workshop n/s

Alan's United

Tel:

6453 8686

of

Blk 7 sin ming

Ind Est 401-76

Policy No:

D-15072762MFSH

Claim No:

D17010827MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18/12/17

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

23/11/17 1139am

Person Contacted:

Kenny

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKM 7786X - X

SHC 7042Y - CS3 / FCL11005241 / RH6K2

DCA: 0910/14

28/11/17 @ 4.17pm revised to Sithara by email.

ASS. REC. BY:

REF: 102/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKN 7786XYr Regn: 01 1 90Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mer 200 Ec.c. 1992Colour: h.v. Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 393261

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDB12402123 042294Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 18/11/17D.O.I. 27/11/17Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/11 with pass to Customer21 Lp 8430d email & confirmed. (Ref 81768.40, 29%)

RECEIVED 29 NOV 2017

Date/Time, File Pass to?

☐

Preli. Report

1) 29/11 transfer☐

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee: 145Transportation: 50

S + RS. SI

Photos: 15

Others: _____

TOTAL

210Report Format: TPLump Sum / I.B.): 4300

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022377/Kqb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7042Y	Veh. Inspected	SKM 7786X
Policy No.		Coverage (\$)	0.00
Claim No.	D17010827MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	23/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/11/2017	Inspection Date
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Cath): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Kenneth): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

[Signature] 29/11/17
Case Handler Date

MOTOR SURVEY ASSIGNMENT

Date	21-11-2017	Our Ref No. D17010827MFSH
Accident Date	18-11-2017	Claim Type. Third Party
Insured Vehicle	SHC7042Y	Third Party Vehicle. SKM7786X
Survey Location	BLK 7 SIN MING INDUSTRIAL ESTATE #01-76	
Contact Person.	KENNY	
Contact No.	64538686/ 64538686	Fax No. 64596550
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ALAN'S UNITED AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230472)



PRI Documents

Close X

PRI Header Details

Claim No	D17010827MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & AL
Workshop Name	ALAN'S UNITED AUTO PTE LTD (Contact Person : KENNY)	Survey Location & Contact Details	BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 Mobile: 64538686 , Phone: 64538686 , Fax: EmailId: KENNYCHAN@ALANUTD.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7042Y	TP Vehicle No	SKM77
PRI Recieved Date	22-11-2017 07:37:28 PM	Surveyor Appointed Date	23-11-2017 10:35:25 AM	Surveyor Accept Date	23-11-

Survey Report Upload

Surveyor Inspection Date *: 	Surveyor Report Date	23-11-2017	Upload Survey Report *: 
---	----------------------	------------	---

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 28 November, 2017 4:12 PM
To: 'Claim Workflow System'; assignments
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010827MFSH/1
Attachments: CSFCI17022377Kqb.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SKM 7786X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 23 November, 2017 11:37 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010827MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Thursday, 23 November, 2017 10:35 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SITHARA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010827MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010827MFSH

Date: 28 November 2017

Our Ref: CS/FC117022377/Kqb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKM 7786X .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/11/2017 at the premises of M/s ALAN'S UNITED. and have the following to report:-

Workshop Estimate Amount	: S\$ 6,068.40 .
Revised Estimate Amount	: S\$ 5,618.40 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the o/s front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	1980Z
Vehicle Details	
Vehicle No.	SKM7786X
Vehicle to be Exported	No
Intended De-registration Date	28 Nov 2017
Vehicle Make	MERCEDES BENZ
Vehicle Model	200E AUTO
Primary Colour	Red
Manufacturing Year	1989
Engine No.	10296322008251
Chassis No.	WDB1240212B042294
Maximum Power Output	-
Open Market Value	\$40,192.00
Original Registration Date	18 Jan 1990
First Registration Date	18 Jan 1990
Transfer Count	9
Actual ARF Paid	\$70,336.00
Intended PARF Rebate Details	
PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	30 Apr 2019
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
PQP Paid	\$3,162.00
COE Rebate Amount	\$449.00
Total Rebate Amount	\$449.00

The information contained herein is correct as at 28 Nov 2017

OK

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5080414932-01

Cover : Third Party, Fire & Theft

- | | |
|---|--------------------------------------|
| 1. Index mark and Registration Number of Vehicle | : SKM7786X |
| Chassis Number | : WDB1240212B042294 |
| 2. Name of Policyholder | : PARAMJEET SINGH S/O JOGINDER SINGH |
| 3. Effective Date of Insurance | : 11 May 2017 |
| 4. Expiry Date of Insurance | : 10 May 2018 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |

6. Limitations as to Use#

- (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
(b) Use for racing, pace-making, reliability trial or speed-testing.
(c) Use for the carriage of goods (other than samples) in connection with any trade or business.
(d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: N/A
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
PRIMARY DRIVER	: PARAMJEET SINGH S/O JOGINDER SINGH
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : AUTO INSURANCE AGENCY (00000613840)
Date of Issue : 11 May 2017 12:19 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

Maximum Laden Weight:	0 kg
Open Market Value:	\$40,192.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
Minimum PARF Benefit:	-
No. of Transfers:	9
IU Label No.:	1125514166
COE No.:	1999042903000592Z
COE Expiry Date:	30 Apr 2019
COE Category:	B - Car (1601cc & above)
COE Registration Category:	B - Car (1601cc & above)
Quota Premium (QP) / Prevailing Quota Premium:	- / \$3,162.00
PQP Paid:	\$3,162.00
QP (Regn Cat):	-
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$0.00
Additional Registration Fee Rate:	175.00 %
Actual ARF Paid:	\$70,336.00
Vehicle Lifespan Expiry Date:	No Lifespan
CO2 Emission:	-
Message:	To renew the COE, the Prevailing Quota Premium payable is that of Category B.

Print

OK

Save as PDF

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHC7042Y (FIRST)

Accident Date : 18-11-2017

Our Ref : SKM7786X / CHAN

217179

PARAMJEET SINGH S/O JOGINDER SINGH

C/O ALAN'S UNITED AUTO PTE LTD

BLK 7 SIN MING IND. EST. SECTOR C

#01-76

SINGAPORE 575642

Date : 22-11-2017

*Not Authorised
L1 Rep @ 430d
Penny After Paint
Yelap*

ESTIMATE COST OF REPAIR FOR MERCEDES-BENZ 200E 2.0 (A) SKM7786X

1 PC	O/S SIDE MIRROR ASSY	<i>CM</i>	\$1,750.00	✓
1 PC	FRONT O/S FENDER	<i>Bw</i>	\$750.00	✓
1 PC	FRONT O/S FENDER PROTECTOR	<i>Red</i>	\$1,077.00	✓
1 PC	FRONT O/S FENDER PROTECTOR MOULDING	<i>Mr</i>	\$99.00	✓
1 PC	FRONT O/S SPORT RIM	<i>Red</i>	\$1,700.00	✓
			\$5,376.00	
		LESS 10%	\$537.60	
			<u>\$4,838.40</u>	

\$4,838.40

1 PC	O/S SIDE MIRROR CHROME COVER (ACCESSORIES)	<i>CM</i>	\$80.00 SN	✓
	TO COMPUTER WHEEL ALIGNMENT		\$50.00	✓
	TO PUTTY AND SPRAY REPLACED PARTS		\$500.00	<i>350d</i>
	TO PANEL BEATING, REMOVE DAMAGED PARTS, ALIGN, ADJUST AND TO RENEW ABOVE PARTS		\$600.00	<i>300d</i>
			<u>\$6,068.40</u>	

Singapore Dollars Six Thousand Sixty Eight And Cents Forty Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022377/Kqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7042Y	Veh. Inspected	SKM 7786X	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17010827MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	23/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES 200E (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	1990	
Chassis No.	WDB1240212B042294	Colour	METALLIC DARK BLUE	
Odometer	393261	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	PIRELLI	6 mm	
L/H Front Tyre	215/50 R17	PIRELLI	6 mm	
R/H Rear Tyre	215/50 R17	PIRELLI	6 mm	
L/H Rear Tyre	215/50 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/11/2017	Inspection Date	27/11/2017	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 7786X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	O/S SIDE MIRROR ASSY	CRACKED	1,750.00	1,750.00
1	FRONT O/S FENDER	BUCKLED	750.00	750.00
1	FRONT O/S FENDER PROTECTOR	DENTED	1,077.00	1,077.00
1	FRONT O/S FENDER PROTECTOR MOULDING	NECESSARY	99.00	99.00
1	FRONT O/S SPORT RIM	DENTED	1,700.00	1,700.00
	LESS 10% DISCOUNT		-537.60	-537.60
			4,838.40	4,838.40
SPECIAL NETT ITEMS				
1	O/S SIDE MIRROR CHROME COVER (ACCESSORIES)(SN)	CRACKED	80.00	80.00
			80.00	80.00
LABOUR				
	TO COMPUTER WHEEL ALIGNMENT.		50.00	50.00
	TO PUTTY AND SPRAY REPLACED PARTS.		500.00	350.00
	TO PANEL BEATING,REMOVE DAMAGED PARTS,ALIGN,ADJUST AND TO RENEW ABOVE PARTS.		600.00	300.00
			1,150.00	700.00
GRAND TOTAL			6,068.40	5,618.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CS/FCI17022377/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.