22/03/2002 ASS. REC. BY:	REF: CS/FCLI?	1022378/	Special Instruction		
Surveyor:		MENT (Office)			
From (Person):	CWS JOGANNE YORY OF	ECL	Date/Time:	93.112017	7.59pm
Estimated Cost:		Bill to:			
OD ITT WS	TP RES / OD RES / EVA / INV / MV				
To Inspect Veh	icle No: SBE 800}		Insured: S1		
at Workshop m	notu to	Nayl	Tel: <u> </u>	323	
of	19 Yorong 87	ioa Paydin			
		Claim No:	08010FIQ	IMI-SH	
Sum Insured:		Excess:			
Make of Veh: (Client's Record)			D.O.A	FIOC-11-FI	
	REP. / REV 24 HRS WD1		HOD Fac	lorsement:	
Date/Time:	23.112017 218pm Person Contacts	: Sayed			
Date/Time	Action/Instruction () Estim	ate			
	SBE 800H - X	iji darkarik da da saya a			
	SHC 339717 - :05/ FCZ 170019	94/Hbnz	Out	F11018 :	
13/18/804/137		Juner nuter ser			
	C3.6pm - Sayed say				
01-10-18 430pm	Daniel say lability not clear.		Ž		
	Emuil to FCI will timparay	close this file.	2/w/8 sals		
		The state of the s	X		

Catherine Chong (LKK Auto)

From:

Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Sent:

Monday, 1 October, 2018 4:36 PM

To:

'Claim Workflow System'

Cc:

JOANNEYONG@FIRST-INSURANCE.COM.SG; ASSIGNMENTS@LKKAUTO.COM

Subject:

RE: SURVEY ASSESSMENT - D17010801MFSH/2

Dear Sir / Madam,

Please be informed that we are unable to conduct the inspection after some attempts to inform the workshop to present the vehicle.

This case has been pending for a long time due to the unavailability of the owner, therefore we decided to temporarily close this case.

Kindly advise us if there is any arrangement made and will be glad to re-open the case accordingly.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Thursday, 23 November, 2017 2:20 PM

To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; ASSIGNMENTS@LKKAUTO.COM

Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; 'SUR' <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D17010801MFSH/2

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@first-insurance.com.sg]

Sent: Thursday, 23 November, 2017 1:59 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D17010801MFSH/2

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date

20-11-2017

Our Ref No. D17010801MFSH

Accident Date

17-11-2017

Claim Type. Third Party

Insured Vehicle

SHC3397A

Third Party Vehicle. SBE800H

Survey Location

19 LORONG 8 TOA PAYOH SINGAPORE 319255

Contact Person.

MOHAMAD FAZLI BIN BACHOK

Contact No.

67038101/90903323

Fax No. 62535535

Survey Type

WITHOUT PREJUDICE:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

MOTOR IMAGE

ENTERPRISES PTE LTD

Attention. NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

JOANNEY

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

V									
Job Sheet (/ClaimWS/Surveyor/JobSheet/230488) PRI Documents Close									
	PRI Header Details								
Claim No	D17010801MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	2 & MC PTE LTI				
Workshop Name	MOTOR IMAGE ENTERPRISES PTE LTD (Contact Person : MOHAMAD FAZLI BIN BACHOK)	Survey Location & Contact Details	19 LORONG 8 TOA PAYOH SINGAPORE 319255 Mobile: 90903323, Phone: 67038101, Fax: EmailId: FAZLIBACHOK@MOTORIMAGE.NET						
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:						
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3397A	TP Vehicle No	SBE800				
PRI Recieved Date	21-11-2017 08:05:10 PM	Surveyor Appointed Date	23-11-2017 01:59:02 PM	Surveyor Accept Date	23-11-				
Survey Report Upload									
Surveyor Inspection Date *:		Surveyor Report Date	23-11-2017	Upload Survey Report *:					
Vehicle Particulars									
Make	Please Select Make	Model	Please Select Model	Year	Select				
Chasis No		Engine No		Mileage					
Color		Cubic Capacity							
Multiple Documents Upload									
Upload Multiple Documents									
File Name Action									

Surveyor Job Remarks