


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5193M
Ref. No : TAX/11/17/2134
Reg. Date : 10/10/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : HAN HOW ENG
Type of Accident : SIDE SWIPE
Date / Time of Accident : 21/11/2017 12:05:00 AM
Accident Reported Date / Time : 21/11/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 21/11/2017
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093223
Special Instruction to ARC, if any :
TOWED \$40 / SFW106L / *MSH/Repair by part*
Prepared Date : 21/11/2017 05:01:28 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FUX03572335

Mileage :


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	845.00	0.00
Total Spray Painting Charges :	1,494.00	0.00
Total Material Charges :	3,617.82	3,617.82
Other Charges :	660.00	0.00
TOTAL :	6,616.82	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	5.00	0.00 ⁴ days - p/p
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	22/11/2017 01:24:12 PM	01/01/1900 12:00:00 AM

 22/11/17
@ 1520

Prepared / Adjusted Date :

Remarks :

Prepared Date : 22/11/2017 01:22:09 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 11/22/2017 1:22:48 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	845.00	0.00 300
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 X
RESPRAY WHEEL CAP	180.00	0.00 X
TO RESPRAY FRONT DOOR RH	378.00	0.00 X
Total Spray Painting & Panel Beating	1,494.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 40
TOWING CHARGE	80.00	0.00 ?
Total Other Costs	660.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119479 62			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace <i>Repair</i>	No
52115470 50			SUPPORT, FR BUMPER RH	1	76.90	25.00	57.67	Replace	Replace <i>X</i>	No
53801470 80			FENDER SUB-ASSY, FR, RH	1	933.10	25.00	699.82	Replace	Replace <i>PT</i>	No
75374471 40			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace <i>Ne</i>	No
42602471 80			CAP SUB-ASSY, WHEEL	1	175.80	25.00	131.85	Replace	Replace <i>8023</i>	No
42611474 50			WHEEL, DISC	1	1,555.10	25.00	1,166.32	Replace	Replace <i>X</i>	No
67001471 52			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	25.00	937.20	Replace	Replace <i>X</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>X</i>	No
68730121 20			HINGE ASSY, FRONT DOOR, LOWER RH	1	92.10	0.00	92.10	Replace	Replace <i>X</i>	No
68710121 51			HINGE ASSY, FRONT DOOR, UPPER RH	1	82.10	25.00	61.57	Replace	Replace <i>X</i>	No
TOTAL MATERIALS								3,617.85	3,617.82	
TOTAL MATERIALS(Discounted)							3,617.82	3,617.82		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									