

ASS. REC. BY:

REF: CS/07117022423/Tr6<sup>32</sup>

Special Instruction:

Surveyor: Carlich ASSIGNMENT (Office)

From (Person): Journe Tay of CTI Date/Time: 24/4/17

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBB 3A27Y Insured: SJV 7401X

at Workshop m/s HKL UM Team Tel: 62956656

of BT Merah

Policy No: DMPCSN307801700 Claim No: SNM17006690C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 17/11/17

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' @ 1.12.2017 @ 3pm owner writing H.O.D. Endorsement: \_\_\_\_\_

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	FBB 3A27Y / SJV 7401X NBA/INCL 702230/Y D.O.A. 17/11/17
	SJV 7401X C83/MSG17010075 / SH3M2 D.O.A. 13/5/17
	confirm \$726, 3 days
	red: \$764, 51%





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17022423/T1rb

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERSINGAPORE 079909

Date : 24-11-2017



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJV 7401X	Veh. Inspected	FBB 3927Y
Policy No.	DMPCSN3078071700	Coverage (\$)	0.00
Claim No.	SNM17D06690C02	Excess (\$)	0.00
Assign From	JOWYN TAY (MERIMEN)	Assign Date	24/11/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	17/11/2017	Inspection Date	01/12/2017
Survey held at	HKL LIM TEAM MOTORSPORT BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722.		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### ...CLAIM SUBFOLDER...(New Assignment)

**CLAIM SUBFOLDER TRACKING**

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Nov 2017		24 Nov 2017 12:50 Assign				<b>New Assignment</b> Cancel Case

Main

Reference

Claim Details

Documents

Show All

**CLAIM SUBFOLDER DETAILS**

[Created by insurer]

Insured:	<b>GOH PENG THIONG</b> , ID: S1673731C		
Main Claimant:	<b>ALORIDE PTE. LTD.</b> , Co. Reg. No.: 201629994W		
Vehicle Reg. No.:	<b>FBB3927Y</b>	Date of Loss:	17/11/2017 23:00 - :59
Claim Type:	<b>TP / SNM17D06690C02</b>	Policy/Cover Note No.:	DMPCSN3078071700 (Comprehensive) Coverage: 05/10/2017 - 04/10/2018
Vehicle Reg. No. (Insured):	<b>SJV7401X</b>	Policy No. (Claimant):	5085645204-01
		Excess:	S\$0.00
Repairer:	<b>Hkl Lim Team Motorsport (HQ)</b> BLK 1008 #01-24 BUKIT MERAH LANE 3, 159722 Bukit Merah - Tel: 62756656/62756566/62727292		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Jowyn Tay</b> - 6389 6174]		
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Final Rpt due 05/12/2017]		
Adj Asg. Remarks:	please proceed to survey and arrange for direct settlement.		

**ASSOCIATED MAIL RECEIVED**

View All

Compose Case Mail

There are no mail for this case.

**ALL ASSOCIATED TASKS**

View All

Search Tasks

Create New Task

Complete

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?  
No results.

*veh not in*

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	21/11/2017 18:44
Date Of Accident	17/11/2017 23:45
Exact Location Of Accident	TRAFFIC JUNCTION OF ORCHARD ROAD/GRANGE ROAD
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	FBB3927Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ALORIDE PTE. LTD.
Co Reg No	201629994W
Email Address	ZULIOS789@GMAIL.COM
Mobile Phone No	(LOCAL) +65-84807926
Alternative Phone No	OFFICE-84807926

**Vehicle Particulars**

Manufacturer	YAMAHA
Model	SPARK-135CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

**Insurance Company**

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5085645204-01
Cover Note Number	

**Driver**

Name of Driver	ZULHILMIE BIN ABU BAKAR
NRIC No	S8939483Z
Date Of Birth	03/11/1989
Occupation	INDOOR
Date Of Driving Pass	18/09/2014
Driving Experience	3 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84807926
Fax Number	
Contact Number	OTHERS-84807926
E Mail Address	ZULIOS789@GMAIL.COM

Address	BLK 14B LORONG 7 TOA PAYOH #04-245
Postcode	312014
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	DRIZZLING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	<b>ROAD:</b> 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING , <b>POSTCODE:</b> 319194 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-2519999 - <b>FAX NO:</b> 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20171118/2161(COLLISION TYPE IS HEAD TO SIDE)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV7401X
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	GOH ZHI BING, BRYAN
NRIC/Passport Number	S9636998J
Contact Number	83224534
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

#### Details of Witness

Name

Phone Number

Email Address

**DETAILS OF INJURED PERSON 1**

Name ZULHILMIE BIN ABU BAKAR

Approximate Age

Injuries Sustain SLIGHT INJURY

Injured person in which vehicle? FBB3927Y

Were seat belts worn?

Was injured conveyed to hospital by ambulance? NO

Address

Postcode

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
  - (ii) regulators, law enforcement and government agencies as reasonably required for the purpose(s) stated; or
  - (iii) for complying with requirements under any regulations, laws or court orders

  
Policyholder's Signature  
Date & Time

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time

  
Recording Centre Personnel's Signature  
Name: ROSLI NAWAZ  
NIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

REFER TO ATTACHMENT 7

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHMENT 7  
POLICE REPORT 7/2017 11/8/2161

DECLARATION

I/We declare the foregoing particulars are true in every respect

1  
  
Witnessed & Signed  
Date & Time

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time

 21/6/2017  
Reporting Officer/Personnel Signature  
Name: Keesli Waters  
NLRB # 1234

Sketch Plan #3



*[Signature]* 21/11/2017

## Sketch Plan #4



**SINGAPORE  
POLICE FORCE**



T/20171118/2161

1 of 3

Report No. T/20171118/2161

Police Station Of Origin:  
Toa Payoh N P C  
93 Toa Payoh Central #01-02 Toa Payoh  
Community Building SINGAPORE 319194  
Tel No: 1800-2519999

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/11/2017 23:54	Video Report No.	Station Diary No. 222
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: ZULHILMIE BIN ABU BAKAR		Address: APT BLK 14B LORONG 7 TOA PAYOH #04-245 SINGAPORE 312014	
ID Type / ID No.: NRIC NO / S8939483Z		Contact No.: Home/Office:                      Mobile: 84807926	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 28	Date of Birth: 03/11/1989	Type of Informant: Rider
Race: Malay		Language: English	Institution / School Name
Occupation: Auxiliary police officer		Driving Licence Information: Class: 2B,2A	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/11/2017 23:45	Type of Location: Straight Road
Location: Junction of Road 1 and Road 2 ORCHARD ROAD GRANGE ROAD Traffic junction of Orchard Road and Grange Road.				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBB3927Y	Motorcycle				Slightly Damaged	0
SJV7401X	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

## Sketch Plan #5



SINGAPORE  
POLICE FORCE



T/20171118/2161

2 of 3

Report No. T/20171118/2161

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No. 1800-2519999

CONTINUATION OF REPORT

Rider			
Name	ZULHILMIE BIN ABU BAKAR	ID No.	S8939483Z
Related Vehicle	FBB3927Y (Motorcycle)	Contact No.	84807926
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	GOH ZHI BING, BRYAN	ID No.	S9636998J
Related Vehicle	SJV7401X (Car)	Contact No.	83224534
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 17/11/17 at about 11.45 p.m, whilst I was riding my motorbicycle bearing vehicle number, FBB3927Y and traveling along a traffic junction of Orchard Road and Grange Road. I was riding straight ahead when traffic light was in my favour. There was a car (V2) bearing vehicle number, SJV7401X was traveling on the same direction at my left side. V2 speed up and made a right turn that caused me to collide onto his vehicle's right side portion.

I had fell from my motor bicycle and suffered bruises and scars on legs

I wish to inform that my motorbike was rented from Aloride company, and notified them about the accident. I was advised to lodge police report to facilitate for the insurance claim by the rental company. I will go to see a doctor for my injuries.

Sketch Plan #6



SINGAPORE  
POLICE FORCE



T/20171118/2161

3 of 3

Report No. T/20171118/2161

Police Station Of Origin

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No. 1800-2519999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report. E / Sgt 2 TEOH PREECHA	Signature Of Informant 
Signature Of Interpreter: Not applicable	Date/Time: 18/11/2017 23.54
Officer In Charge Of Case: TP / AEIT / SSI 2 SITIMARSITA BINTE BOHARI Contact No : 65476219	Classification Of Case:
Authentication Stamp NP168 	



# HKL LIM TEAM MOTORSPORT

Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722  
Email: support@hklilmotorsport.com.sg

Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291  
Website: www.hklilmotorsport.com.sg

FBB3927Y

1. FRONT FENDER - \$60 *cut*
  2. FRONT WHEEL RIM - \$150 *Xm*
  3. FRONT FORK ASSY/UNDER BRACKET - \$550 *SNP/30bt*
  4. STEERING CONE BEARING - \$80 *photo? / rec*
  5. HANDLEBAR - \$70 *? photo / bt*
  6. HANDLEBAR BALANCER - \$20 *cut*
  7. SIDE MIRROR - \$50 *one*
  8. FRONT FOOTBAR - \$60 *bt*
  9. FRONT FOOTBAR RUBBER - \$20 *m*
  10. TAIL BOAD LH - \$80 *cut*
  11. LABOUR - \$350 *200*
- TOTAL - \$1490

Tanjilur 97495749

01/12/12C 1520

Resurvey new parts  
3 days - WP

sur @ lkkauto.com

P/P

*[Handwritten signature]*  
4/12/12

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



# HKL LIM TEAM MOTORSPORT

Blk 100B #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6666, 6275 6566, 62727292 Fax: 6272 9291  
Email: support@hklimmotorsport.com.sg Website: www.hklimmotorsport.com.sg

FBB3927Y

1. FRONT FENDER - \$60 *at*
  2. FRONT WHEEL RIM - \$150 *X m*
  3. FRONT FORK ASSY/UNDER BRACKET - \$550 *SAP/30*
  4. STEERING CONE BEARING - \$80 *proforma*
  5. HANDLEBAR - \$70 *plus to bt*
  6. HANDLEBAR BALANCER - \$20 *at*
  7. SIDE MIRROR - \$50 *at*
  8. FRONT FOOTBAR - \$60 *bt*
  9. FRONT FOOTBAR RUBBER - \$20 *m*
  10. TAIL BOAD LH - \$80 *at*
  11. LABOUR - \$350 *200*
- TOTAL - \$1490

Parts \$440  
10% - 396

Labour \$200  
SN \$150

\$ 726

*hklm* 21/12/17

Tanjilur 97495749

01/12/12C 1520

*hklm*  
21/12/17

Resuming new parts  
3 days - WP

su @ hklm.com

P/P

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Nov 2017		24 Nov 2017 12:50 <a href="#">Edit Adj Rpt</a>	<b>S\$726.00</b> <a href="#">Edit Estimates</a>	<b>S\$726.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>				<b>[Created by insurer]</b>					
Insured:	<b>GOH PENG THIONG</b> , ID: S1673731C								
Main Claimant:	<b>ALORIDE PTE. LTD.</b> , Co. Reg. No.: 201629994W								
Vehicle Reg. No.:	<b>FBB3927Y</b>	Date of Loss:	17/11/2017 23:00 - :59						
Claim Type:	<b>TP / SNM17D06690C02</b>	Policy/Cover Note No.:	DMPCSN3078071700 (Comprehensive) Coverage: 05/10/2017 - 04/10/2018						
Vehicle Reg. No. (Insured):	<b>SJV7401X</b>	Policy No. (Claimant):	5085645204-01						
		Excess:	S\$0.00						
Repairer:	<b>Hkl Lim Team Motorsport (HQ)</b> BLK 1008 #01-24 BUKIT MERAH LANE 3, 159722 Bukit Merah - Tel: 62756656/62756566/62727292								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Jowyn Tay</b> - 6389 6174]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... <b>[Final Rpt due 05/12/2017]</b>								
Adj Asg. Remarks:	please proceed to survey and arrange for direct settlement.								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>	<a href="#">Compose Case Mail</a>				
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>				<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>		
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*FBB3927Y (SNM17D06690C02)  
[SJV7401X]  
TP  
ALORIDE PTE. LTD.  
Nov 17 2017 11:00PM  
[GOH PENG THIONG]  
Hkl Lim Team Motorsport

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value="v"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	<input checked="" type="checkbox"/>
			Thumbnail Print
1	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
2	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
3	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
4	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
5	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
6	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
7	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
8	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
9	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
10	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
11	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
12	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
13	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
14	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
15	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
16	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
17	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
18	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
19	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
20	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
21	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
22	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
23	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
24	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
25	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
26	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
27	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
28	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
29	29/01/18 16:20	General View	<input checked="" type="checkbox"/>
30	29/01/18 16:20	Reinspection Photo	<input checked="" type="checkbox"/>
31	29/01/18 16:20	Reinspection Photo	<input checked="" type="checkbox"/>
32	29/01/18 16:20	Reinspection Photo	<input checked="" type="checkbox"/>
33	29/01/18 16:20	Reinspection Photo	<input checked="" type="checkbox"/>
34	29/01/18 16:20	Reinspection Photo	<input checked="" type="checkbox"/>
35	29/01/18 16:20	Reinspection Photo	<input checked="" type="checkbox"/>

36	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
53	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	29/01/18 16:20	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	22/11/17 14:02	E-filed GIA report OF SJV7401X (INSURED)	1	Load PDF	
2	22/11/17 14:02	Quotation/Replacement/Repair invoice	1	Load JPG	<input checked="" type="checkbox"/>

### Linked Accident Report Documents

				<b>View</b> View in Browser	<input type="checkbox"/>
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		<b>Thumbnail</b>	<b>Print</b>
1	21/11/17 18:56	Accident Statement	1	Load HTM	
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		<b>Thumbnail</b>	<b>Print</b>
1	21/11/17 18:53	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	21/11/17 18:53	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	21/11/17 18:53	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	21/11/17 18:53	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	21/11/17 18:53	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	21/11/17 18:53	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	21/11/17 18:53	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	21/11/17 18:53	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
9	21/11/17 18:53	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
10	21/11/17 18:53	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
11	21/11/17 18:53	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
12	21/11/17 18:53	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
13	21/11/17 18:53	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		<b>Thumbnail</b>	<b>Print</b>
1	21/11/17 18:55	Sketch Plan	1	Load JPG	<input checked="" type="checkbox"/>
2	21/11/17 18:55	Sketch Plan #2	1	Load JPG	

					<input checked="" type="checkbox"/>
3	21/11/17 18:55	Sketch Plan #3		Load JPG	<input checked="" type="checkbox"/>
4	21/11/17 18:55	Sketch Plan #4		Load JPG	<input checked="" type="checkbox"/>
5	21/11/17 18:55	Sketch Plan #5		Load JPG	<input checked="" type="checkbox"/>
6	21/11/17 18:55	Sketch Plan #6		Load JPG	<input checked="" type="checkbox"/>

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17022423/T1RBS2  
Date: 30/01/2018

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN3078071700	
Claimant Vehicle No: FBB3927Y	Insured Vehicle No: SJV7401X	
Date of Loss: 17/11/2017	Nature of Claim: TP	Claim No: SNM17D06690C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBB3927Y	
Make & Model:	YAMAHA SPARK, 135cc	Engine No: 5YP205685
Reg. Date:	22/03/2007 (Man. Year: 2006)	Chassis No: 5YP205685
Colour:	Blue	Odometer: 10329 km
Engine Capacity:	135 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	80/90R17	Rear Tyre Size:	80/90R17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,140.00	526.00	614.00	53.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	350.00	200.00	150.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>1,490.00</b>	<b>726.00</b>	<b>764.00</b>	<b>51.28</b>

#### INSPECTION

Date of Assignment:	24/11/2017	
Date Inspected:	01/12/2017 Inspected At:	Hkl Lim Team Motorsport (HQ) BLK 1008 #01-24 BUKIT MERAH LANE 3 Singapore 159722
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 30 Jan 2018)
<b>Parts:</b>	N/A YAMAHA SPARK 135cc (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBB3927Y)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	60.00 F	*60.00 FL
2	1		*FRONT WHEEL RIM	Not Necessary	150.00 F	*- FL
3	1		*STEERING CONE BEARING	Necessary	80.00 F	*80.00 FL
4	1		*HANDLEBAR	Bent	70.00 F	*70.00 FL
5	1		*HANDLEBAR BALANCER	Cut	20.00 F	*20.00 FL
6	1		*SIDE MIRROR	Cracked	50.00 F	*50.00 FL
7	1		*FRONT FOOTBAR	Bent	60.00 F	*60.00 FL
8	1		*FRONT FOOTBAR RUBBER	Torn	20.00 F	*20.00 FL
9	1		*TAIL BOAD LH	Cut	80.00 F	*80.00 FL
10	1		*FRONT FORK ASSY/UNDER BRACKET	Bent	550.00 FS	*130.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,140.00</b>	<b>570.00</b>
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	44.00
<b>Total Parts (\$\$)</b>	<b>1,140.00</b>	<b>526.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR.	New	350.00	200.00
Gross Labour Cost (S\$)			350.00	200.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;