15/5/2010

INS. CASE OWNER: CC 3 / AIG1702 2424 / klhaz

LKK:

IDAC:

ASSIGNMENT

Surveyor: KALVIN DOI: 23/11/17 Date / Time : 23/11/17

Registered in Merimen: 24/11/17

Pre-assign / CCU / FTE



Insured Vehicle No. : SLB 3805Y

Name of Insured :

Insured Tel No. : HP:

Excess Sec II :S$ D.O.A : 22/11/17

Is driver the owner? (YES / NO)

If **NO**, Driver Name / Age :

Driver Tel No. : (V/L: YES / NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

Nature of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % **Final ? Yes / No**

SHB 4226J →



INSRS:
WSP: COGE (Loyang)
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	
	SHB 4226J - CS/QW09013928/Yoxx DOA: 21/06/09
	-NA/INC1201613C/y1 DOA: 19/08/12
	-NS/INC09022493/Co DOA: 04/10/09
	SLB 3805Y - X

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	

Documentation Check List:	Handler	Typist
Notification ltr (if non-pickup)	☐	☐
After call ltr to OI:	☐	☐
Authorisation To Act:	☐	☐
Release Voucher:	☐	☐
Final Repair Bill:	☐	☐
Car Rental Invoice:	☐	☐
Towing Invoice	☐	☐
LTA / GIA :	☐	☐
Medical Bill:	☐	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☐	☐
LOD	☐	☐
Payment Breakdown Form:		☐
Post-Repair Photos:	☐	☐
Others:	☐	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S$ (days)	Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with	Email ☐ Call ☐
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost:	S$		
Loss of Rental (LOR):	S$ (days)		
Loss of Use (LOU):	S$ ($ x days)		
Loss of Income (LOI):	S$ ($ x days)		
LOR only ☐ LOU only ☐	LOR + LOU ☐	LOR + LOI ☐ [Tick only one]	
GIA/LTA Search	S$		
Medical:	S$		1) Claim status: Normal/Reject/Private Settle
Disbursement:	S$	(e.g. Tow/ Independent)	2) Report Format:
Legal Cost	S$		3) Survey fee:
Total:	**S$**	**Global Sum S$:**	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S$	Name 1:	
Payee 2: (Strike if N.A.)	S$	Name 2:	
Payee 3: (Strike if N.A.)	S$	Name 3:	

(06/11.13)

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : **Yes** or **No**

GIA / PR Seen: _____ Consistent? : **Yes** or **No**

Est. Repairs: _____ days Res.: **Yes** or **No**

Lum Sum: _____ % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: SHB 4226J Yr Regn: 30 Jun / 2015

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or _____

Make: Hyundai I40 c.c 1685

Colour Blue A/C: **Insured / Std / NI / NA**

Sp.Reading 283510 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: KMHLB414MG4075170

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or _____

Brake: **Inorder / Jammed / Leaked / Burnt** or _____

Modi : **Nil / S/Rim / STD A/Rim** or _____

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	22/10/17	D.O.I.	23/10/17

Survey held at COGE (Loyang)

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or

NS Rear

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	AVG P1P

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Report Format : _____

Lump Sum / I.B.I: ($ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Survey Fee:	
Transportation:	
___S + RS, ___SI	
Photos	
Others	
TOTAL	

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

Date/Time: 23.11.2017 09:45 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: JC NO.305091662

JSTOMER	REGN NO.: SHB4226J / MILEAGE
R/MS COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI / FUEL E.....1/2.....F
JSTOMER NO. 7010045	MODEL: I-40 / DATE/TIME IN: 22.11.2017 13:50
DDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717	YR OF MANU: 30.06.2015 / TARGET DATE
L. (R) 65508755 (O) (P)	CHASSIS CODE: KMHLB41UMGU075170 / COMPLETION DATE/TIME:
SCOUNT CARD NO.	

JOB DESCRIPTION

Accident Date: 22.11.2017
NATURE: 3P 22.11.2017

S/NO	LABOR CODE	DESCRIPTION

HECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

owledgement Slip

e:
lo.:
cle No.: SHB4226J CHIANG @

ıe of Service Advisor

Signature/Date

e returned to Service Reception upon collection

Exit Pass

Vehicle No.: SHB4226J

Name of Service Advisor

Date

To be kept by Security Guard