

S. REC. BY:

REF:

C3/CT117022441/T12612

Special Instruction:

Surveyor:

Tcu FKL

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CT1

Date/Time:

23/11/17 @ 347h

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PA 9849P

Insured:

SJY 9849P

at Workshop m/s

Connect 3

Tel:

98509666 Winnie

of

566 Woodlands Rd

Policy No:

DMHCSN1428091703

Claim No:

SNM17D06753C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/11/17

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	Survey at 13 Tuas Ave 4
	PA 9849P x
	SJY 4034B x
13/12/17	LS \$ 3750 confirmed by email (Reel 7420, 662)

Tanghin

REF: CTI

ASSIGNMENT

From: Date: 24/11/17

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

PA 9849P

at Workshop no:

Connect 3

of:

13 Tuas Ave 14

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

98509666 Winnie

Make of Veh:

WIP

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection:



Bel. or Market Value

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lum. Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24HRS

Date:

Person Contacted

Vehicle IN / OUT
Winnie

Van No: PA9849P

VR Page: 2010 10

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make

Yutong ZK6127H

8849

Colour

Yellow / orange

Insured / Std / NI / NA

Sp. Reading

467513

Radio Insured / Std / NI / NA

Eng. No:

1

C. No:

LZYTA TF 61A

1009121

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

295 / 80R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI /

TOYO / YOKO or

Front

Rear

R. Bal:

8

mm

R. Bal:

8/8

mm

L. Bal:

8

mm

L. Bal:

8/8

mm

D.O.A.

D.O.I.

24/11/17 @ 1530

Survey held at:

Connect 3.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

W/S will pass estimate & CIAA later.
12/12 Email winnie c/s \$3750, 5 days no reply yet.

13/12/2017

Date/Time File Pass to:



: Prel. Report

: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee

Transporter

3-PR

Price

Cost

Net

Net

200

200

Date/Time File Return to:

13/12 - typist

Add Fee:



Site Insp

Interview

Test

Test

Report Format:

merimen

Lump Sum / I.B.I.

3750/2

Survey Department Check List (Case Handler)

Reference No. : CS/CTI1702244/TNB
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 13/12/17
Case Handler Date

*C: Critical *N: Nor-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17022441/T1vb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 24-11-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJY 4034B	Veh. Inspected	PA 9849P
Policy No.	DMHCSN1428091703	Coverage (\$)	0.00
Claim No.	SNM17D06753C02	Excess (\$)	0.00
Assign From	IRENE TAY (MERIMEN)	Assign Date	23/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/11/2017	Inspection Date	24/11/2017
Survey held at	CONNECT3 7 OLD TOH TUCK ROAD SINGAPORE 597648		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Nov 2017		23 Nov 2017 15:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	RIC-TAT TRAVEL & COACH SERVICES PTE LTD
Vehicle Reg. No.:	PA9849P
Claim Type:	TP / SNM17D06753C02
Vehicle Reg. No. (Insured):	SJY4034B
Date of Loss:	21/11/2017 09:00 - :59
Policy/Cover Note No.:	DMHCSN1428091703
Policy No. (Claimant):	
Excess:	S\$0.00
Repairer:	Connect3 (mandai Estate) (HQ) 566 Woodlands Road, 728697 Mandai - Tel: 98509666
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/12/2017]
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Wmink
(OUT)

13 Tues Ave 14
~~BASET~~

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	1198R
Vehicle Details	
Vehicle No.	PA9849P
Vehicle to be Exported	No
Intended De-registration Date	27 Nov 2017
Vehicle Make	YUTONG
Vehicle Model	ZK6127H
Primary Colour	Orange
Secondary Colour	Yellow
Manufacturing Year	2010
Engine No.	ISLE436021894000
Chassis No.	LZYTATF61A1009121
Maximum Power Output	-
Open Market Value	\$151,241.00
Original Registration Date	14 Oct 2010
First Registration Date	14 Oct 2010
Transfer Count	0
Actual ARF Paid	\$7,563.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	13 Oct 2020
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
QP Paid	\$31,389.00
COE Rebate Amount	\$9,029.00
Total Rebate Amount	\$9,029.00

The information contained herein is correct as at 27 Nov 2017

OK



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

Enquire Transfer Fee

Vehicle Details			
Vehicle No.	PA9849P		
Vehicle Type	Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus		
Vehicle Attachment 1	Air-Conditioned		
Vehicle Scheme	Public Service Vehicle (Others)		
Vehicle Make	YUTONG		
Vehicle Model	ZK6127H		
Chassis No.	LZYTATF61A1009121		
Propellant	Diesel		
Engine No.	ISLE436021894000		
Engine Capacity	8849 cc		
Maximum Power Output	-		
Maximum Laden Weight	18000 kg		
Unladen Weight	13840 kg		
Year Of Manufacture	2010		
Original Registration Date	14 Oct 2010		
Lifespan Expiry Date	13 Oct 2030		
COE Category	C - Goods Vehicle & Bus		
Quota Premium	\$31,389.00		
COE Expiry Date	13 Oct 2020		
Road Tax Expiry Date	13 Apr 2018		
Inspection Due Date	13 Oct 2018		
Intended Transfer Date	27 Nov 2017		
CO2 Emission	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee (s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee	11.00	-	11.00
Total Amount Payable			11.00

Message

This vehicle has a road tax Over Payment of \$342.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

You may print this page for reference.

[OK](#)[Print](#)

Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/11/2017 15:19
Date Of Accident	21/11/2017 09:50
Exact Location Of Accident	SLIP ROAD TO CTE (CITY) RANGOON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PA9849P
Insured/Policyholder	
Name Of Registered Owner	RIC-TAT TRAVEL & COACH SERVICES PTE LTD
Co Reg No	200821198R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91850628
Vehicle Particulars	
Manufacturer	YUTONG
Model	ZK6127H-8.8 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	M489300
Cover Note Number	
Driver	
Name of Driver	MOHAMED KAMAL BIN MOHAMED SALLEH
NRIC No	S7227461Z
Date Of Birth	15/08/1972
Occupation	OUTDOOR
Date Of Driving Pass	22/11/1994
Driving Experience	22 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93492427
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions DRIZZLING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 16

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

ON 21/11/2017 @ 09:50HRS, I WAS DRIVING MY BUS PA9849P ALONG THE SLIP ROAD TO CTE (CITY) RANGOON RD WITHIN MY OWN LANE WHEN A VEH SJY4034B CUT INTO MY LANE & COLLIDED ONTO MY BUS FRONT RH PORTION AS A RESULT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJY4034B
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any actual misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GAA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application to interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available thereat.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident and insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers" or the insurers, lawyers, law firms, the Regulatory Authority of Singapore and any relevant government agency/authorities, such as the police, for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with the instructions or responding to any enquiries by me;
 - (iv) administering my claims including the making of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the claims as well as on the external cover of envelopes/mail packages; and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims collectively the "Purposes".
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers, lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the insurers and/or GIA to their third party service providers or agents including their lawyers/law firms, which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (i) above may be shared or disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - (ii) regulatory, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name
Add./Phone No.



Sketch Plan #2

SKETCH PLAN

W. 10/10/19 P
B: 219 40 248



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/10/19 at 10:10 PM, I was driving my car (Mazda) along the road
 500 to the (right) Roadside and within my car was also a car (Mazda) B
 out with my car. I was driving my car from the position of a car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time

Driver's Signature
 (If driver is not the policyholder)
 Date & Time

Reporting Centre Personnel's Signature
 Name
 Date & Time



CONNECT 3

7 Old Toh Tuck Road Singapore 597648

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

QT17/PA9849P/TPC-094

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PA9849P

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front RH headlamp	1	1,450.00	1,450.00
2.	Front Rh fog lamp	1	680.00	680.00
3.	Front RH bumper	1	1,350.00	1,350.00
4.	Front panel	1	3,800.00	3,800.00
5.	Front RH inner structure	1	1,250.00	1,250.00
6.	Apply anti rust	1	120.00	120.00
7.	Check wiring	1	20.00	20.00
8.	Spray painting with advertisement	1	1,000.00	1,000.00
9.	Labour charges	1	1,500.00	1,500.00
SUB-TOTAL				S\$11,170.00

Thank you.
Yours faithfully,

Winnie Chai
HP: 9850-9666



Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts 3480

10% - 3132

Labour - 1560

4692

4/58 3750

5 days

Tanjiah 97495749

Veron Chen (LKKAUTO)

From: Winnie Chai <connect3winnie@gmail.com>
Sent: Wednesday, 13 December, 2017 9:23 AM
To: Taufikh (LKKAUTO)
Cc: Veron Chen (LKKAUTO)
Subject: Re: 2nd REMINDER : Finalization for PA9849P

Hi Taufikh,

We confirmed finalization @ \$3750, 05 days.

Thanks & regards

On Tue, Dec 12, 2017 at 5:28 PM, Taufikh (LKK Auto) <taufikh@lkkauto.com> wrote:

Hi Winnie,

COR I/s \$3750 , 5 days.

Regards

Taufikh

Lkk Auto

From: Winnie Chai [<mailto:connect3winnie@gmail.com>]
Sent: Friday, 8 December 2017 11:37 AM
To: Taufikh; Team A
Subject: 2nd REMINDER : Finalization for PA9849P

Hi Taufikh,

I have attached the after repair pics for yr ref.

Pls also kindly forward us yr markings.

Pls kindly revert on the finalization.

Thanks & regards

----- Forwarded message -----

From: **Winnie Chai** <connect3winnie@gmail.com>

Date: Thu, Dec 7, 2017 at 10:17 AM

Subject: REMINDER : Finalization for PA9849P

To: Taufikh <Taufikh@lkkauto.com>

Hi Taufikh,

I have attached the after repair pics for yr ref.

Pls also kindly forward us yr markings.

Pls kindly revert on the finalization.

Thanks & regards

On Thu, Nov 30, 2017 at 3:40 PM, Winnie Chai <connect3winnie@gmail.com> wrote:

Hi Taufikh,

I have attached the after repair pics for yr ref.

Pls also kindly forward us yr marking.

Pls kindly revert on the finalization.

Thanks & regards

Winnie Chai

Connect3

HP:9850-9666

Winnie Chai

Connect3

HP:9850-9666

Winnie Chai

Connect3

HP:9850-9666

Winnie Chai

Connect3

HP:9850-9666

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Nov 2017		23 Nov 2017 15:47 Edit Adj Rpt	S\$3,750.00 Edit Estimates	S\$3,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
<div>CLAIM SUBFOLDER DETAILS [Created by insurer]</div> <div> Insured: -, Co. Reg. No.: - Main Claimant: RIC-TAT TRAVEL & COACH SERVICES PTE LTD Vehicle Reg. No.: PA9849P Date of Loss: 21/11/2017 09:00 - :59 Claim Type: TP / SNM17D06753C02 Policy/Cover Note No.: DMHCSN1428091703 Vehicle Reg. No. (Insured): SJY4034B Policy No. (Claimant): Excess: S\$0.00 Repairer: Connect3 (mandai Estate) (HQ) 566 Woodlands Road, 728697 Mandai - Tel: 98509666 Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192] Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH] ... [Final Rpt due 04/12/2017] Adj Asg. Remarks: PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION </div>				
<div>ASSOCIATED MAIL RECEIVED View All Compose Case Mail</div> <div>There are no mail for this case.</div>				
<div> <div>ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete</div> <div> Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done? </div> <div>No results.</div> </div>				

Claim Documents

*PA9849P (SNM17D06753C02)
[SJY4034B]
































TP

RIC-TAT TRAVEL & COACH SERVICES PTE LTD

Nov 21 2017 9:00AM

[-]

Connect3 (mandai Estate)

Upload Documents		Upload Photos	Compose New Letter	View Use Viewer	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	27/11/17 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	13/12/17 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
22	13/12/17 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
23	13/12/17 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
24	13/12/17 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
25	13/12/17 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
26	13/12/17 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
27	13/12/17 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
28	13/12/17 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
29	13/12/17 10:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	23/11/17 15:49	EMAIL FROM CONNECT3 (1)	 Load PDF		
2	23/11/17 15:49	EMAIL FROM CONNECT3 (2)	 Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117022441/T1VB E2

Date: 27/12/2017

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1428091703
Claimant Vehicle No :	PA9849P	Insured Vehicle No :	SJY4034B
Date of Loss:	21/11/2017	Nature of Claim:	TP
		Claim No:	SNM17D06753C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA9849P	Engine No:	ISLE436021894000
Make & Model:	YUTONG ZK6127H, 8.8 D (M)	Chassis No:	LZYTATF61A1009121
Reg. Date:	14/10/2010 (Man. Year: 2010)	Odometer:	467543 km
Colour:	Yellow/Orange		
Engine Capacity:	8849 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8/8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,530.00	3,132.00	5,398.00	63.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	1,560.00	1,080.00	40.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,170.00	4,692.00	6,478.00	57.99
Approved Total (Overridden) (S\$)		3,750.00		
(S\$)	11,170.00	3,750.00	7,420.00	66.43
+ GST 7.00/7.00% (S\$)	781.90	262.50	519.40	66.43
Nett Amount (S\$)	11,951.90	4,012.50	7,939.40	66.43

INSPECTION

Date of Assignment:	23/11/2017		
Date Inspected:	24/11/2017	Inspected At:	Connect3 (mandai Estate) (HQ) 566 Woodlands Road Singapore 728697
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Dec 2017)	
Parts:	N/A	YUTONG ZK6127H 8.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA9849P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH HEADLAMP	Cracked	1,450.00 F	*1,450.00 FL
2	1		*FRONT RH FOG LAMP	Cracked	680.00 F	*680.00 FL
3	1		*FRONT RH BUMPER	Deformed	1,350.00 F	*1,350.00 FL
4	1		*FRONT PANEL	Repair	3,800.00 F	*- FL
5	1		*FRONT RH INNER STRUCTURE	Repair	1,250.00 F	*- FL
				Sub Total (S\$)	8,530.00	3,480.00
				- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	348.00
				Total Parts (S\$)	8,530.00	3,132.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	APPLY ANTI RUST	New	120.00	40.00
2	CHECK WIRING	New	20.00	20.00
3	SPRAY PAINTING WITH ADVERTISEMENT	New	1,000.00	600.00
4	LABOUR CHARGES	New	1,500.00	900.00
Gross Labour Cost (\$\$)			2,640.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >