


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB150K
 Ref. No : BUS/11/17/1019
 Reg. Date : 21/11/2017
 Vehicle Type : BUS -12M
 Make : MB CITARO MERCEDES
 Model : MB CITARO O530
 Name of Driver : Prabakaran Sangkaranyar
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 17/11/2017 09:44:00 PM
 Accident Reported Date / Time : 20/11/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : AIG
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 smb150k - rear right portion
 skx2684g (tp) - insured with aig
 Prepared Date : 21/11/2017 05:15:15 PM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC Adjusted by Surveyor, if applicable

Total Labour Charges	: 795.00	0.00
Total Spray Painting Charges	: 616.00	0.00
Total Material Charges	: 901.34	901.34
Other Charges	: 0.00	0.00
TOTAL	: 2,312.34	0.00
Lum Sum Total	: 2,300.00	0.00
No. of Repair Days	: 2.00	0.00

Prepared / Adjusted By : *1 day - longer*

Arc / Surveyor Sing Off Date : 23/11/2017 11:24:50 AM 01/01/1900 12:00:00 AM

[Signature]

Per 23/11/17 @ 1315

Prepared / Adjusted Date :

Remarks :

Prepared Date : 23/11/2017 10:04:20 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	795.00	0.00 530
Total Labour	795.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	616.00	0.00 400
Total Spray Painting & Panel Beating	616.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	REAR	6009909	REAR BUMPER RH	1	1837.84	10.00	754.06	Replace	Replace	No <i>pho</i>
00054469 11	VE	6010012	SIDE MARKER LAMP	1	194.50	10.00	85.05	Replace	Replace	No <i>SCA</i>
	REAR	6010010	EXTERIOR LAMP	1	163.15	10.00	56.83	Replace	Replace	No <i>PHOTOGRAPH</i>
	REAR	6009887	CHERIS PIN W HEAD	2	3.00	10.00	5.40	Replace	Replace	No <i>PHOTO</i>
TOTAL MATERIALS								901.34	901.34	
TOTAL MATERIALS(Discounted)								901.34	901.34	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	L.T Check
TOTAL SUPPLEMENTARY MATERIALS									