

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	18	REAR NUMBER PLATE	Reviewing	35	MISSING	
	19	SET REVERSE SENSOR	Reviewing	200	TORN	
	20	REAR FENDER QUARTER GLASS SEALANT	Reviewing	40	NECESSARY	
	21	REAR WINDSCREEN GLASS SEALANT	Reviewing	40	NECESSARY	
	22	REAR SPARE TYRE PANEL TOP COAT	Reviewing	0	NOT NECESSARY	
	23	REVERSE CAMERA	Reviewing	0	SERVICEABLE	

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	 5	REAR BOOT HINGE (DISC 10%)	Reviewing	308.16	BENT	
	 6	REAR BOOT STRUT (DISC 10%)	Reviewing	329.76	BUCKLED	
	 7	REAR BOOT LOGO (DISC 10%)	Reviewing	36.45	NECESSARY	
	 8	REAR BOOT EMBLEM 'TENNA' (DISC 10%)	Reviewing	75.6	NECESSARY	
	 9	REAR BOOT EMBLEM '250XV' & V6' (DISC 10%)	Reviewing	58.14	NECESSARY	
	 10	REAR BOOT LOWER CHROME (DISC 10%)	Reviewing	198	DENTED	
	 11	TAILLAMP (DISC 10%)	Reviewing	932.76	BROKEN	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	11	2			REAR FENDER INNER TRIM			Damaged	233.6		30		327.04
	12	2			REAR FENDER QUARTER GLASS WITH MOULDING			Necessary	971.1		30		1359.54
	13	1			REAR END PANEL			Bent	560.6		30		392.42
	14	1			REAR END PANEL INNER TOP GARNISH			Cracked	90.6		30		63.42
	15	1			REAR SPARE TYRE PANEL			Repair	0		30		0
	16	1			REAR SPARE TYRE PANEL INNER TRIM			Deformed	617.9		30		432.53
	17	1			REAR SPARE TYRE CENTRE SPONGE			Cracked	439.4		30		307.58
	18	2			REAR SPARE TYRE SIDE SPONGE			Serviceable	0		30		0

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
	1		TOWING.	60	0	0	Reviewing	
	2		REMOVE AND REFIX WINDSCREEN GLASS.	120	0	0	Reviewing	
	3		REMOVE & REFIX REAR BOTH FENDER QUARTER GLASSES.	80	0	0	Reviewing	

Detailed Assessment

Inspection Date *

11/27/2017



Condition of Vehicle at time of survey

General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

0

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

215/55R17

Rear Tyre Size

215/55R17

POST SURVEY INF...

CATEGORY	Gender
FNOL INFORMATI...	
POST SURVEY INF...	
CATEGORY	Marital status
FNOL INFORMATI...	
POST SURVEY INF...	
CATEGORY	Identification #
FNOL INFORMATI...	
POST SURVEY INF...	

CATEGORY	Make
POLICY INFORMAT...	LAND ROVER
ASSESSMENT INFO...	NISSAN

CATEGORY	Model
POLICY INFORMAT...	FREELANDER 2 LF 3.2
ASSESSMENT INFO...	TEANA 2.5 CVT ABS D/AB HID 2WD 4i

CATEGORY	Type
POLICY INFORMAT...	
ASSESSMENT INFO...	

CATEGORY	Type of Paint
POLICY INFORMAT...	
ASSESSMENT INFO...	

CATEGORY	Chassis No
POLICY INFORMAT...	SALFA2AA9BH255513

CATEGORY	Date of Birth
FNOL INFORMATI...	
POST SURVEY INF...	mm/dd/yyyy

CATEGORY	Age
FNOL INFORMATI...	
POST SURVEY INF...	

CATEGORY	Occupation
FNOL INFORMATI...	
POST SURVEY INF...	

CATEGORY	Education Qualification
FNOL INFORMATI...	
POST SURVEY INF...	

CATEGORY	Driving Experience
FNOL INFORMATI...	
POST SURVEY INF...	

CATEGORY	Driver License #
FNOL INFORMATI...	
POST SURVEY INF...	



Direct settlement

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

Messages

Assessment

Invoices

Metrics

History

Notes

Documents

Add

(1) TP: ARC (2) HEAD TO REAR

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	4/10/18 5:27 PM	8000	8000	Open	Share	Clone
LOH Cynthia	11/24/17 5:00 PM	14101.64	14101.64	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
From TP-SJE-LKK.tif	Letters and Correspondence	Internal	LOH Cynthia	November 24, 2017
GA116967-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	TAN Jas	November 24, 2017
GA116967-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	TAN Jas	November 24, 2017
MAIL TO TP.pdf	Letters and Correspondence	Others	SHAH Kushal	November 24, 2017
email_abs.pdf	Letters and Correspondence	Others	SHAH Kushal	November 24, 2017
SLF2888T gia report_abs.PDF	Reports & Statement	GIA Report	SHAH Kushal	November 24, 2017

Direct settlement

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

Messages Invoices History Documents

Assessment Metrics Notes

(1) TP: ARC (2) HEAD TO REAR

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	------------------

Accident Statement	Reports & Statement		Merimen	
--------------------	------------------------	--	---------	--

Immediate Advice (with mandate) dd 300718.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 30, 2018
---	------------------------	--------	---	------------------

PARF_COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	April 11, 2018
------------------------	------------------------	--------	---	-------------------