NOTOL:	MUYOUS -		ASSIG		T (Office	)		24 11 2012	JU5pm
rom (Person):	Irena		of	46	SMD		Date/Tim	F10C-11-FC :=	Paspiri
					Bill to:				<del></del>
OD (TP)/WS	TP RES / OI	RES / E	SLH 513			Insur		5148A	
at V/orkshop m	- A- 1	Fos	stech Aut	O			-	16 5415	
of			i Kaki		Ave 6	¥ 01-(	1	***	
Policy No:		:			Claim No	: _ Cm	DITOUZE	of /GPL	7 11 11 11 11 11
Sum Insured:					Excess	:			
Make of Veh:				41.			_ D.O.A.	25.11.2017	
(Client's Record	)	,		41					
(Client's Record	REP. / REV			<u> </u>			H.O.D	. Endorsement:	
(Client's Record CA / REV	)			ntacted: _	Nan	4		. Endorsement:	
(Client's Record CA / REV	REP. / REV	3рт	Person Cor	ntacted:_		4	H.O.D	. Endorsement:	
(Client's Record CA / REV Date/Time:	)   rep. / rev   <u>77-1130</u> 17	3pm	Person Cor			4	H.O.D	. Endorsement:	
(Client's Record CA / REV Date/Time:	Action/Instru	3pm action (	Person Cor			4	H.O.D	. Endorsement:	
(Client's Record CA / REV Date/Time:	REP. / REV	3pm action (	Person Cor			4	H.O.D	. Endorsement:	
(Client's Record CA / REV Date/Time:	Action/Instru	3pm action ( 4Y - × 8A - ×	Person Cor	Stinute		4	H.O.D	. Endorsement:	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation			
SON	IPO INSURANCE S	SINGAPORE PL	Ref:	CS/SMO170224	93/010
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date: 27-11-2017			
		Policy Particulars	Code :		М
1.		GBE 5148A		spected	SLH 5137Y
	Insured Veh.	GBE 3140A	Covera		0.00
	Policy No.	CMTD1704261/GPL	Exces		0.00
_	Claim No.	IRENE	Assign	1.0	27/11/2017
•	Assign From	Vehicle Part			
2.	Make & Model	Vernicie Fait	c.c	Condition	0
-		HIDDEN	Year o	f Rea	(2)
	Engine No. Chassis No.	HIDDEN	Colou		
_	Odometer	8050	Steeri		
_	Brakes		Modification		
	General		- Iniodini	cation	
3.	General	Condi	tions of	Tyres	
J		Size	Make	14 73 576	Balance
-	R/H Front Tyre	777700			mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.		Descript	tion of Da	amages	
5.		Gener	al Inform	nation	
<b>U</b> .	Accident Date	25/11/2017	-	ction Date	27/11/2017
	Survey held at	FASTECH AUTO PTE LTD	1	AND SHOOL STATEMENTS	V-10-4-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.		The property of the second sec	Remarks		

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: CMTD1704261/GPL Our Ref: CS/SMO17022493/Urb

The Motor Claims Department SOMPO INSURANCE SINGAPORE PTE LTD Without Prejudice

Dear Sir/Madam,

# PRELIMINARY ADVICE OF VEHICLE NO. SLH 5137Y .

We thank you for the instruction on 27/11/2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on  $\underline{27/11/2017}$  at the premises of M/s  $\underline{FASTECH\ AUTO}$  and have the following to report:-

Workshop Estimate Amount	: S\$ 23,076.60	ç
Revised Estimate Amount	: S\$ 11,050.08	
"Check" Items Amount	: <u>S</u> \$	
Market Value	: <u>S\$</u>	
LTA Reimbursement Value	: <u>S\$</u>	
Nett Value	: <u>S\$</u>	

Description of Damage: The vehicle sustained damages at the rear portion. rear front offside

Comments/ Present Status: Damages Consistent.

Yours faithfully

MARCUS CHUA Automotive Assessor

### Catherine Chong (LKK Auto)

From:

Henry, Irene James <irene.henry@sompo.com.sg>

Sent:

Monday, 27 November, 2017 2:45 PM

To:

assignments

Cc:

Admin-D (LKKAuto)

Subject:

FW: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SLH5137Y

Our Reference: CMTD1704261/GPL

Hi,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (SLH 5137Y).

Please refer to the email correspondence below.

## Best Regards Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



A Century of Trust

#### Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click <a href="https://example.com/here-privacy-policy.">here-privacy-policy.</a>

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]

Sent: Monday, 27 November, 2017 2:33 PM

To: Henry, Irene James <irene.henry@sompo.com.sg>
Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SLH5137Y

Dear Sir

Please arrange LKK Auto Consultants to survey the car.

Regards, Nancy Lam

Fastech Auto Pte Ltd

Tel: 6746 5405 Fax: 6745 8520 From: Henry, Irene James [mailto:irene.henry@sompo.com.sg]

Sent: Monday, November 27, 2017 2:40 PM
To: Nancy Lam <nancy.lam@fastechauto.com.sg>
Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SLH5137Y

Our Reference: CMTD1704261/GPL

Your Reference: SLH 5137Y

Date: 27<sup>TH</sup> November 2017

Without Prejudice

BY EMAIL ONLY

Attention:

M/S FASTECH AUTO PTE LTD

#### ACCIDENT INVOLVING GBE 5148A & SLH 5137Y ON 25 NOVEMBER 2017

Dear Sir

We refer to your Notice of Accident via email dated 27/11/2017.

Please be informed that Pau Loong is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards
Irene Henry
Claims Division
D: 6322 4618 | T: 6461 6555 | F: 6221 3147





#### Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click <u>here</u> for our Privacy Policy.

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]

Sent: Monday, 27 November, 2017 10:00 AM

To: Motor Survey < MotorSurvey@sompo.com.sg >

Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SLH5137Y

Hi Sir

My client claiming your insured GBE 5148A.

Please kindly arrange PRS for SLH 5137Y.

Date of accident 25.11.2017

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards, Nancy Lam Fastech Auto Pte Ltd Tel: 6746 5405

Fax: 6745 8520

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCI	DENT	CTAT	650	IENT
ACCI	DEN	OIA		
	_			

Date Of Report

27/11/2017 10:47

Date Of Accident

25/11/2017 14:20

Exact Location Of Accident

CTE TOWARDS SLE

Country/State of Loss

SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number

**SLH5137Y** 

Insured/Policyholder

Name Of Registered Owner

LOKELOH

Co Reg No

53366668J

**Email Address** 

NOEMAIL

Mobile Phone No

Alternative Phone No.

OFFICE-98730088

Vehicle Particulars

Manufacturer

MITSUBISHI

Model

ATTRAGE 1.2 CVT

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

Policy Number

5093113846 CLASSIC

Cover Note Number

Driver

Name of Driver

LOKE WENG SAN

NRIC No

S7179035E

Date Of Birth

16/06/1971

Occupation

OUTDOOR

Date Of Driving Pass

19/01/1999

**Driving Experience** 

18 YEARS AND 10 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-98730088

Fax Number

Contact Number

EMail Address

NOEMAIL

Address\*

BLK 628B #03-262 WOODLANDS RING ROAD

Postcode

732628

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

+

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED. ATTENDED BY AINI

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

## **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

GBE5148A

Vehicle Make/Model/Colour

NISSAN NV350 PANEL VAN 2.5 5MT 5DR EURO V

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

SOMPO INSURANCE SINGAPORE PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness** 

Name

Phone Number

**Email Address** 

**DETAILS OF INJURED PERSON 1** 

Name

LOKE WENG SAN

Approximate Age

Page 2 of 12

Injuries Sustain

Injured person in which vehicle?

SLH5137Y

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Driver's Signature

(If driver is not the policyholder)
Date & Time: 2 7 NOV 2017

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4 Singapore 415933

Tel: 67416697 Fax: 67492305

amailinaakbasingnataam.sg

Name: NRIC/FIN No.:

EVETCU DI ANI		
SKETCH PLAN		
		A-SLH 51374 B-GBE 5148A
	A	B-G8-5-31480
DESCRIBE CIRCUMSTANCES OF	THE ACCIDENT	
on 25/11/17 ct	2-40pm. 1 was dr	iving my vehicle(M)
along CTE town	rds SLE, 1 Stop,	my volicle due to in front
of the vehicle	Stop. Suddlenly vehicl	le (B) hit on my new
portion.		
	SLH 51374 - 1 pane	enger. (Foo Me? Mei Catherine)
	3 7	J
A		IDAC KAKI BUKIT (VAC)
DECLARATION  I/We declare the foreholds gardicula	ars are true in every respect.	23 Kaki Bukit Ave 4 Singapore 415933 Tel: 67416697 Fax: 67492305 Email: vackb@singnet.com.sg
Policyholder's Signature  Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time: 2 7 1(0V 2)17	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name:

NRIC/FIN No .:

SKETCH PLAN

A = SLH S 13 7 M

B = GB = S 148 A

B

### **DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

on 25/11/17 ct	2.40 pm.	1 was	driving	my VE	chicle (A)
along CTE towar	ds SLE.	1 stop	ny veh	ile due	e to in from
of the vehicle	Stop. Sudel	lenly vel	icle (B)	hit o	n my news
portion.					7/
	SLH 5137y	- 1 pa	nenger.	(Foo Mei)	yei catherine)

### DECLARATION

I/We declare the for sailing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Date of Accident: 25/11/17	Accident Tin	ie: 2 240	pm
Vehicle (A) No: 5 L H 5 13 7 \( \)	Make Model:	Mitsubis	om hi Attrage 1:
Location: Alony CTE town	ards sle		1
Owner Name: Loke Loh			
Owner Address:			
Owner NRIC: 53366685 Email	:	P 1	
HP: Home:		Office:	
Insurance Company: . NTUC		Insurance Policy l	No:
(Comprehensive / Third Party / Third Party Fire & T	Theft)	5093	113846
Driver Name: Loke Weny San			
Driver NRIC: 57179038 E	Date of Birth	16/5/19	71
Driver Contact No: 98730088	Occupation:	outdoor	
Driving License Pass Date: 19/6/2009	Relationship	With Owner:	4. 6/64 00.
			(F)
Claiming Under: (Own Damage Claim / Third Party Weather Condition: (Clear / Raining / Drizzling / A Road Surface: (Wet / Dry) Damage Portion of Vehicle(A): Rear / Front / Right	After Rained )	e transference	
Weather Condition: (Clear / Raining / Drizzling / A Road Surface: (Wet / Dry) Damage Portion of Vehicle(A): Rear / Front / Right	after Rained ) Side / Left Side / Ch	e tulicità della compania della compania della compania della compania della compania della compania della comp	
Weather Condition: (Clear / Raining / Drizzling / A Road Surface: (Wet / Dry.) Damage Portion of Vehicle(A): Rear / Front / Right Anyone Injured: YES / NO	After Rained ) Side / Left Side / Ch	ain Collision	
Weather Condition: (Clear / Raining / Drizzling / A Road Surface: (Wet / Dry)  Damage Portion of Vehicle(A): Rear / Front / Right  Anyone Injured: YES / NO  Police Report: YES / NO	after Rained ) Side / Left Side / Ch	ain Collision	
Weather Condition: (Clear / Raining / Drizzling / A Road Surface: (Wet / Dry)  Damage Portion of Vehicle(A): Rear / Front / Right  Anyone Injured: YES / NO  Police Report: YES / NO  Passenger In Vehicle (A):	ther Rained )  Side / Left Side / Ch  Name:  If YES, When	ain Collision	TD.
Weather Condition: (Clear / Raining / Drizzling / A Road Surface: (Wet / Dry)  Damage Portion of Vehicle(A): Rear / Front / Right  Anyone Injured: YES / NO  Police Report: YES / NO	After Rained ) Side / Left Side / Ch	ain Collision	IP:
Weather Condition: ( Clear / Raining / Drizzling / A Road Surface: ( Wet / Dry )  Damage Portion of Vehicle(A): Rear / Front / Right  Anyone Injured: YES / NO  Police Report: YES / NO  Passenger In Vehicle (A):  Witness Name:	ther Rained )  Side / Left Side / Ch  Name:  If YES, When	ain Collision	IP:
Weather Condition: ( Clear / Raining / Drizzling / A Road Surface: ( Wet / Dry ) Damage Portion of Vehicle(A): Rear / Front / Right Anyone Injured: YES / NO Police Report: YES / NO Passenger In Vehicle (A): Witness Name:	Name:  If YES, When	ain Collision e:	IP:
Weather Condition: (Clear / Raining / Drizzling / A Road Surface: (Wet / Dry)  Damage Portion of Vehicle(A): Rear / Front / Right  Anyone Injured: YES / NO  Police Report: YES / NO  Passenger In Vehicle (A):  Witness Name:  Vehicle (B) No: GBE 51484	Name:  NRIC:  Vehicle (C)	ain Collision e:	IP:
Weather Condition: (Clear / Raining / Drizzling / A Road Surface: (Wet / Dry)  Damage Portion of Vehicle(A): Rear / Front / Right  Anyone Injured: YES / NO  Police Report: YES / NO  Passenger In Vehicle (A):  Witness Name:  Vehicle (B) No: GBE 5148A  Driver Name:	Name:  If YES, When  Vehicle (C) Name:	ain Collision e:	IP:
Weather Condition: ( Clear / Raining / Drizzling / A Road Surface: ( Wet / Dry )  Damage Portion of Vehicle(A): Rear / Front / Right  Anyone Injured: YES / NO  Police Report: YES / NO  Passenger In Vehicle (A):  Witness Name:  Vehicle (B) No: GBE 5 148 A  Driver Name:  Driver NRIC: Contact No:	Name:  If YES, When  NRIC:  Vehicle (C) Name:  Driver Name:	ain Collision e:	IP:
Weather Condition: (Clear / Raining / Drizzling / A Road Surface: (Wet / Dry)  Damage Portion of Vehicle(A): Rear / Front / Right  Anyone Injured: YES / NO  Police Report: YES / NO  Passenger In Vehicle (A):  Witness Name:  Vehicle (B) No: GBE 5148A  Driver Name:  Driver NRIC:  Contact No:	Name:  If YES, When  NRIC:  Vehicle (C) N  Driver Name:  Driver NRIC:  Contact No:  Insurance:	ain Collision e:	IP:
Weather Condition: (Clear / Raining / Drizzling / A Road Surface: (Wet / Dry)  Damage Portion of Vehicle(A): Rear / Front / Right  Anyone Injured: YES / NO  Police Report: YES / NO  Passenger In Vehicle (A):  Witness Name:  Vehicle (B) No: GBE 5148A  Driver Name:  Driver NRIC: Contact No:  Insurance: Sompo	Name:  If YES, When  NRIC:  Vehicle (C) N  Driver Name:  Driver NRIC:  Contact No:  Insurance:  Damage porti	ain Collision  e:  Ho:  on of vehicle(C):	IP:
Weather Condition: (Clear / Raining / Drizzling / A Road Surface: (Wet / Dry)  Damage Portion of Vehicle(A): Rear / Front / Right  Anyone Injured: YES / NO  Police Report: YES / NO  Passenger In Vehicle (A):  Witness Name:  Vehicle (B) No: GBE 5148A  Driver Name:  Driver NRIC:  Contact No:  Insurance: Sompo  Damage portion of vehicle(B):	Name:  If YES, When  NRIC:  Vehicle (C) N  Driver Name:  Driver NRIC:  Contact No:  Insurance:	ain Collision  e:  Hoose on of vehicle(C):	IP:
Weather Condition: (Clear / Raining / Drizzling / A Road Surface: (Wet / Dry)  Damage Portion of Vehicle(A): Rear / Front / Right  Anyone Injured: YES / NO  Police Report: YES / NO  Passenger In Vehicle (A):  Witness Name:  Vehicle (B) No: GBE 5148A  Driver Name:  Driver NRIC:  Contact No:  Insurance: Sompo  Damage portion of vehicle(B):  Vehicle (D) No:	Name:  If YES, When  NRIC:  Vehicle (C) N  Driver Name:  Driver NRIC:  Contact No:  Insurance:  Damage porti	ain Collision  e:  Io:  on of vehicle(C):	IP:
Weather Condition: (Clear / Raining / Drizzling / A Road Surface: (Wet / Dry)  Damage Portion of Vehicle(A): Rear / Front / Right  Anyone Injured: YES / NO  Police Report: YES / NO  Passenger In Vehicle (A):  Witness Name:  Vehicle (B) No: GBE 5 148 A  Driver Name:  Driver NRIC: Contact No:  Insurance: Sompo  Damage portion of vehicle(B):  Vehicle (D) No:  Driver Name:	Name:  If YES, When  NRIC:  Vehicle (C) N  Driver Name:  Driver NRIC:  Contact No:  Insurance:  Damage porti	ain Collision  e:  Io:  on of vehicle(C):	IP:
Weather Condition: (Clear / Raining / Drizzling / A Road Surface: (Wet / Dry)  Damage Portion of Vehicle(A): Rear / Front / Right  Anyone Injured: YES / NO  Police Report: YES / NO  Passenger In Vehicle (A):  Witness Name:  Vehicle (B) No: GBE 5 148 A  Driver Name:  Driver NRIC:  Contact No:  Insurance: Sompo  Damage portion of vehicle(B):  Vehicle (D) No:  Driver Name:  Driver Name:	Name:  If YES, When  NRIC:  Vehicle (C) N  Driver Name:  Driver NRIC:  Vehicle (E) N  Driver Name:  Driver Name:  Driver Name:  Damage porti	ain Collision  e:  Io:  on of vehicle(C):	IP:


# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Business
Owner ID	6668J
Vehicle Details	
Vehicle No.	SLH5137Y
Vehicle to be Exported	No
Intended De-registration Date	27 Nov 2017
Vehicle Make	MITSUBISHI
Vehicle Model	ATTRAGE 1.2 CVT
Primary Colour	Red
Manufacturing Year	2016
Engine No.	3A92UDN4766
Chassis No.	MMBSTA13AHH003396
Maximum Power Output	57.0 kW (76 bhp)
Open Market Value	\$14,775.00
Original Registration Date	08 Nov 2016
First Registration Date	08 Nov 2016
Transfer Count	1
Actual ARF Paid	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	07 Nov 2026
PARF Rebate Amount	\$3,750.00 2500
Intended COE Rebate Details	
COE Expiry Date	07 Nov 2026
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$50,991.00
COE Rebate Amount	\$45,620.00
Total Rebate Amount	\$49,370.00

The information contained herein is correct as at 27 Nov 2017



Compare



# FASTECH AUTO PTE LTD

Singapore 417883

NUT Item:	SLH 513	74
1PCS ROOT	LID	1

	1111
	Not Andoral
FASTECH AUTO PTE LTD	Llela
Singapore 417883 Fel No: 67452063 / 67467158 Fax No: 67458520 Fax Reg No : 20-0006262-D	Repair Sum \$9900
NUM Item: SLH 5137Y	15day.
1PCS BOOTLID Buc 757	\$1080.00
1PCS BOOTLID REAR LOGO NUC	\$41.00
1PCS BOOTLID 'ATTRAGE' EMBLEM ME	\$26.00
1PCS BOOTLID C&C LOGO MM	\$38.00
1PCS BOOTLID 'MIVEC' EMBLEM M	\$32.00
1PCS BOOTLID OUTER CHROME MOULDING Bertlene 225	\$255.00
2PCS BOOTLID HINGES @\$68.00	\$136.00 🗡
1PCS BOOTLID INNER LOCK 7M	\$65.00
1PCS BOOTLID LOCK STRIKER 17	\$30.00 ×
1PCS BOOTLID WEATHERSTRIP 700	\$148.00
1PCS REAR BUMPER DIS 725	\$808.00
2PCS REAR BUMPER SIDE HOLDERS @\$32.00	\$64.00
2PCS REAR BUMPER BRACKETS @\$35.00	\$70.00
1SET REAR BUMPER CLIPS	\$39.00
2PCS REAR BUMPER REFLECTORS @\$30.00 Olsen	\$60.00 12
2PCS REAR BUMPER SPLASH SHIELDS @\$66.20 /	\$132.40 🗶
1PCS REAR END PANEL 3/150	\$385.00
1PCS REAR END PANEL TOP GARNISH 7~/	\$168.00
2PCS TAILLAMPS @\$485.00 As are ols sto	\$970.00
2PCS TAILLAMP HOUSING PANELS @\$155.00 0/5 35	\$310.00 100
2PCS REAR FENDERS @\$1723.00 MSR D/S D/Buc	\$3446.00 12 C
2PCS REAR FENDER INNER TRIMS @\$158.00 8/5 70-1	\$316.00 / 20
1SET REAR FENDER INNER TRIM CLIPS LLC	\$60.00 _

1402

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 20-0006262-D

Qty Particular	Amount S\$
List Item:	
1PCS REAR WINDSCREEN MOULDING NU	\$148.20
2PCS REAR DOORS @\$765.00	\$1530.00 🔀
1PCS REAR FLOOR PANEL Bolsm/ Au ( 980	\$980.00
1PCS REAR FLOOR PANEL TOP BOARD 70-1	\$166.00
2PCS REAR CHASSIS MEMBERS @\$620.00	\$1240.00
1PCS REAR EXHAUST Suffu	\$576.00
2PCS REAR EXHAUST MOUNTINGS @\$30.00	\$60.00 X
1PCS REAR BOOT, KEYLESS SENSOR NT /0%	\$205.00 ×
1PCS REAR END PANEL OUTER COVER AS	\$62.00 X
List Item Total:	\$13,646.60 69 11-2
Special Nett Item:	
1SET REAR BUMPER REVERSE SENSOR SWALL  1SET REAR BUMPER REVERSE CAMERA SWALL	\$280.00 200
1SET REAR BUMPER REVERSE CAMERA SWAN	\$500.00 300
1PCS REAR END PANEL SEALANT M	\$50.00
1PCS REAR FLOOR PANEL INSULATOR NEC	\$200.00 /00
1PCS REAR WINDSCREEN SEALANT NA	\$50.00 40
1PCS REAR LICENCE PLATE W/HOLDER &M	\$50.00 40
IPCS BOOTLID TOP SPOILER WOJAL (CA)	\$680.00 450
1PCS REAR REVERSE CAMERA REPOOLES	\$480.00
Special Nett Total:	\$2290.00

## FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 20-0006262-D

ı ax ı	Neg 110 . 20-0000202-D	
Qty	<u>Particular</u>	Amount S\$
Lab	our Charge:	
то	CHECK WIRING.	\$80.00 } 0
ТО	DISMANTLE & REPLACING REVERSE SENSO	R. \$80.00 (7)
то	DISMANTLE & REFIX SEAT, CUSHION UPHOL	STERY. \$150.00 Po
ТО	CONDUCT CHASSIS ALIGNMENT.	N1 \$380.00 ×
ТО	CONDUCT WHEEL ALIGNMENT.	1 1 \$100.00 X
то	DISMANTLE & REFIX REAR WINDSCREEN.	\$150.00 / W
то	DISMANTLE & REFIX REAR EXHAUST .	\$100.00 60
ТО	SPRAY ANTI RUST PROOFING.	\$200.00 100
ТО	DISMANTLE & REFIX PETROL TANK.	\$100.00 60
LAB	OUR FOR PANEL BEATING, CUT, WELD, STRA	IGHTEN
& R	EPLACING PARTS.	\$3000.00 /800
то	PUTTY & SPRAY PAINTING.	\$2800.00 / 3540
Lab	our Charge Total:	\$7140.00
	,	11050.08
	3	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$23,076.60

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before latter spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No rie tai modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation	Internationale Des	Experts En Automobile
--------------------------	--------------------	-----------------------

SOMPO INSURANCE SINGAPORE PL Ref: CS/SMO17022493/Urbn2

50 RAFFLES PLACE

#05-01/06

Date: 12-01-2018

SINGAPORE LAND T		TOWERSINGAPORE 048623	l someone		
			Code:	SMO	
1.		Policy Particula	ars :- THIRI	PARTY CLA	JM
	Insured Veh.	GBE 5148A	Veh. Ir	spected	SLH 5137Y
j	Policy No.		Cover	age (\$)	0.00
	Claim No.	CMTD1704261/GPL	Exces	s (\$)	0.00
	Assign From	IRENE	Assign	n Date	27/11/2017

			Paramana composition		
2.	Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI ATTRAGE (A)	c.c	1193	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	MMBSTA13AHH003396	Colour	RED	
	Odometer	30754	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			$\neg$

3.			Conditions of Tyres		
ĵ.		Size	Make	Balance	
	R/H Front Tyre	185/55 R15	BRIDGESTONE	6 mm	
	L/H Front Tyre	185/55 R15	BRIDGESTONE	6 mm	
	R/H Rear Tyre	185/55 R15	BRIDGESTONE	6 mm	
	L/H Rear Tyre	185/55 R15	BRIDGESTONE	6 mm	

4.		Description of Damages
	THE VEHICLE CHOTAINED DAMAGES	AT THE BEAR BORTION

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5.	General Information			
	Accident Date	25/11/2017	Inspection Date	27/11/2017
	Survey held at	FASTECH AUTO PTE LTD		
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a.	Remarks
-	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
1	DVIN ACCORDANCE TO VOLID INSTRUCTIONS WE HAVE NOT ALTHORISED DEDAIDS

5b.	Estimate Da		
	ESTIMATED NORMAL PERIOD FOR REPAIR:	15 Working Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 5137Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID (N)	BUCKLED	1,080.00	751.00
1	BOOTLID REAR LOGO (N)	NECESSARY	41.00	41.00
1	BOOTLID "ATTRAGE" EMBLEM (N)	NECESSARY	26.00	26.00
1	BOOTLID C&C LOGO (N)	NECESSARY	38.00	38.00
1	BOOTLID "MIVEC" EMBLEM (N)	NECESSARY	32.00	32.00
1	BOOTLID OUTER CHROME MOULDING (N)	BENT / CRACKED	255.00	225.00
2	BOOTLID HINGES @\$68.00 (N)	TO REPAIR SEE	136.00	
1	BOOTLID INNER LOCK (N)	TWISTED	65.00	65.00
1	BOOTLID LOCK STRIKER (N)	NOT NECESSARY	30.00	0,000
1	BOOTLID WEATHERSTRIP (N)	TWISTED	148.00	148.00
1	REAR BUMPER (N)	DISTORTED	808.00	725.00
2	REAR BUMPER SIDE HOLDERS @\$32.00 (N)	BENT	64.00	64.00
2	REAR BUMPER BRACKETS @\$35.00 (N)	BENT	70.00	70.00
1	SET REAR BUMPER CLIPS (N)	NECESSARY	39.00	39.00
2	REAR BUMPER REFLECTORS @\$30.00 (N)	O/S CRACKED	60.00	30.00
2	REAR BUMPER SPLASH SHIELDS @\$66.20 (N)	NOT NECESSARY	132.40	2.5
1	REAR END PANEL (N)	BADLY DENTED	385.00	385.00
1	REAR END PANEL TOP GARNISH (N)	TWISTED	168.00	168.00
2	TAILLAMPS @\$485.00 (N)	N/S CRACKED / O/S BROKEN	970.00	970.00
2	TAILLAMP HOUSING PANELS @\$155.00 (N)	O/S DENTED	310.00	155.00
2	REAR FENDERS @\$1723.00 (N)	O/S DENTED / BUCKLED / N/S TO REPAIR SEE LABOUR	3,446.00	891.00
2	REAR FENDER INNER TRIMS @\$158.00 (N)	O/S TORN	316.00	158.00
1	SET REAR FENDER INNER TRIM CLIPS (N)	NECESSARY	60.00	60.00
1	REAR WINDSCREEN MOULDING (N)	NECESSARY	148.20	148.20
2	REAR DOORS @\$765.00 (N)	TO REPAIR SEE LABOUR	1,530.00	£
	REAR FLOOR PANEL (N)	BADLY DENTED / BUCKLED	980.00	980.00
. 1	REAR FLOOR PANEL TOP BOARD (N)	TORN	166.00	166.00
2	REAR CHASSIS MEMBERS @\$620.00 (N)	TO REPAIR SEE LABOUR	1,240.00	j: <del>-</del>

Report Ref No. CS/SMO17022493/Urbn2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST (N)	BENT / TWISTED	576.00	576.00
2	REAR EXHAUST MOUNTINGS @\$30.00 (N)	NOT NECESSARY	60.00	2012-2020
1	REAR BOOT KEYLESS SENSOR (N)	NOT NECESSARY	205.00	
1	REAR END PANEL OUTER COVER (N)	NO SUCH PARTS	62.00	
	LESS 10% DISCOUNT			-691.12
			13,646.60	6,220.08
	SPECIAL NETT ITEMS		227.000.00	200230120000
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
	SET REAR REVERSE CAMERA (SN)	SHORTED	500.00	300.00
5119	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
	REAR FLOOR PANEL INSULATOR (SN)	NECESSARY	200.00	100.00
823	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
233	BOOTLID TOP SPOILER (SN)	WARPED / CUT	680.00	450.00
1	REAR REVERSE CAMERA (SN)	REPEATED	480.00	,00.00
	25 57		2,290.00	1,180.00
	LABOUR			1,100.00
	TO CHECK WIRING.			
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	30.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		80.00	50.00
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	150.00 380.00	80.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	
- 1	TO DISMANTLE & REFIX REAR WINDSCREEN.	INOT NECESOART	150.00	120.00
- 1	TO DISMANTLE & REFIX REAR EXHAUST.		100.00	60.00
- 1	TO SPRAY ANTI RUST PROOFING.		200.00	100.00
- 1	TO DISMANTLE & REFIX PETROL TANK.		100.00	60.00
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID HINGES, N/S REAR FENDERS, REAR DOORS AND REAR CHASSIS MEMBERS.		3,000.00	1,800.00
	TO PUTTY & SPRAY PAINTING.		2,800.00	1,350.00
	-	1	14	
	-		-	
				25
			7,140.00	3,650.00
	GRAND TOTAL		23,076.60	11,050.08

Report Ref No. CS/SMO17022493/Urbn2



Page No.:3 of 3

RECOMMENDED COST OF REPAIR SUM 9,900.00

Report Ref No. CS/SMO17022493/Urbn2

NOTE: NEW PARTS REPLACEMENT

**CHUA KANG SENG** 

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.