

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

RADIATOR
SUPPORT
SIDE
GARNISH
RH

Reviewing

20

(DEFORMED)
SUPP 1 -
30/11/2017

2

WIPER
GRILLE
SIDE
GARNISH
RH

Reviewing

20

(CUT)SUPP 1
- 30/11/2017

3

RADIATOR
COOLANT

Reviewing

35

NECESSARY



4

NUMBER
PLATE

Deny

0

NOT
NECESSARY

5

DAYS OF
REPAIR : 5
DAYS

Reviewing

