

22/03/2002

S. REC. BY:

REF: CS/MSG17027511 / T116a2

Special Instruction:

Survivor:

Taufik

ASSIGNMENT (Office)

Muhim

From (Person):

Caru Milah

of

MSL

Date/Time:

27.11.2017 9:52am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJC 8831 G

Insured:

at Workshop m/s

Performance

Tel:

of

303 Alexandra Rd

Policy No:

27150511SMP

Claim No:

538139

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

(Client's Record)

D.O.A.

20-11-2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

27.11.2017 10:30am

Person Contacted:

Intiran

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SJC 8831 G - 003 / AL1712011049 / Rs03y

DA: 010612

28/11-

Revert via merimen

29/11-@

10.12am authorise repair

-29/11-

10:34am authorise repair excess \$1500

revert supplementary & final.

(05/1/17)

REF:

MSIG

Surveyor: Taylor

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 4500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: 462K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

In Thirah.

Veh No: 3JC 88316 Yr Regn: 2011, JuneType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X1 Sunroof c.c. 1995Colour: Black A/C: Insured / Std / NI / NASp. Reading: 95 938 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WB AVL 320X0VP90080Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/50 R17R: 225/50 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. _____ D.O.I. 27/11/17 C/645Survey held at PMLDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orN/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|------------------|----------------------------------------------------------------------------------------|
| 06/6/18 @ 8.11am | Chen How informed C/A at \$3064.40 via Meamen. |
| 06/6/18 @ 2.16pm | confirmed with Caroline final fig \$3064.40, 3 days. by email. (Red to 95385, 247.) |



RECEIVED 07 JUN 2018

Date/Time, File Pass to?

1) 06/6/18

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)Survey Fee: 200

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Report Format: MEK-TPLump Sum / I.B.I. (\$) 3064.40

10

20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|-------------------------------------------------------------------|------|----------------------------|---------------------------|------------|
| MSG INSURANCE (SINGAPORE) PTE LTD | | | Ref : CS/MSG17022511/T1tb | |
| 16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581 | | | Date : 27-11-2017 | |
| | | | Code : MSG | |
| 1. Policy Particulars :- OWN DAMAGE | | | | |
| Insured Veh. | | Veh. Inspected | | SJC 8831G |
| Policy No. 27150511SMP | | Coverage (\$) | | 0.00 |
| Claim No. 538139 | | Excess (\$) | | 500.00 |
| Assign From MERIMEN (CLARA MILAH) | | Assign Date | | 27/11/2017 |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | c.c | | 0 |
| Engine No. HIDDEN | | Year of Reg. | | |
| Chassis No. | | Colour | | |
| Odometer - | | Steering | | |
| Brakes | | Modification | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date 22/11/2017 | | Inspection Date 27/11/2017 | | |
| Survey held at | | PERFORMANCE MOTORS LTD | | |
| | | 303 ALEXANDRA ROAD | | |
| | | SINGAPORE 159941 | | |
| 5a. Remarks | | | | |
| A)THE MARKET VALUE IS S\$------(EST. AVERAGE) | | | | |
| B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. | | | | |

View Received Message

This mail is associated with :

***SJC8831G (538139)**

OD

Nov 22 2017 6:00PM

[LIM AI LENG]

Performance Motors Limited

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 29/11/2017 10:12 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3274.20) - SJC8831G - Claim Handler: Clara Milah Yeo

Approved:3274.20.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 29 November, 2017 10:34 AM
To: Inthiran Thurasamy
Cc: SUR
Subject: SJC 8831G OD MSIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJC 8831G (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|---------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type | Singapore NRIC |
| Owner ID | 6658E |
| Vehicle Details | |
| Vehicle No. | SJC8831G |
| Vehicle to be Exported | No |
| Intended De-registration Date | 28 Nov 2017 |
| Vehicle Make | B.M.W. |
| Vehicle Model | X1 SDRIVE18I AT D/AB 2WD 5DR GAS/D SR |
| Primary Colour | Black |
| Manufacturing Year | 2011 |
| Engine No. | A118I933N46B20BD |
| Chassis No. | WBAVL320X0VP90080 |
| Maximum Power Output | 110.0 kW (147 bhp) |
| Open Market Value | \$30,414.00 |
| Original Registration Date | 28 Jun 2011 |
| First Registration Date | 28 Jun 2011 |
| Transfer Count | 0 |
| Actual ARF Paid | \$30,414.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility | Yes |
| PARF Eligibility Expiry Date | 27 Jun 2021 |
| PARF Rebate Amount | \$19,769.00 |
| Intended COE Rebate Details | |
| COE Expiry Date | 27 Jun 2021 |
| COE Category | B - Car (1601cc & above) |
| COE Period(Years) | 10 |
| QP Paid | \$67,700.00 |
| COE Rebate Amount | \$24,257.00 |
| Total Rebate Amount | \$44,026.00 |

The information contained herein is correct as at 28 Nov 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-----------------------------|
| Date Of Report | 24/11/2017 13:32 |
| Date Of Accident | 22/11/2017 18:55 |
| Exact Location Of Accident | ALONG ROAD 1 LORONG MARZUKI |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJC8831G |
| Insured/Policyholder | |
| Name Of Registered Owner | LIM AI LENG |
| NRIC No | S1356658E |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-96612778 |
| Alternative Phone No | OFFICE-96612778 |

Vehicle Particulars

| | |
|------------------------------------------------------------------------------|--------------|
| Manufacturer | BMW |
| Model | X1 |
| Exact Purpose for which vehicle was being used at time of accident | NORMAL USAGE |
| Are you claiming under your own insurance policy for repair to your vehicle? | YES |
| If No, Please state action to be taken | |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | MSIG INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | |
| Cover Note Number | |

Driver

| | |
|----------------------|------------------------|
| Name of Driver | LIM AI LENG |
| NRIC No | S1356658E |
| Date Of Birth | 03/01/1959 |
| Occupation | INDOOR |
| Date Of Driving Pass | 29/12/1978 |
| Driving Experience | 38 YEARS AND 10 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-96612778 |
| Fax Number | |
| Contact Number | OFFICE-96612778 |
| EMail Address | NOEMAIL |

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 POLICE STATION NAME [OTHER] KAMPONG KEMBANGAN NPP
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number UNKNOWN
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness


Name
 Phone Number
 Email Address

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan Pg. 2

- Describe Circumstances of the Accident

- Refer to police report

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre Personnel

Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20171123/2097

Police Station Of Origin:
Kampong Kembangan NPP
112 Lengkok Tiga #01-215 SINGAPORE
410112
Tel No: 1800-7489999

1 of 3

Report No. T/20171123/2097

REPORT OF A TRAFFIC ACCIDENT

| | | |
|--------------------------------------------|------------------|--------------------------|
| Date/Time Report Made: 23/11/2017 16:29 | Vide Report No.: | Station Diary No.: 41 |
|--------------------------------------------|------------------|--------------------------|

Informant's Particulars

| | | | |
|------------------------------------------|--------------------------------------------------------|------------------------------|------------------------------|
| Name of Informant: LIM AI LENG | Address: 48B LORONG MARZUKI SINGAPORE 417185 | | |
| ID Type / ID No.: NRIC NO / S1356658E | Contact No.: Home/Office: Mobile: 96612778 | | |
| Nationality: SINGAPORE CITIZEN | Email: | | |
| Sex: Female | Age: 58 | Date of Birth: 03/01/1959 | Type of Informant: Driver |
| Race: Chinese | Language: | | Institution / School Name: |
| Occupation: HOUSE WIFE | Driving Licence Information: Class: Date of Expiry: | | |

General Information of the Accident

| | | | | |
|---------------------------------------------|---------------------------|--------------------|--------------------------------------------|-------------------------------------|
| Type of Accident: | Non-Injury Hit and Run | Drink Drive: No | Date/Time of Accident: 22/11/2017 18:55 | Type of Location: |
| Location: Along Road 1 LORONG MARZUKI | | | | |
| Weather: | | Road Surface: | | Road Speed Limit: |
| Traffic Flow: | | Traffic Control: | | Traffic Volume: |
| Type of Collision: | | | | Anyone conveyed by ambulance: No |

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
|-------------|------|------|-------|-------|------------------|-----------------|
| SJC8831G | Car | | | | Slightly Damaged | 0 |

Details of Person Involved

| | |
|---------------------------------|--------------------------------|
| Any Pedestrian Involved: No | |
| No. of Pedestrians Injured: NIL | Use of Pedestrian Crossing: NA |



**SINGAPORE
POLICE FORCE**



T/20171123/2097

Police Station Of Origin:
Kampong Kembangan NPP
112 Lengkok Tiga #01-215 SINGAPORE
410112
Tel No: 1800-7489999

3 of 3

Report No. T/20171123/2097

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

| | |
|--------------------------------------------------------------------------------------------------|---------------------------------------------------|
| Signature Of Officer Recording The Report: G/ Sgt 1 TAN EDMUND NEIL | Signature Of Informant: <i>Lim Ci Hong</i> |
| Signature Of Interpreter: Not applicable | Date/Time: 23/11/2017 16:29 |
| Officer In Charge Of Case: TP / HRT / Sr Staff Sgt LIM WOON TIONG Contact No.: 65476418 | Classification Of Case: |
| Authentication Stamp NP168 | SN 159 <i>[Signature]</i> |



Signature : _____

Singapore Police Force

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S665500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MPHL 1715549 Vehicle Registration No: SJC 8831 G
Name (as shown in NRIC) : Lim Ai Leng NRIC/FIN/Passport No : _____
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore ()
Contact (Tel) : _____ Mobile No. : _____
Email Address : _____
Date of Accident : 22. 11. 2017 Time of Accident : 1855 hrs
Place of Accident : Along Road 1 Lorong Marzuki
Insurance Company : _____

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

The accident has been reported to police
at Kampong Kembangan NPP

F: [Signature]
Policyholder / Driver's Signature
Date: _____

[Signature]
Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____
Date: _____

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 44950
Date Estimated : 24/11/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Lim Ai Leng
48B Lorong Marzuki

Singapore 417185

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------|------------|--------------|---------|
| SJC8831G | VP90080 | 28/06/2011 | X1 sDrive18i | 0 |

DESCRIPTION

To replace front bumper and attachments.

Painting fender left.

To check electrical wiring systems at the front section for proper function.

To carry out body cavity preservation. (Per panel).

Sundries.

VALUE

880 1,275.00

1062 1,180.00

150 177.00

100 118.00

- 80 80.00

Total Labour 1: 2,830.00

DESCRIPTION

SIDE PNL BRACKET FRT LH2?

Bracket ?

FRT LH FENDER

Def. element ?

Bracket

FRT LH WHEEL HOUSING COVER

WHEEL HOUSING COVER BOTTOM LH ?

FRT LH FENDER SIGNAL LAMP ?

QTY

PRIC

VALUE

1

31.35

44 31.35

1

31.35

44 31.35

1

599.25

44 599.25

1

90.00

44 90.00

1

31.35

44 31.35

1

107.10

44 107.10

1

107.10

44 107.10

1

34.70

44 34.70

Total Parts : 1,032.20

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 44950
Date Estimated : 24/11/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------|------------|--------------|---------|
| SJC8831G | VP90080 | 28/06/2011 | X1 sDrive18i | 0 |

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

100 / 3rd Party / Uninsured losses / Direct Settlement

Regn No _____ Claim No. _____

Date & Time 27/11/17 01645 Excess S\$ 500

Surveyor's Name Taufik Sign *Taufik*

Surveyor's Tel 97498747 Authorised Yes / No

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail *taufik@lkkauto.com*

No. of Working Days Recommend 3 days

| | | |
|----------------|---|-----------------|
| Labour 1 | : | 2,830.00 |
| Parts | : | 1,032.20 |
| Labour 2 | : | 0.00 |
| Excess | : | 0.00 |
| Total GST @ 7% | : | 270.35 |
| Grand Total | : | <u>4,132.55</u> |

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

4015.75

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 44950
Date Estimated : 24/11/2017
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Lim Ai Leng
48B Lorong Marzuki

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 417185

| REGN NO | CHASSIS NO | REGN DATE | MODEL | M LEAGE |
|----------|------------|------------|--------------|---------|
| SJC8831G | VP90080 | 28/06/2011 | X1 sDrive18i | 0 |

| DESCRIPTION | ORIGINAL PRICE | DISC. % | NETT |
|----------------------------------------------------------------------------------------------|----------------|---------|----------|
| To replace front LH fender and attachments include knocking out dents caused by the accident | 850.00 | | 850.00 |
| To spray paint front LH fender | 1062.00 | | 1,062.00 |
| To check electrical wiring systems at the front section for proper function. | 150.00 | | 150.00 |
| To carry out body cavity preservation. (Per panel). | 100.00 | | 100.00 |
| Sundries. | 40.00 | | 40.00 |

| DESCRIPTION | UNIT PRICE | QTY | DISC. % | NETT |
|-----------------------------|------------|-------|---------|--------|
| FRT LH FENDER | 599.25 | 1.00 | | 599.25 |
| FRT LH WHEEL HOUSING COVER | 107.10 | 1.00 | | 107.10 |
| # FRT LH WHEEL ARCH COVER * | 142.55 | 1.00 | | 142.55 |
| # EXPANDING RIVET * | 1.35 | 10.00 | | 13.50 |

SUPPLEMENTARY ITEMS

| | |
|---------------------------------|----------|
| Total Labour : | 2,202.00 |
| Total Parts : | 862.40 |
| Total Labour & Parts : | 3,064.40 |
| Deduction for Excess : | 500.00 |
| Total Repair Costs less Excess: | 2,564.40 |
| GST @7%: | 179.51 |
| Grand Total : | 2,743.91 |

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

| DESCRIPTION | ORIGINAL PRICE | DISC. % | NETT | |
|-----------------------------|----------------|---------|---------|--------|
| | | | | |
| DESCRIPTION | UNIT PRICE | QTY | DISC. % | NETT |
| # FRT LH WHEEL ARCH COVER * | 142.55 | 1.00 | | 142.55 |
| # EXPANDING RIVET * | 1.35 | 10.00 | | 13.50 |

Total Labour :
Total Parts : 156.05
Total Labour & Parts : 156.05

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|------------------------------------------------------|------------------------------------------------------|------------------------------------------------|-------------|-----------------------------------------------------------------|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 24 Nov 2017 | | 27 Nov 2017 09:52 Edit Adj Rpt | S\$3,064.40 Edit Estimates | S\$3,064.40 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS | | [Created by insurer] | | | | | | | |
| Insured: | LIM AI LENG , ID: S1356658E, Tel: +6596612778, Email: NOEMAIL | | | | | | | | |
| Vehicle Reg. No.: | SJC8831G | Date of Loss: | 22/11/2017 18:00 - :59 [76 Months and 25 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | OD / 538139 | Policy/Cover Note No.: | 27150511SMP (Comprehensive) Coverage: 28/06/2017 - 27/06/2018 | | | | | | |
| | | Excess: | S\$500.00 | | | | | | |
| Repairer: | Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174 | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 27/12/2017] | | | | | | | | |
| Driver/Custodian: | LIM AI LENG (58 / Female), NRIC: S1356658E, Tel: +6596612778 | | | | | | | | |
| Adj Asg. Remarks: | Please revert. Thanks. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | View All Compose Case Mail | | | | | | | |
| <ul style="list-style-type: none"> MSIG_SG (06/06/2018): Alert - Adj Mandate Approved (S\$3064.40) - SJC8831G - Claim Handler: Clara Milah... MSIG_SG (29/11/2017): Alert - Adj Mandate Approved (S\$3274.20) - SJC8831G - Claim Handler: Clara Milah... | | | | | | | | | |
| ALL ASSOCIATED TASKS | | View All Search Tasks Create New Task Complete | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SJC8831G (538139)
OD
Nov 22 2017 6:00PM
[LIM AI LENG]
Performance Motors Limited

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
|----|----------------|-------------------------------------------|-----------|-------|
| 1 | 28/11/17 18:03 | Video - Other | Load AVI | |

Assessment Reports

1 per page

| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
|----|----------------|----------------------------------------|-----------|-------|
| 1 | 24/11/17 13:43 | Accident Statement | Load HTM | |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 28/11/17 17:34 | Adjuster Immediate Advice | Load HTM | |
| 2 | 05/06/18 15:40 | Adjuster Immediate Advice | Load HTM | |

Photos/Images

3 per page

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
|----|-----------------|-----------------------------------|-----------|-------------------------------------|
| 1 | 28/11/17 17:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 28/11/17 17:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 28/11/17 17:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 28/11/17 17:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 28/11/17 17:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 28/11/17 17:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 05/06/18 17:27 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 05/06/18 17:27 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 05/06/18 17:27 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> |

Documentation

1 per page

| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
|----|-----------------|-------------------------------------------|-----------|-------|
| 1 | 27/11/17 09:52 | Repair Estimate | Load PDF | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 28/11/17 17:37 | ESTIMATE | Load PDF | |
| 2 | 05/06/18 15:36 | SUPPLEMENTARY | Load PDF | |
| 3 | 05/06/18 16:39 | estimate | Load PDF | |

Linked Accident Report Documents

View

View in Browser

| Assessment Reports | | | | | | | | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|----------------------------------------|--|--|--|--|--|-----------|-------|------------|-------------------------------------|
| No | Finalized On | Performance Motors Limited (Alexandra) | | | | | | Thumbnail | Print | | |
| 1 | 24/11/17 13:43 | Accident Statement | | | | | | Load HTM | | | |
| 2 | 27/11/17 12:21 | Addendum Sheet | | | | | | Load TIF | | | |
| 3 | 27/11/17 12:22 | Accident Statement Addm. #1 | | | | | | Load HTM | | | |

| Photos/Images | | | | | | | | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|----------------------------------------|--|--|--|--|--|-----------|-------------------------------------|------------|-------------------------------------|
| No | Finalized On | Performance Motors Limited (Alexandra) | | | | | | Thumbnail | Print | | |
| 1 | 24/11/17 13:39 | Accident Photo | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 2 | 24/11/17 13:39 | Accident Photo | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 3 | 24/11/17 13:39 | Accident Photo | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |

| Assessment Reports | | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|----------------------------------------|--|------------|-------------------------------------|
| No | Finalized On | Performance Motors Limited (Alexandra) | | Thumbnail | Print |
| 4 | 24/11/17 13:39 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 24/11/17 13:39 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 24/11/17 13:39 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 24/11/17 13:39 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Performance Motors Limited (Alexandra) | | Thumbnail | Print |
| 1 | 24/11/17 13:41 | Sketch Plan | | Load TIF | |

Documents Checklist

| DOCUMENTS CHECKLIST | | | | Reset | Save | Print |
|----------------------------------------------|--|--|--|-------|------|-------|
| There are no document checklists configured. | | | | | | |

| |
|----------------------------------------------------------------------------------------------------------------------------------------------------|
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17022511/T1TBE2

Date: 11/06/2018

REFERENCE

Insured/Claimant: LIM AI LENG Policy No: 27150511SMP
Date of Loss: 22/11/2017 Nature of Claim: OD Claim No: 538139

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJC8831G**
Make & Model: BMW X1, 1.8 SDRIVE 18L (A) Engine No: A118I933N46B20BD
Reg. Date: 28/06/2011 (Man. Year: 2011) Chassis No: WBAVL320X0VP90080
Colour: Black Odometer: 95938 km
Engine Capacity: 1995 cc
Market Value/New Car Price: S\$62,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts | 1,268.25 | 902.40 | 365.85 | 28.85 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,750.00 | 2,162.00 | 588.00 | 21.38 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,018.25 | 3,064.40 | 953.85 | 23.74 |
| - Excess (S\$) | 500.00 | 500.00 | 0.00 | 0.00 |
| (S\$) | 3,518.25 | 2,564.40 | 953.85 | 27.11 |
| + GST 7.00/7.00% (S\$) | 246.28 | 179.51 | 66.77 | 27.11 |
| Nett Amount (S\$) | 3,764.53 | 2,743.91 | 1,020.62 | 27.11 |

INSPECTION

Date of Assignment: 27/11/2017

Date Inspected: 27/11/2017 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 11 Jun 2018) |
| Parts: | M1-SUV | BMW X1 1.8 SDRIVE 18L (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJC8831G) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|------------------------------|-----|----------|--------------------------------|----------------|-----------------|---------------|
| 1 | 1 | | *SUNDRIES | Necessary | 80.00 FS | *40.00 FS |
| 2 | 1 | | *SIDE PNL BRACKET FRT LH2 | Not Necessary | 31.35 FS | *- FS |
| 3 | 1 | | *BRACKET | Not Necessary | 31.35 FS | *- FS |
| 4 | 1 | | *FRT LH FENDER | Bent | 599.25 FS | *599.25 FS |
| 5 | 1 | | *DEF ELEMENT | Not Necessary | 90.00 FS | *- FS |
| 6 | 1 | | *BRACKET | Not Necessary | 31.35 FS | *- FS |
| 7 | 1 | | *FRT LH WHEEL HOUSING COVER | Cut | 107.10 FS | *107.10 FS |
| 8 | 1 | | *WHEEL HOUSING COVER BOTTOM LH | Not Necessary | 107.10 FS | *- FS |
| 9 | 1 | | *FRT LH FENDER SIGNAL LAMP | Not Necessary | 34.70 FS | *- FS |
| 10 | 1 | | *FRT LH WHEEL ARCH COVER | Deformed / Cut | 142.55 FS | *142.55 FS |
| 11 | 10 | | *EXPANDING RIVET | Necessary | 13.50 FS | *13.50 FS |
| F=Franchise part. S=SpcNett. | | | | | | |
| Total Parts (S\$) | | | | | 1,268.25 | 902.40 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|-----------------------------------------------------------------------------|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REPLACE FRONT BUMPER AND ATTACHMENTS | New | 1,275.00 | 850.00 |
| 2 | PAINTING FENDER LEFT | New | 1,180.00 | 1,062.00 |
| 3 | TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION | New | 177.00 | 150.00 |
| 4 | TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL) | New | 118.00 | 100.00 |
| Gross Labour Cost (\$\$) | | | 2,750.00 | 2,162.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >