

7/05/2002

ASS. REC. BY:

REF:

CS/AXA17022515/

b

Special Instruction:

Supervisor:

Smart claim

ASSIGNMENT (Office)

From (Person):

Yunme Ang

of

AXA

Date/Time:

23.11.2017

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJY 3999Z

Insured:

at Workshop m/s

VAG Singapore

Tel:

6515 9515

of

48 Toh Guan Road East #04-123

Policy No:

Claim No:

SF mop403

Sum Insured:

Excess:

TBA

Make of Veh:

(Client's Record)

D.O.A.

22.11.2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Faisal

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJY 3999Z - CS/AXA16011131 / R1601

DUA: 260716

26/11/2017

Received call & email, Insured withdraw claim
from Yunme.

10/7/18



**Re:VNI**

Type

🔗 Question

Message

Insured withdraw claim Please confirm you did not survey the car and will close the file Thanks

[Reply](#)



Service Request Details

Claim

57M004OJ

Reference

None 

Loss Date

November 22, 2017

Request Date

November 23, 2017

Due Date

November 30, 2017

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJY3999Z

Make

VOLKSWAGEN

Service Address

48 Toh Guan Road East, , 628457

Primary Contact/Insured

WEI YANG CHEONG
69P JALAN LIM TAI SEE, 266270, Singapore, Singapore
63327463
weiyang@alum.mit.edu

Claim Handler

Yvonne ANG
6568804461
yvonne.ang@axa.com.sg

Additional Instructions

EXCESS \$1000 PLEASE OBTAINED AUTHORIZED LETTER FROM INSURED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)**TYPE****SENT**

11/24/17 9:51 AM

FROM

Yvonne ANG

SUBJECT

SJY3999Z - Authorized letter

BODY

FYI, Authorized letter received

