

ASS. REC BY

REF: CS3/MSG17018737/mlg0-127

11/20

mermen MA

ASSIGNMENT (Office)

From (Person) Elaine Ng

MSIG

Date Time 21.11.2017

Estimated Cost
OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No. SKB 2763C

Insured: SJB49602

at Workshop re: MJE MOTOR

Tel: 645.4.2203

of Blk 7 Sin Ming Sec C, #01-82, 575642

Policy No. A27246252QMY

Claim No. 531348

Sum Insured

Excess

Make of Veh
(Client's Record)

D.O.A. 27/9/17

CA / REV / REP. / REV 24 HRS 'wpl'

2/10/2017

Date/Time: 29/9/17 3:25pm

by joyce

HOD Endorsement
IN OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Finalize
	SKB 2763C - X	
	SJB 49602 - X	
	Dismantle Part. 03-10-2017	

26/10/17 7:30pm Email to Jasmine Luk thru mermen
 28/11/17 Submit 45. \$3750, 4 day.
 (Red: 2200, 37%).

28/11/2017

RECEIVED 28 NOV 2017



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17018737/M1gb-1	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 27-11-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJB 4960Z	Veh. Inspected	SKB 2763C
Policy No.	A27246252QMY	Coverage (\$)	0.00
Claim No.	531348	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	21/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	27/09/2017	Inspection Date	27/11/2017
Survey held at	MJE MOTOR BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Sep 2017		29 Sep 2017 15:12 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WANG QIWEN, ID: S7585437D								
Main Claimant:	NG YONG JOO, ID: S7831377C								
Vehicle Reg. No.:	SKB2763C	Date of Loss:	27/09/2017 19:00 - :59						
Claim Type:	TP / 531348	Policy/Cover Note No.:	A27246252QMY (Comprehensive) Coverage: 15/01/2017 - 14/01/2018						
Vehicle Reg. No. (Insured):	SJB4960Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 23/11/2017]								
Driver/Custodian (Insured):	CHOW KOK PIAU (), NRIC: S1521351E, Tel: +6597127331								
Adj Asg. Remarks:	Third Party Pre-Repair Survey								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (21/11/2017): Report Send Back Alerts - SKB2763C (TP) MSIG_JLKK (27/10/2017): Re: Pre-repair Inspection 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

NKKH17128811 / K Kwa Hin Auto Pte Ltd - HD
ENTRY DATE & TIME: 28/09/2017 10:41

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/09/2017 16:41
Date Of Accident	27/09/2017 19:30
Exact Location Of Accident	WHITESANDS MALL BASEMENT CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB2763C
Insured/Policyholder	
Name Of Registered Owner	NG YONG JOO
NRIC No	S7631377C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98756755
Alternative Phone No	OFFICE-98756755
Vehicle Particulars	
Manufacturer	BMW
Model	523i-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MW003639-R02
Cover Note Number	
Driver	
Name of Driver	NG PEY LI
NRIC No	S8035143G
Date Of Birth	08/11/1980
Occupation	INDOOR
Date Of Driving Pass	11/05/2001
Driving Experience	16 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98787222
Fax Number	
Contact Number	
EMail Address	KYMNG@YAHOO.COM

Address BLK 515 PASIR RIS ST 52 #10-81
 Postcode 510515
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJB4960Z
 Vehicle Make/Model/Colour TOYOTA WISH
 Details Of Properties
 Name of Driver CHOW KOK PIAU
 NRIC/Passport Number S1521351E
 Contact Number 97127331

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(if driver is not the policyholder)
Date & Time:

08/10/17 @
10-45 AM

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



A: SKB 2763C
 B: SJB 4960Z
 S: Stationary Vehicles

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/09/17 at about 1930 hours, I was driving in White Sands basement carpark searching for a parking lot. I found a carpark lot, positioned my car and started to reverse into the carpark lot. Suddenly, I felt an impact on the left of my vehicle. Vehicle B, came out of his parking lot and collided into the left of my vehicle.

~~Repair at other workshop~~

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

28/9/17 @
10:45am

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



LEE AUTOMOBILE APPRAISERS SERVICES

CORRESPONDENCE : BUKIT PANJANG POST OFFICE, P.O. BOX 244, SINGAPORE 916879.
FAX: (65) 6763 3827. HANDPHONE: 8188 2833
BUSINESS REG. NO.: S2891429D

TO: NG YONG JOO
c/o BLK 7 SIN MING IND. EST. SECTOR C
#01-96
SINGAPORE 575642

OUR REF. LEE/TP/10/1883/17
DATE 22 OCT 2017

AUTOMOBILE APPRAISAL REPORT

Vehicle Registration No. : SKB 2763 C
Make/Model : BMW 523i
Year Manufacture/Register : 2011
Colour : Grey
Engine No. : Obscure
Chassis No. : WBAFP32050C866082
Odometer Reading : 31280km
Nature Of Inspection : Third Party
Date Of Accident : 27 Sept 2017
Date Of Inspection : 02 Oct 2017
Name of Workshop : MJE Motor
: Blk 7 Sin Ming Ind. Est. Sector C #01-96
: Singapore 575642

TYRE CONDITION ON VEHICLE

Location	Make	Size	Thread Balance
Nearside Front	Pirelli	225/55R17	8mm
Offside Front	Pirelli	225/55R17	8mm
Nearside Rear	Pirelli	225/55R17	8mm
Offside Rear	Pirelli	225/55R17	8mm

*(The above represent on estimated remaining life of the tyre thread in mm)

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The damages sustained on the vehicle were apparently confined at its rear n/s portion.
(Details are describe in the attached schedule).

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items in this survey, kindly notify the company within (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.



LEE AUTOMOBILE APPRAISERS SERVICES

CORRESPONDENCE - BUKIT PANJANG POST OFFICE, PO BOX 244, SINGAPORE 916809
FAX: (65) 6763 3827, HANDPHONE: 8188 2833
BUSINESS REG. NO.: 52891429D

APPRAISEMENT SCHEDULE

Vehicle Registration No: SKB 2763 C

Our Ref. LEE/TP/10/1883/17

S/NO.	Qty	Description	Comments/ Conditions	Repairer's Estimate	Assessed Amount
		(LIST ITEMS)			
1	1	Rear n/s fender	distorted/cut ^Q	\$ X 1,035.00	\$ 1,035.00
2	1	Rear n/s lower arm	bent/distorted	\$ 381.00	\$ 381.00
3	1	Rear n/s knuckle arm	bent	\$ 988.00	\$ 988.00
4	1	Rear n/s wheel hub	distorted	\$ 186.00	\$ 186.00
5	1	Rear n/s wheel hub bearing	essential	\$ 154.00	\$ 154.00
6	1	Rear n/s top arm-long	bent	\$ 231.00	\$ 231.00
7	1	Rear n/s top arm-short	bent	\$ 422.00	\$ 422.00
8	1	Rear n/s drive shaft	bent/clangorous N(N)	\$ X 1,256.00	\$ 1,256.00
		Less 10%		\$ 4,653.00	\$ 4,653.00
		Sub Total parts		\$ -	\$ (465.30)
				\$ 4,653.00	\$ 4,187.70
		(SPECIAL NETT ITEMS)			
1	1	Rear n/s rim "Original"	cut/bent	\$ 738.00	\$ 738.00
2	1	Rear n/s tyre	cut/sliced/ 20% depreciation	\$ 400.00	\$ 320.00
		Total parts		\$ 5,791.00	\$ 5,245.70
		To remove & refix rear n/s undercarriage.		\$ 200.00	\$ 180.00
		Labour charge as recommended for replaced damaged parts & repaired rear n/s door.		\$ 1,000.00	\$ 900.00 450
		To putty and spraypainting including touch up all affected areas.		\$ 980.00	\$ 800.00
		To apply rustproof treatment to the replaced/repared panels.		\$ 150.00	\$ 120.00 40
		To check wheel alignment.		\$ 225.00	\$ 200.00 80
		GRAND TOTAL		\$ 8,346.00	\$ 7,445.70



LEE AUTOMOBILE APPRAISERS SERVICES

CORRESPONDENCE - BUKIT PANJANG POST OFFICE P.O. BOX 244, SINGAPORE 916800

FAX: (65) 6763 3827, HANDPHONE: 8188 2833

BUSINESS REG. NO.: 52891429D

Vehicle Number: - SKB 2763 C

Our Ref: LEE/TP/10/1883/17

ASSESSMENT SUMMARY

The damages sustained on the vehicle were thoroughly inspected and every item that was mentioned in the repair estimate against the actual damages found on the vehicle. Before we arrived at our recommendation as to whether the parts needed to be replaced or repair.

We have listed the breakdown of our finding and our recommendation as per schedule attached.

Our assessment to reinstate the vehicle is **\$7445.70** revised amount of the repairer's estimate of **\$8346.00**. The aforesaid recommendation, in our opinion, is fair and reasonable for the restoration of the vehicle to its pre-accident condition.

However, after taken into consideration the age and condition of the vehicle and the availability of the recondition components and to economize the repair, we therefore recommend a contract **Lump Sum at \$5950.00** corresponding to supply of parts, labour and spray painting charges.

39 photographs were taken at the times of static inspection.

Under normal circumstances, the repairs should be completed within a reasonable period **04** full working days

This inspection was conducted entirely on a **'Without Prejudice'** basis and we have not given authorization and instruction to the repairer to proceed with the repair.

We are reverting the matter to you for your discretion.

Very truly yours

K. W. LEE Dip. Auto. Engrg.
MIAME, AMIMI, CAE, ENG. TECH, MSAE, AMIRTE, AMSOE
AUTOMOTIVE ENGINEER ASSESSOR

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Sep 2017		29 Sep 2017 15:12 Edit Adj Rpt	S\$3,750.00 Edit Estimates	S\$3,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	WANG QIWEN, ID: S7585437D	
Main Claimant:	NG YONG JOO, ID: S7831377C	
Vehicle Reg. No.:	SKB2763C	Date of Loss: 27/09/2017 19:00 - :59
Claim Type:	TP / 531348	Policy/Cover Note No.: A27246252QMY (Comprehensive) Coverage: 15/01/2017 - 14/01/2018
Vehicle Reg. No. (Insured):	SJB4960Z	Policy No. (Claimant):
		Excess:
Repairer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 23/11/2017]	
Driver/Custodian (Insured):	CHOW KOK PIAU (), NRIC: S1521351E, Tel: +6597127331	
Adj Asg. Remarks:	Third Party Pre-Repair Survey	
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail
<ul style="list-style-type: none"> ● MSIG_SG (21/11/2017): Report Send Back Alerts - SKB2763C (TP) ● MSIG_LKK (27/10/2017): Re: Pre-repair Inspection 		
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete
Due Date	Priority	Type
Task Group	Subject	Handler
Assigned By	Completed On	Created On
Done?		
No results.		

Claim Documents

*SKB2763C (531348)
[SJB4960Z]
TP
NG YONG JOO
Sep 27 2017 7:00PM
[WANG QIWEN]
Mje Motor

Upload Documents		Upload Photos		Compose New Letter		View Use Viewer	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	29/09/17 14:58	Accident Statement From:SC - Reg. No: SJB4960Z, Claimant: WANG QIWEN			Load HTM		
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	29/09/17 14:58	Accident Photo From:SC - Reg. No: SJB4960Z, Claimant: WANG QIWEN			Load JPG	<input checked="" type="checkbox"/>	
2	29/09/17 14:58	Accident Photo From:SC - Reg. No: SJB4960Z, Claimant: WANG QIWEN			Load JPG	<input checked="" type="checkbox"/>	
3	29/09/17 14:58	Accident Photo From:SC - Reg. No: SJB4960Z, Claimant: WANG QIWEN			Load JPG	<input checked="" type="checkbox"/>	
4	29/09/17 14:58	Accident Photo From:SC - Reg. No: SJB4960Z, Claimant: WANG QIWEN			Load JPG	<input checked="" type="checkbox"/>	
5	29/09/17 14:58	Accident Photo From:SC - Reg. No: SJB4960Z, Claimant: WANG QIWEN			Load JPG	<input checked="" type="checkbox"/>	
6	29/09/17 14:58	Accident Photo From:SC - Reg. No: SJB4960Z, Claimant: WANG QIWEN			Load JPG	<input checked="" type="checkbox"/>	
7	29/09/17 14:58	Accident Photo From:SC - Reg. No: SJB4960Z, Claimant: WANG QIWEN			Load JPG	<input checked="" type="checkbox"/>	
8	29/09/17 14:58	Accident Photo From:SC - Reg. No: SJB4960Z, Claimant: WANG QIWEN			Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	02/10/17 16:55	General View			Load JPG	<input checked="" type="checkbox"/>	
2	02/10/17 16:55	General View			Load JPG	<input checked="" type="checkbox"/>	
3	02/10/17 16:55	General View			Load JPG	<input checked="" type="checkbox"/>	
4	02/10/17 16:55	General View			Load JPG	<input checked="" type="checkbox"/>	
5	02/10/17 16:55	General View			Load JPG	<input checked="" type="checkbox"/>	
6	02/10/17 16:55	General View			Load JPG	<input checked="" type="checkbox"/>	
7	02/10/17 16:55	General View			Load JPG	<input checked="" type="checkbox"/>	
8	02/10/17 16:55	General View			Load JPG	<input checked="" type="checkbox"/>	
9	02/10/17 16:55	General View			Load JPG	<input checked="" type="checkbox"/>	
10	02/10/17 16:55	General View			Load JPG	<input checked="" type="checkbox"/>	
11	02/10/17 16:55	General View			Load JPG	<input checked="" type="checkbox"/>	
12	02/10/17 16:55	General View			Load JPG	<input checked="" type="checkbox"/>	
13	02/10/17 16:55	General View			Load JPG	<input checked="" type="checkbox"/>	
14	02/10/17 16:55	General View			Load JPG	<input checked="" type="checkbox"/>	
15	26/10/17 19:30	Photographs of Damaged Parts			Load JPG	<input checked="" type="checkbox"/>	
16	26/10/17 19:30	Photographs of Damaged Parts			Load JPG	<input checked="" type="checkbox"/>	
17	26/10/17 19:30	Photographs of Damaged Parts			Load JPG	<input checked="" type="checkbox"/>	
18	26/10/17 19:30	Photographs of Damaged Parts			Load JPG	<input checked="" type="checkbox"/>	
19	26/10/17 19:30	Photographs of Damaged Parts			Load JPG	<input checked="" type="checkbox"/>	
20	26/10/17 19:30	Photographs of Damaged Parts			Load JPG	<input checked="" type="checkbox"/>	
21	26/10/17 19:30	Photographs of Damaged Parts			Load JPG	<input checked="" type="checkbox"/>	
22	26/10/17 19:30	Photographs of Damaged Parts			Load JPG	<input checked="" type="checkbox"/>	
23	26/10/17 19:30	Photographs of Damaged Parts			Load JPG	<input checked="" type="checkbox"/>	
24	26/10/17 19:30	Photographs of Damaged Parts			Load JPG	<input checked="" type="checkbox"/>	

25	26/10/17 19:30	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
26	26/10/17 19:30	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
27	26/10/17 19:30	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
28	26/10/17 19:30	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
29	26/10/17 19:30	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	29/09/17 14:58	E-FILE REPORT (SKB2763C) From: SC - Reg. No: SJB4960Z, Claimant: WANG QIWEN	1	Load PDF	
2	29/09/17 15:05	TP PRI & ACCIDENT REPORT	1	Load PDF	
3	29/09/17 15:07	TP LIST OF SJE	1	Load PDF	
4	29/09/17 15:23	OUR REJECTION LETTER & NOMINATED LKK TO BE SJE	1	Load PDF	
5	13/11/17 09:53	THIRD PARTY SURVEY REPORT PHOTOS -SKB2763C	1	Load PDF	
6	13/11/17 09:53	THIRD PARTY SURVEY REPORT PHOTOS-SKB2763C	1	Load PDF	
7	13/11/17 10:09	LEE AUTOMOBILE APPRAISERS SERVICES REPORT - SKB2763C	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/11/17 15:21	Invoice	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid gray; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17018737/M1GBE2-1
Date: 28/11/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A27246252QMY
Claimant Vehicle No :	SKB2763C	Insured Vehicle No :	SJB4960Z
Date of Loss:	27/09/2017	Nature of Claim:	TP
			Claim No: 531348

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB2763C		
Make & Model:	BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)	Engine No:	08647737N52B25AF
Reg. Date:	13/05/2011 (Man. Year: 2011)	Chassis No:	WBAFP32050C866082
Colour:	Silver	Odometer:	311280 km
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,791.00	3,183.80	2,607.20	45.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,555.00	1,500.00	1,055.00	41.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,346.00	4,683.80	3,662.20	43.88
Approved Total (Overridden) (S\$)		3,750.00		
Nett Amount (S\$)	8,346.00	3,750.00	4,596.00	55.07

INSPECTION

Date of Assignment:	29/09/2017	
Date Inspected:	02/10/2017	Inspected At: Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82 Singapore 575642
Estimated Period of Repair:	4.0 days	

Adjuster: MA CHIN FOOK

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2017)
Parts: 143	BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB2763C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR N/S FENDER	Repair	1,035.00 F	*- FL
2	1		*REAR N/S LOWER ARM	Bent / Distorted	381.00 F	*381.00 FL
3	1		*REAR N/S KNUCKLE ARM	Bent	988.00 F	*988.00 FL
4	1		*REAR N/S WHEEL HUB	Distorted	186.00 F	*186.00 FL
5	1		*REAR N/S WHEEL HUB BEARING	Essential	154.00 F	*154.00 FL
6	1		*REAR N/S TOP ARM-LONG	Bent	231.00 F	*231.00 FL
7	1		*REAR N/S TOP ARM-SHORT	Bent	422.00 F	*422.00 FL
8	1		*REAR N/S DRIVE SHAFT	Not Necessary	1,256.00 F	*- FL
9	1		*REAR N/S RIM ORIGINAL	Cut / Bent	738.00 FS	*738.00 FS
10	1		*REAR N/S TYRE	Cut / Sliced	400.00 FS	*320.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,791.00	3,420.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	236.20
Total Parts (S\$)	5,791.00	3,183.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX N/S UNDERCARRIAGE	New	200.00	180.00
2	LABOUR CHARGE AS RECOMMENDED FOR REPLACED DAMAGED PARTS & REPAIRED REAR N/S DOOR	New	1,000.00	400.00
3	TO PUTTY AND SPRAY PAINTING INCLUDING TOUCH UP ALL AFFECTED AREAS	New	980.00	800.00
4	TO APPLY RUSTPROOF TREATMENT TO THE REPLACED / REPAIRED PANELS	New	150.00	40.00
5	TO CHECK WHEEL ALIGNMENT	New	225.00	80.00
Gross Labour Cost (\$\$)			2,555.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >