

22/03/2012

ASS. REC. BY:

REF: CS3/FCI17022557/WB3

Special Instruction:

Surveyor:

Wilson

ASSIGNMENT (Office)

CWS

From (Person): May chua

of FCI

Date/Time: 4:25pm @ 27/11/17

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

FBD 4648K

Insured:

SHC 3440H

at Workshop m/s

Motoplex Pte. Ltd

Tel:

6747

of 10 Keki Bkt Rd 2 # 01-24, 417868

Policy No:

Claim No:

D17009602 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

7/10/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

28/11/2017

H.O.D. Endorsement:

Date/Time: 4:35pm @ 27/11/17

Person Contacted:

Ah beng

Vehicle IN/OUT

Date/Time

Action/Instruction (

X Estimate

FBD 4648K-X

SHC 3440H - CC3/AIG0901393/Dp92-1-D.O.A: 18/06/2009

Survey Department Check List (Case Handler)

Reference No.:

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

--	--

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS3/FCI17022557/Wb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 27-11-2017



Code : FCI2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHC 3440H	Veh. Inspected	FBD 4648K
Policy No.		Coverage (\$)	0.00
Claim No.	D17009602MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	27/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/10/2017	Inspection Date	28/11/2017
Survey held at	MOTOPLEX PTE LTD 10 KAKI BUKIT ROAD 2 #01-24 FIRST EAST CENTRE SINGAPORE 417868		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	10-10-2017	Our Ref No. D17009602MFSH
Accident Date	07-10-2017	Claim Type. Third Party
Insured Vehicle	SHC3440H	Third Party Vehicle. FBD4648K
Survey Location	10 KAKI BUKIT ROAD 2 #01-24 FIRST EAST CENTRE	
Contact Person.	NA	
Contact No.	67476774/ 67476774	Fax No. 65322007
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOTOPLEX PTE LTD	Attention. NIL
Cc : TP Solicitor	KURU & CO	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228992)



PRI Documents



Close



PRI Header Details

Claim No	D17009602MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & KURU & C
Workshop Name	MOTOPLEX PTE LTD (Contact Person : NA)	Survey Location & Contact Details	10 KAKI BUKIT ROAD 2 #01-24 FIRST EAST CENTRE Mobile: 67476774 , Phone: 67476774 , Fax: 6532200; EmailId: KURULEGAL@YAHOO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3440H	TP Vehicle No	FBD4648K
PRI Recieved Date	27-11-2017 12:53:26 PM	Surveyor Appointed Date	27-11-2017 04:24:58 PM	Surveyor Accept Date	27-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-11-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

KURU & CO

Advocates & Solicitors
UEN / GST Registration No: 53130937A

150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727

Kurubalan s/o Manickam Rengaraju
Jan Chua Peck Kiang

Tel: 65322 009 (5 lines)
Fax: 65322 007 (Our fax no. is not for service of court documents)

Our ref: L17.1326.lt(jt)
(Please quote our reference when replying)

27 November 2017

First Capital Insurance Ltd
6 Robinson Road
#16-01 City House
Singapore 068877

BY FAX ONLY : 6507 3849
Your ref : SHC 3440H

Dear Sirs,

**ACCIDENT INVOLVING FBD 4648K AND SHC 3440H ON 07.10.17
AT/ALONG TELOK KURAU ROAD TOWARDS MARIE PARADE ROAD
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY**


We act for **Teh Hock Koon**, whose vehicle registration number **FBD 4648K** was damaged in the above accident.

A copy of the **Police Report** filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,



Cc. client



SINGAPORE POLICE FORCE



T/20171008/2083

Police Station Of Origin:
Tanah Merah NPP
51 New Upper Changi Road #01-1514
SINGAPORE 461051
Tel No: 1800-4499999

1 of 4

Report No. T/20171008/2083

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/10/2017 19:47	Vide Report No.:	Station Diary No.: 17
--	------------------	--------------------------

Informant's Particulars

Name of Informant: TEH HOCK KOON			Address: APT BLK 48 BEDOK SOUTH AVENUE 3 #02-232 SINGAPORE 460048		
ID Type / ID No.: NRIC NO / S2635631H			Contact No.: Home/Office: Mobile: 97271963		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 52	Date of Birth: 08/11/1964	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: DELIVERY MAN			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 07/10/2017 21:00	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 TELOK KURAU ROAD MARINE PARADE ROAD Telok Kurau Road going towards Marine Parade Road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBD4648K	Motorcycle	SUZUKI	KATANA 125 M	Black	Slightly Damaged	0
SHC3440H	TAXI	HYUNDAI		Blue	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBD4648K	AXA INSURANCE SINGAPORE PTE LTD	P1930156	13/04/2017	12/04/2018



SINGAPORE POLICE FORCE



T/20171008/2083

2 of 4

Police Station Of Origin:
Tanah Merah NPP
51 New Upper Changi Road #01-1514
SINGAPORE 461051
Tel No: 1800-4499999

Report No. T/20171008/2083

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	TEH HOCK KOON	ID No.	S2635631H
Related Vehicle	FBD4648K (Motorcycle)	Contact No.	97271963
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	07/10/2017	Date Discharge	NIL
No. of Days granted Medical Leave	21	Degree of Injury	Slight
TAXI DRIVER			
Name	LAU THONG YEW	ID No.	S1263639C
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 08/10/2017 at about 2100hrs I was riding on my motorcycle bearing, (FBD4648K) along Telok Kurau Road going towards Marine Parade Road. It was a two way road. As I was travelling straight I noticed that there was a Taxi bearing, (SHC 3440H) turning right from Lorong J Telok Kurau Road. I then quickly applied the brakes. The taxi then stopped as the driver realized that I was in the right of way. After noticing that the taxi driver had come to a stop I decided to continue to ride ahead.

As I started to ride suddenly the Taxi also started to make a right turn without realizing that I was moving ahead. I did not had enough time to stop and as such the head of my motorcycle hit onto the right side of the Taxi. due to the impact of the accident I fell to the ground. There were fellow passer-by motorist who came and helped me. The Taxi driver then alighted from his Taxi and helped me up and picked up my belongings. We then moved to the side of the road, took pictures of the accident and exchanged particulars with each other. Subsequently the taxi driver offered to bring me to the hospital however I wanted to go back home instead going to the hospital. The taxi driver then offered to send me back home instead.

After reaching home I decided to go to the hospital. I then went to Changi General Hospital to seek for treatment. I was then diagnose with Leg fracture, (Avulsion fracture of right femur), Rib fracture and occult fracture. I then obtained a total of 21 days of MC. Due to the accident my motorcycle sustained damages at the head and the taxi sustained damages at the right side. I am not sure if there was camera installed at the said incident location and I am not sure if there was a in car camera installed in the taxi. I am



**SINGAPORE
POLICE FORCE**



T/20171008/2083

Police Station Of Origin:
Tanah Merah NPP
51 New Upper Changi Road #01-1514
SINGAPORE 461051
Tel No: 1800-4499999

3 of 4

Report No. T/20171008/2083

CONTINUATION OF REPORT

lodging this report for insurance purpose.



**SINGAPORE
POLICE FORCE**



T/20171008/2083

4 of 4

Police Station Of Origin:
Tanah Merah NPP
51 New Upper Changi Road #01-1514
SINGAPORE 461051
Tel No: 1800-4499999

Report No. T/20171008/2083

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 1 SARVESHVERAN S/O JAGATHESAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 YEO KIA HUAT

Contact No.: 65476325

SN 100

Authentication Stamp

NP188

Signature :

Singapore Police Force

Signature Of Informant:

Date/Time:

08/10/2017 19:47

Classification Of Case:

D.O.A

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5631H 03 ³⁰ 03 ¹¹ 2018 ⁸
Vehicle Details	- 07 10 2017
Vehicle No.:	FBD4648K 26 04 1
Vehicle to be Exported:	No (Bal → 0.9 month)
Intended De-registration Date:	02 Jan 2018
Vehicle Make:	SUZUKI Bal → 1 yrs 4.9 month
Vehicle Model:	KATANA 125 M
Primary Colour:	Blue
Manufacturing Year:	2006
Engine No.:	F483TH103040
Chassis No.:	BF44YTH103040
Maximum Power Output:	-
Open Market Value:	\$1,459.00
Original Registration Date:	04 Mar 2009
First Registration Date:	04 Mar 2009
Transfer Count:	7
Actual ARF Paid:	\$219.00
Intended PARF Rebate Details	X M.V. → \$800
PARF Eligibility:	No to \$1400
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Mar 2019
COE Category:	D - Motorcycle

COE Period(Years):	10
CP Paid:	\$701.00
COE Rebate Amount:	\$158.00
Total Rebate Amount:	\$158.00

The information contained herein is correct as at 02 Jan 2018

OK

Sg bike merit dur je
the model resale info.


Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	5631H
Vehicle Details	
Vehicle No.	FBD4648K
Vehicle to be Exported	No
Intended De-registration Date	15 Dec 2017
Vehicle Make	SUZUKI
Vehicle Model	KATANA 125 M
Primary Colour	Blue
Manufacturing Year	2006
Engine No.	F483TH103040
Chassis No.	BF44YTH103040
Maximum Power Output	-
Open Market Value	\$1,459.00
Original Registration Date	04 Mar 2009
First Registration Date	04 Mar 2009
Transfer Count	7
Actual ARF Paid	\$219.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	03 Mar 2019
COE Category	D - Motorcycle
COE Period(Years)	10
QP Paid	\$701.00
COE Rebate Amount	\$161.00
Total Rebate Amount	\$161.00

The information contained herein is correct as at 15 Dec 2017

OK



PRE-REPAIR INSPECTION REPORT				
FIRST CAPITAL INSURANCE LTD		Ref: CS3/FCI17022557/Wbs2		
36 ROBINSON ROAD		Date: 16-01-2018		
#16-01 CITY HOUSESINGAPORE 068877		Code: FCI2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHC 3440H	Veh. Inspected	FBD 4648K	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17009602MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	27/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	SUZUKI KATANA 125 M	c.c	124	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	BF44YTH103040	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/90-17 MC	PIRELLI	3 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	90/80-17 MC	DUNLOP	3 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.				
5. General Information				
Accident Date	07/10/2017	Inspect Date / Time	28/11/2017 (04:25 PM)	
Survey held at	MOTOPLEX PTE LTD 10 KAKI BUKIT ROAD 2 #01-24 FIRST EAST CENTRE SINGAPORE 417868			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) MARKET VALUE:\$1,300.00				

Report Ref No. CS3/FCI17022557/Wbs2

Inspected By

WILSON TEO CHENG MING

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.