

ASS. REC. BY:

REF: CS/MSG17022559/Kgbst Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSIG

Date/Time: 27/11/17 @ 1:39pm

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFE6655Z

Insured:

FT 4917C

at Workshop m/s

Hui Yang Motor

Tel:

64515752

of 176 Sin Ming Drive #04-02, 575721

Policy No:

MSD/VMT/17-986645-WTT

Claim No:

MSC/V/17-001842

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

1wp

1/12/17 @ After 11am

H.O.D. Endorsement:

Date/Time:

4:31pm @ 27/11/17

Person Contacted:

Belle

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SFE6655Z-X

FT 4917C-X

REF:

MSG

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFE 6655Z

at Workshop m/s: Hui Yang

of 176 S/M #04-02

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

After 11am.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SFE 6655Z Yr Regn: 17 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius Hybrid 17 17

Colour: M. Blue A/C Insured / Std / NI / NA

Sp. Reading: 38164 T/Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C/No: BVW 40 0025098

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: Hiflex 205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 9 mm

L/Bal: 9 mm

D.O.A: 23/11/17

Survey held at: \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/12 The pass to Catherine

11/12/17 Kenneth confirmed 4s \$760 with Marco.  
(red: 920.25, 55%).

RECEIVED 2 DEC 2017

Date/Time File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee

Transportation

S + PS + S

Photo

Diagn

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: \$760

200

10



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17022559/Kgb

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 27-11-2017



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FT 4917C	Veh. Inspected	SFE 6655Z
Policy No.	MSD/VMT/17-980645-WTT	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	27/11/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	23/11/2017	Inspection Date
Survey held at	HUI YANG MOTOR SERVICE BLOCK 176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721	

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Nov 2017		27 Nov 2017 13:39 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	MUHAMMAD AUFAR BIN SIDIK, ID: S9426419G, Tel: +6596422756		
Main Claimant:	HYMS CAR LEASING PTE LTD, Co. Reg. No.: 201320561K		
Vehicle Reg. No.:	SFE6655Z	Date of Loss:	23/11/2017 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMT/17-980645-WTT (Third Party Only) Coverage: 24/02/2017 - 23/02/2018
Vehicle Reg. No. (Insured):	FT4917C	Policy No. (Claimant):	
		Excess:	
Repairer:	Hul Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752 <i>non auth-use</i>		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/11/2017]		
Adj Asg. Remarks:	Appoint Kenneth Kong to survey the vehicle on 4th December 2017. (next MONDAY) after 11 AM.		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/11/2017 12:58
Date Of Accident	23/11/2017 22:15
Exact Location Of Accident	ALONG PUNGGOL 1 ROAD IN FRONT OF BLK 189B
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFE6655Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HYMS CAR LEASING PTE LTD
Co Reg No	201320561K
Email Address	HYMS@LIVE.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64515752

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8S AT ABS AIRBAG
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5082578000-01
Cover Note Number	

### Driver

Name of Driver	CHONG WEI LOONG
NRIC No	S7248312Z
Date Of Birth	20/12/1972
Occupation	OUTDOOR
Date Of Driving Pass	14/07/1997
Driving Experience	20 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93899244
Fax Number	
Contact Number	
EMail Address	NOEMAIL

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 24. 11. 17

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

MS16  
04/12/17

# 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

24/11/2017

Owner: HYMS CAR LEASING PTE LTD

*Not Withheld  
C11hp 8760L  
Painting After Repair  
2 days*

## ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SFE6655Z

1pc rear bumper  
2pcs rear bumper side retainer @\$35.00  
1pc rear tailgate outer garnish

*Bu/Out* \$ 240.00 ✓  
*in* \$ 70.00 X  
*n* \$ 125.00 X

\$ 435.00

cost + 15% X

\$ 65.25

\$ 500.25

1set rear parking sensor

*in* s.nett \$ 280.00 X

spray painting

\$ 500.00 *3200*

labours charges

\$ 400.00 *2000*

Total

\$ 1,680.25



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Nov 2017		27 Nov 2017 13:39 <a href="#">Edit Adj Rpt</a>	<b>S\$760.00</b> <a href="#">Edit Estimates</a>	<b>S\$760.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
<b>Insured:</b> MUHAMMAD AUFAR BIN SIDIK, ID: S9426419G, Tel: +6596422756									
<b>Main Claimant:</b> HYMS CAR LEASING PTE LTD, Co. Reg. No.: 201320561K									
<b>Vehicle Reg. No.:</b> SFE6655Z		<b>Date of Loss:</b> 23/11/2017 00:00 - :59							
<b>Claim Type:</b> TP / MSC/V/17-001842		<b>Policy/Cover Note No.:</b> MSD/VMT/17-980645-WTT (Third Party Only) Coverage: 24/02/2017 - 23/02/2018							
<b>Vehicle Reg. No. (Insured):</b> FT4917C		<b>Policy No. (Claimant):</b>							
<b>Excess:</b>									
<b>Repairer:</b> Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752									
<b>Handling Insurer:</b> MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]									
<b>Adjuster:</b> LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Imm.Advice due 28/11/2017]									
<b>Adj Asg. Remarks:</b> Appoint Kenneth Kong to survey the vehicle on 4th December 2017. (next MONDAY) after 11 AM.									
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>					
Compose Case Mail									
There are no mail for this case.									
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b>									
<div style="display: flex; justify-content: space-between;"> <span><a href="#">View All</a></span> <span><a href="#">Search Tasks</a></span> <span><a href="#">Create New Task</a></span> <span><a href="#">Complete</a></span> </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SFE6655Z (MSC/V/17-001842)**  
**[FT4917C]**

TP

**HYMS CAR LEASING PTE LTD**  
**Nov 23 2017 12:00AM**  
**[MUHAMMAD AUFAR BIN SIDIK]**  
**Hui Yang Motor Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>		<b>View</b> <a href="#">Use Viewer</a>		
<b>Photos/Images</b>		3 per page <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/17 14:54	General View	Load JPG	<input checked="" type="checkbox"/>
2	05/12/17 14:54	General View	Load JPG	<input checked="" type="checkbox"/>
3	05/12/17 14:54	General View	Load JPG	<input checked="" type="checkbox"/>
4	05/12/17 14:54	General View	Load JPG	<input checked="" type="checkbox"/>
5	05/12/17 14:54	General View	Load JPG	<input checked="" type="checkbox"/>
6	05/12/17 14:54	General View	Load JPG	<input checked="" type="checkbox"/>
7	05/12/17 14:54	General View	Load JPG	<input checked="" type="checkbox"/>
8	05/12/17 14:54	General View	Load JPG	<input checked="" type="checkbox"/>
9	05/12/17 14:54	General View	Load JPG	<input checked="" type="checkbox"/>
10	05/12/17 14:54	General View	Load JPG	<input checked="" type="checkbox"/>
11	05/12/17 14:54	General View	Load JPG	<input checked="" type="checkbox"/>
12	12/12/17 15:37	RE-SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
13	12/12/17 15:37	RE-SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>		1 per page <input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/11/17 13:40	Survey AGREE ON SJE, Appoint LKK as Surveyor	Load PDF	
2	27/11/17 13:42	Request Pre-Repair Inspection, SFE6655Z GIA RPT	Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a> <a href="#">Save</a> <a href="#">Print</a>
There are no document checklists configured.	
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>	
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022559/KGBS2

Date: 15/12/2017

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-980645-WTT	
Claimant Vehicle No :	SFE6655Z	Insured Vehicle No :	FT4917C	
Date of Loss:	23/11/2017	Nature of Claim:	TP	Claim No: MSC/V/17-001842

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SFE6655Z	Engine No:	2ZR1948936
Make & Model:	TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)	Chassis No:	ZVW400025098
Reg. Date:	14/07/2017 (Man. Year: 2017)	Odometer:	38164 km
Colour:	Metallic Blue		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	HIFLEX 9 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	HIFLEX 9 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	780.25	240.00	540.25	69.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	520.00	380.00	42.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>1,680.25</b>	<b>760.00</b>	<b>920.25</b>	<b>54.77</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>117.62</b>	<b>53.20</b>	<b>64.42</b>	<b>54.77</b>
<b>Nett Amount (\$\$)</b>	<b>1,797.87</b>	<b>813.20</b>	<b>984.67</b>	<b>54.77</b>

## INSPECTION

Date of Assignment:	27/11/2017	
Date Inspected:	04/12/2017	Inspected At: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	<b>Version:</b> 1.0 (Last Synchronised: 15 Dec 2017)
<b>Parts:</b>	144	TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFE6655Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Buckled/Dented	240.00 F	*240.00 F
2	2		*REAR BUMPER SIDE RETAINER (WCP)	Serviceable	70.00 F	*- F
3	1		*REAR TAILGATE OUTER GARNISH (WCP)	Repair	125.00 F	*- F
4	1		*SET REAR PARKING SENSOR	Serviceable	280.00 FS	*- FS
					<b>Sub Total (S\$)</b>	<b>715.00 240.00</b>
					<b>+ Margin on L,N Items 15.00/0.00% (S\$)</b>	<b>65.25 0.00</b>
					<b>Total Parts (S\$)</b>	<b>780.25 240.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING	New	500.00	320.00
2	LABOUR CHARGES	New	400.00	200.00
Gross Labour Cost (S\$)			<b>900.00</b>	<b>520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >