

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	 5	EXHAUST CHROME BRACKET LH	Reviewing	108	CRACKED	
☐	 6	EXHAUST HEAT SHIELD LH	Reviewing	185	BENT	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR J BTTR%	DISC COUN%	SALV AGE%	PART PRICE(NET)
	10	1			REAR BUMPER LOWER BRACKET RH/LH (N/S)			Cracked	86		10		77.4
	11	1			REAR BUMPER LOWER BRACKET RH/LH (O/S)			Serviceable	0		10		0
	12	1			REAR BUMPER SIDE RETAINER RH/LH (N/S)			Bent	96		10		86.4
	13	1			REAR BUMPER SIDE RETAINER RH/LH (O/S)			Serviceable	0		10		0
	14	1			REAR BUMPER TOWING COVER			Serviceable	0		10		0
	15	1			REAR BUMPER REINFORCEMENT			Bent	983.46		10		885.11
	16	1			REAR END PANEL			Repair	0		10		0
	17	1			TAILLAMP LH			Damaged	864.23		10		777.81
	18	1			TAILLAMP TOP GARNISH LH			Twisted	70.27		10		63.24
	19	1			REAR BUMPER SPOILER			Damaged	698		10		628.2
	20	1			BOOTLID RUBBER			Serviceable	0		10		0
	21	2			REVERSE SENSOR			Shorted	246.42		10		443.56

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
Approve								
Deny								

Save

Detailed Assessment

Inspection Date *

11/28/2017



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

235/40R18

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

235/35R18

FNOL INFORMATION... 42 MEI HWAN DRIVE, 200311, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATION...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATION...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATION...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATION...

S1500858Z

POST SURVEY INF...

CATEGORY

POLICY INFORMAT...

AUDI

ASSESSMENT INFO...

MERCEDES BENZ

CATEGORY

Model

POLICY INFORMAT...

A5 SPORTBACK 2.0 TFSI

ASSESSMENT INFO...

CLS 350 BLUEEFFICIENCY SHOOTING

CATEGORY

Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT...

WAUZZZ8T6AA024702

CATEGORY

Date of Birth

FNOL INFORMATI...

August 25, 1961

POST SURVEY INF...

mm/dd/yyyy

CATEGORY

Age

FNOL INFORMATI...

56

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF...

CATEGORY

Driving Experience

kane.seow@gmail.com

Pending verification -
Direct Settlement

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes
- Add

Additional Instructions

NO TP Xs. NON ARC

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
--------------	--------------	------------------	-----------------	--------	-------	-------

TAN Wancong	11/27/17 3:15 PM	\$8,301.38	\$8,301.38	Open	Share	Clone
-------------	------------------	------------	------------	------	-------	-------

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
TP ESTIMATE-MARKED.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	November 28, 2017
Preliminary Advice.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	November 28, 2017
GA176397-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	TAN Wancong	November 27, 2017
GA176397-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	TAN Wancong	November 27, 2017
SFH7777H TP GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Amol	November 27, 2017
EMAIL.pdf	Letters and Correspondence	Others	PATIL Amol	November 27, 2017

kane.seow@gmail.com

Pending verification -
Direct Settlement

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Messages Invoices History Documents

Assessment Metrics Notes

Document Type

Additional Instructions

NO TP Xs. NON ARC

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 4, 2018
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	May 4, 2018
DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	May 4, 2018