
























PAR Automotive Consultancy

Regn. No. S2986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131

Report No: 0310-17-TCA

11 September 2017

ACCIDENT VEHICLE SURVEY REPORT

Joaquim Florist & Gifts Pte Ltd
9 Kaki Bukit Road 2 #03-06
Singapore 417842

VEHICLE INFORMATION:

Vehicle Reg No.:	SJH4727A	Odometer:	139500km
Make & Model:	Honda Stream 1.8X A	Colour:	Black
Chassis number:	RN61063223	Date of accident:	24/01/2017
Year of Regn.:	08/08/2008	Date inspected:	07/02/2017
Repairer at:	Twincar Automotive Pte Ltd	Date inspected (After Repair):	13/02/2017
	Blk 2 Kaki Bukit Ave 2 #01-17		
	Kaki Bukit Auto Hub		
	Singapore 417921		

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.







