

ASS. REC. BY:

REF: CS/AXA17022600/Urbez

Special Instruction:

Survivor:
Merimen

Marluc.

ASSIGNMENT (Office)

From (Person):

Khor Saw Theng

of

AXA

Date/Time:

28-11-2017 952am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 948Y

Insured:

SHD 9281E

at Workshop m/s

V.Z. Automotive

Tel:

9336 5311

of

Blk 1 Kaki Bukit Ave 6 #02-02.

Policy No:

P1680520

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26-11-2017

CA / REV / REP. / REV 24 HRS WP1

H.O.D. Endorsement:

Date/Time:

28-11-2017 10am

Person Contacted:

Ah Huat

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJS 948Y - CS/CH1700692/H3

DUA: 18/11/2017

SHD 9281E - CS/ALH1302035/KV13W2

DUA: 28/11/2017

29/11/17

Informed Saw Theng pending est from repairer by merimen

30/11/18

Send preli revised by merimen

Surinder Marcup

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

5559484

Yr Regn:

29/7/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(0)

Make:

KIA cerato Forte C.C 159/

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

276592

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAFu41MA5101614

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Newton

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

26/11/17

D.O.I.

28/11/17

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 8673

14th June. Day 9

6/2/18 4/5 10.000 confirmed with AH huoy (Ref 13,915.87, 5890)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

3/2-typist

Days Of Repair:

10

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) \$ - RS - SI

Photos

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Report Format :

merimen

Lump Sum / I.B.I: (\$

10,000p

TOTAL

300

Survey Department Check List (Case Handler)

Reference No.: **CS AXA17022600 Uvb**
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: **VERON** **7/2/18**
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CS/AXA17022600/Uvb		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 28-11-2017		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 9281E	Veh. Inspected	SJS 948Y	
Policy No.	P1680520	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (KHOR SAW THENG)	Assign Date	28/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/11/2017	Inspection Date	28/11/2017	
Survey held at	V.Z. AUTOMOTIVE - BLK 1 KAKI BUKIT AVE 6 #02-02			
Repairer	SIONG HAI MOTOR WORKSHOP			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Nov 2017		28 Nov 2017 09:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		TRANS-CAB SERVICES PTE LTD							
Main Claimant:		HN ENTERPRISE							
Vehicle Reg. No.:		SJS948Y							
Claim Type:		TP							
Vehicle Reg. No. (Insured):		SHD9281E							
Repalrer:		- Not Applicable - (-)							
Handling Insurer:		AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Khor Saw Theng - 6880 4754]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/12/2017]							
Adj Asg. Remarks:		Please assign Marcus Chua.							
DATE OF LOSS:		26/11/2017 00:00 - :59							
POLICY/COVER NOTE NO.:		P1680520 (Third Party Only)							
POLICY NO. (CLAIMANT):									
EXCESS:		S\$5,000.00							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (28/11/2017): WP/ PRI Assignment - /P1680520 									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khor Saw Theng

Date: 07 Feb 2018

Preliminary Advice

Insured Vehicle No : SHD9281E

TP Vehicle No : SJS948Y

Make : KIA CERATO FORTE (A)

Date of Inspection : 28/11/2017

Inspection At : V.Z.AUTOMOTIVE

Accident Date : 26/11/2017

Assignment Date : 28/11/2017

Est. Duration of Repair : 10.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion. The chassis frame affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 23,915.87
Revised Amount	:S\$ 10,000.00 (lump sum)
Check Items (Estimated)	:S\$ 0.00
Total	:S\$ 0.00
Lump Sum Repair	:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

☐ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☐ Other comments :

View Sent Message

This mail is associated with :

***SJS948Y**
[SHD9281E]
TP
HN ENTERPRISE
Nov 26 2017 12:00AM
[TRANS-CAB SERVICES PTE LTD]

Resend	View Recipients	Print Message	Delete Message	Forward
--------	-----------------	---------------	----------------	---------

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 29/11/2017 08:48 AM.
To AXA_KhorSawTheng
CC AXA_SG
Subject TP SURVEY REPORT

Dear Saw Theng,

Please be informed that we have inspected the vehicle SJS 948Y on 28/11/2017.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

Satwant Singh
Danny Teo Kim Soon
Pritam Singh
Tan Shu Hua, Vanessa
Khong Zi-Wei

SATWANT ASSOCIATES

AN OFFICIAL MEMBER OF THE LAWYER NETWORK, AN INTERNATIONAL NETWORK OF LAW FIRMS

CONVEYANCING OFFICE:
450 Lorong 6 Toa Payoh
#02-03 Harsing Centre
Singapore 319394
Tel: 6221 6114
Fax: 6266 6925
www.satwantlaw.com.sg
(Fax not for service
of documents)

An Official Member of The Lawyer Network, an international network of law firms

(Please quote our Ref. when replying)

Your Ref: To be advised
Our Ref: PD/DL/1701261 (ml) – Toa Payoh Office
(margaretlim@satwantlaw.com.sg)

27 November 2017

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

BY EMAIL ONLY

Attention: Motor Claims Department

Dear Sir/Mdm,

**ACCIDENT INVOLVING SJS948Y & SHD9281E ALONG JUNCTION OF BEDOK ROAD
X UPPER CHANGI ROAD EAST ON 26/11/2017 @ 22:45**

We refer to our emails dated 27 November 2017 regarding pre-repair survey on our client's vehicle SJS948Y.

Please be informed that said vehicle can be inspected at:

Location: 1 Kaki Bukit Avenue 6 #02-02 Singapore 417883
Contact Person: Ah Huat (HP: 9336 5311)

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



SATWANT & ASSOCIATES
(Danny Teo)

cc client

For Surveyor: To initial after Completion

1st Inspection
Appointed surveyor
(Name & Signature)

Date & Time

2nd Inspection
Appointed surveyor
(Name & Signature)

Date & Time

3rd Inspection
Appointed surveyor
(Name & Signature)

Date & Time

NB: Any Settlement of offer is on the express condition that this settlement is in respect of our client's claim for property related damaged only and shall not preclude our client from claiming injury-related damages arising from this accident.
This document is intended for the addressee(s) only and may contain confidential information and/or may be subject to legal privilege. If you have received this in error, please contact us immediately and destroy the original message.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Business
Owner ID	4387M

Vehicle Details

Vehicle No.	SJS948Y
Vehicle to be Exported	No
Intended De-registration Date	28 Nov 2017
Vehicle Make	KIA
Vehicle Model	CERATO EX FORTE 1.6L A/T ABS AB 2WD 4DR
Primary Colour	Silver
Manufacturing Year	2009
Engine No.	G4FC9H276073
Chassis No.	KNAFU411MA5101614
Maximum Power Output	92.7 kW (124 bhp)
Open Market Value	\$11,433.00
Original Registration Date	29 Jul 2009
First Registration Date	29 Jul 2009
Transfer Count	2
Actual ARF Paid	\$11,433.00 5716

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	28 Jul 2019
PARF Rebate Amount	\$6,288.00

Intended COE Rebate Details

COE Expiry Date	28 Jul 2019
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$14,310.00
COE Rebate Amount	\$2,385.00
Total Rebate Amount	\$8,673.00

The information contained herein is correct as at 28 Nov 2017

OK

SGCARMART.COM
 THE ONLY PLACE FOR SMART CAR BUYERS

All Car Make or Model

Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS

Username / Email Add
password Submit Qu
f Connect Sign Up New Account
Forgot Password

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

11/12 Volvo XC60T5 2.0A, Powerful 2.0L 16V Turbo Engine



An Ideal SUV For Any Family!
 Maintained At Wearnes.High
 ARF \$41,861.1 Owner
 Shine Connect StarAd

Browse by Category

◀ Back (1 2 3 4) Next ▶

Sort by Date Posted









20 results/page

80 vehicles

kia cerato

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	kia cerato		Any	Any	2009	Any	Any	Any	Available
	Kia Cerato Forte 1.6A SX		\$21,800	\$9,570 /yr	19-May-2009	1,591 cc	103,083 km	Sedan	Available
Rare, Like New Condition 8.5 Years Old Car! Serviced At C&C With Proof. Super Low Mileage Clocked Of 12000km Annually. 1 Lady Owner. New Paintwork. Road Tax Till May 18. 100% Accident Free. Call Now!									<div>PREMIUM ID</div>
Lake View Credit Pte Ltd									<div> Details</div>
Posted: 28-Nov-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia									
	Kia Cerato Forte 1.6A EX		\$17,500	\$8,030 /yr	10-Mar-2009	1,591 cc	102,000 km	Sedan	Available
Best Buy. Nice, Clean And Comfortable Car. Fairly Low Mileage. Reliable Engine With Low Maintenance Cost. Low Fuel Consumption. View To Appreciate.									<div> Details</div>
Posted: 28-Nov-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia									
	Kia Cerato Forte 1.6A EX		\$24,800	\$10,440 /yr	30-Sep-2009	1,591 cc	110,000 km	Sedan	Available
Premium Dealer 2013 To 2017! Cheapest, \$2000 Down Payment Only! Monthly Installment From \$900! Uber/Grab Driver Welcome, Original Good Condition, Spacious And Comfortable For Daily Use, Excellent Fuel...									<div> Details</div>
Posted: 28-Nov-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, used Kia									
	Kia Cerato Forte 1.6A EX		\$17,600	\$7,950 /yr	19-May-2009	1,591 cc	118,000 km	Sedan	Available
Kindly Compare! One Owner, Fully Serviced By C&C (Records Available) From Day One, STA Grade B, Superb Condition, Beautiful Paintwork And Sparkling Interior, Accident Free, Road Tax Till May 2018, Low ...									<div> Details</div>
Posted: 28-Nov-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia									
Car Buying		Car Selling		Car Aftermarket					
Car Ownership		On The Move		Lifestyle				<div>► Buy Tyres Online! ► Latest Special Offers from Tyrepack!</div>	
	Kia Cerato Forte 1.6A SX		\$21,800	\$8,970 /yr	22-Jul-2009	1,591 cc	-	Sedan	Available
Interest Rate As Low As 1.99%! Extended Warranty! Fully Maintained / Serviced By C&C. Buy With A Peace Of Mind From A Company Accredited With Outstanding Awards, Professional After Sales Service Assur...									<div> Details</div>
Dickson Automobile									<div> Details</div>
Posted: 28-Nov-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia									
	Kia Cerato Forte 1.6A SX		\$19,180	\$7,710 /yr	29-Jun-2009	1,591 cc	97,000 km	Sedan	Available
Original Condition And Lowest Depreciation! Car Is In Good Working Condition. Wait No More And Call Us To Make An Appointment Now!									<div> Details</div>
Posted: 28-Nov-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia									
	Kia Cerato Forte 1.6A SX		\$19,800	\$8,450 /yr	20-May-2009	1,591 cc	-	Sedan	Available
Lowest Price In The Market, One Owner, Agent Maintained. Accident Free, New Paint. Factory Body Kit, Sporty Red. View To Appreciate Tip Top Condition. Call Our Friendly Sale Advisor, Viewing Daily By ...									<div> Details</div>
Posted: 27-Nov-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia									
	Kia Cerato Forte 1.6A EX		\$15,788	\$7,820 /yr	20-May-2009	1,591 cc	140,000 km	Sedan	Available
1 Current Owner With Genuine Mileage With Regularly Serviced. Pristine Condition, No Repairs Needed, Original Paintwork And Clean Interior, Accident Free, Price Negotiable.									<div>DIRECT OWNER</div>
Posted: 27-Nov-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia									<div> Details</div>

SGCARMART.COM
 THE ONLY PLACE FOR SMART CAR BUYERS

All Car Make or Model

Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS

- ALL consolidated SMRT/NEL/KT.. simisai BREAKDOWNS here...
- MOE kindergartens primary schools priority phase 2a2
- PSLE Results coming out soon!

Username / Email Add

password

Submit Qu

f Connect

Sign Up New Account

Forgot Password

kia cerato

Price Range

Depreciation

2009

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Sincere Motoring Pte Ltd » Kia Cerato Forte 1.6A SX

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Kia Cerato Forte 1.6A SX

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$19,888	
Depreciation	\$8,100 /yr	
	View models with similar depreciation	
Reg Date	30-Jun-2009	
	(1yr 7mths 1day COE left)	
Manufactured	2009	
Mileage	135,298 km (16.1k /yr)	
Transmission	Auto	
Engine Cap	1,591 cc	
Road Tax	\$738 /yr	
Power	92.7 kW (124 bhp)	
	View specs of the Kia Cerato Forte (2009-2013)	
Curb Weight	1,251 kg	
Features	Original Condition.	
Accessories	Factory Fitted Interior.	
Description	(100% Quality Buy!) 1st Owner Unit. Pre Owned From A Family Man, Selling Due To Upgrading. Purchase Comes With 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assistance Coverage. STA/VICOM/AA/IDAC Evaluation Friendly. Bank And In House Loan Available. (Test Drive Available Daily By Appointment.)	
COE	\$11,690	
OMV	\$14,114	
ARF	\$14,114	
Dereg Value	\$9,614 as of today (change)	
No. of Owners	1	
Type of Veh	Mid-Sized Sedan	
Category	PARF Car, Premium Ad Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note



Seller Information

Company	Sincere Motoring Pte Ltd
	<ul style="list-style-type: none"> dealer's pricelist 158 vehs sold 28 vehs available
Address	115 Eunos Avenue 3 #01-05
	Search cars nearby this location
Location	Zhaolim Building
Office No	67476066
Contact Person(s)	Benny 82003243 Sky 98583118 Sady 85247485 Hermann 98595755



Posted on: 26-Nov-2017 | Last Updated on: 28-Nov-2017

Tags: Kia Cerato, Kia Cerato, 2009 Kia Cerato, 2009 Kia Cerato, Kia, Cerato, Cerato, Used Kia

Upfront Payment

view Financial info

Transfer Fee	\$11	
Down Payment	\$5,966 (change)	Maximum 70% Loan



*Total amount from SGD656.70 including airport tax & fuel surcharges SGD 76.70.

A-Assurance
Assurance in Insurance
Car Insurance Expiring?
 We get you the cheapest insurance renewal
[Click to get quote](#)
 Username / Email Add

 password

Submit Qu

[Sign Up New Account](#)
[Forgot Password](#)
 Kia cerato

 Price Range

 Depreciation

 2009

 Vehicle Type

 Advanced
Search

[Home](#) > [Used Cars](#) > [SK Auto](#) > [Kia Cerato Forte 1.6A EX](#)

Tools & Tips

[Car Buying](#)[Car Selling](#)[Car Aftermarket](#)[Car Ownership](#)[On The Move](#)[Lifestyle](#)

Commercial Vehicle

PAN PACIFIC

YEAR END PROMOTION

BRAND NEW VEHICLES FOR LEASE

\$1,200

92385150 87972000

\$1,500

88298620 90103844

Kia Cerato Forte 1.6A EX

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)
[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#) [Report Error](#) [More Actions](#) [Share](#)

Car Details

Price **\$21,555**

Depreciation **\$8,670 /yr**
 View models with similar depreciation

Reg Date 24-Jul-2009
 (1yr 7mths 25days COE left)

Manufactured 2008

Mileage 107,332 km (12.8k /yr)

Transmission Auto

Engine Cap 1,591 cc

Road Tax \$738 /yr

Power 92.7 kW (124 bhp)
 View specs of the Kia Cerato

Features 1.6L DOHC 124 Bhp, 4 Cylinders 16 Valves Auto Transmission, ABS, Airbags, Multi Function Steering Wheel, Front And Rear Disc Brakes.

Accessories Sports Rims, Retractable Side Mirrors With Indicator, Factory Fitted Audio System, Fog Lights, Solar Film, Reverse Sensors.

Description Lowest Depreciation And Mileage In The Market. 1 Owner Only, Regularly Serviced/Well Maintained By Previous Owner, Pristine Condition, No Repairs Needed, Flawless Exterior And Clean Interior, Accident Free, Viewing Kindly Call For Appointment.

COE \$14,310

OMV \$14,495

ARF \$14,495

Dereg Value \$10,332 as of today (change)

No. of Owners 1

Type of Veh Mid-Sized Sedan

Category PARF Car

Availability Available

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

Posted on: 26-Nov-2017 | Last Updated on: 26-Nov-2017

 Tags: [Kia Cerato](#), [Kia Cerato](#), [2009 Kia Cerato](#), [2009 Kia Cerato](#), [Kia](#), [Cerato](#), [Cerato](#), [Used Kia](#)

Upfront Payment

[» more Financial Info](#)

Transfer Fee \$11

Down Payment \$5,467 (change) [Maximum 70% Loan](#)

1st Instalment \$832

Total Upfront Payment \$7,310 (excluding insurance)

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.



Location Map



Price Analysis

Seller Information

Company SK Auto
 * dealer's pricelist
 * 39 vehs sold | 29 vehs available

Address 3 Ang Mo Kio Street 62 #02-27
 Search cars nearby this location

Location Link @ AMK

Office No 66595090

Contact Person(s) Bernard 96879313
 Ken 96980361
 Kenji 86600400

Useful Services



Make sure of this car condition with STA Evaluation.

[Vehicle Evaluation](#)


Find out the market value for your car. Get a free Car Valuation.

[Free Valuation](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/11/2017 18:40
Date Of Accident	26/11/2017 22:45
Exact Location Of Accident	JCT OF BEDOK RD X UPP CHANGI RD EAST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS948Y
Insured/Policyholder	
Name Of Registered Owner	HN ENTERPRISE
Co Reg No	53334387M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97503811
Alternative Phone No	OFFICE-97503811

Vehicle Particulars

Manufacturer	KIA
Model	CERATO-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO

Policy Number
Cover Note Number

Driver

Name of Driver	NG JING XUAN
NRIC No	S9404542H
Date Of Birth	07/02/1994
Occupation	INDOOR
Date Of Driving Pass	17/11/2014
Driving Experience	3 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97503811
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured CHILDREN

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name CHANGI N.P.C

Police Station Address ROAD: 9 SIMEI STREET 2 , POSTCODE: 529914 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN/POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD9281E

Vehicle Make/Model/Colour CHEVROLET EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name NG JING XUAN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJS948Y

Were seat belts worn? YES

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name NG JING XUAN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJS948Y

Were seat belts worn?

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 3

Name HOW YI SHAN,BEATRICE

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJS948Y

Were seat belts worn?

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. This report must be correctly filled in and must be submitted to the relevant authority.

2. Completed by the Policyholder and/or the Authorized Driver

3. The information provided must be truthful and accurate as possible to avoid the possibility of repudiate policy liability.

4. The information provided must be truthful and accurate as possible to avoid the possibility of repudiate policy liability.

Any false reporting may be referred to the Police for investigation

5. The information provided must be truthful and accurate as possible to avoid the possibility of repudiate policy liability.

6. The information provided must be truthful and accurate as possible to avoid the possibility of repudiate policy liability.

7. The information provided must be truthful and accurate as possible to avoid the possibility of repudiate policy liability.

8. The information provided must be truthful and accurate as possible to avoid the possibility of repudiate policy liability.

9. The information provided must be truthful and accurate as possible to avoid the possibility of repudiate policy liability.

10. The information provided must be truthful and accurate as possible to avoid the possibility of repudiate policy liability.

11. The information provided must be truthful and accurate as possible to avoid the possibility of repudiate policy liability.

12. The information provided must be truthful and accurate as possible to avoid the possibility of repudiate policy liability.

13. The information provided must be truthful and accurate as possible to avoid the possibility of repudiate policy liability.

14. The information provided must be truthful and accurate as possible to avoid the possibility of repudiate policy liability.



Signature

Signature

Signature


Sketch Plan #2

SKETCH PLAN

Vehicle A 8JS 946Y

Vehicle B. SHD9181E

Upper Changi Rd Est.



DETAILED DESCRIPTION OF THE ACCIDENT

Refer to Police Report

Bedok Rd



[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

The undersigned is the
[Signature]
 of the Police Force



**SINGAPORE
POLICE FORCE**



T/20171127/2003

1 of 4

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

Report No. T/20171127/2003

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/11/2017 02:05		Vide Report No.:		Station Diary No.: 9	
Name of Informant: NG JING XUAN		Address: APT BLK 135 SIMEI STREET 1 #03-52 SINGAPORE 520135			
ID Type / ID No.: NRIC NO / S9404542H		Contact No.: Home/Office:		Mobile: 92317273	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 23	Date of Birth: 07/02/1994	Type of Informant: Driver		
Race: Chinese		Language:		Institution / School Name:	
Occupation: MILITARY PERSONNEL		Driving Licence Information: Class:		Date of Expiry:	

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 26/11/2017 23:30	Type of Location: X-Junction
Location: Along Road 1 UPPER CHANGI ROAD EAST				
Junction of Bedok Road and Upper Changi Road East				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

SHD9281E	Car					1
SJS948Y	Car					2

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			



**SINGAPORE
POLICE FORCE**



T/20171127/2003

2 of 4

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

Report No. T/20171127/2003

CONTINUATION OF REPORT

Name	Effendi Mustafa	ID No.	S2621827F
Related Vehicle	SHD9281E (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	Ting Jia Yan	ID No.	S9444704F
Related Vehicle	SJS948Y (Car)	Contact No.	97121794
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	27/11/2017	Date Discharge	27/11/2017
No. of Days granted Medical Leave	02	Degree of Injury	NIL
Name	NG JING XUAN	ID No.	S9404542H
Related Vehicle	SJS948Y (Car)	Contact No.	92317273
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	27/11/2017	Date Discharge	27/11/2017
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Name	How Yi Shan, Beatrice	ID No.	S9415106F
Related Vehicle	SJS948Y (Car)	Contact No.	90607800
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	27/11/2017	Date Discharge	27/11/2017
No. of Days granted Medical Leave	02	Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20171127/2003

3 of 4

Report No. T/20171127/2003

Police Station Of Origin:

Changi N.P.C

9 Simei Street 2 SINGAPORE 529914

Tel No: 1800-5872999

CONTINUATION OF REPORT

Brief Details.

On 26/11/2017 at 2330hrs, I was driving along Upper Changi Road East and I was at the junction of Bedok Road when the accident happened. While the traffic light was green, I continued driving forward. Suddenly the taxi SHD9281E came from my right and was turning to the right to my direction. He had beaten the red light and this cause my front to collide with the taxi's left side rear door.

After the accident happened, I made a check and took photos of the incident before calling for police's assistance. I took photo of the taxi driver's IC after. Ambulance came first and followed by police shortly after. I pass my 11B to the police before being conveyed by the ambulance. My 2 other passengers were also conveyed together with me.



SINGAPORE POLICE FORCE



T/20171127/2003

4 of 4

Report No. T/20171127/2003

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Staff Sgt NUR MUHAMMAD ISKANDAR BIN
REINDIO

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
JP / GIT /
Insp NORHIDAWATI BINTE AHMAD
No.: 65476310 SN 160

Authentication Stamp

N.P.C.

Singapore Police Force

Signature Of Informant:

Date/Time:
27/11/2017 02:05

Classification Of Case:

V.Z AUTOMOTIVE PTE. LTD.

Blk 1 Kaki Bukit Avenue 6, #02-02, Singapore 417883

TEL: 6555 7272

HP: 9879 0000

FAX: 6741 1019

not Afford
28/11/17
Total price Afford
1/5 # 10.000
10 day.

Vehicle No.: SJS948Y

Model: KIA CERATO FORTE

QTY	List Items:	Amount \$
1	Front bonnet <i>f125</i>	Buc 875.00
1	Front bonnet rubber - inner	17 32.00 <i>x</i>
1	Front bonnet rubber - outer	17 38.00 <i>a</i>
1	Front bonnet lock	17 115.00
1	Front bonnet lock cable	3m 89.50
2	Front bonnet hinges - L/R @ 45	Bul 90.00
1	Front bonnet stand clip	17 15.00 <i>x</i>
1	Front bonnet stand	17 62.00 <i>x</i>
1	Front bumper	205 668.00
1	Front bumper CTR grille	17 82.00 <i>x</i>
2	Front bumper fog lamps - L/R @ 215	Che 430.00
2	Front bumper fog lamp grille - L/R @ 48	0/57m 96.00 <i>1/2 C</i>
1	Front bumper sponge	70-2 135.60
1	Front bumper reinforcement <i>34</i>	74 389.20
2	Front bumper side retainers - L/R @ 36	Bul 72.00
1	Front bumper lower lip	17 146.00 <i>x</i>
10	Front bumper clips @ 4.50	17 45.00
2	Front fenders - L/R @ 386 <i>0/57</i>	n/s bul/suc 772.00 <i>1/2 C</i>
2	Front fender inner shields - L/R @ 112.60	De/10m 225.20
30	Front fender inner shield clips @ 4.50	17 135.00 <i>50</i>
2	Front fender wheel housings - L/R @ 697	17 1,394.00 <i>x</i>
1	Front grille	Bul/Che 286.00
1	Front grille logo	17 58.60
2	Front headlamps - L/R @ 562	Che 1,124.00
2	Front headlamp lower brackets - L/R @ 89.60	Bul 179.20
1	Front no. plate garnish	De 86.60
1	Front support panel	Bul/Che 698.50
1	Front chassis member - RH	17/Buc 1,081.50
1	Air con condenser <i>703</i>	Bul/17m 723.60
1	Air con discharge pipe	17 386.20 <i>x</i>
1	Air con suction pipe	17 345.00 <i>x</i>
1	Air con liquid pipe	17 195.50 <i>x</i>
1	Air con compressor	17 1,362.50 <i>x</i>
1	Air con compressor belt	17 241.50 <i>x</i>
1	Air cleaner intake duct	Che 112.60
1	Air cleaner box assy	17 265.00 <i>x</i>
1	Air cleaner hose	17 142.60 <i>x</i>

Auto Club Singapore notify
of the following:
• To survey before spray painting
• To survey before part(s) during resurvey
• Parts prior are subject to confirmation survey
• Third party survey is on "Without Prejudice" basis
• No life-gain modification is allowed
• Subject to final approval from Insurance Company
Acknowledged by Repairer
Page 1 of 2
Signature: _____
Date: _____

Vehicle No.: SJS948Y

Model: KIA CERATO FORTE

1	Alternator assy	17	1,335.50	X
1	Power steering cooling pipe	17	181.20	X
1	Radiator assy	sup/2ur	680.60	✓
2	Radiator top mounts @ 14.50	7w1	29.00	✓
1	Radiator top hose	17	48.80	X
1	Radiator bottom hose	17	58.60	X
1	Radiator electric fan assy	cr/gm	445.00	✓
1	Battery tray	17	86.00	X
1	Inlet manifold	20/cr	832.00	✓
1	Engine mounting - RH	17	291.60	X
1	Engine mounting - LH	17	285.00	X
1	Engine mounting - Frt	17	255.20	X
1	Engine mounting - Rear	17	242.60	X
1	Washer tank	22	110.20	✓
1	Wiper panel garnish	17	142.60	X
1	Front sub frame assy	17	1,865.00	X
Sub Total			20,084.30	✓
Less 10%			2,008.43	9884.5
Total List			18,075.87	8896.05

Special Nett Items:

1 set	Front no. plate wih holder	54	60.00	40
1 bot	Air con oil	11	60.00	50
1 bot	Radiator coolant	22	60.00	30
1	Battery	17	280.00	X
Total Special Nett			460.00	

Labour Charges:

Towing charges	100.00	50
To remove, refix front undercarriage	450.00	350
To check wheel alignment	120.00	60
To check front electrical wiring	80.00	20
To remove, refix front engine parts	300.00	✓
To haul up, reinstall whole engine to assist repair	17	600.00 X
To remove, refix A/C condenser & refill A/C gas	180.00	100
To respray undercoating	150.00	120
To respray painting & etc	1,400.00	200
Panel beating, cut, weld, remove & replacing above parts	2,000.00	300
Total Labour	5,380.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 23,915.87

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI BI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Nov 2017		28 Nov 2017 09:52 Edit Adj Rpt	S\$10,000.00 Edit Estimates	S\$10,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS				[Created by Insurer]		
Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K, Tel: +6591783319					
Main Claimant:	HN ENTERPRISE					
Vehicle Reg. No.:	SJS948Y	Date of Loss:	26/11/2017 00:00 - :59			
Claim Type:	TP / C0464224	Policy/Cover Note No.:	P1680520 (Third Party Only)			
Vehicle Reg. No. (Insured):	SHD9281E	Policy No. (Claimant):				
		Excess:	S\$5,000.00			
Repairer:	- Not Applicable - (-)					
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Khor Saw Theng - 6880 4754]					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 07/12/2017]					
Adj Asg. Remarks:	Please assign Marcus Chua.					

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> AXA_SG (28/11/2017): WP/ PRI Assignment - /P1680520 		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJS948Y (C0464224)**
[SHD9281E]
TP
HN ENTERPRISE
Nov 26 2017 12:00AM
[TRANS-CAB SERVICES PTE LTD]

Upload Documents Upload Photos Compose New Letter		View View In Browser
Assessment Reports		1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)
1	07/02/18 16:12	Adjuster Immediate Advice
		1 Load HTM
Photos/Images		3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	07/02/18 16:00	SURVEY PHOTOS
2	07/02/18 16:00	RESURVEY PHOTOS 1
3	07/02/18 16:00	RESURVEY PHOTOS 2
		1 Load PDF 1 Load PDF 1 Load PDF
Documentation		1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)
1	27/11/17 16:38	EMAIL
2	27/11/17 16:38	CO LEGAL
3	27/11/17 16:38	PHOTO
4	27/11/17 16:38	PHOTO
5	27/11/17 16:38	PHOTO
6	28/11/17 09:41	FRM TP
7	28/11/17 09:41	FRM TP
8	28/11/17 09:43	SHD9281E GIA REPORT
9	28/11/17 09:44	SJS948Y GIA REPORT
		1 Load PDF 1 Load PDF 1 Load JPG <input checked="" type="checkbox"/> 1 Load JPG <input checked="" type="checkbox"/> 1 Load JPG <input checked="" type="checkbox"/> 1 Load PDF 1 Load TIF 1 Load PDF 1 Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AXA17022600/UVBE2**Date:** 13/02/2018**REFERENCE**

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1680520
Claimant Vehicle No :	SJS948Y	Insured Vehicle No :	SHD9281E
Date of Loss:	26/11/2017	Nature of Claim:	TP
		Claim No:	C0464224

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS948Y		
Make & Model:	KIA CERATO FORTE, 1.6 A/T ABS AB 2WD 4DR (A)	Engine No:	G4FC9H276073
Reg. Date:	29/07/2009 (Man. Year: 2009)	Chassis No:	KNAFU411MA5101614
Colour:	Grey	Odometer:	276592 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Neuton 6 mm	Rear Left Side:	Neuton 6 mm
Front Right Side:	Neuton 6 mm	Rear Right Side:	Neuton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,535.87	9,016.05	9,519.82	51.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,380.00	3,500.00	1,880.00	34.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,915.87	12,516.05	11,399.82	47.67
Approved Total (Overridden) (\$\$)		10,000.00		
Nett Amount (\$\$)	23,915.87	10,000.00	13,915.87	58.19

INSPECTION

Date of Assignment:	28/11/2017		
Date Inspected:	28/11/2017	Inspected At:	BLK 1 KAKI BUKIT AVE 6 #02-02
			Repairer : V.Z. AUTOMOTIVE
Estimated Period of Repair:	10.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 13 Feb 2018)

Parts: 143 **KIA CERATO FORTE 1.6 A/T ABS AB 2WD 4DR (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJS948Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (CONSISTENT)	Buckled	875.00 FL	*825.00 FL
2	1		*FRONT BONNET RUBBER - INNER (CONSISTENT)	Not Necessary	32.00 FL	*- FL
3	1		*FRONT BONNET RUBBER - OUTER (CONSISTENT)	Not Necessary	38.00 FL	*- FL
4	1		*FRONT BONNET LOCK (CONSISTENT)	Twisted	115.00 FL	*115.00 FL
5	1		*FRONT BONNET LOCK CABLE (CONSISTENT)	Jammed	89.50 FL	*89.50 FL
6	2		*FRONT BONNET HINGES - L/R (CONSISTENT)	Bent	90.00 FL	*90.00 FL
7	1		*FRONT BONNET STAND CLIP (CONSISTENT)	Not Necessary	15.00 FL	*- FL
8	1		*FRONT BONNET STAND (CONSISTENT)	Not Necessary	62.00 FL	*- FL
9	1		*FRONT BUMPER (CONSISTENT)	Distorted	668.00 FL	*668.00 FL
10	1		*FRONT BUMPER CTR GRILLE (CONSISTENT)	Not Necessary	82.00 FL	*- FL
11	2		*FRONT BUMPER FOG LAMPS - L/R (CONSISTENT)	Cracked	430.00 FL	*430.00 FL
12	1		*FRONT BUMPER FOG LAMP GRILLE - L/R (CONSISTENT)	O/S Twisted	96.00 FL	*48.00 FL
13	1		*FRONT BUMPER SPONGE (CONSISTENT)	Torn	135.60 FL	*135.60 FL
14	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT)	Distorted	389.20 FL	*321.00 FL
15	2		*FRONT BUMPER SIDE RETAINERS - L/R (CONSISTENT)	Bent	72.00 FL	*72.00 FL
16	1		*FRONT BUMPER LOWER LIP (CONSISTENT)	Not Necessary	146.00 FL	*- FL
17	10		*FRONT BUMPER CLIPS (CONSISTENT)	Necessary	45.00 FL	*45.00 FL
18	1		*FRONT FENDERS - L/R (CONSISTENT)	O/S Repair/N/SBent/Buckled	772.00 FL	*386.00 FL
19	2		*FRONT FENDER INNER SHIELDS - L/R (CONSISTENT)	Deformed / Torn	225.20 FL	*225.20 FL
20	1		*FRONT FENDER INNER SHIELD CLIPS (30 PCS)(CONSISTENT)	Necessary	135.00 FL	*50.00 FL
21	2		*FRONT FENDER WHEEL HOUSINGS - L/R (CONSISTENT)	Repair	1,394.00 FL	*- FL
22	1		*FRONT GRILLE (CONSISTENT)	Bent / Cracked	286.00 FL	*286.00 FL
23	1		*FRONT GRILLE LOGO (CONSISTENT)	Necessary	58.60 FL	*58.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
24	2		*FRONT HEADLAMPS - L/R (CONSISTENT)	Cracked	1,124.00 FL	*1,124.00 FL
25	2		*FRONT HEADLAMP LOWER BRACKETS - L/R (CONSISTENT)	Bent	179.20 FL	*179.20 FL
26	1		*FRONT NO. PLATE GARNISH (CONSISTENT)	Deformed	86.60 FL	*86.60 FL
27	1		*FRONT SUPPORT PANEL (CONSISTENT)	Bent / Cracked	698.50 FL	*698.50 FL
28	1		*FRONT CHASSIS MEMBER - RH (CONSISTENT)	Dented / Buckled	1,081.50 FL	*1,081.50 FL
29	1		*AIR CON CONDENSER (CONSISTENT)	Bent / Punctured	723.60 FL	*703.00 FL
30	1		*AIR CON DISCHARGE PIPE (CONSISTENT)	Not Necessary	386.20 FL	*- FL
31	1		*AIR CON SUCTION PIPE (CONSISTENT)	Not Necessary	345.00 FL	*- FL
32	1		*AIR CON LIQUID PIPE (CONSISTENT)	Not Necessary	195.50 FL	*- FL
33	1		*AIR CON COMPRESSOR (CONSISTENT)	Not Necessary	1,362.50 FL	*- FL
34	1		*AIR CON COMPRESSOR BELT (CONSISTENT)	Not Necessary	241.50 FL	*- FL
35	1		*AIR CLEANER INTAKE DUCT (CONSISTENT)	Cracked	112.60 FL	*112.60 FL
36	1		*AIR CLEANER BOX ASSY (CONSISTENT)	Not Necessary	265.00 FL	*- FL
37	1		*AIR CLEANER HOSE (CONSISTENT)	Not Necessary	142.60 FL	*- FL
38	1		*ALTERNATOR ASSY (CONSISTENT)	Not Necessary	1,335.50 FL	*- FL
39	1		*POWER STEERING COOLING PIPE (CONSISTENT)	Not Necessary	181.20 FL	*- FL
40	1		*RADIATOR PIPE (CONSISTENT)	Bent / Punctured	680.60 FL	*638.00 FL
41	2		*RADIATOR TOP MOUNTS (CONSISTENT)	Twisted	29.00 FL	*29.00 FL
42	1		*RADIATOR TOP HOSE (CONSISTENT)	Not Necessary	48.80 FL	*- FL
43	1		*RADIATOR BOTTOM HOSE (CONSISTENT)	Not Necessary	58.60 FL	*- FL
44	1		*RADIATOR ELECTRIC FAN ASSY (CONSISTENT)	Cracked / Jammed	445.00 FL	*445.00 FL
45	1		*BATTERY TRAY (CONSISTENT)	Not Necessary	86.00 FL	*- FL
46	1		*INLET MANIFOLD (CONSISTENT)	Dented / Cracked	832.00 FL	*832.00 FL
47	1		*ENGINE MOUNTING - RH (CONSISTENT)	Not Necessary	291.60 FL	*- FL
48	1		*ENGINE MOUNTING - LH (CONSISTENT)	Not Necessary	285.00 FL	*- FL
49	1		*ENGINE MOUNTING - FRT (CONSISTENT)	Not Necessary	255.20 FL	*- FL
50	1		*ENGINE MOUNTING - REAR (CONSISTENT)	Not Necessary	242.60 FL	*- FL
51	1		*WASHER TANK (CONSISTENT)	Deformed	110.20 FL	*110.20 FL
52	1		*WIPER PANEL GARNISH (CONSISTENT)	Not Necessary	142.60 FL	*- FL
53	1		*FRONT SUB FRAME ASSY (CONSISTENT)	Not Necessary	1,865.00 FL	*- FL
54	1		*SET FRONT NO. PLATE WITH HOLDER (CONSISTENT)	Bent	60.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*BOT AIR CON OIL (CONSISTENT)	Necessary	60.00 FS	*50.00 FS
56	1		*BOT RADIATOR COOLANT (CONSISTENT)	Necessary	60.00 FS	*30.00 FS
57	1		*BATTERY (CONSISTENT)	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	20,544.30	10,004.50
- List Item Discount on L Items 10.00/10.00% (S\$)	2,008.43	988.45
Total Parts (S\$)	18,535.87	9,016.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	100.00	50.00
2	TO REMOVE, REFIX FRONT UNDERCARRIAGE	New	450.00	350.00
3	TO CHECK WHEEL ALIGNMENT	New	120.00	60.00
4	TO CHECK FRONT ELECTRICAL WIRING	New	80.00	20.00
5	TO REMOVE, REFIX FRONT ENGINE PARTS	New	300.00	300.00
6	TO HAUL UP, REINSTALL WHOLE ENGINE TO ASSIST REPAIR	New	600.00	0.00
7	TO REMOVE, REFIX A/C CONDENSER & REFILL A/C GAS	New	180.00	100.00
8	TO RESPRAY UNDERCOATING	New	150.00	120.00
9	TO RESPRAY PAINTING & ETC	New	1,400.00	1,200.00
10	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS	New	2,000.00	1,300.00
Gross Labour Cost (S\$)			5,380.00	3,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >