

ASS. REC. BY:

REF: CS/FCI17022617/K1#61ⁿ²

Special Instruction:

Survivor:

CWS

ASSIGNMENT (Office)

From (Person):

joanne yong

of

FCI

Date/Time: 27/11/17 @ 5:22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 6991C

Insured:

SHB 4037M

at Workshop m/s

Premier Automotive

Tel:

65446589

of 23 Changi South Ave 2 # 03-02

Policy No:

Claim No:

D17010927MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up,

H.O.D. Endorsement:

Date/Time:

9:05am @ 28/11/17

Person Contacted:

Vinecent

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate.
	SHC 6991P - CS/FCI17001401/H1h3n2 - D.O.A.: 19/01/2017
	SHB 4037M - CC3/AXA10021775/Fq1f2g2 - D.O.A.: 24/10/2010
12/12-	1:33pm revert via email.

NAME: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no: _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Van No: SHC6991P Reg: 4 Dec 2015

Type: M/Car / M/Cycle / Bus / Van / Lorry / T/B / Prime Mover

Truck / Trailer or

Make: KIA optima cc: 1.6

Colour: silver A/C: Ins / Std / NI / NA

Sp. Reading: 26438 T/F: Ins / Std / NI / NA

Eng. No: _____

C.No: 1KNA6M414MF565764

Gen. Cond: Good / P / Poor / Burnt

Steering: In order / J / Jammed / Leaked / Burnt or

Brake: In order / J / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achi 110

Front _____ Rear _____

R.Bel. 7 mm R.Bel. 7 mm

L.Bel. 7 mm L.Bel. 7 mm

D.O.A. 23/1/12 D.O.A. 11/12/12

Survey held at Premis

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S pch.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
18/12/12 Call r/p & 1081 / 1P, (red: 350 : 24%) FCI

RECEIVED 10 DEC 2011

Date/Time File Pass CP: _____

18/12/12 Typst ☐ : Preli. Report

☒ : Final Report

Date/Time File Return CP: _____

Days Of Repair: 1

Resurvey No. of Trip: 1

Survey Fee

Transporter

Food

Other

Add Fee: ☐ : Site Insp \$

☐ : Interview \$

☐ : Tech. Insp \$

☐ : Weekend \$

100
50
50
20
220

Report Format: TP

Lump Sum / L.S. : 1081



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022617/K1tb

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 28-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4037M	Veh. Inspected	SHC 6991C
Policy No.		Coverage (\$)	0.00
Claim No.	D17010927MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	28/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/11/2017	Inspection Date
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010927MFSH

Date: 12/12/2017

Our Ref: CS/FCI17022617/K1tb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6991C

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/12/2017 at the premises of M/s Premier at and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,431.00</u>
Revised Estimate Amount	: S\$ <u>1,081.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
At n/s body portion.



Repair days: 1

Yours faithfully

Kalvin

Motor Surveyor

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 12 December, 2017 1:33 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010927MFSH/1
Attachments: PRELI ADVISED SHC 6991C.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHC 6991C**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 28 November, 2017 9:09 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010927MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Monday, 27 November, 2017 5:21 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010927MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

• Motor Claims Department

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	24-11-2017	Our Ref No. D17010927MFSH
Accident Date	23-11-2017	Claim Type. Third Party
Insured Vehicle	SHB4037M	Third Party Vehicle. SHC6991P
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GOH WEE DEK	
Contact No.	65446676/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230678)



PRI Documents



Close



PRI Header Details

Claim No	D17010927MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & PREMIER
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : GOH WEE DEK)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446689 , Phone: 65446676 , Fax: 62141511 EmailId: WEEDEK.GOH@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHB4037M	TP Vehicle No	SHC6991P
PRI Recieved Date	24-11-2017 05:19:28 PM	Surveyor Appointed Date	27-11-2017 05:21:19 PM	Surveyor Accept Date	28-11-2017 11

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	28-11-2017	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	04 Dec 2015 / 08:59:07	Receipt No.:	AACCK001-AX239-151204-000005
Asset Type:	Vehicle	Transaction Amount:	\$68,285.00
Asset ID:	SHC6991P	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151204085907215690		
Vehicle No.:	SHC6991P		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	04 Dec 2015		
Original Registration Date:	04 Dec 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5657644		
Engine No.:	D4FDH314381		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2015		
Open Market Value:	\$21,913.00		
Minimum PARF Benefit:	\$13,607.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	04 Dec 2015 08:59:07		
COE No.:	2015120401003351C		
COE Expiry Date:	03 Dec 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$45,466.00		
Lifespan Expiry Date:	03 Dec 2023		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

24-Nov-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6991 P

1 pc	n/s mirror Assy		\$	590.00
		Less 10%	\$	59.00
			\$	531.00
	Sundry	net	\$	50.00 20
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front n/s fender etc		\$	500.00 300
	To putty and spray painting on front n/s fender, n/s mirror		\$	350.00 270
			\$	1,431.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kalvi (C/C)

11/12/17 0940 hrs

1 Days

P/P

Before Paint photo

LKK 4.0L 1.8L 2.0L 2.4L 3.0L 3.5L 4.0L 4.5L 5.0L 5.5L 6.0L 6.5L 7.0L 7.5L 8.0L 8.5L 9.0L 9.5L 10.0L 10.5L 11.0L 11.5L 12.0L 12.5L 13.0L 13.5L 14.0L 14.5L 15.0L 15.5L 16.0L 16.5L 17.0L 17.5L 18.0L 18.5L 19.0L 19.5L 20.0L 20.5L 21.0L 21.5L 22.0L 22.5L 23.0L 23.5L 24.0L 24.5L 25.0L 25.5L 26.0L 26.5L 27.0L 27.5L 28.0L 28.5L 29.0L 29.5L 30.0L 30.5L 31.0L 31.5L 32.0L 32.5L 33.0L 33.5L 34.0L 34.5L 35.0L 35.5L 36.0L 36.5L 37.0L 37.5L 38.0L 38.5L 39.0L 39.5L 40.0L 40.5L 41.0L 41.5L 42.0L 42.5L 43.0L 43.5L 44.0L 44.5L 45.0L 45.5L 46.0L 46.5L 47.0L 47.5L 48.0L 48.5L 49.0L 49.5L 50.0L 50.5L 51.0L 51.5L 52.0L 52.5L 53.0L 53.5L 54.0L 54.5L 55.0L 55.5L 56.0L 56.5L 57.0L 57.5L 58.0L 58.5L 59.0L 59.5L 60.0L 60.5L 61.0L 61.5L 62.0L 62.5L 63.0L 63.5L 64.0L 64.5L 65.0L 65.5L 66.0L 66.5L 67.0L 67.5L 68.0L 68.5L 69.0L 69.5L 70.0L 70.5L 71.0L 71.5L 72.0L 72.5L 73.0L 73.5L 74.0L 74.5L 75.0L 75.5L 76.0L 76.5L 77.0L 77.5L 78.0L 78.5L 79.0L 79.5L 80.0L 80.5L 81.0L 81.5L 82.0L 82.5L 83.0L 83.5L 84.0L 84.5L 85.0L 85.5L 86.0L 86.5L 87.0L 87.5L 88.0L 88.5L 89.0L 89.5L 90.0L 90.5L 91.0L 91.5L 92.0L 92.5L 93.0L 93.5L 94.0L 94.5L 95.0L 95.5L 96.0L 96.5L 97.0L 97.5L 98.0L 98.5L 99.0L 99.5L 100.0L 100.5L 101.0L 101.5L 102.0L 102.5L 103.0L 103.5L 104.0L 104.5L 105.0L 105.5L 106.0L 106.5L 107.0L 107.5L 108.0L 108.5L 109.0L 109.5L 110.0L 110.5L 111.0L 111.5L 112.0L 112.5L 113.0L 113.5L 114.0L 114.5L 115.0L 115.5L 116.0L 116.5L 117.0L 117.5L 118.0L 118.5L 119.0L 119.5L 120.0L 120.5L 121.0L 121.5L 122.0L 122.5L 123.0L 123.5L 124.0L 124.5L 125.0L 125.5L 126.0L 126.5L 127.0L 127.5L 128.0L 128.5L 129.0L 129.5L 130.0L 130.5L 131.0L 131.5L 132.0L 132.5L 133.0L 133.5L 134.0L 134.5L 135.0L 135.5L 136.0L 136.5L 137.0L 137.5L 138.0L 138.5L 139.0L 139.5L 140.0L 140.5L 141.0L 141.5L 142.0L 142.5L 143.0L 143.5L 144.0L 144.5L 145.0L 145.5L 146.0L 146.5L 147.0L 147.5L 148.0L 148.5L 149.0L 149.5L 150.0L 150.5L 151.0L 151.5L 152.0L 152.5L 153.0L 153.5L 154.0L 154.5L 155.0L 155.5L 156.0L 156.5L 157.0L 157.5L 158.0L 158.5L 159.0L 159.5L 160.0L 160.5L 161.0L 161.5L 162.0L 162.5L 163.0L 163.5L 164.0L 164.5L 165.0L 165.5L 166.0L 166.5L 167.0L 167.5L 168.0L 168.5L 169.0L 169.5L 170.0L 170.5L 171.0L 171.5L 172.0L 172.5L 173.0L 173.5L 174.0L 174.5L 175.0L 175.5L 176.0L 176.5L 177.0L 177.5L 178.0L 178.5L 179.0L 179.5L 180.0L 180.5L 181.0L 181.5L 182.0L 182.5L 183.0L 183.5L 184.0L 184.5L 185.0L 185.5L 186.0L 186.5L 187.0L 187.5L 188.0L 188.5L 189.0L 189.5L 190.0L 190.5L 191.0L 191.5L 192.0L 192.5L 193.0L 193.5L 194.0L 194.5L 195.0L 195.5L 196.0L 196.5L 197.0L 197.5L 198.0L 198.5L 199.0L 199.5L 200.0L 200.5L 201.0L 201.5L 202.0L 202.5L 203.0L 203.5L 204.0L 204.5L 205.0L 205.5L 206.0L 206.5L 207.0L 207.5L 208.0L 208.5L 209.0L 209.5L 210.0L 210.5L 211.0L 211.5L 212.0L 212.5L 213.0L 213.5L 214.0L 214.5L 215.0L 215.5L 216.0L 216.5L 217.0L 217.5L 218.0L 218.5L 219.0L 219.5L 220.0L 220.5L 221.0L 221.5L 222.0L 222.5L 223.0L 223.5L 224.0L 224.5L 225.0L 225.5L 226.0L 226.5L 227.0L 227.5L 228.0L 228.5L 229.0L 229.5L 230.0L 230.5L 231.0L 231.5L 232.0L 232.5L 233.0L 233.5L 234.0L 234.5L 235.0L 235.5L 236.0L 236.5L 237.0L 237.5L 238.0L 238.5L 239.0L 239.5L 240.0L 240.5L 241.0L 241.5L 242.0L 242.5L 243.0L 243.5L 244.0L 244.5L 245.0L 245.5L 246.0L 246.5L 247.0L 247.5L 248.0L 248.5L 249.0L 249.5L 250.0L 250.5L 251.0L 251.5L 252.0L 252.5L 253.0L 253.5L 254.0L 254.5L 255.0L 255.5L 256.0L 256.5L 257.0L 257.5L 258.0L 258.5L 259.0L 259.5L 260.0L 260.5L 261.0L 261.5L 262.0L 262.5L 263.0L 263.5L 264.0L 264.5L 265.0L 265.5L 266.0L 266.5L 267.0L 267.5L 268.0L 268.5L 269.0L 269.5L 270.0L 270.5L 271.0L 271.5L 272.0L 272.5L 273.0L 273.5L 274.0L 274.5L 275.0L 275.5L 276.0L 276.5L 277.0L 277.5L 278.0L 278.5L 279.0L 279.5L 280.0L 280.5L 281.0L 281.5L 282.0L 282.5L 283.0L 283.5L 284.0L 284.5L 285.0L 285.5L 286.0L 286.5L 287.0L 287.5L 288.0L 288.5L 289.0L 289.5L 290.0L 290.5L 291.0L 291.5L 292.0L 292.5L 293.0L 293.5L 294.0L 294.5L 295.0L 295.5L 296.0L 296.5L 297.0L 297.5L 298.0L 298.5L 299.0L 299.5L 300.0L 300.5L 301.0L 301.5L 302.0L 302.5L 303.0L 303.5L 304.0L 304.5L 305.0L 305.5L 306.0L 306.5L 307.0L 307.5L 308.0L 308.5L 309.0L 309.5L 310.0L 310.5L 311.0L 311.5L 312.0L 312.5L 313.0L 313.5L 314.0L 314.5L 315.0L 315.5L 316.0L 316.5L 317.0L 317.5L 318.0L 318.5L 319.0L 319.5L 320.0L 320.5L 321.0L 321.5L 322.0L 322.5L 323.0L 323.5L 324.0L 324.5L 325.0L 325.5L 326.0L 326.5L 327.0L 327.5L 328.0L 328.5L 329.0L 329.5L 330.0L 330.5L 331.0L 331.5L 332.0L 332.5L 333.0L 333.5L 334.0L 334.5L 335.0L 335.5L 336.0L 336.5L 337.0L 337.5L 338.0L 338.5L 339.0L 339.5L 340.0L 340.5L 341.0L 341.5L 342.0L 342.5L 343.0L 343.5L 344.0L 344.5L 345.0L 345.5L 346.0L 346.5L 347.0L 347.5L 348.0L 348.5L 349.0L 349.5L 350.0L 350.5L 351.0L 351.5L 352.0L 352.5L 353.0L 353.5L 354.0L 354.5L 355.0L 355.5L 356.0L 356.5L 357.0L 357.5L 358.0L 358.5L 359.0L 359.5L 360.0L 360.5L 361.0L 361.5L 362.0L 362.5L 363.0L 363.5L 364.0L 364.5L 365.0L 365.5L 366.0L 366.5L 367.0L 367.5L 368.0L 368.5L 369.0L 369.5L 370.0L 370.5L 371.0L 371.5L 372.0L 372.5L 373.0L 373.5L 374.0L 374.5L 375.0L 375.5L 376.0L 376.5L 377.0L 377.5L 378.0L 378.5L 379.0L 379.5L 380.0L 380.5L 381.0L 381.5L 382.0L 382.5L 383.0L 383.5L 384.0L 384.5L 385.0L 385.5L 386.0L 386.5L 387.0L 387.5L 388.0L 388.5L 389.0L 389.5L 390.0L 390.5L 391.0L 391.5L 392.0L 392.5L 393.0L 393.5L 394.0L 394.5L 395.0L 395.5L 396.0L 396.5L 397.0L 397.5L 398.0L 398.5L 399.0L 399.5L 400.0L 400.5L 401.0L 401.5L 402.0L 402.5L 403.0L 403.5L 404.0L 404.5L 405.0L 405.5L 406.0L 406.5L 407.0L 407.5L 408.0L 408.5L 409.0L 409.5L 410.0L 410.5L 411.0L 411.5L 412.0L 412.5L 413.0L 413.5L 414.0L 414.5L 415.0L 415.5L 416.0L 416.5L 417.0L 417.5L 418.0L 418.5L 419.0L 419.5L 420.0L 420.5L 421.0L 421.5L 422.0L 422.5L 423.0L 423.5L 424.0L 424.5L 425.0L 425.5L 426.0L 426.5L 427.0L 427.5L 428.0L 428.5L 429.0L 429.5L 430.0L 430.5L 431.0L 431.5L 432.0L 432.5L 433.0L 433.5L 434.0L 434.5L 435.0L 435.5L 436.0L 436.5L 437.0L 437.5L 438.0L 438.5L 439.0L 439.5L 440.0L 440.5L 441.0L 441.5L 442.0L 442.5L 443.0L 443.5L 444.0L 444.5L 445.0L 445.5L 446.0L 446.5L 447.0L 447.5L 448.0L 448.5L 449.0L 449.5L 450.0L 450.5L 451.0L 451.5L 452.0L 452.5L 453.0L 453.5L 454.0L 454.5L 455.0L 455.5L 456.0L 456.5L 457.0L 457.5L 458.0L 458.5L 459.0L 459.5L 460.0L 460.5L 461.0L 461.5L 462.0L 462.5L 463.0L 463.5L 464.0L 464.5L 465.0L 465.5L 466.0L 466.5L 467.0L 467.5L 468.0L 468.5L 469.0L 469.5L 470.0L 470.5L 471.0L 471.5L 472.0L 472.5L 473.0L 473.5L 474.0L 474.5L 475.0L 475.5L 476.0L 476.5L 477.0L 477.5L 478.0L 478.5L 479.0L 479.5L 480.0L 480.5L 481.0L 481.5L 482.0L 482.5L 483.0L 483.5L 484.0L 484.5L 485.0L 485.5L 486.0L 486.5L 487.0L 487.5L 488.0L 488.5L 489.0L 489.5L 490.0L 490.5L 491.0L 491.5L 492.0L 492.5L 493.0L 493.5L 494.0L 494.5L 495.0L 495.5L 496.0L 496.5L 497.0L 497.5L 498.0L 498.5L 499.0L 499.5L 500.0L 500.5L 501.0L 501.5L 502.0L 502.5L 503.0L 503.5L 504.0L 504.5L 505.0L 505.5L 506.0L 506.5L 507.0L 507.5L 508.0L 508.5L 509.0L 509.5L 510.0L 510.5L 511.0L 511.5L 512.0L 512.5L 513.0L 513.5L 514.0L 514.5L 515.0L 515.5L 516.0L 516.5L 517.0L 517.5L 518.0L 518.5L 519.0L 519.5L 520.0L 520.5L 521.0L 521.5L 522.0L 522.5L 523.0L 523.5L 524.0L 524.5L 525.0L 525.5L 526.0L 526.5L 527.0L 527.5L 528.0L 528.5L 529.0L 529.5L 530.0L 530.5L 531.0L 531.5L 532.0L 532.5L 533.0L 533.5L 534.0L 534.5L 535.0L 535.5L 536.0L 536.5L 537.0L 537.5L 538.0L 538.5L 539.0L 539.5L 540.0L 540.5L 541.0L 541.5L 542.0L 542.5L 543.0L 543.5L 544.0L 544.5L 545.0L 545.5L 546.0L 546.5L 547.0L 547.5L 548.0L 548.5L 549.0L 549.5L 550.0L 550.5L 551.0L 551.5L 552.0L 552.5L 553.0L 553.5L 554.0L 554.5L 555.0L 555.5L 556.0L 556.5L 557.0L 557.5L 558.0L 558.5L 559.0L 559.5L 560.0L 560.5L 561.0L 561.5L 562.0L 562.5L 563.0L 563.5L 564.0L 564.5L 565.0L 565.5L 566.0L 566.5L 567.0L 567.5L 568.0L 568.5L 569.0L 569.5L 570.0L 570.5L 571.0L 571.5L 572.0L 572.5L 573.0L 573.5L 574.0L 574.5L 575.0L 575.5L 576.0L 576.5L 577.0L 577.5L 578.0L 578.5L 579.0L 579.5L 580.0L 580.5L 581.0L 581.5L 582.0L 582.5L 583.0L 583.5L 584.0L 584.5L 585.0L 585.5L 586.0L 586.5L 587.0L 587.5L 588.0L 588.5L 589.0L 589.5L 590.0L 590.5L 591.0L 591.5L 592.0L 592.5L 593.0L 593.5L 594.0L 594.5L 595.0L 595.5L 596.0L 596.5L 597.0L 597.5L 598.0L 598.5L 599.0L 599.5L 600.0L 600.5L 601.0L 601.5L 602.0L 602.5L 603.0L 603.5L 604.0L 604.5L 605.0L 605.5L 606.0L 606.5L 607.0L 607.5L 608.0L 608.5L 609.0L 609.5L 610.0L 610.5L 611.0L 611.5L 612.0L 612.5L 613.0L 613.5L 614.0L 614.5L 615.0L 615.5L 616.0L 616.5L 617.0L 617.5L 618.0L 618.5L 619.0L 619.5L 620.0L 620.5L 621.0L 621.5L 622.0L 622.5L 623.0L 623.5L 624.0L 624.5L 625.0L 625.5L 626.0L 626.5L 627.0L 627.5L 628.0L 628.5L 629.0L 629.5L 630.0L 630.5L 631.0L 631.5L 632.0L 632.5L 633.0L 633.5L 634.0L 634.5L 635.0L 635.5L 636.0L 636.5L 637.0L 637.5L 638.0L 638.5L 639.0L 639.5L 640.0L 640.5L 641.0L 641.5L 642.0L 642.5L 643.0L 643.5L 644.0L 644.5L 645.0L 645.5L 646.0L 646.5L 647.0L 647.5L 648.0L 648.5L 649.0L 649.5L 650.0L 650.5L 651.0L 651.5L 652.0L 652.5L 653.0L 653.5L 654.0L 654.5L 655.0L 655.5L 656.0L 656.5L 657.0L 657.5L 658.0L 658.5L 659.0L 659.5L 660.0L 660.5L 661.0L 661.5L 662.0L 662.5L 663.0L 663.5L 664.0L 664.5L 665.0L 665.5L 666.0L 666.5L 667.0L 667.5L 668.0L 668.5L 669.0L 669.5L 670.0L 670.5L 671.0L 671.5L 672.0L 672.5L 673.0L 673.5L 674.0L 674.5L 675.0L 675.5L 676.0L 676.5L 677.0L 677.5L 678.0L 678.5L 679.0L 679.5L 680.0L 680.5L 681.0L 681.5L 682.0L 682.5L 683.0L 683.5L 684.0L 684.5L 685.0L 685.5L 686.0L 686.5L 687.0L 687.5L 688.0L 688.5L 689.0L 689.5L 690.0L 690.5L 691.0L 691.5L 692.0L 692.5L 693.0L 693.5L 694.0L 694.5L 695.0L 695.5L 696.0L 696.5L 697.0L 697.5L 698.0L 698.5L 699.0L 699.5L 700.0L 700.5L 701.0L 701.5L 702.0L 702.5L 703.0L 703.5L 704.0L 704.5L 705.0L 705.5L 706.0L 706.5L 707.0L 707.5L 708.0L 708.5L 709.0L 709.5L 710.0L 710.5L 711.0L 711.5L 712.0L 712.5L 713.0L 713.5L 714.0L 714.5L 715.0L 715.5L 716.0L 716.5L 717.0L 717.5L 718.0L 718.5L 719.0L 719.5L 720.0L 720.5L 721.0L 721.5L 722.0L 722.5L 723.0L 723.5L 724.0L 724.5L 725.0L 725.5L 726.0L 726.5L 727.0L 727.5L 728.0L 728.5L 729.0L 729.5L 730.0L 730.5L 731.0L 731.5L 732.0L 732.5L 733.0L 733.5L 734.0L 734.5L 735.0L 735.5L 736.0L 736.5L 737.0L 737.5L 738.0L 738.5L 739.0L 739.5L 740.0L 740.5L 741.0L 741.5L 742.0L 742.5L 743.0L 743.5L 744.0L 744.5L 745.0L 745.5L 746.0L 746.5L 747.0L 747.5L 748.0L 748.5L 749.0L 749.5L 750.0L 750.5L 751.0L 751.5L 752.0L 752.5L 753.0L 753.5L 754.0L 754.5L 755.0L 755.5L 756.0L 756.5L 757.0L 757.5L 758.0L 758.5L 759.0L 759.5L 760.0L 760.5L 761.0L 761.5L 762.0L 762.5L 763.0L 763.5L 764.0L 764.5L 765.0L 765.5L 766.0L 766.5L 767.0L 767.5L 768.0L 768.5L 769.0L 769.5L 770.0L 770.5L 771.0L 771.5L 772.0L 772.5L 773.0L 773.5L 774.0L 774.5L 775.0L 775.5L 776.0L 776.5L 777.0L 777.5L 778.0L 778.5L 779.0L 779.5L 780.0L 780.5L 781.0L 781.5L 782.0L 782.5L 783.0L 783.5L 784.0L 784.5L 785.0L 785.5L 786.0L 786.5L 787.0L 787.5L 788.0L 788.5L 789.0L 789.5L 790.0L 790.5L 791.0L 791.5L 792.0L 792.5L 793.0L 793.5L 794.0L 794.5L 795.0L 795.5L 796.0L 796.5L 797.0L 797.5L 798.0L 798.5L 799.0L 799.5L 800.0L 800.5L 801.0L 801.5L 802.0L 802.5L 803.0L 803.5L 804.0L 804.5L 805.0L 805.5L 806.0L 806.5L 807.0L 807.5L 808.0L 808.5L 809.0L 809.5L 810.0L 810.5L 811.0L 811.5L 812.0L 812.5L 813.0L 813.5L 814.0L 814.5L 815.0L 815.5L 816.0L 816.5L 817.0L 817.5L 818.0L 818.5L 819.0L 819.5L 820.0L 820.5L 821.0L 821.5L 822.0L 822.5L 823.0L 823.5L 824.0L 824.5L 825.0L 825.5L 826.0L 826.5L 827.0L 827.5L 828.0L 828.5L 829.0L 829.5L 830.0L 830.5L 831.0L 831.5L 832.0L 832	
--	--



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022617/K1tbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 22-12-2017		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4037M	Veh. Inspected	SHC 6991P	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010927MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	27/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5657644	Colour	SILVER	
Odometer	264389	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	7 mm	
L/H Front Tyre	205/65 R16	ACHILLES	7 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/11/2017	Inspection Date	11/12/2017	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6991P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	N/S MIRROR ASSY	CRACKED	590.00	590.00
	LESS 10% DISCOUNT		-59.00	-59.00
			531.00	531.00
	SPECIAL NETT ITEMS			
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			50.00	20.00
	LABOUR			
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE FRONT N/S FENDER ETC.		500.00	300.00
	TO PUTTY AND SPRAY PAINTING ON FRONT N/S FENDER,N/S MIRROR.		350.00	230.00
			850.00	530.00
	GRAND TOTAL		1,431.00	1,081.00
RECOMMENDED COST OF REPAIRS				1,081.00

Report Ref No. CS/FCI17022617/K1tbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.