SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Contact Number

EMail Address

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

atoresald.	
	ACCIDENT STATEMENT
Date Of Report	28/11/2017 14:37
Date Of Accident	28/11/2017 09:30
Exact Location Of Accident	CARPARK LOT32 @BLK27 CHAI CHEE RD NEAR EXIT GANTRY
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SFD4002B
Insured/Policyholder	
Name Of Registered Owner	TAN LIP LIN
NRIC No	S2010956D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93574386
Alternative Phone No	OFFICE-93574386
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	E200 ML
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00424661
Cover Note Number	-
Driver	
Name of Driver	TAN LIP LIN
NRIC No	S2010956D
Date Of Birth	08/11/1951
Occupation	INDOOR
Date Of Driving Pass	02/02/1971
Driving Experience	46 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93574386
Fax Number	

OFFICE-93574386

NOEMAIL

Address 69 TERANG BULAN AVE

Postcode 455592

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident COLLIDED INTO PARKED VEHICLE

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Number of Passengers (Including Driver)

Police Station Name BEDOK SOUTH NEIGHBOURHOOD POLICE CENTRE

0

Police Station Address ROAD: 20 CHAI CHEE DRIVE, POSTCODE: 469045, COUNTRY:

SINGAPORE

Police Station Contact **TEL NO**: 1800-2448999 - **FAX NO**: 62446558

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? YES

Remarks/ Reasons: WITH DRIVER

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GX2718R

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number Email Address

	BLK 27A
Ushicus A - SAD 40028	
15 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	A
Nemicre B - Exsdisk	
	TANK
	RE VERSINE
	L
	BLK 27
SCRIBE CIRCUMSTANCES OF THE ACCIDENT	
AS PER POLICE REPORT	Risorn Number
	7/20171128/2049
Vehicle A - SF04002B	
VEHICLE B- GXZ718R	
Verriodic 13 - Cratification	
DECLARATION	
DECLARATION //We declare the foregoing particulars are true in every respect	

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time

Driver's Signature

(If driver is not the policyholder) Date & Time:

NRIC/FIN No.:

Reporting Centre Personnel's Signature

POLICE REPORT





1 of 3

Police Station Of Origin: Bedok South N.P.C 20 Chai Chee Drive SINGAPORE 469045

Tel No: 1800-2448999

Report No. T/20171128/2049

REPORT O	F A TRAFFIC	ACCIDENT		Otation Diam No.		
Date/Time Report Made: 28/11/2017 12:41			Vide Report No.;	Station Diary No. 25		
Informa	nt's Particu	ulars	THE RESERVE OF THE SECOND			
Name of Informant: TAN LIP LIN			Address: 69 TERANG BULAN AVENUE SINGAPORE 455592			
ID Type / ID No.: NRIC NO / S2010956D			Contact No.: Home/Office:	Mobile: 93574386		
Nationality: SINGAPORE CITIZEN			Email:			
Sex: Age: Date of Birth:			Type of Informant: Vehicle Owner			
Race: Chinese			Language: English	Institution / School Name:		
Occupation: Retiree			Driving Licence Information: Class: 3	Date of Expiry:		

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 28/11/2017 09:30	Type of Location Car Park
Location: Along Road (CHAI CHEE	ROAD	CHAI CHEE ROAD.	NEAR TO EXIT GANTR	Υ
Weather:	01 110.02 OF BESTEE	Road Surface: Dry		Road Speed Limit:
Clear				
Clear Traffic Flow: One Way		Traffic Control:		Traffic Volume: Anyone conveyed by

Details of V	emcie mvo	The second secon	Taxable 1	Color	Condition	No of Passenge
Vehicle No.	Type	Make	Model	Color	Condition	140 or r aboutings
GX2718R	Van	TOYOTA	HIACE	White		0
SFD4002B	Car	MERCEDES BENZ	E200	Beige	Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	The state of the s
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT



Police Station Of Origin: Bedok South N.P.C 20 Chai Chee Drive SINGAPORE 469045 Tel No: 1800-2448999

2 of 3 Report No. T/20171128/2049

CONTINUATION OF REPORT

Vehicle Owner	The state of the s		120-120-1			000100100
Name	TAN LIP LIN			ID No.		S2010956D
Related Vehicle	SFD4002B (Car)			Conta	ct No.	93574386
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g	Class: 3 Date of Expiry: NIL
Date Treatment	NIL Date D				NIL	
No. of Days granted Medical Leave NIL Degree				finjury	NIL	

Brief Details.

On the 28/11/17 at about 0920hrs, I parked and secured my vehicle bearing registration umber SFD4002B at Lot No. 32, which was a parallel parking lot, at the above mentioned location and left to do some marketing. Everything was intact and in order.

At about 1000hrs, I came back to my car and discovered my front bumper cracked and the left two headlights scratched. There was no note left behind on my vehicle.

I then viewed the footage from my in-car camera and it was established that at about 0932hrs, one van bearing registration number GX2718R, had stopped in front of my parked vehicle, where he was observed to be reversing and collided onto the front part of my vehicle. The driver was later seen realigning himself to the kerb, before coming out to make a check on my vehicle.

I wish to state my vehicle was parked nearest to the exit gantry of the carpark and there was no lot in front of me. The van had parked along the double yellow lines, before later leaving prior my discovery.

I wish to further state that I am able to provide the footage from my in-car camera.

POLICE REPORT





Police Station Of Origin: Bedok South N.P.C 20 Chai Chee Drive SINGAPORE 469045 Tel No: 1800-2448999 3 of 3 Report No. T/20171128/2049

CONTINUATION OF REPORT


٠		2	D	h	tc	-	L	C	
	ı	а	ы	n	tr	•	w	•	

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Sgt 3 MUHAMMAD AZHAR BIN MISSUAN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 28/11/2017 12:41
Officer In Charge Of Case: TP / HRT / SI KALESWARI PALANI Contact No.: 65476902	Classification Of Case:
Authoritication Stamp Signature: Singapore Police Force	




















120 140 160 80 180 After start 1:55 h 28 km 15 km/h 18.0 l/100 km 0 km/h 283.3 km 260 km/h P 116343 km C

