

ASS. REC. BY:

REF: CS/FWD17022635/Gvbs24 Special Instruction:

SURVEYOR  
Merimen

60

ASSIGNMENT (Office)

From (Person): Clara Li of FWD Date/Time: 27/11/17 @ 5:20pm

Estimated Cost: Bill to:

OD /  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV /  CS

To Inspect Vehicle No: SKL 7118 E Insured:

at Workshop m/s Kan Fook Sing Tel: 6747 9560

of No. 61 Defu Lane 12 539147

Policy No: PNPV 2017-00004365 Claim No:

Sum Insured: Excess: TBA 500

Make of Veh: D.O.A. 25/11/2017  
(Client's Record)

CA /  REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 11:19am @ 28/11/17 Person Contacted: Yen Vehicle: IN 1011

Date/Time	Action/Instruction (✓) Estimate
	SKL 7118E - X
29/11/17	@ 11:25am part said repair cost est \$20K
29/11/17	Revert vehicle TL by merimen
29/11/17	Submit Ext TL - mv: \$82K (EST) HTA = \$66,010 NV: \$15,990



## Survey Department Check List (Case Handler)

Reference No.: CS/FWD 17022635/Grb  
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin** ( ): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form		Case Handler		Typist	
		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor** ( ): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Case Handler	Typist
C	Vehicle No	✓	
C	Regn Month/Year	✓	
N	Vehicle Type	✓	
N	Make & Model	✓	
C	Engine Capacity. (C.C)	✓	
N	Colour	✓	
C	Odometer. (Sp.Reading)	✓	
C	Chassis No	✓	
N	General Condition	✓	
N	Steering	✓	
N	Brake	✓	
N	Modification (Modi)	✓	
C	Tyre Size	✓	
N	Tyre Make	✓	
C	Tyre Balance	✓	
C	Date of Inspection	✓	
N	Survey held	✓	
N	Des.of Damages	✓	

(2) System - (Views/Merimen)		Case Handler	Typist
C	Damaged Vehicle Photographs Uploaded	✓	

(3) Workshop Estimate/Assignment Form		Case Handler	Typist
N	ALL Parts condition		
C	Market Value for OD cases	✓	
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)		
C	Days of repair		
C	Finalised Amount		
C	Re-inspection Cases to Finalize within 5 Days		

(4) System - (Views/Merimen)		Case Handler	Typist
C	Resurvey photo Uploaded		

Check By: VERON 29/11/17  
 Case Handler                      Date

\*C: Critical \*N: Non-Critical



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FWD SINGAPORE PTE LTD		Ref : CS/FWD17022635/Gvb	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986		Date : 28-11-2017	
		Code : FWD	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SKL 7118E
Policy No.	PNPV2017-00004365	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (CLARA LI)	Assign Date	27/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/11/2017	Inspection Date	28/11/2017
Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Nov 2017 16:46 <a href="#">Sendback Est</a>	27 Nov 2017 16:46 <b>S\$0.00</b>	27 Nov 2017 17:20 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	LEONG KHIN MUN ARNOLD, ID: S6908413C, Tel: +6596793629, Email: arnold.leongkm@gmail.com		
Vehicle Reg. No.:	SKL7118E	Date of Loss:	25/11/2017 16:00 - :59
Claim Type:	OD	Policy/Cover Note No.:	PNPV2017-00004365 (Comprehensive)
		Excess:	
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/12/2017]		
Driver/Custodian:	LEONG KHIN MUN ARNOLD (48 / Male), NRIC: S6908413C, Tel: +6596793629		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

### View Received Message

This mail is associated with :  
**SKL7118E (1201700008223)**  
OD  
Nov 25 2017 4:00PM  
[LEONG KHIN MUN ARNOLD]  
Kan Fook Sing Motor Workshop

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

**From** FWD Singapore Pte. Ltd. (HQ) (FWD\_SG), sent on 29/11/2017 14:23 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Revoked - SKL7118E - Claim Handler: Clara Li Zi Rong

Revoked.

**DOCUMENTS SUMMARY**  
There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Clara Li Zi Rong	Date: 29 Nov 2017

### Preliminary Advice

Vehicle No	: SKL7118E	Accident Date	: 25/11/2017
Make	: TOYOTA WISH	Policy No.	: PNPV2017-00004365
Assignment Date	: 27/11/2017	Excess	: S\$0.00
Date of Inspection	: 28/11/2017	Est. Duration of Repair	: 0.00
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) NO. 61 DEFU LANE 12 SINGAPORE 539147		

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

#### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	66,010.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,990.00

#### Remarks

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the judgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/11/2017 12:22
Date Of Accident	25/11/2017 16:15
Exact Location Of Accident	NORTH SOUTH H'WAY MSIA NEAR MALAKA
Country/State of Loss	MALAYSIA/MELAKA

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL7118E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEONG KHIN MUN ARNOLD
Work Permit No	S6908413C
Email Address	ARNOLD.LEONGKM@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96793629
Alternative Phone No	OFFICE-96793629

### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00004365
Cover Note Number	

### Driver

Name of Driver	LEONG KHIN MUN ARNOLD
Work Permit No	S6908413C
Date Of Birth	22/03/1969
Occupation	INDOOR
Date Of Driving Pass	02/09/1986
Driving Experience	31 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96793629
Fax Number	
Contact Number	OFFICE-96793629
EMail Address	ARNOLD.LEONGKM@GMAIL.COM

Name	NA
Phone Number	NA
Email Address	NA

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
Address	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	NA
Phone Number	NA
Email Address	NA

#### DETAILS OF INJURED PERSON 1

Name	LEE LI HUI
Approximate Age	
Injuries Sustain	HEAD, CUT ON RIGHT EYE AND BRUISE ON HANDS & LEGS
Injured person in which vehicle?	SKL7118E
Were seat belts worn?	YES
Was injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

#### DETAILS OF INJURED PERSON 2

Name	LEONG KHIM MUN ARNOLD
Approximate Age	
Injuries Sustain	NECK & BACK
Injured person in which vehicle?	SKL7118E
Were seat belts worn?	
Was injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

#### DETAILS OF INJURED PERSON 3

Name	UNKNOWN
Approximate Age	
Injuries Sustain	LEG
Injured person in which vehicle?	BEC6827
Were seat belts worn?	
Was injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

#### DETAILS OF INJURED PERSON 4

Name	UNKNOWN
------	---------

## Accident Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

*Lh*

Policyholder's Signature  
Date & Time:

*Lh* 27/11/17 1240

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	8413C
Vehicle Details	
Vehicle No.	SKL7118E
Vehicle to be Exported	No
Intended De-registration Date	29 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	WISH CVT
Primary Colour	Beige
Manufacturing Year	2013
Engine No.	2ZR1321593
Chassis No.	JTDGG20W00J000505
Maximum Power Output	105.0 kW (140 bhp)
Open Market Value	\$23,453.00
Original Registration Date	17 Dec 2013
First Registration Date	17 Dec 2013
Transfer Count	1
Actual ARF Paid	\$19,835.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	16 Dec 2023
PARF Rebate Amount	\$14,876.00
Intended COE Rebate Details	
COE Expiry Date	16 Dec 2023
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$84,578.00
COE Rebate Amount	\$51,134.00
<b>Total Rebate Amount</b>	<b>\$66,010.00</b>

The information contained herein is correct as at 29 Nov 2017

OK



Vote for your favourite car!

All Car Make or Model

Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS &amp; TIPS

**A-Assurance**  
 Assurance in Insurance

**Car Insurance Expiring?**  
 We get you the cheapest insurance renewal

Click to get quote



Username / Email Add

password

Login

Connect

 Sign Up New Account  
 Forgot Password

**Post an Advertisement**  
 Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

**New 5 Year Coe Renewal 2007 Toyota Estima 2.4A Aeras**

**\$6800 Downpayment Monthly**  
 From \$889 Onwards, Lowest  
 3.88%P.A@ GV Cars Financing  
 GV Credit Pte Ltd - StarAd


Think One Automobile

**NEW & USED**  
**COMMERCIAL VEHICLES**


Browse by Category

Save Search

Print

Sort by Reg. Date

20 results/page

4 vehicles

Search toyota wish

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection toyota wish Any Any 2013 Any Any Any Available


 Toyota Wish 1.8A

\$83,800

\$12,290 /yr

03-Dec-2013

1,798 cc

64,167 km

MPV

Available

Graded **B** by **STP**

Sta Graded 'B'.1 Owner Toyota Wish 1.8a Cvt. 5 Years Warranty Til 18/12/2018. Original Interior And Exterior.High Paper Value, High Coe Value. Call Now For Viewing

Autolink Holdings Pte Ltd

Posted: 27-Nov-2017 Tags: 2013 Toyota Wish, 2013 Toyota Wish, Toyota Wish, Toyota Wish, Toyota Wish, Wish, Used Toyota

Details


 Toyota Wish 1.8A

\$83,800

\$12,950 /yr

14-Aug-2013

1,798 cc

30,000 km

MPV

Available

At Borneo Motors Singapore, Only The Best Can Meet The Mark. When You Purchased A Toyota Certified Pre Owned, You Can Be Confident It Will Perform Like The Day It Left The Showroom.

Borneo Motors (S)

Posted: 27-Sep-2017 Tags: 2013 Toyota Wish, 2013 Toyota Wish, Toyota Wish, Toyota Wish, Toyota Wish, Wish, Used Toyota

Details


 Toyota Wish 1.8A

\$76,800

\$12,300 /yr

08-May-2013

1,798 cc

90,000 km

MPV

Available

1 Owner Toyota Wish 1.8A CVT With Agent Maintained Since New. 5 Years Warranty. Original Interior And Exterior. Accident Free. High Paper Value, High COE Value. Call Now For Viewing

Posted: 25-Nov-2017 Tags: 2013 Toyota Wish, 2013 Toyota Wish, Toyota Wish, Toyota Wish, Toyota Wish, Wish, Used Toyota

Details


 Toyota Wish 1.8A

\$76,500

\$12,340 /yr

22-Apr-2013

1,798 cc

85,400 km

MPV

Available

Cheapest In Market, 1 Owner, Best Selling MPV In Market, Well Maintained, Borneo Unit, High Loan Available, Price Negotiable.

Posted: 25-Nov-2017 Tags: 2013 Toyota Wish, 2013 Toyota Wish, Toyota Wish, Toyota Wish, Toyota Wish, Wish, Used Toyota

Details

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used toyota wish, toyota wish Singapore, used toyota wish Singapore, used toyota wish, used vehicles Singapore or even buy used toyota wish Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- About Us
- Careers
- Contact Us
- Sitemap



簡福星噴呔工廠  
KAN FOOK SING MOTOR WORKSHOP

51 Defu Lane 12 Singapore 539147  
Tel (65) 6747 9560, 6858 2126, 6858 4381  
Fax (65) 6748 1006, 6281 8428  
E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg. No. 201408034  
UIC Reg. No. M9 00031014

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00004365	Date of Loss:	25/11/2017
Vehicle Reg. No.:	SKL7118E	Driveable?	
Driver Age/Info:	48 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	LEONG KHIN MUN ARNOLD	Contact No:	+6596793629
Driver:	LEONG KHIN MUN ARNOLD		
Make/Model:	TOYOTA WISH, 1.8 X (ZGE20) (A)	Vehicle Reg. Date:	17/12/2013
Vehicle Colour:	GOLD	Chassis No:	JTDGG20W00J000505
Engine No:	2ZR1321593		
Odometer:	0 KM		
Paint Type:			
Total Loss?	YES		
Est. Duration of Repair (day)	30		
Description of Accident/Loss	REFER TO ATTACHED POLICE REPORT		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	0.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
<b>Nett Amount (S\$)</b>	<b>0.00</b>

**This claim is handled by: TAN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	27 Nov 2017	27 Nov 2017 16:46 <b>S\$0.00</b>	27 Nov 2017 17:20 Edit Adj Rpt	<b>S\$0.00</b> Edit Estimates	<b>S\$0.00</b> View Rpt	<b>Pending for Survey Report</b>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS	
<b>Insured:</b>	LEONG KHIN MUN ARNOLD, ID: S6908413C, Tel: +6596793629, Email: arnold.leongkm@gmail.com
<b>Vehicle Reg. No.:</b>	SKL7118E
<b>Date of Loss:</b>	25/11/2017 16:00 - :59
<b>Claim Type:</b>	OD / 1201700008223
<b>Policy/Cover Note No.:</b>	PNPV2017-00004365 (Comprehensive)
<b>Excess:</b>	S\$500.00
<b>Repairer:</b>	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560
<b>Handling Insurer:</b>	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 06/12/2017]
<b>Driver/Custodian:</b>	LEONG KHIN MUN ARNOLD (48 / Male), NRIC: S6908413C, Tel: +6596793629
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>	
<ul style="list-style-type: none"> <li>FWD_SG (29/11/2017): Alert - Adj Mandate Revoked - SKL7118E - Claim Handler: Clara Li Zi Rong</li> </ul>	
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>	
<b>Due Date</b>	<b>Priority</b>
<b>Type</b>	<b>Task Group</b>
<b>Subject</b>	<b>Handler</b>
<b>Assigned By</b>	<b>Completed On</b>
<b>Created On</b>	<b>Done?</b>
No results.	

### Claim Documents

**SKL7118E (1201700008223)**  
**OD**  
**Nov 25 2017 4:00PM**  
**[LEONG KHIN MUN ARNOLD]**  
**Kan Fook Sing Motor Workshop**

Upload Documents		Upload Photos		Compose New Letter		View Use Viewer	
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print		
1	27/11/17 16:46	<b>Repairer Estimates</b>		Load HTM			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	29/11/17 11:27	<b>Adjuster Immediate Advice</b>		Load HTM			
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
2	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
3	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
4	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
5	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
6	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
7	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
8	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
9	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
10	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
11	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
12	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
13	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
14	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
15	29/11/17 11:19	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print		
1	27/11/17 16:46	<b>E-filed GIA report</b>		Load PDF			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	29/11/17 11:36	<b>Log card (if available)</b>		Load PDF			

### Linked Accident Report Documents

				View Use Viewer			
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print		
1	27/11/17 15:45	<b>Accident Statement</b>		Load HTM			
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print		
1	27/11/17 12:58	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
2	27/11/17 12:58	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
3	27/11/17 12:58	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
4	27/11/17 12:58	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
5	27/11/17 12:58	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
6	27/11/17 12:58	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
7	27/11/17 12:58	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
8	27/11/17 12:58	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
9	27/11/17 12:58	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
10	27/11/17 12:58	<b>Accident Photo</b>		Load JPG	<input checked="" type="checkbox"/>		

11	27/11/17 12:58	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	27/11/17 12:58	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
13	27/11/17 12:58	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
14	27/11/17 12:58	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
15	27/11/17 12:58	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
16	27/11/17 12:58	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
17	27/11/17 12:58	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
18	27/11/17 12:58	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
19	27/11/17 12:58	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
20	27/11/17 12:58	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
21	27/11/17 12:58	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
22	27/11/17 12:58	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	Kan Fook Sing Motor Workshop (Defu)		<b>Thumbnail</b>	<b>Print</b>
1	27/11/17 13:05	Accident Sketch Plan		Load TIF	
2	27/11/17 13:05	Accident Sketch Plan		Load TIF	
3	27/11/17 13:05	POLICE REPORT		Load TIF	
4	27/11/17 13:05	NRIC & LICENCE		Load TIF	
5	27/11/17 13:05	NRIC & LICENCE		Load TIF	

### Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<p><b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b></p> <div style="border: 1px solid gray; height: 40px; width: 100%;"></div>				
<p><b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower 4  
Singapore 038986

Our File No: CS/FWD17022635/GVBS2

Date: 01/12/2017

## REFERENCE

Insured/Claimant: LEONG KHIN MUN ARNOLD Policy No: PNPV2017-00004365

Date of Loss: 25/11/2017

Nature of Claim: OD

Claim No: 1201700008223

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKL7118E	Engine No:	2ZR1321593
Make & Model:	TOYOTA WISH, 1.8 X (ZGE20) (A)	Chassis No:	JTDGG20W00J000505
Reg. Date:	17/12/2013 (Man. Year: 2013)	Odometer:	0 km
Colour:	Beige		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$82,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	215/50R17	Rear Tyre Size:	215/50R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	27/11/2017	Present Location:	Kan Fook Sing Motor Workshop (Defu)
Date Inspected:	28/11/2017	Inspected At:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12 Singapore 539147

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**TOTAL LOSS ASPECT**

Market Value :	\$82,000.00
OMV :	\$23,453.00
PARF Rebate (1) :	\$14,876.00
Quota Premium Paid :	\$84,578.00
COE Rebate (2) :	\$51,134.00
Total Rebate (1) + (2) = :	\$66,010.00

The total amount incurred will be Market Value \$82,000.00 minus Total Rebate \$66,010.00 = \$15,990.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 01 Dec 2017)
<b>Parts:</b> M1-MPV	TOYOTA WISH 1.8 X (ZGE20) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKL7118E)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

**There are no new parts selected.**

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

**There are no new miscellaneous items selected.**

### Recommended Labour

**There are no labour items selected.**

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >