

ASS. REC. BY:

REF: CS/TM47022639/Dtbsz

Special Instruction:

Surveyor: Bryan ASSIGNMENT (Office)From (Person): menmen Zheng Hanyang of TMI Date/Time: 28/11/2017 2.01pm

Estimated Cost: _____ Bill to: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SUM 1200Y Insured: _____at Workshop m/s Ah Lim Motor Tel: 6483 1244of Blk 10 Amk Ind Park 2A #01-09Policy No: MV0004875 Claim No: M1705581Sum Insured: _____ Excess: \$600.00Make of Veh: _____ D.O.A. 30.10.2017
(Client's Record)CA / REV / REP. / REV 24 HRS30.11.2017

H.O.D. Endorsement: _____

Date/Time: 28/11/2017 2.40pm Person Contacted: Wei Jie Vehicle IN / OUT

Date/Time	Action/Instruction () Estimate Investigation
	<u>Sum 1200Y - X</u>
<u>30/11</u>	<u>Revert via menmen, Pending Investigation</u>
	<u>Submit extensive damage.</u>
	<u>MV: 22K (TA: 10,000 (est)) NV: 12,000/- (use letter)</u>

SIRVUE

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 8LM1200Y Yr Regn: 2009 / June/6Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Corolla Altis C.C. 1598

Colour: _____ A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Michelin

Front _____ Rear _____

R/Bal. S' mm R/Bal. S' mmL/Bal. S' mm L/Bal. S' mmD.O.A. 31/10/2017 D.O.I. 30/11/2017Survey held at Ah Lim Motor AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The vehicle caught fire. Cause ofThe U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taken OD.

Total Loss.

Vehicle has been de-registered. Unable to print LTA.
Need to obtain from owner.MV pending further information / documents.
MV 22K.

LTA 10K → using Simdu make and model.

HL 12K → approximate.

Fire likely due to electrical nature.
Pending investigations.

Date/Time: File Pass to?

☐

Preli. Report

1) 15/12 Typist☒

Final Report

Date/Time: File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photos

Others

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

TOTAL

380

10

RECEIVED 15 DEC 2017

50018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD

Ref : CS/TMI17022639/Dtb

20 MCCALLUM STREET #09-01

TOKIO MARINE CENTRESINGAPORE 069046

Date : 28-11-2017



Code : TMI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLM 1200Y
Policy No.	MV004875	Coverage (\$)	0.00
Claim No.	M1705581	Excess (\$)	600.00
Assign From	MERIMEN (ZHENG HANYANG)	Assign Date	28/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/10/2017	Inspection Date	28/11/2017
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2017 Sendback Est	28 Nov 2017 13:15 S\$10.00	28 Nov 2017 14:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: ANG KIAN HUAT, ID: S17426381, Tel: +6593435566, Email: NOEMAIL									
Vehicle Reg. No.: SLM1200Y		Date of Loss: 30/10/2017 03:00 - :59							
Claim Type: OD / M1705581		Policy/Cover Note No.: MV004875 (Comprehensive) Coverage: 06/06/2017 - 17/05/2018							
		Excess: S\$600.00							
Repairer: Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244									
Handling Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Zheng Hanyang - 65926416]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/12/2017]									
Driver/Custodian: ANG KIAN HUAT (51 / Male), NRIC: S17426381, Tel: +6593435566									
Adj Asg. Remarks: PLEASE NOTE: ===== 1. SPOKEN TO VERON. LKK AUTO 2. OI CAUGHT FIRE 3. PLEASE ASSIGN TO BYRAN TO INVESTIGATE THE CAUSE & SURVEY THE VEHICLE - 28.11.17(BW)									
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/10/2017 17:10
Date Of Accident	30/10/2017 03:20
Exact Location Of Accident	ANG MO KIO AVE 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM1200Y
Insured/Policyholder	
Name Of Registered Owner	ANG KIAN HUAT
NRIC No	S1742638I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93435566
Alternative Phone No	OTHERS-93435566

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MV004875
Cover Note Number	06/06/2017 - 17/05/2018

Driver

Name of Driver	ANG KIAN HUAT
NRIC No	S1742638I
Date Of Birth	09/01/1966
Occupation	INDOOR
Date Of Driving Pass	28/09/1983
Driving Experience	34 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93435566
Fax Number	
Contact Number	OTHERS-93435566
Email Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



F/20171030/2092

1 of 2

POLICE REPORT (NP299)

Report No. F/20171030/2092

Police Station Of Origin
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999


Date/Time Report Made 30/10/2017 13:28	Vide Report No. F/20171030/0062	Station Diary No. 77	
Name Of Informant ANG KIAN HUAT	Address APT BLK 427 ANG MO KIO AVENUE 3 #06-2612 SINGAPORE 560427		
ID Type / ID No. NRIC NO / S1742638I	Contact No. Home/Office	Mobile 93495566	
Nationality SINGAPORE CITIZEN	Email Address		
Occupation Carpenter	Sex Male	Age 51	Date of Birth 09/01/1966
Institution/School Name	Race Chinese		
Date/Time Of Incident 30/10/2017 03:20	Language English		
	Location Of Incident ANG MO KIO AVENUE 10 SINGAPORE		

Brief details.

On 30/10/17 at about 0320hrs I was driving my vehicle SLM1200Y along Ang Mo Kio Avenue 10. While I was near to a bus stop beside Blk 409 AMK Market, there was some smoke coming out from the front bonnet. I quickly braked and my vehicle mount the kerb. The fire started from the front bonnet as such I came out from the vehicle and asked around for help. A passer-by helped to call for the police. As I was in state of shock I left the place after seeking advice from my friend. Around 0530hrs I went back the incident location however my vehicle was no longer there. I am lodging this report for my own record purpose.

Signature Of Officer Recording The Report: F / Sgt 2 RAMESH S/O KOLILINGAM	
Signature Of Interpreter: Not applicable	
Officer In-Charge Of Case: F / Ang Mo Kio South N.P.C / Sgt 2 RAMESH S/O KOLILINGAM Contact No.: 64519999 TP 10 : Dylan Mah	
Authentication Stamp	

Signature Of Informant:
Date/Time: 30/10/2017 13:29
Classification Of Case:



Tokio Marine Insurance Singapore Ltd.

(Company Reg. No.: 192300014M) (GST Reg. No.: M2-000023-4)

20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046

T: (65) 6221 6111 F: (65) 6221 4355 / (65) 6224 0895 E: tmis@tokiomarine.com.sg W: www.tokiomarine.com

A member of the
Tokio Marine GroupTOKIO MARINE
INSURANCE GROUP

FORM MX1

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: 17-MV004875-R01 (Private Motor Car)

- | | | |
|--|--|--------------------------------|
| 1. Index Mark and Registration Number of Vehicle | SLM1200Y | Chassis No.: MR053ZEE106145252 |
| 2. Name of Policyholder | MR ANG KIAN HUAT | |
| 3. Effective date of the Commencement of Insurance for the purposes of the Act | 06/06/2017 | |
| 4. Date of Expiry of Insurance | 17/05/2018 | |
| 5. Persons or Class of Persons entitled to drive* | (a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his permission. | |
| 6. Limitations as to use* | Use only for social domestic and pleasure purposes and for the Policyholder's business.
The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade. | |

* Limitations rendered imperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost or destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account: 2403DDA

Insurance Plan:	Comprehensive Approved Workshop Plan	
Limit for total loss or theft:	Prevailing Market Value	
Policy Excess:	Own Damage Claims	SGD 600
	Windscreen Excess	SGD 100
Financial Interest:	HONG LEONG FINANCE LTD	

Tokio Marine Insurance Singapore Ltd.

Authorized Signature

AH LIM MOTOR COMPANY

No. 10, Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel : 6483 1244 Fax : 64836170
ST Reg No : M9-0007732-A

SURVEYOR COPY

Your Ref :

Date: 28/11/2017

Our Ref : VEHICLE NO. SLM1200Y
MODEL : TOYOTA COROLLA ALTIS 1.6A

M/S TOKIO MARINE INSURANCE SINGAPORE LTD
20 McCALLUM STREET
SINGAPORE 069046

Attention:- Motor Claims Department
Own Damage Claim

Dear Sirs

Accident involving our insured's Vehicle No. SLM1200Y on 30/10/2017


We refer to the above matter.

Vehicle sustained extremely extensive damages.

We are not putting up the estimate for the time being and kindly arrange for survey soonest possible. After the survey if there is a need, we will furnish the estimate accordingly.

Best Regards

Yours faithfully,


Zila
Ah Lim Motor Company

Ah Lim Motor Company

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Zheng Hanyang

Date: 30 Nov 2017

Preliminary Advice

Vehicle No	: SLM1200Y	Accident Date	: 30/10/2017
Make	: TOYOTA COROLLA ALTIS	Policy No.	: MV004875
Assignment Date	: 28/11/2017	Excess	: S\$600.00
Date of Inspection	: 30/11/2017	Est. Duration of Repair	: 0.00
Inspection At	: AH LIM MOTOR COMPANY (AMK) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle caught fire.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	TBA
COE / PARF Rebate	:S\$	TBA
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Pending Investigation. Please be informed that we are still checking with the insured on the PART/COE Rebate, as vehicle has been de-registered.
Market value pending further information/documents.

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A

#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg

GST Reg No: M9-0009639-E

INSURER: Tokio Marine Insurance Singapore Ltd (HQ)

SURVEYOR COPY

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MV004875	Date of Loss:	30/10/2017
Vehicle Reg. No.:	SLM1200Y	Driveable?	NO
Driver Age/Info:	51 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	NO
Insured/Claimant:	ANG KIAN HUAT	Contact No:	+6593435566
Driver:	ANG KIAN HUAT		
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Vehicle Reg. Date:	06/06/2009
Vehicle Colour:	SILVER	Gen Condition:	POOR
Engine No:	3ZZ4888635	Chassis No:	MR053ZEE106145252
Odometer:	0 KM		
Paint Type:			
Total Loss?	YES		
Est. Duration of Repair (day)	20		
Description of Accident/Loss	OI:SLM1200Y CAUGHT FIRE-HY - HY - ALONG ANG MO KIO AVE 10 REPORTED @AH LIM MOTOR(P) DRIVER=INSURED-27.11.17(BW) X'S WAIVED(\$600/-) X'S \$600/-(APPLICABLE FOR TOTAL LOSS) **NCD 50% **YOM 2009		
Remarks:	CAR TOW IN @ ALM AMK AUTOPOINT WORKSHOP		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	10.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	10.00
- Excess (S\$)	600.00
(S\$)	-590.00
+ GST 7.00% (S\$)	-41.30
Nett Amount (S\$)	-631.30

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Nov 2017)
Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Ah Lim Motor Company/SLM1200Y/28/11/2017 13:15
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

There are no new parts selected.

Ah Lim Motor Company/SLM1200Y/28/11/2017 13:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

There are no labour items selected.

Ah Lim Motor Company/SLM1200Y/28/11/2017 13:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	01 Nov 2017 Sendback Est	28 Nov 2017 13:15 S\$10.00	28 Nov 2017 14:01 Edit Adj Rpt	S\$10.00 Edit Estimates	S\$10.00 View Rpt	
						Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS																								
Insured: ANG KIAN HUAT, ID: S17426381, Tel: +6593435566, Email: NOEMAIL																								
Vehicle Reg. No.: SLM1200Y		Date of Loss:	30/10/2017 03:00 - :59																					
Claim Type: OD / M1705581		Policy/Cover Note No.:	MV004875 (Comprehensive) Coverage: 06/06/2017 - 17/05/2018																					
		Excess:	S\$600.00																					
Repairer: Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244																								
Handling Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Zheng Hanyang - 65926416]																								
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 07/12/2017]																								
Driver/Custodian: ANG KIAN HUAT (51 / Male), NRIC: S17426381, Tel: +6593435566																								
Adj Asg. Remarks: PLEASE NOTE: ===== 1. SPOKEN TO VERON, LKK AUTO 2. OI CAUGHT FIRE 3. PLEASE ASSIGN TO BYRAN TO INVESTIGATE THE CAUSE & SURVEY THE VEHICLE - 28.11.17(BW)																								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail																				
There are no mail for this case.																								
ALL ASSOCIATED TASKS																								
<div> View All Search Tasks Create New Task Complete </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

SLM1200Y (M1705581)
OD
Oct 30 2017 3:00AM
[ANG KIAN HUAT]
Ah Lim Motor Company

Upload Documents		Upload Photos	Compose New Letter	View Use Viewer	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print
1	31/10/17 17:29	Accident Statement		Load HTM	
2	28/11/17 13:15	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/11/17 14:40	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
2	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
3	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
4	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
5	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
6	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
7	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
8	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
9	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
10	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
11	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
12	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
13	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
14	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
15	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
16	12/12/17 13:40	General View		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	27/11/17 17:50	OI - SLM1200Y - AMENDED Singapore Accident Statement		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/12/17 09:07	INTERVIEW STATEMENT		Load PDF	
2	18/12/17 09:07	INVESTIGATION REPORT		Load PDF	
3	20/12/17 09:02	TOTAL LOSS LETTER		Load PDF	

Linked Accident Report Documents

		View Use Viewer	
Assessment Reports		1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	
1	31/10/17 17:29	Accident Statement	
2	27/11/17 17:21	Addendum Sheet	
3	27/11/17 17:21	Accident Statement Addm. #1	
Photos/Images		3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	
1	27/11/17 17:18	Accident Photo	
2	27/11/17 17:18	Accident Photo	
3	27/11/17 17:18	Accident Photo	
4	27/11/17 17:18	Accident Photo	
5	27/11/17 17:18	Accident Photo	

6	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
13	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
14	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
15	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
16	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
17	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
18	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
19	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
20	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
21	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
22	27/11/17 17:18	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print
1	31/10/17 17:29	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Tokio Marine Insurance Singapore Ltd
20 McCallum Street, #09-01 Tokio Marine Centre
Singapore 069046

Our File No: CS/TMI17022639/DTBS2

Date: 20/12/2017

REFERENCE

Insured/Claimant:	ANG KIAN HUAT	Policy No:	MV004875	Claim No:	M1705581
Date of Loss:	30/10/2017	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM1200Y	Engine No:	3ZZ4888635
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106145252
Reg. Date:	06/06/2009 (Man. Year: 2009)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$22,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Poor	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Poor

CONDITION OF TYRES

Front Tyre Size:	0	Rear Tyre Size:	0
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10.00	10.00	0.00	0.00
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	-590.00	-590.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	-41.30	-41.30	0.00	0.00
Nett Amount (S\$)	-631.30	-631.30	0.00	0.00

INSPECTION

Date of Assignment:	28/11/2017	Present Location:
Date Inspected:	30/11/2017	Inspected At:

Ah Lim Motor Company (AMK)
Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 0.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REFER TO UPLOADED TOTAL LOSS REPORT

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Dec 2017)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM1200Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >