

22/03/2002

ASS. REC. BY:

REF: CS/FCI17022646/R19607

Special Instruction:

Surveyor:

Rusu

CWS

ASSIGNMENT (Office)

From (Person):

Sithara

of

FCI

Date/Time:

11:16am @ 28/11/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBL 4812K

Insured:

SHB 2552E

at Workshop m/s

SG 98 Motor

Tel:

91711655

of

Bik 4001 AMK Ind. Prk 1 # 01-21

Policy No:

D-15077707MF54

Claim No:

D17010930MF54

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

22/11/2017

CA / REV / REP. / REV 24 HRS

(wp)

29/11/2017

H.O.D. Endorsement:

Date/Time:

3:22pm @ 28/11/17

Person Contacted:

Gany

Vehicle IN OUT

Date/Time	Action/Instruction
	(✓) Estimate
	FBL 4812K - X
	SHB 2552E - NBH / T113024265 / S - D.O.A : 22/12/2013
30/11/17 @ 3:39pm	Informed Sithara, we are pending estimate from repairer.
26/12/18 @ 1:30pm	Revised to Sithara by email.
13/1/18:	Pass finalised with Rose LS @ 3000, 4 days.
	(Red @ 3055.40, 50%)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022646/R1qb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-11-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2552E	Veh. Inspected	FBL 4812K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17010930MFSH	Excess (\$)	0.00	
Assign From	CWS (SITHARA)	Assign Date	28/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/11/2017	Inspection Date		
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Survey Department Check List (Case Handler)

Reference No. : Cy/KE1702264/RSqb
 Policy Type: OD / TP / TP RES / TL / EVA

FBL 4812K

Case Handler

Typist

Admin (Cater): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		

Surveyor (Ramy): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

<input checked="" type="checkbox"/>	
-------------------------------------	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

<input checked="" type="checkbox"/>	
-------------------------------------	--

Check By:

[Signature] 26/01/18

Case Handler

Date

*C: Critical *N: Non-Critical

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	24-11-2017	Our Ref No. D17010930MFSH
Accident Date	22-11-2017	Claim Type. Third Party
Insured Vehicle	SHB2552E	Third Party Vehicle. FBL4812K
Survey Location	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21	
Contact Person.	LEENA	
Contact No.	64524898/ 91711655	Fax No. 64524868
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SG 98 MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE



Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



PRI Header Details

Claim No	D17010930MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & SG 98 MO
Workshop Name	SG 98 MOTOR PTE LTD (Contact Person : LEENA)	Survey Location & Contact Details	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 Mobile: 91711655 , Phone: 64524898 , Fax: 64524868 EmailId: SGMOTOR2000@YAHOO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB2552E	TP Vehicle No	FBL4812K
PRI Recieved Date	27-11-2017 05:17:41 PM	Surveyor Appointed Date	28-11-2017 11:15:39 AM	Surveyor Accept Date	28-11-2017 0

Survey Report Upload

Surveyor Inspection Date *: 	Surveyor Report Date	28-11-2017	Upload Survey Report *: 	<input type="button" value="Choose File"/>
---	----------------------	------------	---	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAuto)

From: Rasul (LKKAuto)
Sent: Friday, 23 February 2018 10:19 AM
To: Sg Motor
Cc: Shiau Chan (LKKAuto); Sg Motor
Subject: RE: Please finalize the bike FBL 4812K

Hi Linda,

As spoken to Rose, finalised amount for this bike is \$3,000.00 / 4 days lump sum
Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Sg Motor [mailto:sgmotor2000@yahoo.com.sg]
Sent: Wednesday, 31 January, 2018 6:00 PM
To: Rasul (LKKAuto)
Cc: Shiau Chan (LKKAuto); Sg Motor
Subject: Re: Please finalize the bike FBL 4812K

Dear Rasul/Shiau Chan

Please finalize bike FBL 4812K.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

On Tuesday, 16 January 2018, 5:47:17 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Rasul/Shiau Chan

Please finalize bike FBL 4812K.

Thank You

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 26 February 2018 11:39 AM
To: 'Claim Workflow System'; assignments
Cc: SUR; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: RE: SURVEY ASSESSMENT - D17010930MFSH/1

Dear Sithara,

Enclosed herewith preliminary advice of FBL 4812K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 30 November 2017 3:39 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010930MFSH/1

Dear Sithara,

Please be informed that we have inspected the motorbike FBL 4812K.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 28 November, 2017 3:27 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010930MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010930MFSH

Date: 26 February 2018

Our Ref: CS/FCI17022646/R1qb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FBL 4812K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/11/2017 at the premises of M/s SG 98 MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,055.40</u> .
Revised Estimate Amount	: S\$ <u>3,000.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the front & n/s portion.



Yours faithfully

Rasul
Automotive Assessor

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 30 November, 2017 3:39 PM
To: 'Claim Workflow System'; assignments
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010930MFSH/1

Dear Sithara,

Please be informed that we have inspected the motorbike FBL 4812K.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 28 November, 2017 3:27 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010930MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 28 November, 2017 11:15 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SITHARA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010930MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/11/2017 15:46
Date Of Accident	22/11/2017 22:50
Exact Location Of Accident	JALAN BESAR AFTER DESKER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL4812K
Insured/Policyholder	
Name Of Registered Owner	CHANDRAN S/O M SELLIAH
NRIC No	S1764486F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97945423
Alternative Phone No	OTHERS-97945423

Vehicle Particulars

Manufacturer	HONDA
Model	CBF190WH
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MSD/VMS/17-987417-WTT
Cover Note Number	

Driver

Name of Driver	CHANDRAN S/O M SELLIAH
NRIC No	S1764486F
Date Of Birth	16/02/1966
Occupation	INDOOR
Date Of Driving Pass	27/09/1990
Driving Experience	27 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97945423
Fax Number	
Contact Number	OTHERS-97945423
Email Address	NOEMAIL

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name CHANDRAN S/O M SELLIAH

Approximate Age

Injuries Sustain REFER REPORT

Injured person in which vehicle? FBL4812K


Were seat belts worn?

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police Report no: 7/2017/123/2099

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SS Shahrul Nizam Bin Samarri
Investigation Section
Traffic Police
10 Ubi Ave 3
Singapore 408865

Name : *Chandran S/O M. Sathian*
NRIC : *9174486F*
Address : *8/64, Ulu Pandan Rd*
#15-142
Singapore (*24124*)
Tel : *97445425*
Pg / Hp :

Dear Sir

ACCIDENT INVOLVING FBL4812K & SHB2552E

ALONG JALAN BESAR

ON 22/11/2017 AT 11:50 PM

With reference to the above, I have on 23/11/2017 at 1654hrs made a police report at Rochor NPC in NP 168 / T/20171123/2099.


2 On 24/11/2017, at 1330hrs, at Rochor NPC, I make the following amendments to the above report.

On the accident date, I was travelling along Jalan Besar on the second lane instead of the third.

I then moved to the first lane instead of the fourth.

I only realized that the m/taxi might have knocked on my left side of my m/cycle instead of my right side.

Yours faithfully


Signature

If a police officer records this amendment, please complete the following:

Name / Rank No: SGT Joshua Ong

Station Diary No. *98*

Signature 



Rochor Neighbourhood
Police Centre
14 Manday Road
Singapore 408999
Tel : 6744 6688



SINGAPORE POLICE FORCE



T/20171123/2099

1 of 4

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

Report No. T/20171123/2099

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/11/2017 16:54	Vide Report No.: A/20171122/0170	Station Diary No.: 90
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: CHANDRAN S/O M SELLIAH			Address: APT BLK 634 VEERASAMY ROAD #15-142 SINGAPORE 200634		
ID Type / ID No.: NRIC NO / S1764486F			Contact No.: Home/Office: Mobile: 97945423		
Nationality: SINGAPORE CITIZEN			Email: mschan1602@yahoo.com		
Sex: Male	Age: 51	Date of Birth: 16/02/1966	Type of Informant: Rider		
Race: Indian			Language: English		Institution / School Name:
Occupation: LOGISTICS SUPERVISOR			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 22/11/2017 22:50	Type of Location: Straight Road
Location: Junction of Road 1 and Road 2 JALAN BESAR DESKER ROAD Jalan Besar after Desker Road				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 50 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBL4812K	Motorcycle	HONDA	CBF190WH	Orange	Seriously Damaged	0
SHB2552E	motor taxi	MERCEDES BENZ	E 220 CDI	White	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBL4812K	MSIG INSURANCE (SINGAPORE) PTE. LTD.	60772830	17/11/2017	16/11/2018



**SINGAPORE
POLICE FORCE**



T/20171123/2099

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

3 of 4

Report No. T/20171123/2099

CONTINUATION OF REPORT

discharged from the A & E with five days hospital medical leave. There is one witness who informed me that the m/taxi just cut through the lane as there is someone flag the m/taxi from the other side of the road. That's all.

Lat on 07/02/18

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569822

Tel: 6452 4898 Fax: 6452 4888

Email: sg_motor_enterprise@yahoo.com.sg

Date: 1 December 2017

To : LKK

By Fax: 6256-4315

Attn : Rasul

Tel : 90010068

VEHICLE NO : FBL 4812K

Honda CBF 190 WH

ACCIDENT DATE: 22 November 2017

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Headlamp Assy	1	480.00 X <i>scr</i>
2 Handle Bar LH	1	170.00 M <i>/</i>
3 Mirror LH	1	95.00 scr <i>/</i>
4 Brake Lever	1	68.00 X <i>scr</i>
5 Front LH Signal	1	110.00 scr <i>/</i>
6 Front Mudguard	1	140 275.00 CR <i>/</i>
7 Fork Tube	1 set	1,040.00 BF <i>/</i>
8 Fork Under Bracket	1	380.00 BF <i>/</i>
9 Front Rim	1	<i>LR scr</i> 380.00 R (150) - <i>labur</i>
10 Brake Disc	1	290.00 X <i>scr</i>
11 Front Side Fairing	1	220.00 scr <i>/</i>
12 Balancer	1 set	290.00 scr <i>/</i>
13 Clutch Lever	1	40 75.00 scr <i>/</i>
14 Gear Pedal	1	60 78.00 PA <i>/</i>
15 Gear Rod	1	50.00 X <i>scr</i>
16 Front Footrest LH	1	50 155.00 Pro <i>/</i>
17 Footrest Bracket	1	180 250.00 at <i>/</i>
Sub-Total		4,406.00
Less 10%		440.60
Sub-Total		3,965.40

2775
102
2497.50

①

VEHICLE NO : FBL 4812K

Honda CBF 190 WH

Nett items

- 1 Towing fee (lift up bike)
- 2 IU Unit
- 3 Rear box - Kappa
- 4 Remove & replace parts, align & etc
- 5 Remove & replace fork tube, front rim, brake disc & top up fork oil
- 6 Supply body original decal sticker - 1 set
- 7 Putty & respray print to affected areas
- 8 Align body frame - welding

~~60.00~~ 40
~~160.00~~ XSVL
~~450.00~~ 200 sun ✓
~~320.00~~ 200
~~220.00~~ 150

net ~~280.00~~ 150

~~250.00~~ 150
~~350.00~~ 200

Sub-Total

2,090.00

Nett Total

6,055.40

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

Ram

Hp 90010068

4 days

4/8

29/11/17 @ 1030

2497.50

1240.00

3737.50

20%

2990

4/8 3,000.

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2

26/2/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022646/R1qbe2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 27-02-2018



Code : FCI2

1. Policy Particulars : THIRD PARTY CLAIM

Insured Veh.	SHB 2552E	Veh. Inspected	FBL 4812K
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17010930MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	28/11/2017

2. Vehicle Particulars & Condition

Make & Model	HONDA CBF190WH	c.c	184
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	LWBMC4698H1103975	Colour	MULTI COLOUR
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/70 R17	RADIAL	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70 R17	RADIAL	4 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/11/2017	Inspection Date	29/11/2017
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 4812K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HEADLAMP ASSY	SERVICEABLE	480.00	-
1	HANDLE BAR LH	BENT	170.00	170.00
1	MIRROR LH	SCRATCHED	95.00	95.00
1	BRAKE LEVER	SERVICEABLE	68.00	-
1	FRONT LH SIGNAL	SCRATCHED	110.00	110.00
1	FRONT MUDGUARD	CRACKED	275.00	140.00
1	SET FORK TUBE	BENT	1,040.00	1,040.00
1	FORK UNDER BRACKET	BENT	380.00	380.00
1	BRAKE DISC	SERVICEABLE	290.00	-
1	FRONT SIDE FAIRING	SCRATCHED	220.00	220.00
1	SET BALANCER	SCRATCHED	290.00	290.00
1	CLUTCH LEVER	SCRATCHED	75.00	40.00
1	GEAR PEDAL	BENT	78.00	60.00
1	GEAR ROD	SERVICEABLE	50.00	-
1	FRONT FOOTREST LH	BROKEN	155.00	50.00
1	FOOTREST BRACKET	CUT	250.00	180.00
	LESS 10% DISCOUNT		-402.60	-277.50
			3,623.40	2,497.50
1	FRONT RIM (LOCAL REPAIR) (SN)	SCRATCHED	380.00	150.00
	LESS 10% DISCOUNT		-38.00	-
			342.00	150.00
SPECIAL NETT ITEMS				
1	IU UNIT (SN)	SERVICEABLE	160.00	-
1	REAR BOX - KAPPA (SN)	SCRATCHED	450.00	200.00
	SET BODY ORIGINAL DECAL STICKER (SN)	NECESSARY	280.00	150.00
			890.00	350.00
LABOUR				
	TOWING FEE (LIFT UP BIKE)		60.00	40.00

Report Ref No. CS/FCI17022646/R1qbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REPLACE PARTS, ALIGN & ETC.		320.00	200.00
	REMOVE & REPLACE FORK TUBE, FRONT RIM, BRAKE DISC & TOP UP FORK OIL.		220.00	150.00
	PUTTY & RESPRAY PRINT TO AFFECTED AREAS.		250.00	150.00
	ALIGN BODY FRAME - WELDING.		350.00	200.00
			1,200.00	740.00
GRAND TOTAL			6,055.40	3,737.50

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00
--	--	--	--	----------

Report Ref No. CS/FCI17022646/R1qbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.