

range

20/09/2017

ASS: REC BY:

REF: CS3/MSG17022681/sbz

Special Instruction:

Surveyor: Sebastian
Maimen

ASSIGNMENT (Office)

From (Person): Catherine Thia

of MSIG

Date/Time: 28/11/17 @ 9.34

Estimated Cost:

Bill to:

OD ☒ TP WS TP RES / OD RES / EVA / INV / MV / CS

Insured: E26A

To Inspect Vehicle No: SJS 1971Y

Tel: 63671772

at Workshop m/s Lim Joo Kim Trading

of Blk 6, Krunji Lerup, # 61-27, 739542

Policy No: A28810555 MPQ

Claim No: 538184

Sum Insured:

Excess:

D.O.A. 23/11/2017

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement

Date/Time: 8.52am @ 29/11/17

Person Contacted

Irene

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJS 1971Y - X
	E26A - X
	After repair: 30.11.2017

15/12/17 333pm Email to Catherine Thia Thia Maimen

ASSIGNMENT

From: Date: 29/11/17

Vehicle: SJS 1971Y Yr Regn: 2009 Jun 24

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SJS 1971Y

Make: Honda Accord 2.4L C.O. 2354

at Workshop No: Lim Joo Kim Trading

Colour: Black A/C Insured / Std / NI / NA

of Blk 6, Kranji Loop # 01-27, 739542

Sp. Reading: 169203 T. Radio: Insured / Std / NI / NA

Insured:

Eng No:

Policy No:

C.No: MKHCP 263 of 1020081

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: Excess:

Steering: In Order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In Order / Jammed / Leaked / Burnt or

Make of Veh:

Mod: M / S Rim / STD A/Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 225/50ZR17

R: 11

Ball or Market Value:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

IDAC Accident Report: Consistent? Yes or No

TOYO / YOKO or Champiro

GIA / PR Seen: Consistent? Yes or No

Front Rear

Est. Repairs: days Res: Yes or No

R/Bal: 6 mm R/Bal: 6 mm

Lum Sum: % 3 Val: Yes or No

L/Bal: 6 mm L/Bal: 6 mm

CA / REV / REP. / 24 HRS 'wps'

D.O.A: 23/11/2017 D.O.I: 29/11/2017 @ 1139am

Date: Person Contacted:

Survey held at Lim Joo Kim

Vehicle IN / OUT

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis/frame / Body Structure affected due to collision

Date/Time Action/Instruction
29/11/17. Owner IC incorrect, pls help to print PARV rebate.

\$4,000 (Shirley Hwe 09/04/18) with 5 days.

\$3500 - \$4000.

OK 16/04/18

RECEIVED 16 APR 2018.

Date/Time File Pass to: ☐ : Preli. Report

Days Of Repair:

☐ : Final Report

Resurvey No. of Trip:

Date/Time File Return to:

Survey Fee

Add Fee: ☐ Site Insp: \$

Transportation

☐ Intensive: \$

Photo

☐ Tech Insp: \$

Draw

☐ 1 day and \$

Report Format:

Lum Sum / LB / S

120
50
10
180



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17022681/Sb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 29-11-2017		
		Code : MSG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	E 26A	Veh. Inspected	SJS 1971Y	
Policy No.	A28810555MPQ	Coverage (\$)	0.00	
Claim No.	538184	Excess (\$)	0.00	
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	29/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/11/2017	Inspection Date	29/11/2017	
Survey held at	LIM JOO KIM TRADING CO BLK 6 #01-27 KRANJI LOOP SINGAPORE 739542			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Ext Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Nov 2017		28 Nov 2017 09:34 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	BOH CHEK KWONG , ID: S1310058F, Tel: +6598283962, Email: ALBERT@POLYGON-GP.COM [Created by insurer]		
Main Claimant:	CHIA MIANG WHEE , ID: S1658525D		
Vehicle Reg. No.:	SJS1971Y	Date of Loss:	23/11/2017 19:00 - :59
Claim Type:	TP / 538184	Policy/Cover Note No.:	A28810555MPQ (Comprehensive)
Vehicle Reg. No. (Insured):	E26A	Policy No. (Claimant):	Coverage: 01/09/2017 - 31/08/2018
Repairer:	Lim Joo Kim Trading Co (HQ) Blk 6, Kranji Loop, #01-27, 739542 Kranji - Tel: 63671772		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/11/2017]		
Driver/Custodian (Insured):	BOH CHEK KWONG (59 / Male), NRIC: S1310058F, Tel: +6598283962		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks

(Incorporated with limited liability)

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65358802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
TIWARY ANURADHA
SHARON PARWANI
ONG BOCK KEE
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YING XIAN SELWYN

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO **HEAD OFFICE** FOR THIS MATTER

Our Ref: AM.jt.Ins.L1.SJS1971Y.17 (sj)
Your Ref: E 26 A

27 November 2017

MSIG INSURANCE (S'PORE) PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807
Attention: Motor Claims Department

BY FAX: 6225-6371

claims@sg.msig-asia.com

Dear Sirs,

**ACCIDENT INVOLVING SJS 1971 Y & E 26 A & GQ 9897 Y ON 23 NOVEMBER 2017 ALONG KJE TOWARDS BKE AT ABOUT 1900 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We are instructed by Chia Miang Whee to notify you of a road traffic accident on 23 November 2017 at about 1900 hours at/along KJE Towards BKE involving our client's vehicle registration number SJS 1971 Y and vehicle registration number E 26 A driven by you/your insured at the material time

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

cc: SJS 1971 Y - By fax: 6367 1773 only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

Survey Department Check List (Case Handler)

Reference No.:

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (

): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA/REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/11/2017 18:26
Date Of Accident	23/11/2017 19:00
Exact Location Of Accident	ALONG KJE TOWARDS BKE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS1971Y
Insured/Policyholder	
Name Of Registered Owner	CHIA MIANG WHEE
NRIC No	S1658525D
Email Address	DAVIDCHIA@TIONGAIK.COM.SG
Mobile Phone No	(LOCAL) +65-91882590
Alternative Phone No	OFFICE-91882590

Vehicle Particulars

Manufacturer	HONDA
Model	ACCORD

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28742951QMY
Cover Note Number	

Driver

Name of Driver	CHIA MIANG KHOON NELSON
NRIC No	S8022889I
Date Of Birth	01/08/1980
Occupation	INDOOR
Date Of Driving Pass	09/09/1999
Driving Experience	18 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81610098
Fax Number	
Contact Number	
Email Address	DAVIDCHIA@TIONGAIK.COM.SG

Address	BLK 530 WOODLANDS DR 14 #09-545
Postcode	730530
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GQ9897Y
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	HAYQAL BIN MOHAMAD RIDUAN
NRIC/Passport Number	S8239699C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	BOH CHEK KWONG
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	CHIA MIANG KHOON NELSON
Approximate Age	

Injuries Sustain

Injured person in which vehicle?

SJS1971Y


Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving home along KJE towards BKE, where I got into a chain collision involving three cars near Exit 1 on 23 Nov 17, approx 7pm. My car SJS 1971Y was the first in the chain collision, followed by car was E26A, and the last car GR 9897Y. My car was stationary when the accident occurred. The force of impact from the 2 cars behind caused my rear bumper to be dented. As I was having discomfort on my lower back and neck, I went to KTHH for an x-ray and was given 2 days MC from 24-25 Nov 2017 due to low back strain.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(if driver is not the policyholder)
Date & Time: 24/11/17 1431hrs

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	2889I
Vehicle Details	
Vehicle No.	SJS1971Y
Vehicle to be Exported	No
Intended De-registration Date	30 Nov 2018
Vehicle Make	HONDA
Vehicle Model	ACCORD 2.4L
Primary Colour	Black
Manufacturing Year	2008
Engine No.	K24Z22950563
Chassis No.	MRHCP26309P020081
Maximum Power Output	133.0 kW (178 bhp)
Open Market Value	\$35,066.00
Original Registration Date	24 Jun 2009
First Registration Date	24 Jun 2009
Transfer Count	1
Actual ARF Paid	\$35,066.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	23 Jun 2019
PARF Rebate Amount	\$17,533.00
Intended COE Rebate Details	
COE Expiry Date	23 Jun 2019
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$14,840.00
COE Rebate Amount	\$836.00
Total Rebate Amount	\$18,369.00

The information contained herein is correct as at 30 Nov 2017

OK

View Sent Message

This mail is associated with :

***SJS1971Y (538184)**
[E26A]

TP
CHIA MIANG WHEE
Nov 23 2017 7:00PM
[BOH CHEK KWONG]
Lim Joo Kim Trading Co

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 15/12/2017 15:33 PM.
To MSI_TSY
Subject Pre-repair Inspection

Dear Catherine,

Refer to your assignment on 28.11.2017 at 9.34AM.

Please be informed that we have inspected the vehicle SJS 1971Y on 29.11.2017 at 11.39AM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

VEHICLE'S TOP VIEW

FRONT PORTION

REAR PORTION

	FRONT BUMPER	RADIATOR, PANEL, CONDENSER, HEADLAMP	FRONT FENDER			SPARE TYRE PANEL	REAR FENDER	REAR PANEL	REAR BUMPER
PRS PRICE GUIDE	\$3 500	\$7,000	\$9,000			\$9,800	\$7500	\$3500	\$2500

FOR NON JAPAN MODEL ADD 20%



Y } Can't find
G } this information
P }
E }

VEHICLE'S TOP VIEW

(UNDERCARRIAGE & DOORS)

FRONT PORTION

REAR PORTION

HEAD LAMP	WHEELS \$5000	DOOR \$3000	WHEEL \$3000 EACH	TAIL LAMP
				
HEAD LAMP	WHEELS \$5000	DOOR \$3000	WHEEL \$3000 EACH	TAIL LAMP

FOR NON JAPAN MODEL ADD 20%

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Nov 2017		28 Nov 2017 09:34 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: BOH CHEK KWONG , ID: S1310058F, Tel: +6598283962, Email: ALBERT@POLYGON-GP.COM									
Main Claimant: CHIA MIANG WHEE , ID: S1658525D									
Vehicle Reg. No.: SJS1971Y		Date of Loss: 23/11/2017 19:00 - :59 [100 Months and 30 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 538184		Policy/Cover Note No.: A28810555MPQ (Comprehensive) Coverage: 01/09/2017 - 31/08/2018							
Vehicle Reg. No. (Insured): E26A		Policy No. (Claimant):							
		Excess:							
Repairer: Lim Joo Kim Trading Co (HQ) Blk 6, Kranji Loop, #01-27, 739542 Kranji - Tel: 63671772									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eng Huey NI - 6643 1314]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Imm.Advice due 29/11/2017]									
Driver/Custodian (Insured): BOH CHEK KWONG (59 / Male) , NRIC: S1310058F, Tel: +6598283962									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJS1971Y (538184)

[E26A]

TP

CHIA MIANG WHEE

Nov 23 2017 7:00PM

[BOH CHEK KWONG]

Lim Joo Kim Trading Co






































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
















































View [View In Browser](#)

Photos/Images

3 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
2	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
3	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
4	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
5	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
6	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
7	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
8	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
9	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
10	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
11	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
12	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
13	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
14	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
15	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
16	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
17	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
18	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
19	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
20	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
21	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
22	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
23	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
24	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
25	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
26	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
27	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
28	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
29	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
30	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
31	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
32	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
33	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
34	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
35	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
36	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
37	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
39	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
40	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
41	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
42	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
43	09/04/18 11:52	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
44	09/04/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
45	09/04/18 11:52	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
46	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	16/04/18 10:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/11/17 14:28	Fax From Third Party	 Load PDF	
2	27/11/17 14:28	TP GIA Rep - SJS1971Y	 Load PDF	
3	28/11/17 09:34	Disagree on SJE	 Load PDF	
4	28/11/17 09:34	Reply on Disagree of SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17022681/SBE2

Date: 17/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28810555MPQ

Claimant Vehicle No : SJS1971Y

Insured Vehicle No : E26A

Date of Loss: 23/11/2017

Nature of Claim: TP

Claim No: 538184

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS1971Y

Make & Model: HONDA ACCORD, 1.6 (M)

Engine No: K24Z22950563

Reg. Date: 24/06/2009 (Man. Year: 2008)

Chassis No: MRHCP26309P020081

Colour: Black

Odometer: 169203 km

Engine Capacity: 2354 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50Z R17

Rear Tyre Size: 225/50Z R17

Front Left Side: Champiro 6 mm

Rear Left Side: Champiro 6 mm

Front Right Side: Champiro 6 mm

Rear Right Side: Champiro 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/11/2017

Date Inspected: 29/11/2017 Inspected At:

Lim Joo Kim Trading Co (HQ)

Blk 6, Kranji Loop, #01-27

Singapore 739542

Estimated Period of Repair: 0.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 17 Apr 2018)

Parts: 143 HONDA ACCORD 1.6 (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJS1971Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >