

ASS. REC. BY:

REF: CS/CTI17022685/Kab

Special Instruction:

Surveyor: Kenneth ASSIGNMENT (Office)From (Person): Irene Tay of CTI Date/Time: 29/11/17 @ 5:37pm

Estimated Cost: _____ Bill to: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CSTo Inspect Vehicle No: YN 3596H Insured: GBF85494at Workshop m/s RC Auto Tel: 9761 9383of 160 Sin Ming Drive #06-20, 575722Policy No: BMCVSN1723171900 Claim No: SNM17D06807C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 25/11/17
(Client's Record) lwp

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 9:37am @ 29/11/17 Person Contacted: Mr. Tan Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	(✓) Estimate
	YN3596H-X
	GBF85494-X
	Kenneth confirmed US \$7100, 7 days.
	(Red 45475.36, 44%)

REF: CTI

ASSIGNMENT

From:

Date: 29/11/17

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

YN 3596H

at Workshop no:

RC Auto

at 160 Sin Ming Drive #06-20 575722

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Mr. Tan

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

768

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

1wp

Vehicle: IN / OUT

Date:

Person Contacted:

Job No:

YN 3596H Page 04/02 13

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make:

Mit Canter

CC

2977

Colour:

White

A/C

Insured / Std / NI / NA

Sp. Reading:

372541

T. Radio

Insured / Std / NI / NA

Eng. No:

FE 833EA 20991

Q No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

700R16x10

R:

(2)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ OK or

Front

Rear

R. Bal:

S

mm

R. Bal:

11

mm

L. Bal:

S

mm

L. Bal:

11

mm

D.O.A:

25/11/17

D.O.I:

29/11/17

Survey held at:

Des. of Damages: Fnt / Rear / ☒ O/S / N/S / U/C / Rooftop or

A/R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/11 File pass to Catherine

RECEIVED 10 DEC

Date/Time: File Passed?



Prel. Report

09/12 final



Final Report

Date/Time: File Returned?

Days Of Repair:

7

Resurvey No. of Trip:

1

Survey Fee

200

Transportation

Add Fee:



Site Insp: \$



Inter. Insp: \$



Tech. Insp: \$



Assess. Insp: \$

Report Format:

WEEK-7P

Lump Sum / 12/1/18

7100

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17022685/Kqb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 29-11-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 8549U	Veh. Inspected	YN 3596H
Policy No.	DMCVSN1723171700	Coverage (\$)	0.00
Claim No.	SNM17D06802C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	29/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/11/2017	Inspection Date	29/11/2017
Survey held at	160 SIN MING DRIVE # 06-20, 575722		
Repairer	R C AUTO		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Survey Department Check List (Case Handler)

Reference No.: C9/CT117022683/K 96
 Policy Type: OD / TP / TP RES / TL / EVA

YN 359641

Case Handler

Typist

Admin (Cath): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Kerpath): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓			
---	--	--	--

Check By:

Cath 12/05/2014
 Case Handler Date

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 28 November, 2017 5:37 PM
To: yue@kscgp.com; assignments@lkkauto.com
Cc: assignments@lkkauto.com
Subject: CTP REF NO. GBF8594U KSCGP REF NO. YN3596H - ACCIDENT INVOLVING GBF8594U AND YN3596H ON 25 NOVEMBER 2017

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and the email below.

Please assist to get your surveyor to liaise with RC Auto.

Regards

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: yue@kscgp.com [mailto:yue@kscgp.com]
Sent: Tuesday, 28 November, 2017 12:25 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: RE: CTP REF NO. GBF8594U KSCGP REF NO. YN3596H - ACCIDENT INVOLVING GBF8594U AND YN3596H ON 25 NOVEMBER 2017

Dear Irene,

We refer to our telephone conversation with you earlier. With regard to your list below, our client is agreeable to any of the surveyors who are from **LKK Auto Consultants**.

The repair workshop details are as follows:

RC Auto
160 Sin Ming Drive
#06-20 Sin Ming AutoCity
Singapore 575722
Contact person: Mr Tan Kim Chuan / HP: 9761 9383

Thank you and best regards,
Yu E (YE)
M/s KSCGP Juris LLP

10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611
Fax: 6538 3708
E-mail: yue@kscgp.com

----- Original Message -----

From: Irene Tay [<mailto:irene.tay@sg.cntaiping.com>]
To: yue@kscgp.com
Cc: yue@kscgp.com
Sent: Tue, 28 Nov 2017 03:55:36 +0000
Subject:

Without Prejudice
Save As To Costs

Dear Sir/Mdm,

We refer to your pre-repair survey request / email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

Here are the list of surveyors :

Tay Beng Hee
See Chew Seng
Dereck Oh Siong Wee
Kalvin Ang
Bryan Ang
Steven Foong
Adrian Ling
Marcus Chua
Kenneth Kong
Henry Ng

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com

From: Tee Sunny [<mailto:sunny@wahhong.sg>]

Sent: Friday, 17 November, 2017 2:10 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>

Cc: Wah Hong Motors (Nicholas Tee) <nicholas@wahhong.sg>; Wah Hong Motors (Michael Tee) <michael@wahhong.sg>

Subject: Re: Pre-Repairs Assessment Request for SJM9058M - Accident with SCR6656M (China Taiping) on 2017-11-12 - our case no. 171111

Hi Irene

Here are the files.

This email has been scanned by the MxScan Email Security System.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/11/2017 18:22
Date Of Accident	25/11/2017 18:00
Exact Location Of Accident	SLE(LAMP POST 104)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN3596H
Insured/Policyholder	
Name Of Registered Owner	DFINE ENGINEERING PTE LTD
Co Reg No	NA
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91656915

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MV001098-R01
Cover Note Number	

Driver

Name of Driver	KALIYAMOORTHY KATHIRAVAN
NRIC No	G8328356X
Date Of Birth	11/03/1987
Occupation	OUTDOOR
Date Of Driving Pass	21/07/2015
Driving Experience	2 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91656915
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Postcode 408830
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions AFTER RAIN
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name 10 UBI AVENUE 3
Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF8594U
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLA3638T

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

C - SLA
 C - 3632 T
 A - YN 3596 H
 B - GBE
 8594 U

Longest
 104



SLE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Traffic Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20171125/2145

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20171125/2145

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/11/2017 23:56	Vide Report No.: F/20171125/0231	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars		
Name of Informant: KALIYAMOORTHY KATHIRAVAN		Address: 81 UBI AVE 4 #06-25 UB. ONE SINGAPORE 408830
ID Type / ID No.: FIN NO / G8328356X		Contact No.: Home/Office: Mobile: 91656915
Nationality: INDIAN		Email:
Sex: Male	Age: 30	Date of Birth: 11/03/1987
Type of Informant: Driver		Institution / School Name:
Race: Indian		Language:
Occupation: Lorry driver		Driving Licence Information: Class: 2B,3,4,5 Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 25/11/2017 18:00	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 SELETAR EXPRESSWAY TAMPINES EXPRESSWAY LAMPOST NUMBER- 104				
Weather: Cloudy		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF8594U						7
SLA3638T	Car				Slightly Damaged	1
YN3596H	Lorry				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20171125/2145

2 of 3

Report No. T/20171125/2145

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Driver			
Name	KALIYAMOORTHY KATHIRAVAN	ID No.	G8328356X
Related Vehicle	NIL	Contact No.	91656915
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	DESMOND KOH TECK BENG	ID No.	S7613794C
Related Vehicle	NIL	Contact No.	83837389
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious

Brief Details.

AT THE ABOVE STATED DATE, TIME AND LOCATION, THE CAR INFRONT OF ME SUDDENLY BRAKED, SO I ALSO BRAKED, WHEN I BRAKED, IN 2 SECONDS THE LORRY BEHIND ME HIT THE REAR OF MY LORRY. AFTER THAT, MY BRAKED VEHICLE MOVED FORWARD DUE TO THE IMPACT OF THE REAR COLLISION AND HIT THE REAR OF THE CAR INFRONT OF ME. AFTER THAT I WENT OUT TO SEE WHAT HAPPENED. THE DRIVER AND THE CHILD BESIDE HIM IN THE LORRY BEHIND ME COULD NOT GET OUT OF THE CRASHED VEHICLE. POLICE THEMN ARRIVED AT THE SCENE TO ASSIST THE SITUATION. THE DRIVER AND CHILD WERE CONVEYED IN AMBULANCE. I WOULD LIKE TO STAE THAT THE CONVEYED DRIVER'S BOSS'S PARTICULARS IS 96795797. I, AS THE CENTRE LORRY DRIVER, AM HAVING BACK PAINS DUE TO THE INCIDENT. THATS ALL.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20171125/2145

3 of 3

Report No. T/20171125/2145

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
S SIVAVIKNESH

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TF / GIT /
Staff Sgt LEE GUANG HUI
Contact No.: 65476138

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
25/11/2017 23:56

Classification Of Case:




SINGAPORE
POLICE FORCE

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ESTIMATE RC AUTO

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel : 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168K

*Not Authorised
1/15/17 @ 7100h
Resurvey After Paint
7days*

VEHICLE NUMBER: YN3596H

Date : 30-Nov-2017

MODEL: MITSUBISHI CANTER FE83BEA20991

Quantity	Description/Particular	Unit Price	Amount
1 PC	FRONT BUMPER	@999.86	999.86
1 PC	FRONT PANEL	@1206.86	1,206.86
2 PCS	FRONT HEADLAMP	@703.58	1,407.16
1 PC	FRONT GRILLE	@913.38	913.38
1 PC	FRONT BUMPER STAY	@155	155.00
1 PC	REAR BUMPER	@786.40	786.40
1 PC	REAR TAILGATE	@1989.10	1,989.10
2 PCS	REAR LAMP	@296	592.00
1 PC	REAR LICENSE PLATE LAMP	@114.20	114.20
1 PC	REAR BUMPER BRACKET	@290	290.00
1 PC	REAR PANEL	@290	290.00
2 PCS	REAR CENTRE BRACKET	@212	424.00
1 PC	REAR STEP BAR	@280	280.00
1 PC	TAILGATE EMBLEM (MITSUBISHI)	@108	108.00
	DRIVER SEATS	@900	900.00
	TOTAL		10,455.96
	-LESS 10%		(1,045.60)
	TO DISMANTLE DASHBOARD		200.00
	TO REPLACE FRONT & REAR PORTION		1,820.00
	TO CHECK WIRING		60.00
2 PC	FRONT & REAR NUMBER PLATE		50.00
1 PC	60 KM/H STICKER		20.00
1 PC	22 PAX STICKER		15.00
	SPRAY PAINTING (Panel, Tailgate, Bumper, Rear bumper.)		1000
	GRAND TOTAL		12,225.36

Received the above goods in good order and condition

Received by

E.&O.E.

for RC AUTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party is on "judice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12225.36

...CLAIM SUBFOLDER...(Pending for Survey Report)






CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Nov 2017		30 Nov 2017 10:29 Edit Adj Rpt	S\$7,100.00 Edit Estimates	S\$7,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: DFINE ENGINEERING PTE LTD, Co. Reg. No.: NA									
Vehicle Reg. No.: YN3596H		Date of Loss: 25/11/2017 18:00 - :59							
Claim Type: TP / SNM17D06802C02		Policy/Cover Note No.: DMCVSN1723171700							
Vehicle Reg. No. (Insured): GBF8594U		Policy No. (Claimant): 17-MV001098-R01							
		Excess: S\$0.00							
Repairer: RC AUTO (HQ) 18 Sin Ming Industrial Estate Sector A, #01-43, 575676 Sin Ming - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Claimant's Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/12/2017]									
Adj Asg. Remarks: PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*YN3596H (SNM17D06802C02)
[GBF8594U]
TP
DFINE ENGINEERING PTE LTD
Nov 25 2017 6:00PM
[-]
RC AUTO

Upload Documents			Upload Photos		Compose New Letter		View Use Viewer	
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print			
1	27/11/17 18:32	Accident Statement		 Load HTM				
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print			
1	27/11/17 18:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
2	27/11/17 18:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
3	27/11/17 18:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
4	27/11/17 18:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
5	27/11/17 18:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
6	27/11/17 18:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
7	27/11/17 18:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
8	27/11/17 18:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
9	27/11/17 18:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
10	27/11/17 18:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
11	27/11/17 18:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
12	27/11/17 18:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
2	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
3	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
4	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
5	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
6	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
7	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
8	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
9	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
10	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
11	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
12	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
13	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
14	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
15	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
16	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
17	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
18	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			
19	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>			

20	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>
21	19/12/17 11:48	General View		Load JPG	<input checked="" type="checkbox"/>
22	19/12/17 11:48	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
23	19/12/17 11:48	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
24	19/12/17 11:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
25	19/12/17 11:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	19/12/17 11:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	19/12/17 11:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
28	19/12/17 11:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
29	19/12/17 11:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
30	19/12/17 11:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
31	19/12/17 11:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	19/12/17 11:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	30/11/17 10:29	EMAIL FROM KSCGP (1)		Load PDF	
2	30/11/17 10:29	EMAIL FROM KSCGP (2)		Load PDF	
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	27/11/17 18:28	Common Statement [Linked Accident Report Documents]		Load TIF	
2	27/11/17 18:28	Common Statement [Linked Accident Report Documents]		Load TIF	
3	27/11/17 18:28	Common Statement [Linked Accident Report Documents]		Load TIF	
4	27/11/17 18:32	Sketch Plan [Linked Accident Report Documents]		Load TIF	
5	27/11/17 18:32	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	

Linked Accident Report Documents

			View Use Viewer		
Assessment Reports			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	27/11/17 18:32	Accident Statement		Load HTM	
Photos/Images			3 per page		<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	27/11/17 18:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	27/11/17 18:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	27/11/17 18:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	27/11/17 18:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	27/11/17 18:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	27/11/17 18:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	27/11/17 18:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	27/11/17 18:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	27/11/17 18:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	27/11/17 18:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	27/11/17 18:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	27/11/17 18:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	27/11/17 18:28	Common Statement		Load TIF	
2	27/11/17 18:28	Common Statement		Load TIF	
3	27/11/17 18:28	Common Statement		Load TIF	
4	27/11/17 18:32	Sketch Plan		Load TIF	
5	27/11/17 18:32	Sketch Plan #2		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117022685/KQBE2

Date: 27/12/2017

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1723171700		
Claimant Vehicle No :	YN3596H	Insured Vehicle No :	GBF8594U		
Date of Loss:	25/11/2017	Nature of Claim:	TP	Claim No:	SNM17D06802C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN3596H	Engine No:	HIDDEN
Make & Model:	MITSUBISHI CANTER, 2.5 D FB510B (M)	Chassis No:	FE83BEA20991
Reg. Date:	04/02/2013 (Man. Year: 2012)	Odometer:	372541 km
Colour:	White		
Engine Capacity:	2977 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	700R16X10	Rear Tyre Size:	700R16X10 (D)
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 1/1 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 1/1 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,495.36	6,575.77	2,919.59	30.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	2,340.00	740.00	24.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,575.36	8,915.77	3,659.59	29.10
Approved Total (Overridden) (S\$)		7,100.00		
Nett Amount (S\$)	12,575.36	7,100.00	5,475.36	43.54

INSPECTION

Date of Assignment:	30/11/2017	
Date Inspected:	29/11/2017	Inspected At: 160 SIN MING DRIVE # 06-20, 575722 Repairer : RC AUTO (HQ)
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Dec 2017)	
Parts:	N/A	mitsubishi canter 2.5 D FB510B (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN3596H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	999.86 FL	*999.86 FL
2	1		*FRONT PANEL	Bent	1,206.86 FL	*1,206.86 FL
3	1		*FRONT HEADLAMP	O/S MTG Cracked/N/SServiceable	1,407.16 FL	*703.56 FL
4	1		*FRONT GRILLE	Dented/Warped	913.38 FL	*913.38 FL
5	1		*FRONT BUMPER STAY	Bent	155.00 FL	*155.00 FL
6	1		*REAR BUMPER	Bent	786.40 FL	*786.40 FL
7	1		*REAR TAILGATE	Bent	1,989.10 FL	*1,989.10 FL
8	1		*REAR LAMP	N/S Cracked	592.00 FL	*296.00 FL
9	1		*REAR LICENSE PLATE LAMP	Cracked	114.20 FL	*114.20 FL
10	1		*REAR BUMPER BRACKET	Bent	290.00 FL	*290.00 FL
11	1		*REAR PANEL	Repair	290.00 FL	* FL
12	2		*REAR CENTRE BRACKET	Bent-1 Pc only	424.00 FL	*212.00 FL
13	1		*REAR STEP BAR	Bent	280.00 FL	*280.00 FL
14	1		*TAILGATE EMBLEM (MITSUBISHI)	Necessary	108.00 FL	*108.00 FL
15	1		*DRIVER SEATS (LOCAL REPAIR)	Distorted/Jammed	810.00 FS	*450.00 FS
16	2		*FRONT & REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
17	1		*60KM/H STICKER	Necessary	20.00 FS	*20.00 FS
18	1		*22 PAX STICKER	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,450.96	8,589.36
- List Item Discount on L Items 10.00/25.00% (\$\$)	955.60	2,013.59
Total Parts (\$\$)	9,495.36	6,575.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DASHBOARD	New	200.00	200.00
2	TO REPLACE FRONT & REAR PORTION	New	1,820.00	1,300.00
3	TO CHECK WIRING	New	60.00	40.00
4	SPRAY PAINTING (PANEL, TAILGATE, BUMPER, REAR BUMPER)	New	1,000.00	800.00
Gross Labour Cost (S\$)			3,080.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >