

ASS. REC. BY:

REF: CS/SM017022688/Ktbnz

Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

From (Person): Sheng Wong of SMO Date/Time: 29/11/17 @ 10:14am

Estimated Cost: Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SBF 8181C Insured: SKS 54774

at Workshop m/s Ngick Motor Works Tel: 9850 2253

of Blk 7 Sin Ming Ind. Est C # 01-84, 575642

Policy No: Claim No: CMTD 1704260/GPL

Sum Insured: Excess:

Make of Veh: D.O.A. 25/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time: 10:23am @ 29/11/17 Person Contacted: Mr. Kwan Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SBF 8181C - X
	SKS 54774 - X
21/12	L1 Lm @ 3250 email & confirm (Red: 324832:49%)

ASS. REC. BY:

REF: *Souh**Kenneth*

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

04 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SBR 8181C*Yr Regn: *08, 08*Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Honda Civic*c.c. *1595*Colour: *N. Black*

A/C: Insured / Std / NI / NA

Sp. Reading: *120650*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JHMF046208S202157*Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

*205/55R16*BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

Rear

R/Bal. *2* mm

mm

R/Bal. *3* mm

mm

L/Bal. *2* mm

mm

L/Bal. *3* mm

mm

D.O.A. *25/11/17*D.O.I. *29/11/17*Survey held at *✓*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s R & L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/11/17 *File pass to Customer*

RECEIVED 23 DEC 2017

Date/Time, File Pass to?

11/12/17 *Typist*

Date/Time, File Return to?

2)

☐

Preli. Report

☒

Final Report

Days Of Repair: *4*Resurvey No. of Trip: *1*

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

*250*Report Format: *TP*Lump Sum / I.B.I. (\$) *3250*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17022688/Ktb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 29-11-2017



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 5477U	Veh. Inspected	SBF 8181C
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704260/GPL	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	29/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/11/2017	Inspection Date	29/11/2017
Survey held at	BLK 7 SIN MING IND. EST. SEC C # 01/84,575642		
Repairer	NGIAK MOTOR WORKS		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>
Sent: Wednesday, 29 November, 2017 10:14 AM
To: 'weekwanchia@yahoo.com'; 'assignments'
Cc: Henry, Irene James; Gnoh, Pau Loong; 'Nivitha (LKK Auto)'
Subject: RE: Fwd: pri E 676 nm
Attachments: prie676nm.jpg

VI
Kenneth
Mr. Kwan
10.23am

Our Reference: CMTD1704260/GPL

Hi,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (SBF8181C).

Please refer to the email correspondence below.

Best Regards

Shery Wong

Claims Division

T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: WeeKwan Chia [mailto:weekwanchia@yahoo.com]

Sent: Tuesday, November 28, 2017 5:27 PM

To: Wong, Shi Yi Shery

Subject: Fw: Fwd: pri E 676 nm

Hi Shery,

We opt for

Kenneth Kong from LKK Auto Consultants .

Thank you.

Sent from Yahoo Mail on Android

----- Forwarded message -----

From: "tonygn tonygn" <tonygn18@hotmail.com>
To: "weekwanchia@yahoo.com" <weekwanchia@yahoo.com>
Cc:

Sent: Tue, 28 Nov 2017 at 17:17
Subject: Fwd: pri E 676 nm

Sent from my Samsung device

----- Original message -----

From: "Wong, Shi Yi Shery" <Shery.Wong@sompo.com.sg>
Date: 28/11/2017 16:52 (GMT+08:00)
To: "tonygn18@hotmail.com" <tonygn18@hotmail.com>
Cc: "Henry, Irene James" <irene.henry@sompo.com.sg>, "Gnoh, Pau Loong" <PaulLoong.Gnoh@sompo.com.sg>
Subject: RE: pri E 676 nm

Our Reference: CMTD1704260/GPL
Your Reference: SBF8181C

Date: 28TH November 2017

Without Prejudice

BY EMAIL ONLY

Attention:

M/S NGIAK MOTOR

ACCIDENT INVOLVING SBF8181C & SKS5477U ON 25.11.17

Dear Sir

We refer to your Notice of Accident via email dated 28/11/2017.

Please be informed that Pau Loong is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	

		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Shery Wong

Claims Division

T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: tonygn tonygn [<mailto:tonygn18@hotmail.com>]

Sent: Tuesday, November 28, 2017 4:11 PM

To: Motor Survey; claimsreport

Subject: pri E 676 nm

Sent from [Outlook](#)

NGIAK MOTOR WORKS

Blk. 7, Sin Ming Industrial Estate C, #01 - 84, Singapore 575642

Fax : 6458 - 5589 H/P : 9850 - 2253

Business Reg. No: 207300/00C

COPY

Date :- 28 / 11 / 2017

Motor Claims Department

Sompo Insurance (S) Pte. Ltd

BY FAX :-

BY HAND

Dear Sir,

6221 - 3147

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF
PRE-ACTION PROTOCOL FOR NIMA CASES**

We have been appointed by the Owner to repair his/her motor vehicle

No. SBF 8181C on 25-11-16 with another vehicle

No. SKS 5477U along AMK Trei

Please be informed that the said vehicle can be inspected at:-

Contact

Workshop : NGIAK MOTOR WORKS

Sector C, Bik. 7, #01 - 84

Sin Ming Road Singapore 575642

Contact

Fax : 6458 - 5589

Person : Mr. Kwan / 9850 - 2253

Email : weekwanchia@yahoo.com

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Holiday. We will commence repairs thereafter without further reference to you.
Yours faithfully,

Wu LLC - Law Firm - Tony Gn

Our Ref : 17

E 676

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/11/2017 11:03
Date Of Accident	25/11/2017 21:05
Exact Location Of Accident	ANG MO KIO AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBF8181C
Insured/Policyholder	
Name Of Registered Owner	NEW DIRECTION PTE LTD
Co Reg No	201228912D
Email Address	NEWDIRECTION88@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94881757
Alternative Phone No	OFFICE-94881757

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5076176287-01
Cover Note Number	

Driver

Name of Driver	SOH YONG HO
NRIC No	S1565774Z
Date Of Birth	27/03/1962
Occupation	OUTDOOR
Date Of Driving Pass	23/01/1980
Driving Experience	37 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97838093
Fax Number	
Contact Number	
EMail Address	NEWDIRECTION88@GMAIL.COM

Address	BLK 778 WOODLANDS DRIVE 60 #11-00
Postcode	730778
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	CANNOT BE UPLOADED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKS5477U
Vehicle Make/Model/Colour	TOYOTA ALTIS
Details Of Properties	
Name of Driver	THNG LAY TEEN
NRIC/Passport Number	S1100947F
Contact Number	96258015
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 28 NOV 2017

Sh

Driver's Signature

(If driver is not the policyholder)


Date & Time: 28 NOV 2017



Reporting Centre Personnel's Signature

Name: NG WING KIN JAMES
NRIC/FIN No.: S7927881E

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I'm driving along Ang Mo Kio Ave 1 at the extreme left lane at normal speed with my passengers on board. This Altis suddenly knocked my right side of my car & damaged my side mirror & scrape my body parts.

DECLARATION

I declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time: 28 NOV 2017

Sh

Driver's Signature
(If driver is not the policyholder)
Date & Time: 28 NOV 2017



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

NG WING KIN JAMES
S7927881E

CITY AUTO PTE LTD

BLK 8 SIN MING IND. EST., #01-58/60/62

SINGAPORE 575643

Phone Number: 6453-1235

Fax Number: 6453-7944

Customer: TPS
Company:
License NO: SBF 8181C
Odometer:

Date: 11/29/2017 2:31 PM
VIN:
Technician:
Order NO:

VEHICLE ALIGNMENT REPORT HONDA, CIVIC Hybrid FD3, 05-05 (Customized)

HONDA, CIVIC Hybrid FD3, 05-05 (Customized)						
Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	2°24'	6°00'	8°00'	2°18'
		Right	2°49'	6°00'	8°00'	2°54'
	Camber	Left	-1°12'	-0°35'	0°25'	-0°48'
		Right	-1°24'	-0°35'	0°25'	-1°24'
	Toe	Left	0°03'	-0°05'	0°05'	-1°12'
		Right	0°03'	-0°05'	0°05'	1°12'
Total		0°06'	-0°11'	0°11'	0°00'	
Rear	Camber	Left	-1°12'	-2°15'	-0°25'	-1°12'
		Right	-1°30'	-2°15'	-0°25'	-1°30'
	Toe	Left	0°12'	0°00'	0°08'	0°12'
		Right	0°12'	0°00'	0°08'	0°12'
		Total	0°24'	0°00'	0°16'	0°24'
	Thrust Angle		0°00'	----		0°00'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		12°51'	12°55'	12°55'	12°51'
	Right		12°52'	12°55'	12°55'	12°52'
Included Angle	Left		11°39'	----	----	12°03'
	Right		11°28'	----	----	11°28'
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Max Turn Inside	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		-1mm	----	----	-1mm
	Rear		1mm	----	----	1mm
Track Width Diff.			23mm			23mm
Wheel Base Diff			-2mm			-2mm
Front Ride Height	Left		----	----		----
	Right		----	----		----
Rear Ride Height	Left		----	----		----
	Right		----	----		----
Frame Angle						

ONE STOP AUTOMOTIVE SOLUTION

NGIAK MOTOR WORKS

MAILING ADDRESS: BLK 6, GHIM MOH ROAD #10-194

SINGAPORE 270006

H/P: 9850 2253

Reg. No. 207300/00C

Not Authorized
U/Lm 83250
Putney - After Paint
4 days

Kenneth
29/11/17 11:10am

Date: 28th Nov 2017

Quotation: SBF P.I.P.I.C Honda Civic

1 Pc. Front bumper	Bul/m/cm SBF	569.00 L
1 Pc. Front RH fender	R	536.70 X
1 Pc. Front RH fender - signal lamp assy.	Sn	49.60 X
1 Pc. Front RH headlamp assy.	Wt/cm 1,	136.50 L
1 Pc. Front RH door side mirror assy.	Bu	480.10 L
1 Pc. Front RH absorber	Ry	399.40 Z
1 Pc. Front RH ABS sensor	Sn	230.60 X
1 Pc. Front RH lower arm	Sn	298.70 X
1 Pc. Front RH knuckle	Ry	359.80 Z
1 Pc. Front RH wheel bearing	W	125.00 Z
		4,685.40
	Less 20%	937.08

NETS Items:-

1 Pc. Front RH tyre	Sn	250.00 X
1 Pc. Front RH sport Rim	R	500.00 Ban

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Charges:-

① Check wiring & do resetting	120.00	2ol
② Computerised wheel alignment	150.00	2ol
③ Fix tyre & wheel balancing	80.00	X
④ To change suspension	250.00	16d
⑤ Panel beating	600.00	40ol
⑥ Spray painting	800.00	52ol
Total:	6,498.32	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17022688/Ktbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 27-12-2017



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 5477U	Veh. Inspected	SBF 8181C
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704260/GPL	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	29/11/2017

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JHMF46208S202157	Colour	METALLIC BLACK
Odometer	120650	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	SUMITOMO	2 mm
L/H Front Tyre	205/55 R16	SUMITOMO	2 mm
R/H Rear Tyre	205/55 R16	SUMITOMO	3 mm
L/H Rear Tyre	205/55 R16	SUMITOMO	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/11/2017	Inspection Date	29/11/2017
Survey held at	BLK 7 SIN MING IND. EST. SEC C # 01/84,575642		
Repairer	NGIAK MOTOR WORKS		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBF 8181C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED / MTG CRACKED	569.00	569.00
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	536.70	-
1	FRONT RH FENDER SIGNAL LAMP ASSY	SERVICEABLE	49.60	-
1	FRONT RH HEADLAMP ASSY	CUT / CRACKED	1,136.50	1,136.50
1	FRONT RH DOOR SIDE MIRROR ASSY	BUCKLED	980.10	980.10
1	FRONT RH ABSORBER	BENT	399.40	399.40
1	FRONT RH ABS SENSOR	SERVICEABLE	230.60	-
1	FRONT RH LOWER ARM	SERVICEABLE	298.70	-
1	FRONT RH KNUCKLE	BENT	359.80	359.80
1	FRONT RH WHEEL BEARING	NECESSARY	125.00	125.00
	LESS 20% DISCOUNT		-937.08	-713.96
			3,748.32	2,855.84
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT RH TYRE (SN)	SERVICEABLE	250.00	-
1	FRONT RH SPORT RIM (SN)	TO REPAIR SEE LABOUR	500.00	-
			750.00	-
	<u>LABOUR</u>			
	CHECK WIRING & DO RESETTNG.		120.00	20.00
	COMPUTERISED WHEEL ALIGNMENT.		150.00	80.00
	FIX TYRE & WHEEL BALANCING.		80.00	-
	TO CHANGE SUSPENSION.		250.00	160.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT RH FENDER AND FRONT RH SPORT RIM.		600.00	400.00
	SPRAY PAINTING.		800.00	520.00
	-		-	-
	-		-	-
	-		-	-
			2,000.00	1,180.00
	GRAND TOTAL		6,498.32	4,035.84
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,250.00

Report Ref No. CS/SMO17022688/Ktbn2



Report Ref No. CS/SMO17022688/Ktbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.