

ASS. REC BY

REF CS/MSG17022700 / Tlvb n2

Surveyor
merimen

Taufikh

ASSIGNMENT (Office)

From (Person)

Irene Tan

MSG

Date/Time 28/11/17 @ 18:42pm

Estimated Cost

Bill to

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SJS 9838Y

Insured

SCH 1825C

at Workshop m/s

Performance

Tel

63190174

of

303 Alexandra Road

Policy No.

8039 5952 AVW

Claim No.

538250

Sum Insured

Excess

Make of Vehl

(Client's Record)

D.O.A. 25/11/2017

CA / REV / REP. / REV 24 HRS

lwp

04.12.2017

H.O.D. Endorsement

Date/Time

8:54am @ 29/11/17

Person Contacted

Carohite

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

Han

SJS 9838Y - X

SCH 1825C - NA/MSG17022489/h4-D.O.A. = 25/11/2017

5/12/17

Send preli revised by merimen

31/1/18

Final fig \$ 6599.45 confirmed by email (Red 1374.25, 17/1/18)
waiting for

Signature: Taufik

REF: MSG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SSS 9838Y
 at Workshop m/s: Performance Motor
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$46K
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 5 days Taufik 31/1/18 Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Plan

Vehicle IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Rehbe 31/1/18

Veh No: SSS 9838Y Yr Regn: 2009 July
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW 525I C.C. 2497
 Colour: Black A/C: _____ Insured / Std / NI / NA
 Sp. Reading: 119337 T. Radio: Insured / Std / NI / NA
 Eng. No: _____
 C/No: WB ANM 5209.0C 228630
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/45R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: 6 mm Rear: 6 mm
 R/Bal: 6 mm L/Bal: 6 mm
 D.O.A: 25/11/17 D.O.I: 4/12/17 4:55pm
 Survey held at: pmc
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Int o/s

meant
31/1/2018

waiting for make & model in merimen.

Date/Time File Pass to? ☐ : Preli. Report

☐ : Final Report

Date/Time File Return to?

31/1- typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee

Transportation

100-250

Phone

Direct

Add Fee: ☐ Site Insp. \$

☐ Interview \$

☐ Tech. Insp. \$

☐ Weekend \$

Report Format: merimen

Lump Sum / I.B.I. \$ 6599.45

200
10

210

Survey Department Check List (Case Handler)

Reference No.: CS/MSG/17022700/TWB
Policy Type: OD/TP/TP RES/TL/EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA/REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp. Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des. of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 31/1/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17022700/T1vb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 29-11-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCH 1825C	Veh. Inspected	SJS 9838Y	
Policy No.	80395952AVW	Coverage (\$)	0.00	
Claim No.	538250	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAN)	Assign Date	29/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/11/2017	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Exc Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Nov 2017		28 Nov 2017 18:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SOH LAY MUI, ID: S1195391C		
Main Claimant:	STEPHANIE YONG CHIN YEE, ID: S6944193I		
Vehicle Reg. No.:	SJS9838Y	Date of Loss:	25/11/2017 00:00 - :59
Claim Type:	TP / 538250	Policy/Cover Note No.:	80395952AVW (Comprehensive) Coverage: 12/03/2017 - 11/03/2018
Vehicle Reg. No. (Insured):	SCH1825C	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/11/2017]		
Driver/Custodian (Insured):	YEO BENG HUAT DAVID (66 / Male), NRIC: S0151808I		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 05 Dec 2017

Preliminary Advice

Insured Vehicle No	: SCH1825C	Accident Date	: 25/11/2017
TP Vehicle No	: SJS9838Y	Assignment Date	: 28/11/2017
Make	: VOLKSWAGEN GOLF	Est. Duration of Repair	: 4-5.00
Date of Inspection	: 04/12/2017		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,731.65
Revised Amount	:S\$	6,295.55
Check Items (Estimated)	:S\$	311.10
Total	:S\$	6,606.65

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	4193I
Vehicle Details	
Vehicle No.	SJS9838Y
Vehicle to be Exported	No
Intended De-registration Date	05 Dec 2017
Vehicle Make	B.M.W.
Vehicle Model	525I XL
Primary Colour	Black
Manufacturing Year	2009
Engine No.	79234524N52B25AF
Chassis No.	WBANU52090C228630
Maximum Power Output	160.0 kW (214 bhp)
Open Market Value	\$52,369.00
Original Registration Date	24 Jul 2009
First Registration Date	24 Jul 2009
Transfer Count	0
Actual ARF Paid	\$52,369.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	23 Jul 2019
PARF Rebate Amount	\$28,802.00
Intended COE Rebate Details	
COE Expiry Date	23 Jul 2019
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$17,501.00
COE Rebate Amount	\$2,741.00
Total Rebate Amount	\$31,543.00

The information contained herein is correct as at 05 Dec 2017

OK

A-Assurance
Assurance in Insurance
Car Insurance Expiring?
 We get you the cheapest insurance renewal

[Click to get quote](#)

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!
[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)
Classic Promo! Best Deal! Fast Selling! Hurry Down Now!

 Flexible Loan. Trade In Are
 Welcome. 100% Deposit Refund
 For Unapproved Loan.
 Classic Credit [Start Now](#)






Browse by Category

Sort by Da

17 vehicles

bmw 525

Advanced S

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	bmw 525		Any	Any	2009	Any	Any
	BMW 5 Series 525i		\$45,500	\$9,120 /yr	29-Oct-2009	2,497 cc	92,000
Very Well Maintained Interior And Exterior. Excellent Condition. 100% Accident Free And Zero Repairs Required. View To Bell Mind From The Largest Consignment Company In SG, Consig... Prem Roy Motoring Posted: 04-Dec-2017 Tags: 2009 BMW 525i, 2009 BMW 525i, BMW 525i, BMW 525i, BMW, 525i, 525i, Used BMW							
	BMW 5 Series 525i XL		\$45,088	\$9,450 /yr	18-Nov-2009	2,497 cc	185,000
Sexy Silver With Black Interior, Selling Due To Upgrade. Regular Servicing And Inspection Done. Body Grooming Also Done R Guarantee A Low Price. Why Wait? Call/SMS Today To Arrange ... Posted: 03-Dec-2017 Tags: 2009 BMW 525i, 2009 BMW 525i, BMW 525i, BMW 525i, BMW, 525i, 525i, Used BMW							
	BMW 5 Series 525i XL		\$49,800	\$11,410 /yr	30-Dec-2009	2,497 cc	-
High/Flexible Loan! Professional 6 Months Workshop's Warranty! Well Maintained By Fussy Owner, Excellent Condition, 100% Upgraded! Mint Condition, Price Negotiable! Call Now To Vi... GS Automobiles Pte Ltd Posted: 03-Dec-2017 Tags: 2009 BMW 525i, 2009 BMW 525i, BMW 525i, BMW 525i, BMW, 525i, 525i, Used BMW							
	BMW 5 Series 525i XL		\$47,900	\$13,990 /yr	22-Jun-2009	2,497 cc	157,530
(We Assure 100% Genuine Mileage,) 100% Accident Free, Original Paintwork, Tip Top Condition, Expensive Rays Engineering Piston BBK x 4, Value For Money, Call And View This Luxur... Posted: 02-Dec-2017 Tags: 2009 BMW 525i, 2009 BMW 525i, BMW 525i, BMW 525i, BMW, 525i, 525i, Used BMW							

[Car Buying](#)
[Car Selling](#)
[Car Aftermarket](#)
[Car Ownership](#)
[On The Move](#)
[Lifestyle](#)
[Buy Tyre](#)
[Latest Sp](#)
[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/11/2017 15:15
Date Of Accident	25/11/2017 11:50
Exact Location Of Accident	RAFFLES BOULEVARD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS9838Y
Insured/Policyholder	
Name Of Registered Owner	STEPHANIE YONG CHIN YEE
NRIC No	S6944193I
Email Address	STEPHANIE.PROP@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97222789
Alternative Phone No	OFFICE-97222789

Vehicle Particulars

Manufacturer	BMW
Model	525
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B80224228SMP
Cover Note Number	

Driver

Name of Driver	STEPHANIE YONG CHIN YEE
NRIC No	S6944193I
Date Of Birth	22/12/1969
Occupation	INDOOR
Date Of Driving Pass	14/04/1994
Driving Experience	23 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97222789
Fax Number	
Contact Number	OFFICE-97222789
Email Address	STEPHANIE.PROP@GMAIL.COM

Address	1 FARRER RD #12-05
Postcode	268817
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	BT TIMAH NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCH1825C
Vehicle Make/Model/Colour	VW GOLF
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

<p>X </p> <p>Policyholder's Signature / Date & Time <u>27/11/17</u></p>	<p></p> <p>Driver's Signature (If driver is not the policyholder) / Date & Time <u>12.19 PM</u></p>	<p></p> <p>Witnessed by Reporting Centre Personnel</p>
--	--	---

Sketch Plan Pg. 2

Describe Circumstances of the Accident

Refer police report no: T/2017/1126/2088

Declaration

I/We declare the foregoing particulars are true in every respect.

X

Policyholder's Signature / Date & Time *[Signature]*

27/11/17
(12.19 pm)

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20171126/2088

1 of 3

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

Report No. T/20171126/2088

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/11/2017 21:28		Vide Report No.:		Station Diary No.: 103	
Informant's Particulars					
Name of Informant: STEPHANIE YONG CHIN YEE			Address: 1 FARRER ROAD #12-05 SINGAPORE 268817		
ID Type / ID No.: NRIC NO / S6944193I			Contact No.: Home/Office: Mobile: 97222789		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 47	Date of Birth: 22/12/1969	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Real estate agent			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 25/11/2017 11:50	Type of Location:
Location: Along Road 1 RAFFLES BOULEVARD Along Raffles Boulevard before Marina Square				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SCH1825C	Car	VOLKSWAGO N	Golf	Grey		0
SHB6373D	Car	MERCEDES BENZ		White		0
SJS9838Y	Car	BMW	525	Black	Slightly Damaged	0



SINGAPORE
POLICE FORCE



T/20171126/2088

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

2 of 3

Report No. T/20171126/2088

CONTINUATION OF REPORT

Brief Details.

On the 25 November 2017 at about 11.50am, I was driving along Raffles Blvg on the 2nd lane from the extreme right. Suddenly, a vehicle VolksWagon golf SCH1825C who was coming out from the minor road along Raffles Link had drove out failing to slow down, did not even Signal and came out from the road and right into my lane and hit onto my front driver bumper and again cut into the lane on my left and wanted to enter Temasek Blvd. while doing so, a comfort Mercedes Benz cab SHB6373D had to brake in order to prevent the collision onto the said vehicle. The said vehicle did not stop and continued to drive off. I notices it's a male driver.

I did not suffered any injuries. My vehicle front driver bumper and dented inward. I have the whole footage capture in my in-build car camera and was able to produce the footage to the police.



SINGAPORE
POLICE FORCE



T/20171126/2088

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

3 of 3

Report No. T/20171126/2088

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Staff Sgt CHEN TIANXIANG, IVAN	Signature Of Informant: 15
Signature Of Interpreter: Not applicable	Date/Time: 26/11/2017 21:28
Officer In Charge Of Case: TP / HRT / SSI 2 SOH PENG GUAN Contact No.: 65476171	Classification Of Case: SN 170
Authentication Stamp NP168	Signature: Singapore Police Force

Mon 04/12 @ 8am
32R

SJS9838Y

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Karpong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/510 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

28 NOV 2017

Estimate No. : b1 44972
Date Estimated : 27/11/2017
Prepared By : Han Kwan Yong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Stephanie Yong Chin Yee
1 FARRER ROAD
#12-05
TULIP GARDEN
Singapore 268817

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJS9838Y	C228630	24/07/2009	525iA	0

DESCRIPTION

To replace front bumper & attachments, front right fender including to knock out dented area caused by the accident

To respray front bumper and front right fender

To carry out body cavity preservation.
(Per panel).

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1X).

To remove old PDC assembly and reconnect to new bumper including conduct checks for proper function.

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

Sundries.

VALUE

✓ 1770. 2,550.00
✓ 1730. 1,923.00
✓ 100. 118.00
✓ 451. 531.00
✓ 150. 177.00
✓ 150. 177.00
✓ 7. 80.00

Total Labour 1: 5,556.00

DESCRIPTION

FRT RH FENDER bt ✓
FRT BUMPER RH SIDE SUPPORT BKT ✓
FRT BUMPER (PDC) ✓
FRT BUMPER SPOILER ✓
RIVET ✓
@ FRT RH FENDER INNER COVERING ?
FRT BUMPER RH BOTTOM COVER ?

QTY	PRIC	VALUE
1	800.15	800.15
1	18.15	18.15
1	1,121.75	1,121.75
1	29.35	29.35
10	0.45	4.50
1	147.25	147.25
1	54.50	54.50

Total Parts : 2,175.65

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

316, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 44972
Date Estimated : 27/11/2017
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJS9838Y	C228630	24/07/2009	525iA	0

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 4/12/17 2455pm Claim No.

Date & Time Excess \$5

Surveyor's Name Taufik Sign Taufik

Surveyor's Tel 97495749. Authorised Yes / No

Authorised Date up Time

RESURVEY PARTS PHOTO BY SURVEYOR No PML Yes / No

Surveyor's E-mail tafik@khairat.com

No. of Working Days Recommended 4-5 days

7973.70

Labour 1	:	5,556.00
Parts	:	2,175.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	541.22
Grand Total	:	8,272.87

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 31 January 2018 11:09 AM
To: 'PBSP'; Taufikh (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SJS9838Y

Dear Caroline,

Confirmed Total Labour & Parts : \$6,599.45

Repair days: 5 days

Final invoice and all supporting documents sent to MSIG

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Monday, 8 January 2018 5:03 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SJS9838Y

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,431.00
Total Parts : 2,168.45
Total Labour & Parts : 6,599.45

Repair days: 5

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 44972
Date Estimated : 27/11/2017
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Stephanie Yong Chin Yee
1 FARRER ROAD
#12-05
TULIP GARDEN
Singapore 268817

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SJS9838Y	C228630	24/07/2009	525ia	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace front bumper and attachments, front RH fender include knocking out dented areas caused by the accident	1770.00		1,770.00			
To respray front bumper and front RH fender	1730.00		1,730.00			
To carry out body cavity preservation. (Per panel).	100.00		100.00			
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00			
To remove old PDC assembly and reconnect to new bumper include conducting checks for proper function	150.00		150.00			
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00			
Sundries.	80.00		80.00			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT RH FENDER	800.15	1.00		800.15
# FRT BUMPER RH SIDE BKT *	17.70	1.00		17.70
FRT BUMPER W/PDC (-M-)	1,346.10	1.00		1,346.10
RIVET	0.45	10.00		4.50

SUPPLEMENTARY ITEMS

Total Labour :	4,431.00
Total Parts :	2,168.45
Total Labour & Parts :	6,599.45
Deduction for Excess :	0.00
Total Repair Costs less Excess:	6,599.45
GST @7%:	461.96
Grand Total :	7,061.41

(A) new

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 44972
Date Estimated : 27/11/2017
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Stephanie Yong Chin Yee
1 FARRER ROAD
#12-05
TULIP GARDEN
Singapore 268817

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJS9838Y	C228630	24/07/2009	525iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT BUMPER RH SIDE BKT *	17.70	1.00		17.70 <i>all</i>

Total Labour :	0.00
Total Parts :	17.70
Total Labour & Parts :	17.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022700/T1VBN2

Date: 07/02/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80395952AVW
Claimant Vehicle No :	SJS9838Y	Insured Vehicle No :	SCH1825C
Date of Loss:	25/11/2017	Nature of Claim:	TP
		Claim No:	538250

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS9838Y	Engine No:	79234524N52B25AF
Make & Model:	BMW 525i, 2.5 XL (A)	Chassis No:	WBANU52090C228630
Reg. Date:	24/07/2009 (Man. Year: 2009)	Odometer:	119337 km
Colour:	Black		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R17	Rear Tyre Size:	245/45R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,497.70	2,248.45	249.25	9.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,476.00	4,351.00	1,125.00	20.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,973.70	6,599.45	1,374.25	17.23
+ GST 7.00/7.00% (S\$)	558.16	461.96	96.20	17.24
Nett Amount (S\$)	8,531.86	7,061.41	1,470.45	17.23

INSPECTION

Date of Assignment:	28/11/2017	
Date Inspected:	04/12/2017	Inspected At:
		Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Feb 2018)
Parts: 143	BMW 525I 2.5 XL (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJS9838Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH FENDER	Bent	800.15 FS	*800.15 FS
2	1		*FRT BUMPER RH SIDE SUPPORT BKT	Not Necessary	18.15 FS	*- FS
3	1		*FRT BUMPER (PDC)	Deformed	1,346.10 FS	*1,346.10 FS
4	1		*FRT BUMPER SPOILER	Not Necessary	29.35 FS	*- FS
5	10		*RIVET	Necessary	4.50 FS	*4.50 FS
6	1		*FRT RH FENDER INNER COVERING	Not Necessary	147.25 FS	*- FS
7	1		*FRT BUMPER RH BOTTOM COVER	Not Necessary	54.50 FS	*- FS
8	1		*FRT BUMPER RH SIDE BKT	Necessary	17.70 FS	*17.70 FS
9	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
					Total Parts (\$\$)	2,497.70 2,248.45

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER & ATTACHMENTS, FRONT RIGHT FENDER INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	2,550.00	1,770.00
2	TO RESPRAY FRONT BUMPER AND FRONT RIGHT FENDER	New	1,923.00	1,730.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
4	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	531.00	451.00
5	TO REMOVE OLD PDC ASSEMBLY AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
6	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (S\$)			5,476.00	4,351.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >