

22/03/2001

ASS. REC. BY:

REF: CS/FCI17022703/Kqbnz

Special Instruction:

Surveyor: Kenneth
CWS

ASSIGNMENT (Office)

From (Person): Lurene Jaw

of FCI

Date/Time: 6:16pm @ 28/11/17

Estimated Cost:

Bill to:

OD TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKT 5876X

Insured: SHB3949M

at Workshop m/s

City Auto

Tel: 64531235

of 160 Sing Ming Drive

Policy No:

Claim No:

D17010973 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:43am @ 29/11/17

Person Contacted:

Vronica

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKT 5876X - X

SHB 3949M - CS/FCI13023610/Uqm3d1 - D.O.A.: 27/11/2013

30/11/17 @ 3:44pm revised to Lurene by email.

1614 @ 12801 Confirmed by email (Ref # 930, 42%)

REF: FCL

ASSIGNMENT

From: Date: 21/12/17

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKT 5876X

at Workshop m/s City Auto
of 160 Sin Ming Dr

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

after 10am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1-B, % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKT 5876X Yr Regn: 06/15

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 c.c. 1496

Colour: M. Red A/C: Insured / Std / NI / NA

Sp. Reading: 17875 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM 8 BM. 42 A 8 G 0311626

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 28/11/17 D.O.I. 28/11/17

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/11 19h pass to Cathrine

RECEIVED 16 APR 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1) 16/4 19h 15h

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + RS: \$

Photos

Others

TOTAL

110
50
50
11
221

Report Format: 7P

Lump Sum / I.B.I. (\$) 1280

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022703/Kqb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-11-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3949M		Veh. Inspected	SKT 5876X
Policy No.			Coverage (\$)	0.00
Claim No.	D17010973MFSH		Excess (\$)	0.00
Assign From	CWS (LURENE JAW)		Assign Date	29/11/2017
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/11/2017		Inspection Date	29/11/2017
Survey held at	160 SIN MING DRIVE # 06-20,			
Repairer	CITY AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010973MFSH

Date: 30 November 2017

Our Ref: CS/FCI17022703/Kqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKT 5876X .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/11/2017 at the premises of M/s CITY AUTO. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,210.00</u> .
Revised Estimate Amount	: S\$ <u>1,280.00</u> .
"Check" Items Amount	: S\$ <u>350.00</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	27-11-2017	Our Ref No. D17010973MFSH
Accident Date	24-11-2017	Claim Type. Third Party
Insured Vehicle	SHB3949M	Third Party Vehicle. SKT5876X
Survey Location	160 BLK 8 SIN MING ROAD #01-58/60/62 SIN MING IND EST	
Contact Person.	VRONICA LAW	
Contact No.	64531235/ 64531235	Fax No. 64537944
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CITY AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231121)



PRI Documents



Close



PRI Header Details

Claim No	D17010973MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & CITY AUTO
Workshop Name	CITY AUTO PTE LTD (Contact Person : VRONICA LAW)	Survey Location & Contact Details	BLK 8 SIN MING ROAD #01-58/60/62 SIN MING IND ES Mobile: 64531235 , Phone: 64531235 , Fax: 64537944 EmailId: CITYAUTO@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM 1		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3949M	TP Vehicle No	SKT5876X
PRI Recieved Date	28-11-2017 02:07:28 PM	Surveyor Appointed Date	28-11-2017 06:14:59 PM	Surveyor Accept Date	29-11-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	29-11-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 30 November, 2017 3:44 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010973MFSH/1
Attachments: CSFCI17022703Kqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SKT 5876X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 29 November, 2017 9:46 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010973MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 28 November, 2017 6:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010973MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

First Capital Insurance Limited

36 Robinson Road

#16-01 City House 048546

Singapore

Attention : Motor Claim Department

Contact : 65073848 Fax No. : 65073849

Estimate : ES004850

Date : 27/11/2017

Vehicle Num. : SKT 5876X

Make/Model : Mazda 3

Chassis/Eng# : JM6BM42A8C0311626

Accident Date : 24/11/2017

Claim No. : TP FC

Reference :

Policy No. : DHOM120021331601

S/N Quantity Particular Unit Price Amount S\$

1.	1	LIST ITEMS : Rear bumper		1,075.00	✓
		List Total S\$:		1,075.00	
		20.00% Discount S\$:		215.00	
				860.00	
1.	1	SPECIAL NETT ITEMS : Reverse sensor		350.00	✗
		Special Nett Total S\$:		350.00	
		LABOUR :			
		*To knock jackout damaged parts, panel beating,		350.00	2000
		welding, align, refix and to renew accident parts			
		*Spray painting on affected & replace parts		650.00	2200
		Labour Total S\$:		1,000.00	

E. & O.E.

Total S\$: 2,210.00

for CITY AUTO PTE LTD

LKK Auto Consultants hence notify the Repalrer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repalrer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022703/Kqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3949M	Veh. Inspected	SKT 5876X	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17010973MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	28/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JM6BM42A8G0311626	Colour	METALLIC RED	
Odometer	17875	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TOYO	8 mm	
L/H Front Tyre	205/60 R16	TOYO	8 mm	
R/H Rear Tyre	205/60 R16	TOYO	8 mm	
L/H Rear Tyre	205/60 R16	TOYO	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/11/2017	Inspection Date	29/11/2017	
Survey held at	160 SIN MING DRIVE # 06-20,			
Repairer	CITY AUTO PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 5876X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / CRACKED	1,075.00	1,075.00
	LESS 20% DISCOUNT		-215.00	-215.00
			860.00	860.00
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	SERVICEABLE	350.00	-
			350.00	-
	LABOUR			
	TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.		350.00	200.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		650.00	220.00
			1,000.00	420.00
	GRAND TOTAL		2,210.00	1,280.00
RECOMMENDED COST OF REPAIRS				1,280.00

Report Ref No. CS/FC117022703/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.