

<<

Service Request Details

Claim

S7M004VS

Reference

CS3/ASM17022721/Apb3s2 

Loss Date

November 27, 2017

Request Date

July 27, 2018

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Direct settlement

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration #

SJX5358R

Make

TPVD VOLKSWAGEN

Model

SCIRROCCO

Service Address

7 KOVAN ROAD, , , 544896

Primary Contact/Insured

LIM YEW BIN
7 KOVAN ROAD, 544896, Singapore
97899409
YEWBINLIM@YAHOO.COM.SG

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

NO TP Xs. NON ARC

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document Type	Document SubType			
+ Upload Documents				
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1[1].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	November 9, 2018
 LKKPreRepairInspection[1].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 9, 2018
 LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 1, 2018
 Email to TP_reject dd 231217.pdf	Letters and Correspondence	Third Party	LKK AUTO CONSULTANTS PTE LTD (TP)	December 23, 2017
 Cl.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	TAN Wancong	November 29, 2017
 Pol Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	TAN Wancong	November 29, 2017

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 GIA SJX5358R TP.pdf	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	November 29, 2017
 GIA SCH5454M INSD.PDF	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	November 29, 2017
 EMAIL.pdf	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	November 29, 2017