

INS. CASE OWNER:

CC 3/1AIG1702

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE

ASSIGNMENT



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time		STAGE	DATE / PIC
1/1/14	SLQ 4731R	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
1/15/14	Email letter to OI	Documentation Check List: Handler	Typist
	Receive TP accident photo.	Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
Specialization	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$5	(days) Reduction:	%
Final Settlement	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	NIL
Repair Cost:	\$5 830.00		
Loss of Rental (LOR):	\$5	(days)	
Loss of Use (LOU):	\$5 325.00	(5325 x 1 days)	
Loss of Income (LOI):	\$5	(5 x days)	
LOI only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	\$5 5.00		
Medical:	\$5		
Disbursement:	\$5	(e.g. Tow/ Independent)	
Repair Cost	\$5		
Global Sum	\$5 1160.00	Global Sum \$5: 1150.00	
Final Payment	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Invoice 1:	\$5 1150.00	Name 1:	SMRT Buses Ltd
Invoice 2: (Strike if N.A.)	\$5	Name 2:	
Invoice 3: (Strike if N.A.)	\$5	Name 3:	

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 3.8% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SG 58074. Yr Regn: 5/6/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN A95 cc 1057g

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 300/7 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMAA 9522 897005482

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / SiRim / STD A/Rim or

Tyre Size: F: 275/70R22-5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 1/11/2017

D.O.I. 17/11/2017

Survey held at 3 MKJ

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction

17/10/18 Confirm I-B = \$830.00 with 1 working days

(Red = \$397.00
32.1.)

Date/Time. File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time. File Return to?

Survey Fee: _____

2)

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

S + RS _____

☐ : Interview (\$ _____)

Photos _____

☐ : Tech. Invs (\$ _____)

Others _____

☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC0/LCR17022724/Swb3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 29-11-2017



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 4731R	Veh. Inspected	SG 5807U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	01/11/2017	Inspection Date	27/11/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		



5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG5807U
Ref. No : BUS/11/17/1001
Reg. Date : 05/06/2017
Vehicle Type : DOUBLE DECK
Make : MAN
Model : MAN A95
Name of Driver : Liu Changyue
Type of Accident : SIDE SWIPE
Date / Time of Accident : 01/11/2017 12:10:00 PM
Accident Reported Date / Time : 03/11/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Chartis
Vehicle is Towed Back? : No
Towed Back Date/Time : 01/01/2000
Replacement Vehicle Issued? : No
Accident Repair Job Card No : 000024093742
Special Instruction to ARC, if any :
RIGHT REAR SCRATCH
Prepared Date : 06/11/2017 10:49:31 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : WMAA95ZZ8G7003452

Mileage

0

Work Shop :

Repair Completed Date / Time :

01/01/2000

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 795.00	530.00
Total Spray Painting Charges	: 432.00	300.00
Total Material Charges	: 0.00	0.00
Other Charges	: 0.00	0.00
TOTAL	: 1,227.00	830.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 2.00	1.00
Prepared / Adjusted By	:	SEBASTIAN-LKK
Arc / Surveyor Sign Off Date	: 27/11/2017 01:00:11 PM	10/02/2018 05:05:00 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 27/11/2017 12:01:06 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	795.00	530.00 /
Total Labour	795.00	530.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	432.00	300.00 /
Total Spray Painting & Panel Beating	432.00	300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

530
+ 300

830

Sebastian
19/5/18

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)								0.00	0.00	



Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG5807U
 Ref. No : BUS/11/17/1001
 Reg. Date : 01/01/1900
 Vehicle Type : DOUBLE DECK
 Make : MAN
 Model : MAN A95
 Name of Driver : Liu Changyue
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 01/11/2017 12:10:00 PM
 Accident Reported Date / Time : 03/11/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Charis
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 RIGHT REAR SCRATCH
 Prepared Date : 06/11/2017 10:49:31 AM



LRX Auto Consultants hence notify the Repaiar of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repaiar

Signature:

Date:

Sebastian

27/11/2017

- Part by part repair

- Photo After Repair.

Chassis No : Mileage : 0
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	795.00	0.00
Total Spray Painting Charges	432.00	0.00
Total Material Charges	0.00	0.00
Other Charges	0.00	0.00
TOTAL	1,227.00	0.00
Lum Sum Total	0.00	0.00
No. of Repair Days	2.00	0.99 ^{1 Day}
Prepared / Adjusted By		
Arc / Surveyor Sing Off Date	27/11/2017 01:00:11 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 27/11/2017 12:01:06 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	795.00	-0.00 530
Total Labour	795.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	432.00	-0.00 360
Total Spray Painting & Panel Beating	432.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
-------------	---------	----------	-----------	-----	-----------------	--------------	------------------	-----------------	-------------------	-----------------

TOTAL MATERIALS

TOTAL MATERIALS(Discounted)

0.00 0.00

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Vivian Lau (LKKAuto)

From: Eileen Bay Yee Ling (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)
<eileenbay@smrt.com.sg>
Sent: Tuesday, 24 July, 2018 5:41 PM
To: Admin A
Cc: CS A Team
Subject: LOD - ACCIDENT INVOLVING SG5807U AND SLQ4731R ON 01/11/2017 ALONG TEMASEK BOULEVARD
Attachments: img-724173321-0001.pdf

Our Ref: BUS/11/17/1001/EB

Dear Sir / Madam,

We claim on behalf of SMRT BUSES LTD, owner of the vehicle Reg. No.: SG5807U.
Your driver's negligent driving has caused the above accident. As a result, my client has suffered the following losses:-

Cost of Repair	\$830.00
Loss of Use	\$350.00 (1 days x \$350.00)
LTA Search Fee	\$5.00
Total	\$1,185.00

We enclose the following documents:

- 1) Repair Invoice
- 2) LTA Search
- 3) SAS report

We look forward to your confirmation to settle our claims within 15 days from the date of this email.
Kindly issue payment in favour to SMRT BUSES LTD.

Thanks and regards,

Eileen Bay

Claims and Insurance Agency (Bus Team)
DID: +65 6556 3549 | E: eileenbay@smrt.com.sg
6 Ang Mo Kio Street 62
Singapore 569140



Vivian Lau (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Friday, 1 December, 2017 2:48 PM
To: 'eyap@lioncityrentals.com.sg'
Cc: Zayyer (LKKAUTO); Hsiao Tong (LKKAUTO)
Subject: ACCIDENT INVOLVING SLQ 4731R AND SG 5807U ON 01/11/2017

Our Ref: CC3/LCR17022656/K1wa3

01 December 2017

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLQ 4731R AND SG 5807U ON 01/11/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within 7 days i.e. by **12/12/2017**, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORISATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I/WE, SMRT BUSES LTD (the third party claimant) of 6 Ang Mo Kio Street 62 Singapore 569140 (address), owner of SG 5807U (vehicle no.) hereby authorize SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SG 5807U that was damaged pursuant to the accident which occurred on 01/11/2017 (date) along ROUNDAABOUT AT FOUNTAION OF WEALTH (location) involving vehicle no/s SLQ 4731R ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the SMRT BUSES LTD

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 11 (day) of April (month) 2019 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG ASIA PACIFIC-EXPRESS THIRD PARTY CLAIM)

"We/I, SMRT AUTOMOTIVE SERVICES PTE LTD (the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for \$ 1,150.00 (Global Sum) for vehicle no. SG 5807U that was damaged pursuant to the accident which occurred on 01/11/2017 (date) along ROUNDAABOUT AT FOUNTAION OF WEALTH (location) involving vehicle no/s SLQ 4731R

This is pursuant to the inspection conducted on 27/11/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SMRT BUSES LTD (the third party claimant") of vehicle no. SG 5807U make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage SG 5807U (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 11 (day) of April (month) 20 19 (year)

MRB



Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"



Customer Code: 3000066

SMRT BUSES LTD

Block Unit
STREET 62
6 ANG MO KIO
SINGAPORE 569140



PT
SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 1990042802
Invoice No. : IV180300536
Date : 21.03.2018
Vehicle No. : SG5807U
Your Ref No. : BUS/11/17/1001
Our Ref No. : 24093742
Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
Labour					
TO REPAIR RH REAR PORTION	1.00	\$ 530.00	0.00	\$ 0.00	\$ 530.00
Others					
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR TEMS	1.00	\$ 300.00	0.00	\$ 0.00	\$ 300.00

GRAND TOTAL \$ 830.00

Remark :

Make/Model : MAN A95
Accident Date : 01.11.2017

N.B. Payment by cheque should be crossed and made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.


Authorized Signature
for SMRT Automotive Services Pte Ltd

Enquire Transaction History

Transaction History Details

Log Date/Time: 06 Nov 2017 / 08:55:03

Asset Type:	Vehicle	Transaction Amount:	\$5.35
Asset ID:	SLQ4731R		
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)	Channel:	External Agency
User ID:	ESASBAHO - BALQISH BINTE ABDUL HALIL	Business Transaction Reference No.:	20171106085503853150

Search Date / Time: 01 Nov 2017 12:10:00

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Information displayed is correct as at the log date and time.

Enquire Related Logs

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Nov 2017 Edit Reg		27 Nov 2017 00:00 Edit Adj Rpt	S\$830.00 Edit Estimates	S\$830.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF Pte Ltd, Co. Reg. No.: NA		
Main Claimant:	SMRT BUSES LTD, Co. Reg. No.: 198202292D		
Vehicle Reg. No.:	SG5807U	Date of Loss:	01/11/2017 12:00 - :59 [4 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5365515995SG	Policy/Cover Note No.:	0999995068
Vehicle Reg. No. (Insured):	SLQ4731R	Policy No. (Claimant):	D-IIO27592MFBP
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Cheok, Lee Wai] Cheok.LeeWai@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 08/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SG5807U (5365515995SG)**
[SLQ4731R]

TP

SMRT BUSES LTD

Nov 1 2017 12:00PM

[LCRF Pte Ltd]

SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit
Photos/Images				
			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/05/18 17:39	General View		Load JPG
2	31/05/18 17:39	General View		Load JPG
3	31/05/18 17:39	General View		Load JPG
4	31/05/18 17:39	General View		Load JPG
5	31/05/18 17:39	General View		Load JPG
6	31/05/18 17:39	General View		Load JPG
7	31/05/18 17:39	General View		Load JPG
8	31/05/18 17:39	General View		Load JPG
9	31/05/18 17:39	General View		Load JPG
10	31/05/18 17:39	General View		Load JPG
11	31/05/18 17:39	General View		Load JPG
12	31/05/18 17:39	Odometer Reading		Load JPG
13	31/05/18 17:39	Chassis Number		Load JPG
Documentation				
			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/11/17 19:12	TP ESTIMATE- MARKED		Load PDF
2	29/11/17 19:12	TP GIA REPORT		Load PDF
3	01/12/17 14:58	Email letter to OIACCIDENT INVOLVING SLQ 4731R AND SG 5807U ON 01.11.2017		Load PDF
4	15/11/18 17:41	TP accident photos		Load PDF
5	26/04/19 12:14	WORKSHOP INVOICE		Load PDF
6	26/04/19 12:14	AUTHORISATION TO ACT FORM		Load PDF
7	26/04/19 12:14	Release Voucher		Load PDF
8	26/04/19 12:14	LTA SEARCH		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/11/17 10:35	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLQ4731R (Insd veh)	Model:	MAN A95 10.5 D (A)
	SG5807U (TP veh)		
Date of Accident:	01/11/2017		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	:	\$	1,227.00	
Final Repair Cost	:	\$	1,150.00	
Loss of Use	:	\$		1.00 days at \$325.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$	1,150.00	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	SMRT Buses Ltd	: \$	1,150.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

26 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:189607188R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR17022724/SWB3Q2

Date: 26/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995068

Claimant Vehicle No: SG5807U Insured Vehicle No: SLQ4731R

Date of Loss: 01/11/2017 Nature of Claim: TP Claim No: 5365515995SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SG5807U**
 Make & Model: MAN A95, 10.5 D (A) Engine No: 50344472024450
 Reg. Date: 05/06/2017 (Man, Year: 2016) Chassis No: WMAA95ZZ8G7003452
 Colour: Green Odometer: 30017 km
 Engine Capacity: 10518 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,227.00	830.00	397.00	32.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,227.00	830.00	397.00	32.36
+ Loss of Use (1.0 x S\$325.00/day) (S\$)		325.00		
+ Doc/Search Fee (S\$)		5.00		
Nett Liability (S\$)		1,160.00		
Global Sum Settlement (S\$)		1,150.00		

INSPECTION

Date of Assignment: 27/11/2017

Date Inspected: 27/11/2017 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 1.0 days

Adjuster: Sebastian Yeang Wai Keen**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR RH REAR PORTION	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	432.00	300.00
Gross Labour Cost (S\$)			1,227.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >