

ASS. REC. BY:

REF: CS/FCI17022735/R1 vbm2

Special Instruction:

Surveyor: Rasu

ASSIGNMENT (Office)

CWS

From (Person): Joanne Yongof FCIDate/Time: 3:35 pm @ 29/11/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGK6238B

Insured:

SHC2567H

at Workshop m/s

Bain Cheron Motor

Tel:

62641191

of

Blk 3 Pioneer Road North # 01-14/15

Policy No:

Claim No:

D17011018MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5:31 pm @ 29/11/17

Person Contacted:

PertinVehicle IN / OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	<u>SGK6238B-NA/INC15015971/h4-D.O.A: 22/09/2015</u>
	<u>SHC2567H-NS/INC17016316/k2 rbn2-D.O.A: 18/08/2017</u>
<u>30/11/17</u>	<u>Send preli revised by email</u>
<u>14/12/17</u>	<u>LS \$1500 confirmed by email (Ref 1249.81, 4519)</u>

Page 1 of 1

REF:

# ASSIGNMENT

14/12

COX KPI 4:2021/2022

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY  
 To/Inspect Vehicle No: **SGK 6238K**  
 at Workshop mis: **Bam Chon**  
 of: **3, Promea 20 North #61-14/15**  
 Insured: **FU/imp**  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **SGK 6238B** VR Reg: **2086 424**  
 Type: **C** M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: **TOYOTA VIOS 1.5 EA** DO: **1497**  
 Colour: **Gold** A/C: \_\_\_\_\_ Insured / Std / NI / NA  
 Sp. Reading: **737.2** T. Radio: Insured / Std / NI / NA  
 Eng No: \_\_\_\_\_  
 O.No: **MROS 344 4204199450**  
 Gen. Cond: Good / **C** Fair / Poor / Burnt  
 Steering: In order / **C** Jammed / Leaked / Burnt or  
 Brake: In order / **C** Jammed / Leaked / Burnt or  
 Mod: Nil / **C** SRM / STD AirRim or  
 Tyre Size: F: **195/50R15**  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / **C** MC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: **5** mm R/Bal: **5** mm  
 L/Bal: **5** mm L/Bal: **5** mm  
 D.O.A: **26/11/17** D.O.L: **29/11/17**  
 Survey held at: **Bam Chon**  
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or  
**RGAR N/S**  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 14 DEC 2021

Date/Time File Pass to: ☐ Prel. Report

☐ Final Report

Date/Time File Return to:

14/12 - Typist

Report Format: **CWS**

Lump Sum / I.B: **1500/2**

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp: \$

☐ Interfey: \$

☐ Tech: \$

☐ Weekend: \$

Survey Fee

Transportation

Food

Other

Total

110

50

50

33

243

## Survey Department Check List (Case Handler)

Reference No. : **CS/FC 170 22735/ Rlvb**

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

### (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

### (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

### (4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 14/12/17  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022735/R1vb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-11-2017	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 2567H		Veh. Inspected	SGK 6238B
Policy No.			Coverage (\$)	0.00
Claim No.	D17011018MFSH		Excess (\$)	0.00
Assign From	CWS ( JOANNE YONG)		Assign Date	29/11/2017
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	26/11/2017		Inspection Date	29/11/2017
Survey held at	BAN CHOON MOTOR WORKS 3 PIONEER ROAD NORTH #01-14/15 SINGAPORE 628457			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

<b>Date</b>	28-11-2017	<b>Our Ref No.</b> D17011018MFSH
<b>Accident Date</b>	26-11-2017	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC2567H	<b>Third Party Vehicle.</b> SGK6238B
<b>Survey Location</b>	BLK 3 PIONEER ROAD NORTH #01-14/15	
<b>Contact Person.</b>	PERLIN	
<b>Contact No.</b>	62641191/ 0	<b>Fax No.</b> 62611324
<b>Survey Type</b>	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	BAN CHOON MOTOR WORKS	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	JOANNEY	

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231176)



PRI Documents



Close



## PRI Header Details

Claim No	D17011018MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & BAN CHOC
Workshop Name	BAN CHOON MOTOR WORKS (Contact Person : PERLIN)	Survey Location & Contact Details	BLK 3 PIONEER ROAD NORTH #01-14/15 Mobile: 0 , Phone: 62641191 , Fax: 62611324 EmailId: BANCHOON@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC2567H	TP Vehicle No	SGK6238B
PRI Recieved Date	28-11-2017 07:18:57 PM	Surveyor Appointed Date	29-11-2017 03:34:45 PM	Surveyor Accept Date	29-11-2017 0

## Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	29-11-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

## Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 14 December, 2017 4:29 PM  
**To:** 'perlin'; SUR  
**Subject:** RE: Vehicle No. SGK 6238 B - Finalization

Dear Perlin,

Noted with thanks.

**Final invoice and all supporting documents sent to First Capital Ins Ltd.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** perlin [mailto:banchoon@singnet.com.sg]  
**Sent:** Thursday, 14 December, 2017 4:21 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** Re: Vehicle No. SGK 6238 B - Finalization

Dear Veron

COR @ lump sum \$1,500.00 (before GST) and 5 days for repairs - confirmed.

By the way, Final invoice and all supporting documents sent to LKK Auto or First Capital Ins Ltd.

Regards

Perlin

On 14/12/2017 4:07 PM, Veron Chen (LKKAuto) wrote:

Dear Perlin,

Kindly confirmed Lump Sum \$1500/-

No of days: 5 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** perlin [<mailto:banchoon@singnet.com.sg>]  
**Sent:** Thursday, 14 December, 2017 3:38 PM  
**To:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** Fwd: Vehicle No. SGK 6238 B - Finalization

Re-send

----- Forwarded Message -----

**Subject:** Vehicle No. SGK 6238 B - Finalization  
**Date:** Mon, 4 Dec 2017 14:08:13 +0800  
**From:** perlin <[banchoon@singnet.com.sg](mailto:banchoon@singnet.com.sg)>  
**To:** Rasul (LKKAuto) <[rasul@lkkauto.com](mailto:rasul@lkkauto.com)>

Hi Rasul

Attached herewith are vehicle no. SGK 6238 B revised quotation and  
after spray paint photos for your finalization.

Thanks & Regards.

Perlin



Virus-free. [www.avg.com](http://www.avg.com)



Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Thursday, 30 November, 2017 12:26 PM  
**To:** 'Claim Workflow System'  
**Cc:** JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D17011018MFSH/1, SGK 6238B  
**Attachments:** SGK 6238B PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGK 6238B  
Date of survey: 29/11/2017  
Number of days: 5 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 29 November, 2017 5:33 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D17011018MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]  
**Sent:** Wednesday, 29 November, 2017 3:35 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG](mailto:CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG); [JOANNEYONG@FIRST-INSURANCE.COM.SG](mailto:JOANNEYONG@FIRST-INSURANCE.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D17011018MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17011018MFSH  
Our Ref: CS/FCI17022735/R1vb

Date : 30/11/2017

The Motor Claims Department  
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SGK 6238B**


We thank you for your instruction on 29/11/2017

Please be informed that we had conducted the inspection of the above mentioned  
29/11/2017 at the premises of M/s BAN CHOON MOTOR WORKS  
and have the following to report:-

Workshop Estimate Amount	: S\$	2,749.81
Revised Estimate Amount	: S\$	1,896.94
"Check" Items Amount	: S\$	94.05
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	

**Description of Damage:**

The vehicle sustained damages at the  
rear n/s portion.



Comments/Present Status:  
Damages Consistent

Yours faithfully,

**MOHAMMED RASUL**  
**Automotive Assessor**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type	Singapore NRIC
Owner ID	2413Z
<b>Vehicle Details</b>	
Vehicle No.	SGK6238B
Vehicle to be Exported	No
Intended De-registration Date	14 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	VIOS 1.5E A
Primary Colour	Gold
Manufacturing Year	2006
Engine No.	1NZX463248
Chassis No.	MR053HY4204199450
Maximum Power Output	80.0 kW (107 bhp)
Open Market Value	\$12,347.00
Original Registration Date	21 Aug 2006
First Registration Date	21 Aug 2006
Transfer Count	4
Actual ARF Paid	\$9,734.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date	30 Jun 2021
COE Category	A - Car (1600cc & below)
COE Period(Years)	5
PQP Paid	\$23,227.00
COE Rebate Amount	\$16,465.00
<b>Total Rebate Amount</b>	<b>\$16,465.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Dec 2017

OK



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM



# 萬 春 摩 哆 BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GSTReg. No. 351915/00A

**GST Regn No. 35191500A**

30/11/17 Send IA

28/11/2017

First Capital Insurance Ltd  
36 Robinson Road  
#16-01 City House  
Singapore 068877

Attn: Motor Claims Dept.

Dear Sirs

QUOTATION FOR REPAIRS OF VEHICLE NO. SGK 6238 B  
MODEL: TOYOTA VIOS  
DATE OF ACCIDENT: 26/11/2017  
YOUR INSURED VEHICLE NO. SHC 2567 H

1 pc	LH taillamp	\$	374.80	<i>pho /</i>
1 pc	Rear bumper		374.45	<i>add DE</i>
2 pcs	Rear bumper side retainers @ \$132.55 each		265.10	<i>X 43.20</i>
10 pcs	Rear bumper clips @ \$2.00 each		20.00	<i>new</i>
1 pc	Rear fender air scoop		125.40	<i>7. x nn</i>
		\$	1,159.75	
	Less: 25% discount		289.94	
		\$	869.81	
1 pc	Reverse sensor		280.00	<i>SN 220 NW</i>

## LABOUR CHARGES:

To knocking and straightening of all necessary damaged parts,  
To changing of the above part.  
To putty and spray painting on accident damaged parts.

800.00 *500*  
800.00 *600*  
\$ 2,749.81

Yours faithfully,

*Perindoloy*

*Rasul*  
*Hp 90010068*

*5 days*

*48*

*29/11/17 @ 1545*

*Resurvey after repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022735/R1vbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-12-2017	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 2567H	Veh. Inspected	SGK 6238B	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011018MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	29/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA VIOS 1.5E A	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	MR053HY4204199450	Colour	GOLD	
Odometer	73712	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/50 R15	MICHELIN	5 mm	
L/H Front Tyre	195/50 R15	MICHELIN	5 mm	
R/H Rear Tyre	195/50 R15	MICHELIN	5 mm	
L/H Rear Tyre	195/50 R15	MICHELIN	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/11/2017	Inspection Date	29/11/2017	
Survey held at	BAN CHOON MOTOR WORKS 3 PIONEER ROAD NORTH #01-14/15 SINGAPORE 628457			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGK 6238B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	LH TAILLAMP	BROKEN	374.80	374.80
1	REAR BUMPER	DEFORMED	374.45	374.45
2	REAR BUMPER SIDE RETAINERS @\$132.55	N/S CRACKED	265.10	43.20
10	REAR BUMPER CLIPS @\$2.00	NECESSARY	20.00	20.00
1	REAR FENDER AIR SCOOP	NOT NECESSARY	125.40	-
	LESS 25% DISCOUNT		-289.94	-203.11
			869.81	609.34
<b>SPECIAL NETT ITEMS</b>				
1	REVERSE SENSOR (SN)	NOT WORKING	280.00	220.00
			280.00	220.00
<b>LABOUR</b>				
	TO KNOCKING AND STRAIGHTENING OF ALL NECESSARY DAMAGED PARTS, TO CHANGING OF THE ABOVE PART.		800.00	500.00
	TO PUTTY AND SPRAY PAINTING ON ACCIDENT DAMAGED PARTS.		800.00	600.00
			1,600.00	1,100.00
<b>GRAND TOTAL</b>			<b>2,749.81</b>	<b>1,929.34</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,500.00</b>

Report Ref No. CS/FCI17022735/R1vbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.