

SMRT Accident Vehicle Repair Estimates

AIG

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5983A
 Ref. No : TAX/11/17/2156
 Reg. Date : 05/06/2013
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : CHNG AH GUAN
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 24/11/2017 03:30:00 PM
 Accident Reported Date / Time : 25/11/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093290
 Special Instruction to ARC, if any :
 SF77Y
 Prepared Date : 25/11/2017 11:27:03 AM



Sebastian.
 27/11/2017.
 - Lump Sum Repair.
 - Question Mark Item
 Photo.
 - Photo After Paint.

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB135661


Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	338.00	0.00
Total Spray Painting Charges :	378.00	0.00
Total Material Charges :	2,382.10	2,430.72
Other Charges :	896.88	0.00
TOTAL :	3,994.98	0.00
Lum Sum Total :	4,000.00	0.00
No. of Repair Days :	3.00	0.00
Prepared / Adjusted By :		2 days
Arc / Surveyor Sign Off Date :	27/11/2017 10:05:13 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 27/11/2017 09:16:00 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00 200
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
Total Spray Painting & Panel Beating	378.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	0.00 ✓
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓
Total Other Costs	896.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace ✓	Replace 04/04/11	No
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace ✓	Replace 07/	No
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace ?	Replace	No
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace ?	Replace	No
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace ?	Replace	No
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace ?	Replace	No
96873820	REAR		COVER TOWING EYE RR	1	21.00	10.00	18.90	Replace X	Replace	No
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace ?	Replace	No
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace ?	Replace	No
TOTAL MATERIALS							3,038.40	3,038.40		
TOTAL MATERIALS(Discounted)							2,382.10	2,430.72		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									