Surveyor: Rame | REF: AXA 227745 | MPA3 | 8939C

ASSIGNMENT

From: | Date: 01.12.2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 3022

at Workshop m/s Connect 3

of 566 Woodlands Rd

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: Winnie - 98509666

10.30 am

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: PC 3022 Yr Regn: 2011 FEB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: GOLDEN DRAGON c.c 8849

Colour MULTI A/C: Insured / Std / NI / NA

Sp.Reading 276701 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: LFZBHCDKOAA003658

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 11R22.5

R: " " O/P

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or WESTLAKE

Front		Rear	
R/Bal.	8 mm	R/Bal.	8/8 mm
L/Bal.	8 mm	L/Bal.	8/8 mm
D.O.A.	16/11/17	D.O.I.	01/12/17

Survey held at CONNECT 3

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($ ☐ : Interview ($ ☐ : Tech. Invs ($ ☐ : Weekend ($

Report Format :

Lump Sum / I.B.I: ($

Survey Fee:

Transportation:

($ + PS $)

Photos

Others

TOTAL