

Surveyor

REF: CS/LAW17022768/Dqbe2

Special Instruction:

US: \$ 19950.00

Third Parties:

Claimant:

Surveyor: Constant Appraiser

Workshop: LYS Engineering

From (Person): Scarlett Lim of Central Chambers Date/Time: 30.11.2017
Estimated Cost: _____ Bill to: _____

OD (TP Re-inspection) / Evaluation

To Inspect Vehicle No: XE 1733B Insured: XD 8776L
at Workshop m/s LYS Engineering Tel: 9730 8695
of 77A Jurong Port Rd #01-24/26
Policy No: _____ Claim No: RKC/170489/p/mm
Sum Insured: _____ Excess: _____
Make of Veh: _____ D.O.A. 09.09.2016
(Client's Record)

06.12.2017 (Wednesday) @ 1pm

SJE

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 8 days)
Date/Time: 5/1/18 Submit Final Fig \$ 10 000, 7 days (Red \$ 9950 / 50 %; Original 9 days)

Date/Time	Action/Instruction
	15 Pioneer Walk Singapore 627753
	XE 1733B - x
	XD 8776L - x
05/01/2018	To Submit L/S 10K with 7 days of rep. SVL = most parts photo show no damage (Record only) Damage minor

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 05 JAN 2018

\$ 1000.00

Para(3) : Nett Value

Market Value : _____
Salvage Value : _____
Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date:

Basic & Add
Transport
Photos
Others
Total

- | | |
|---------------------------------------|-----------------------------------------|
| 1) Date/Time _____ File Pass to _____ | 2) Date/Time _____ File Return to _____ |
| 3) Date/Time _____ File Pass to _____ | 4) Date/Time _____ File Return to _____ |
| 5) Date/Time _____ File Pass to _____ | 6) Date/Time _____ File Return to _____ |

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____ Excess: _____

(Client's Record)

Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No. **XE 1733B** Page **May 2016**Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: **Mitsubishi Fuso FP51** to **11967**Colour: **Blue** A.O. Insured / Std / NI / NASo. Reading: **151806** T. Radio: Insured / Std / NI / NAEng No: **0M457320816**C No: **FP518DA20025**Gen. Cond: **Good** / Fair / Poor / BurntSteering: **In order** / Jammed / Leaked / Burnt orBrake: **In order** / Jammed / Leaked / Burnt orModi: **Nil** S/Rim / STD A/Rim orTyre Size F: **295 / 80 R22.5**
R: **— " — (double)**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front **P211en** Rear **P211 Firenze**R.Bal. **6** mm R.Bal. **6 / 6** mmL.Bal. **6** mm L.Bal. **6 / 6** mmD.O.A. **09/09/2016** D.O.I. **06/12/2017**Survey held at: **15 Pioneer Walk**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

Date/Time File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee

Transporter

Lump Sum / I.B.I. / S

Folio

Sheet

TOTAL

Add Fee: ☐ Site Insp. / S☐ Interview / S☐ Tech. Ins. / S☐ Vehicle / S

Report Format: _____

Lump Sum / I.B.I. / S




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CENTRAL CHAMBERS LAW CORPORATION		Ref : CS/LAW17022768/Dgb	
150 CECIL STREET #03-00 SINGAPORE 069543		Date : 30-11-2017	
SINGAPORE 069543		Code : L139	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	XD 8776L	Veh. Inspected	XE 1733B
Policy No.		Coverage (\$)	0.00
Claim No.	RKC/170489/p/mm	Excess (\$)	0.00
Assign From	SCARLETT LIM	Assign Date	30/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/09/2016	Inspection Date	06/12/2017
Survey held at	15 PIONEER WALK		
Repairer	LYS ENGINEERING		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>
Sent: Thursday, 30 November, 2017 9:13 AM
To: assignments
Subject: FW: SJE Appointment for MC/MC 11756/2017
Attachments: 171129-Ltr to LKK Auto (SJE appointment).pdf; Pf Accident Statement (XE 1733B).pdf; Df Accident Statement (XD 8776L).pdf; Pf Surveyor Constant Appraiser.pdf

Dear Assignment Team

Please mark down this RI appointment and print documents for me.

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Scarlett Lim [mailto:scarlett@centralchambers.com.sg]

Sent: Wednesday, 29 November 2017 7:00 PM

To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Cc: Pushpa <Pushpa@centralchambers.com.sg>; Celine Fong (LKKAuto) <celinefong@lkkauto.com>

Subject: RE: SJE Appointment for MC/MC 11756/2017

Dear Bryan,

We attach herewith our letter dated 29 Nov 2017, and the relevant documents from both the Plaintiff and the Defendants:-

1. Accident Statement of XE 1733B (Plaintiff's vehicle);
2. Accident Statement of XD 8776L (1st Defendant's vehicle);
3. Plaintiff's survey report from Constant Appraiser Services dated 6 February 2017;
4. 45 pages of colour photographs of XE 1733B from Constant Appraiser Services (available for download at <https://spaces.hightail.com/space/ogdgz0uSAg>); and
5. In-vehicle video footage from XE 1733B (Plaintiff's vehicle) (available for download at <https://spaces.hightail.com/space/ogdgz0uSAg>).

Kindly note that the Defendants do not have a re-survey report or photographs.

Regards,

Scarlett LIM

Associate

Central Chambers Law Corporation

150 Cecil Street

#03-00

Singapore 069543

Tel: (65) 65380 100

DID: (65) 65971 856

Fax: (65) 65384 123

Email: scarlett@centralchambers.com.sg

CONFIDENTIALITY NOTICE: This email is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by return email and delete the original email from all your files and storage devices. Thank you.

From: Bryan Ang (LKKAUTO) [<mailto:bryanang@lkkauto.com>]
Sent: Friday, 24 November, 2017 2:20 PM
To: Scarlett Lim <scarlett@centralchambers.com.sg>; Celine Fong (LKKAUTO) <celinefong@lkkauto.com>
Cc: Dillen Selvarajoo <DillenSelvarajoo@tokiomarine.com.sg>
Subject: RE: Request for CV of Mr Bryan Ang

Dear Scarlett

The proposed timing is fine with me.

Kindly provide full set of Plaintiff survey report and photos, Defendant's re-inspection report and photos, both sets of accident reports.

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Scarlett Lim [<mailto:scarlett@centralchambers.com.sg>]
Sent: Friday, 24 November 2017 12:32 PM
To: Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; Celine Fong (LKKAUTO) <celinefong@lkkauto.com>
Cc: Dillen Selvarajoo <DillenSelvarajoo@tokiomarine.com.sg>
Subject: RE: Request for CV of Mr Bryan Ang

Dear Bryan and Celine,

1. We are pleased to confirm Bryan's appointment as parties' Single Joint Expert in MC/MC 11756/2017.
2. We will require Bryan to conduct a physical inspection of the Plaintiff's prime mover XE 1733B before furnishing his survey report. To this end, the Plaintiff has proposed the survey to be conducted at:-
 - a. Time: Wednesday, 6 Dec 2017 at 1.00 pm
 - b. Location: 15 Pioneer Walk Singapore 627753
3. Kindly confirm whether the above date and time is suitable for you.

Regards,

Scarlett LIM

Associate

Central Chambers Law Corporation

150 Cecil Street

#03-00

Singapore 069543

Tel: (65) 65380 100

DID: (65) 65971 856

Fax: (65) 65384 123

Email: scarlett@centralchambers.com.sg

CONFIDENTIALITY NOTICE: This email is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by return email and delete the original email from all your files and storage devices. Thank you.

From: Celine Fong (LKKAuto) [<mailto:celinefong@lkkauto.com>]
Sent: Friday, 17 November, 2017 11:24 AM
To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; Scarlett Lim <scarlett@centralchambers.com.sg>
Subject: RE: Request for CV of Mr Bryan Ang

Dear Scarlett,

We are pleased to submit our Professional Fee Charges (Single Joint Expert) as follows:

Paper Survey - \$700.00

Physical Re-inspection - \$1,000.00

Court Attendance Expert Witness Fee :

- (a) State Courts
 - i) Half day \$400.00
 - ii) Full day \$800.00

All above charges are subject to GST 7%.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Bryan Ang (LKKAuto)
Sent: Friday, 17 November, 2017 10:26 AM
To: Scarlett Lim <scarlett@centralchambers.com.sg>; Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Subject: RE: Request for CV of Mr Bryan Ang

Dear Scarlett

Attached is my CV.

Dear Celine

Please provide our fees for SJE.

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Scarlett Lim [<mailto:scarlett@centralchambers.com.sg>]

Sent: Friday, 17 November 2017 10:20 AM

To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Subject: Request for CV of Mr Bryan Ang

Our ref: RKC/SCA/170489/p(Tokio-PeckTiongChoon)

Dear Bryan,

1. We have been appointed by Tokio Marine Insurance Singapore Ltd to act for one of their insureds in legal proceedings in the State Courts of Singapore.
2. We have our client's instructions to propose you as one of the motor surveyors to be appointed as the Single Joint Expert between parties to give evidence in Court. As such, kindly let us have your Curriculum Vitae so that we may write to the opposing party accordingly.
3. We look forward to hearing from you. Thank you.

Regards,

Scarlett LIM

Associate

Central Chambers Law Corporation

150 Cecil Street

#03-00

Singapore 069543

Tel: (65) 65380 100

DID: (65) 65971 856

Fax: (65) 65384 123

Email: scarlett@centralchambers.com.sg

CONFIDENTIALITY NOTICE: This email is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by return email and delete the original email from all your files and storage devices. Thank you.

CENTRAL CHAMBERS

LAW CORPORATION

IN ASSOCIATION WITH DAC BEACHCROFT LLP

Company Registration No. 200204140R (Incorporated with limited liability)

- Advocates & Solicitors
- Notaries Public
- Commissioners for Oaths
- Agent for Trademarks

150 Cecil Street, #03-00, Singapore 069543

Tel: (65) 6538 0100 Fax: (65) 6538 4123 (Telefax not for service of court documents)

Email: lawyers@centralchambers.com.sg Website: www.centralchambers.com.sg

RONNIE TAN	TWANG KERN ZERN	SARA LIEW	SANDRA LIM CHING CHING	RAMASAMY K CHETTIAR
Joyce Siew	Soo Lup Soon	Wee Qianliang	Beitris Yong	Lisa Lim
Kea Cheng Han	Wong Ying Chung	Scarlett Lim	Samantha Tan	Serenella Liew
Simone B Chettiar	Mark Lam			
CONSULTANTS:				
A.K. Masagoes	Chia Chor Leong	Chan Fook Meng	Rajendran Kumaresan	

Your Ref: Please advise

Our Ref: RKC/170489/p/mm (Tokio-PeckTiongChoon)
(Kindly quote our reference no. when you reply)

Writer's email: scarlett@centralchambers.com.sg

Secretary's email: nazmi@centralchambers.com.sg

Secretary's DID: 65971 842

24 November 2017

LKK Auto Consultants Pte Ltd
Blk 51, Paya Ubi Industrial Park
Ubi Avenue 1 #02-25
Singapore 408933
Attention: Mr Bryan Ang

BY EMAIL ONLY

E: bryanang@lkkauto.com

Dear Mr Bryan Ang,

MC/MC 11756/2017

**SG SAGAWA AMEROID PTE LTD V PECK TIONG CHOON LEASING PTE LTD & ANOR
APPOINTMENT AS SINGLE JOINT EXPERT**

- We act for the Defendants in MC/MC 11756/2017, Peck Tiong Choon Leasing Pte Ltd and Tan Kang Chwee. The Plaintiff, SG Sagawa Ameroid Pte Ltd (formerly known as Ameroid Logistics (S) Pte Ltd) is represented by Bonnie Kwok LLC. MC/MC 11756/2017 is the Plaintiff's claims against the Defendant for loss and damage sustained as a result of a road traffic accident on 9 September 2016 involving the Plaintiff's vehicle XE 1733B and the 1st Defendant's vehicle XD 8776L.
- We write to confirm your appointment as parties' Single Joint Expert ("SJE") in MC/MC 11756/2017.
- As the SJE, we will need you to conduct a physical inspection of the Plaintiff's vehicle before preparing your survey report. The date, time, and location of the said inspection is:-

Date	6 December 2017, Wednesday
Time	1.00 pm
Location	15 Pioneer Walk Singapore 6277753

- The following relevant documents are enclosed for your perusal:-
 - Accident Statement of XE 1733B (Plaintiff's vehicle);
 - Accident Statement of XD 8776L (1st Defendant's vehicle);
 - Plaintiff's survey report from Constant Appraiser Services dated 6 February 2017;
 - 45 pages of colour photographs of XE 1733B from Constant Appraiser Services; and
 - In-vehicle video footage from XE 1733B (Plaintiff's vehicle).
- The Defendants do not have any re-survey reports or photographs.

Messrs Justice Law Corporation (Tax Law)
Messrs Chris Koh & Chew - Kuala Lumpur (Malaysia)
Messrs Yeoh Mazline & Partners - Kuala Lumpur (Malaysia)
Messrs Loke, King, Goh & Partners - Sarawak (Malaysia)
Messrs Valish Associates Advocates - India
Messrs The Legal Partners Limited - London (U.K.)

Also working in association with the following:

Member of Consulegis, an International Association of Law Firms



CONSULEGIS EWT/EEIG


Messrs Mag. Hubertus Weber - Innsbruck (Austria)
Messrs Morvilliers Sentenac Avocats - Toulouse (France)
Messrs Junge, Schlingeler, Wendland Rechtsanwälte Partnerschaft - Cologne (Germany)
Messrs Brödermann & Jahn Rechtsanwalts-Gesellschaft mbH - Hamburg (Germany)
Messrs Seelig & Fein LLP - New York (U.S.A.)
Messrs Ermini AG - Zürich (Switzerland)

MC/MC 11756/2017

**SG SAGAWA AMERIOD PTE LTD V PECK TIONG CHOON LEASING PTE LTD & ANOR
APPOINTMENT AS SINGLE JOINT EXPERT**

6. Kindly let us know if you require any further documents in preparation of your physical inspection/survey report.

Yours faithfully,



**Ramasamy K Chettiar/Scarlett Lim
Central Chambers Law Corporation**

enc

cc client

cc Bonnie Kwok LLC (Ref: BK.17738.17.jl)
(By fax only & without enc: 6536 2279)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2016 13:39
Date Of Accident	09/09/2016 14:05
Exact Location Of Accident	25 PENJURU LANE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE1733B
Insured/Policyholder	
Name Of Registered Owner	AMEROID LOGISTICS (S) PTE LTD
Co Reg No	199100423D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-97780432

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FUSO FP51SDR3VDEA

Exact Purpose for which vehicle was being used
at time of accident

Are you claiming under your own insurance policy
for repair to your vehicle? No

If No, Please state action to be taken Third Party

Vehicle Category Commercial Vehicle

Insurance Company

Name of Insurance Company	Sompo Insurance Singapore Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	D16MTHCVE000215

Cover Note Number

Driver

Name of Driver	GENG XUEDONG
Passport No/FIN	G6266286M
Date Of Birth	01/01/1978
Occupation	Outdoor
Date Of Driving Pass	21/12/2010
Driving Experience	5 Years And 8 Months
Gender	Male
Mobile Number	
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address
Postcode
Was driver an employee of the Insured's Company Yes
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident Unknown - REFER SKETCH PLAN
Weather Conditions Clear
Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No
Was any body injured in the Accident? No
Was any other material or property damaged? Yes
Was there any video captured by Car Camera? No
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? No
If Yes, Please state which Police Station
Was notice of intended Prosecution given? No
If Yes, against whom?

Circumstances of Accident

REFER SKETCH PLAN

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD8776L

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
IVAN TEO

Sketch Plan



Describe Circumstances of the Accident

I was stop my vehicle XE 1733B at
 NO 25 Penjuru Lane inside the
 YARD. Suddenly Front vehicle NO XD8776L
 PECK TIONG CHON vehicle reverse
 and hit on to my vehicle Front
 Body damage.

You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only

Claim OD

Claim TP

☒ Claim OD/TP at other workshop

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
 IVAN TEO

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/09/2016 14:14
Date Of Accident	09/09/2016 14:30
Exact Location Of Accident	INSIDE COMPOUND OF 3 PENJURU ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD8776L
Insured/Policyholder	
Name Of Registered Owner	PECK TIONG CHOON LEASING PTE LTD
Co Reg No	199204891W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-63560288

Vehicle Particulars

Manufacturer	SCANIA
Model	P400LA-12.7 D 4X2 MSZ (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	16-MF000307-R02
Cover Note Number	

Driver

Name of Driver	TAN KANG CHWEE
NRIC No	S1149688A
Date Of Birth	09/09/1955
Occupation	OUTDOOR
Date Of Driving Pass	29/11/1976
Driving Experience	39 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82649226
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 305 BUKIT BATOK STREET 31
Postcode	#10-89 650305
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION- HEAD TO REAR (TP HIT INSURED)
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Was there any video captured by Car Camera?	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE ABOVE MENTIONED DATE AND TIME, MY VEHICLE 'A' (XD8776L) WITH 40FT" TRAILER (TRD1102Z) WAS QUEUEING TO UNLOAD THE CONTAINER INSIDE THE COMPOUND OF 8 PENJURU ROAD. SUDDENLY, I FELT AN IMPACT FROM THE REAR OF MY VEHICLE. I GET OUT FROM MY VEHICLE AND REALISED THAT VEHICLE 'B' (XE1733B) HAS HIT ONTO MY VEHICLE. NO ONE WAS INJURED.

Are accident photos available for attachment?	YES
-----------------------------------------------	-----

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE1733P
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident


As per report




Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

✓  - 15-9-2016 14.30

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

01000 000
0000 0000
0000 0000
0000 0000
0000 0000

Sketch Plan #3

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Ameroid Logistics (S) Pte Ltd
c/o Blk 138 Bukit Batok West Ave 6
#11-411
Singapore 650138

Date : 06/02/2017

Reference No : CAS/17-02/022

General Information

Registration No. : XE 1733B
Accident Date : 09/09/2016

Particulars of Damaged Vehicle

Colour	: Blue	Make & Model	: Mitsubishi Fuso FP51SDR3VDEA
Engine Capacity	: 11967 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 31762	Engine No.	: OM457320816
Chassis No.	: FP51SDA20025	Steering	: In Order
Registration Date	: 12/05/2016	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	295/80R22.5	BRIDGESTONE	80%
L/H Front Tyre	295/80R22.5	BRIDGESTONE	80%
R/H Rear Tyre	295/80R22.5 (D)	BRIDGESTONE	80% / 80%
L/H Rear Tyre	295/80R22.5 (D)	BRIDGESTONE	80% / 80%

Inspection

Repairer : LYS Engineering
Blk 138 Bukit Batok West Ave 6, #11-411, Singapore 650138

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$26,883.05
Revised Amount : \$19,950.00
Less Excess : -
Nett Total : \$19,950.00

Remarks

- (A) Survey was done on 14/09/2016
- (B) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (C) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Constant Appraiser Services

Vehicle No : XE 1733B

Our ref : CAS/17-02/022

Adjustment On Repair Costs And Replacement Of Parts:

\$/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – LIST ITEMS</u>			
1	1pc	Front bumper assy	Dented/Bent	3,688.09	3,688.09 ✓
2	2pcs	Front bumper top L & R garnish cover @ \$699.09	Broken	1,398.18	1,398.18 ✓
3	2pcs	Front bumper top L & R garnish inner bracket @ \$298.13	Bent	596.26	596.26 ✓
4	1pc	Front panel grille top	Broken	758.09	758.09 ✓
5	1pc	Front panel grille lower	Broken	926.24	926.24 ✓
6	20pcs	Front grille top & lower clip @ \$6.50	Necessary	130.00	130.00 ✓
7	1pc	Front panel inner cylinder absorber	Bent	480.00	480.00 ✓
8	1pc	Front bumper center top skirt panel	Dented	866.24	866.24 ✓
9	1pc	Front Mitsubishi mark	Necessary	227.14	227.14 ✓
10	1pc	Front Mitsubishi emblem Fuso	Necessary	228.08	228.08 ✓
11	1pc	Front panel center inner latch	Bent	389.09	389.09 ✓
12	1pc	Front bumper top step garnish center	Twisted/Deformed	499.05	499.05 ✓
13	2pcs	Front L & R corner panel big @ \$996.07	Broken	1,992.14	1,992.14 ✓
14	2pcs	Front L & R corner panel inner signal lamp @ \$296.63	O/S Broken	593.26	296.63 ✓
15	2pcs	Signal lamp bulb L & R @ \$12.50	Serviceable	25.00	- ✓
16	2pcs	Front head lamp assy L & R @ \$1,654.03	Broken	3,308.06	3,308.06 ✓
17	2pcs	Front head lamp bulb L & R @ \$48.02	Serviceable	96.04	- ✓
18	2pcs	Front head lamp bezel L & R @ \$298.09	Broken	596.18	596.18 ✓
19	2pcs	Front fog lamp L & R @ \$658.42	O/S Broken	1,316.84	658.42 ✓
20	8pcs	Front fog lamp clip L & R @ \$6.50	Necessary	52.00	52.00 ✓
21	2pcs	Front lamp bezel L & R @ \$389.56	Broken	779.12	779.12 ✓
22	2pcs	Front bumper corner cover L & R @ \$298.17	Deformed/Twisted	596.34	596.34 ✓
23	2pcs	Front bumper center garnish cover L & R @ \$498.56	Broken	997.12	997.12 ✓
24	8pcs	Garnish cover clip @ \$8.50	Necessary	68.00	68.00 ✓
25	2pcs	Front center crossmember side bracket L & R @ \$588.43	Bent	1,176.86	1,176.86 ✓
26	1pc	Front windscreen glass	Cracked	3,982.13	3,982.13 NC
27	1pc	Front windscreen rubber	Necessary	498.22	498.22 NN
28	Pes	Front wiper panel handle @ \$299.23	Dented/Broken	598.46	598.46 ✓
29	2pcs	Front corner panel inner weatherstrip L & R @ \$86.13	Necessary	172.26	172.26 ✓
30	1pc	Front wiper link assy	Bent	698.23	698.23 ✓
31	1pc	Front left side mirror stay assy	Bent	986.24	986.24 ✓

Constant Appraiser Services

Vehicle No : XE 1733B

Our ref : CAS/17-02/022

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT - LIST ITEMS (CONT'D)</u>			
32	1pc	Front left round mirror	Broken	140.89	140.89 ✓
33	2pcs	Front left side mirror @ \$160.02	Grazed	320.04	320.04 SVL ✓
34	3pcs	Front wiper arm assy @ \$220.22	Serviceable	660.66	-
35	1pc	Front bumper center step garnish cover	Serviceable	533.47	-
36	3pcs	Front wiper arm head cover @ \$46.22	Broken	138.66	138.66 ✓
37	2pcs	Front CAB panel grip @ \$298.13	Dented/Twisted	596.26	596.26 SVL ✓
38	1pc	Front bumper top center panel	Dented	850.22	850.22 ✓
39	1pc	Front bumper top center panel inner reinforcement	Dented/Bent	658.23	658.23 SVL ✓
		14170.91		32,617.39	30,347.17
		Less 25% 10628.18		(8,154.34)	(7,586.79)
		<u>LABOUR & MISC. CHARGES</u>			
1		Writing front panel co logo	Necessary	150.00	80.00 ✓
2		To disconnect & reconnect, check electrical wiring harness wires, sockets & replace damaged parts		120.00	60.00 ✓
3		To spray painting front body panel (big) & inner dash panel, front bumper, skirt & inner crossmember chassis frame & front L & R fender		950.00	900.00 800/-
4		Labour charges: - Dismantle front bumper assy, front left head lamp assy & front right fender - To repair & beating front panel - To remove & replace the above damaged parts, straighten, knock out, realign & to re-adjust to the original position using power tools	1940/-	1,200.00	1,100.00 1000/-
		Grand total		26,883.05	24,900.38
		Recommended cost of lump sum repair (To its pre-accident condition)			19,950.00

12568.18

7 days. 4510,000/-


Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$19,950.00 on a contractual basis. Under normal circumstances, the repair period would be about 9 (Nine) working days.

Yours faithfully,

Constant Appraiser Services

A handwritten signature in black ink, appearing to read 'Lim Yong Tian', is written over a circular stamp. The stamp contains the text 'CAS' in the center and 'Constant Appraiser Services' around the perimeter.

Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CENTRAL CHAMBERS LAW CORPORATION			Ref : CS/LAW17022768/Dgbe2	
150 CECIL STREET #03-00 SINGAPORE 069543 SINGAPORE 069543			Date : 08-01-2018	
			Code : L139	
1. Policy Particulars - THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	XD 8776L	Veh. Inspected	XE 1733B	
Policy No.		Coverage (\$)	0.00	
Claim No.	RKC/170489/p/mm	Excess (\$)	0.00	
Assign From	SCARLETT LIM	Assign Date	30/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FUSO FP51SDR3VDEA	c.c	11967	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	FP51SDA20025	Colour	BLUE	
Odometer	151806	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	FALKEN	6 mm	
L/H Front Tyre	295/80 R22.5	FALKEN	6 mm	
R/H Rear Tyre	295/80 R22.5 (D)	FIRENZA	6/6 mm	
L/H Rear Tyre	295/80 R22.5 (D)	FIRENZA	6/6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	09/09/2016	Inspection Date	06/12/2017	
Survey held at	15 PIONEER WALK			
Repairer	LYS ENGINEERING			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 1733B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER ASSY	REPAIRED SEE LABOUR	3,688.09	-
2	FRONT BUMPER TOP L & R GARNISH COVER @\$699.09	REPLACED	1,398.18	1,398.18
2	FRONT BUMPER TOP L & R GARNISH INNER BRACKET @\$298.13	SERVICEABLE	596.26	-
1	FRONT PANEL GRILLE TOP	SERVICEABLE	758.09	-
1	FRONT PANEL GRILLE LOWER	SERVICEABLE	926.24	-
20	FRONT GRILLE TOP & LOWER CLIP @\$6.50	SERVICEABLE	130.00	-
1	FRONT PANEL INNER CYLINDER ABSORBER	SERVICEABLE	480.00	-
1	FRONT BUMPER CENTER TOP SKIRT PANEL	REPLACED	866.24	866.24
1	FRONT MITSUBISHI MARK	SERVICEABLE	227.14	-
1	FRONT MITSUBISHI EMBLEM FUSO	SERVICEABLE	228.08	-
1	FRONT PANEL CENTER INNER LATCH	SERVICEABLE	389.09	-
1	FRONT BUMPER TOP STEP GARNISH CENTER	SERVICEABLE	499.05	-
2	FRONT L & R CORNER PANEL BIG @\$996.07	REPLACED	1,992.14	1,992.14
2	FRONT L & R CORNER PANEL INNER SIGNAL LAMP @\$296.63	O/S REPLACED	593.26	296.63
2	SIGNAL LAMP BULB L & R @\$12.50	SERVICEABLE	25.00	-
2	FRONT HEAD LAMP ASSY L & R @\$1654.03	REPLACED	3,308.06	3,308.06
2	FRONT HEAD LAMP BULB L & R @\$48.02	SERVICEABLE	96.04	-
2	FRONT HEAD LAMP BEZEL L & R @\$298.09	REPLACED	596.18	596.18
2	FRONT FOG LAMP L & R @\$658.42	O/S REPLACED	1,316.84	658.42
8	FRONT FOG LAMP CLIP L & R @\$6.50	REPLACED	52.00	52.00
2	FRONT LAMP BEZEL L & R @\$389.56	REPLACED	779.12	779.12
2	FRONT BUMPER CORNER COVER L & R @\$298.17	REPLACED	596.34	596.34
2	FRONT BUMPER CENTER GARNISH COVER L & R @\$498.56	REPLACED	997.12	997.12
8	GARNISH COVER CLIP @\$8.50	REPLACED	68.00	68.00
2	FRONT CENTER CROSSMEMBER SIDE BRACKET L & R @\$588.43	SERVICEABLE	1,176.86	-
1	FRONT WINDSCREEN GLASS (CRACKED)	NOT CONSISTENT WITH THE IMPACT	3,982.13	-
1	FRONT WINDSCREEN RUBBER	NOT NECESSARY	498.22	-

Report Ref No. CS/LAW17022768/Dgbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT WIPER PANEL HANDLE @\$299.23	REPLACED	598.46	598.46
2	FRONT CORNER PANEL INNER WEATHERSTRIP L & R @\$86.13	SERVICEABLE	172.26	-
1	FRONT WIPER LINK ASSY	REPLACED	698.23	698.23
1	FRONT LEFT SIDE MIRROR STAY ASSY	REPLACED	986.24	986.24
1	FRONT LEFT ROUND MIRROR	REPLACED	140.89	140.89
2	FRONT LEFT SIDE MIRROR @\$160.02	SERVICEABLE	320.04	-
3	FRONT WIPER ARM ASSY @\$220.22	SERVICEABLE	660.66	-
1	FRONT BUMPER CENTER STEP GARNISH COVER	SERVICEABLE	533.47	-
3	FRONT WIPER ARM HEAD COVER @\$46.22	REPLACED	138.66	138.66
2	FRONT CAB PANEL GRIP @\$298.13	SERVICEABLE	596.26	-
1	FRONT BUMPER TOP CENTER PANEL	REPAIRED SEE LABOUR	850.22	-
1	FRONT BUMPER TOP CENTER PANEL INNER REINFORCEMENT	SERVICEABLE	658.23	-
	LESS 25% DISCOUNT		-8,154.34	-3,542.73
			24,463.05	10,628.18
	LABOUR			
	WRITING FRONT PANEL CO LOGO.		150.00	80.00
	TO DISCONNECT & RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRES, SOCKETS & REPLACE DAMAGED PARTS.		120.00	60.00
	TO SPRAY PAINTING FRONT BODY PANEL (BIG) & INNER DASH PANEL, FRONT BUMPER, SKIRT & INNER CROSSMEMBER CHASSIS FRAME & FRONT L & R FENDER.		950.00	800.00
	LABOUR CHARGES : - DISMANTLE FRONT BUMPER ASSY, FRONT LEFT HEAD LAMP ASSY & FRONT RIGHT FENDER. - TO REPAIR & BEATING FRONT PANEL. - TO REMOVE & REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN & TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER ASSY AND FRONT BUMPER TOP CENTER PANEL.		1,200.00	1,000.00
			2,420.00	1,940.00
	GRAND TOTAL		26,883.05	12,568.18

Report Ref No. CS/LAW17022768/Dgbe2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,000.00
-------------------------------------------------------------------------	--	--	-----------

Report Ref No. CS/LAW17022768/Dgbe2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.