



Your Ref: MSC/V/17-001339

Date: 07th December 2017

Our Ref: CS1/MSG17022842/Krbs2

M/s MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay
#24-01 Hong Leong Bldg
Singapore 048581
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SLH 4957D**

INSURED VEHICLE: FY 4886G

ACCIDENT DATE: 22/08/2017

We thank you for your instruction on 01/12/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLH 4957D from M/s Sincere Appraisal Services.
- b) Singapore Accident Statement of Vehicles SLH 4957D and FY 4886G.
- c) Colour damaged vehicle photographs of SLH 4957D.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLH 4957D
Make & Model	: Toyota Aqua Hybrid 1.5S
Year of Registration	: 2016
Chassis Number	: NHP106530888
Engine Capacity	: 1496cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.