

ASS. REC. BY:

REF: CS/CTI17022847/Kvb Special Instruction:

Survivor
MennenASSIGNMENT (Office)From (Person): Joel Goh of CTI Date/Time: 11/12/17 @ 9:57am

Estimated Cost: _____ Bill to: _____

OD TP FWS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBF 3735M Insured: SLQ 6518Cat Workshop m/s Lim Yew Boon Spray Paint Tel: 96852332of Blk 10 8n Ming Ind. Est # 81-10, 5756 45Policy No: DMPCSN3057231700 Claim No: SNM17D06856C02/8

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 28/11/2017
(Client's Record)CA / REV / REP. / REV 24 HRS ^{1wp}

H.O.D. Endorsement: _____

Date/Time: 10am @ 11/12/17 Person Contacted: Serene Vehicle: IN OUT

Date/Time	Action/Instruction
	(✓) Estimate
	GBF 3735M-X
	SLQ 6518C-X
21/12	@ 2918.75 email & confirm (Red 1594.75, 35%)

ASS. REC. BY:

REF: C72 /

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

04 days

Res.: Yes or No

Lum Sum: _____

1.41 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

GBF-3735 Yr Regn: 09, 16

Type: M.Car / M.Cycle / Bus / Van / Com / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toy Dyno

c.c. 2982

Colour: _____

Black

A/C: Insured / Std / NI / NA

Sp. Reading: _____

2888P

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

KDY 231 - 8024716

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

195R 15X8

R: _____

195R 13X68X2

SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. _____

9

mm

R/Bal. _____

5

5

mm

L/Bal. _____

9

mm

L/Bal. _____

5

5

mm

D.O.A. _____

28/11/17

D.O.I. _____

11/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/12

File parts continue

RECEIVED 28/12/2017

RECEIVED 28/12/2017

Date/Time, File Pass to?

☐

Prell. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

26/12 - typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + RS SI

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

merimen

Lump Sum / I.B.I: (\$

2919.75

220

220

Survey Department Check List (Case Handler)

Reference No. : CS/CTI/7033847/Kv
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp. Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des. of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 23/12/17
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17022847/Kvb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 01-12-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLQ 6518C	Veh. Inspected	GBF 3735M	
Policy No.	DMPCSN3057231700	Coverage (\$)	0.00	
Claim No.	SNM17D06856C02/8	Excess (\$)	0.00	
Assign From	MERIMEN (JOEL GOH)	Assign Date	01/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/11/2017	Inspection Date		
Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case No.	Case Date	Case Status	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Assigned	Status
Main	30 Nov 2017		01 Dec 2017 09:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NG SENG LOON, ID: S7602729C								
Main Claimant:	TAI SIN RADIO & ELECTRICAL PTE LTD, Co. Reg. No.: 201523626E								
Vehicle Reg. No.:	GBF3735M	Date of Loss:	28/11/2017 15:00 - :59						
Claim Type:	TP / SNM17D06856C02/8	Policy/Cover Note No.:	DMPCSN3057231700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLQ6518C	Policy No. (Claimant):	5084301712-01						
		Excess:	S\$0.00						
Repairer:	Lim Yew Boo Spray Paint Co (HQ) Blk 10 Sin Ming Industrial Estate, #01-10, 575645 Sin Ming - Tel: 96852332								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/12/2017]								
Driver/Custodian (Insured):	NG SENG LOON (41 / Male), NRIC: S7602729C								
Adj. Asg. Remarks:	NO ESTIMATES. KENNETH KONG SELECTED AS SJE FOR WP PRS								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/11/2017 10:44
Date Of Accident	28/11/2017 15:15
Exact Location Of Accident	JURONG EAST ST 21
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF3735M
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	TAI SIN RADIO & ELECTRICAL PTE LTD
Co Reg No	201523626E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92371479
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150

Exact Purpose for which vehicle was being used at time of accident	WORK
--	------

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
--	-------------

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5084301712-01
Cover Note Number	

Driver

Name of Driver	AZMIN BIN ABU
NRIC No	S6936349J
Date Of Birth	09/10/1969
Occupation	OUTDOOR
Date Of Driving Pass	05/03/2005
Driving Experience	12 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92371479
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 119 LORONG 1 TOA PAYOH #09-457
Postcode	310119
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED FILES

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SLQ6518C
Vehicle Make/Model/Colour	FORD
Details Of Properties	
Name of Driver	VINCENT
NRIC/Passport Number	
Contact Number	97979332
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan #2

SKETCH PLAN



Van A 6BF 3745A

Van B 9LB 6512C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Juryng East Street & I and came to a stopped to check oncoming traffic from main road before moving out. When I came to a stopped & was stationary for estimated a few seconds. Suddenly Van B hit into the rear of my stationary vehicle. That's all

DECLARATION

I/we declare the foregoing particulars are true to every respect.

大新電器有限公司
TAI SAN RADIO & ELECTRICAL PTE. LTD.

401-101 Yee Pooi Central Bldg., Singapore 310-001

Tel. 4355-8012, 4355-1700, 4355-7922

Policeholder's Signature

Driver's Signature

[Signature]
Witness and Endorser's Signature



Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to contest their policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available stored.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Statutory Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims,
 - (ii) investigating the accident and/or my claims,
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the internal cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, contesting or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

大新電器私人有限公司
TAI SIN RADIO & ELECTRICAL PTE. LTD.
60, 602 Tanjong Pagar Canal Road Singapore 068463
Tel: 6250 8142, 4365 8246 Fax: 6256 2885

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRAC/ITS No.





LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645

No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare. Singapore 575721

Tel: 6453 4177 Fax: 6459 3724

Email: limyewboo@singnet.com.sg

Company Reg. No. : 200514/001.

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
105 CECIL STREET #19-00
THE OCTAGON SINGAPORE 069534

Attention : Motor Claim Department

Contact : 69896111 Fax No. : 62247175/ 62247478

Estimate : TP17/058

Date : 29/11/2017

Vehicle Num. : GBF 3735M

Make/Model : TOYOTA DYNA 150D

Chassis/Eng# : KDY2318024716

Accident Date : 28/11/2017

Claim No. :

Reference : LYB/GBF3735M/chinataiping/tp/s

Policy No. :

S/N Quantity Particular Unit Price Amount S\$

- LIST ITEMS :
1. 1 REAR TAILGATE
 2. 1 REAR TAILLAMP (LH)
 3. 2 REAR TAILGATE BRACKET

List Total S\$:

25.00% Discount S\$:

1,588.00

280.00

410.00

2,278.00

569.50

1,708.50

- SPECIAL NETT ITEMS :
1. 1 REAR NO PLATE
 2. 1 REAR NO PLATE HOLDER
 3. 1 REAR TAILGATE STICKER

Special Nett Total S\$:

506.00

LABOUR :

TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS
TO CHECK & RECTIFY WIRING SYSTEM
TO REMOVE & REPAIR REAR EXHAUST SILENCER
TO HEAT,CUT/WELD REAR PANEL INCLUDING TO HEAT,KNOCK OUT
TO STRAIGHTEN ON AFFECTED AREA & LABOUR TO REPLACE PART

120.00 X

60.00

120.00 X

1,000.00

TO PUTTY,PRIMER TO SPRAY ON REAR TAILGATE,TO TOUCH UP

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

All cheques should be crossed and made payable to

Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645

No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721

Tel: 6453 4177 Fax: 6459 3724

Email: limyewboo@singnet.com.sg

Company Reg. No. : 200514/001.

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
105 CECIL STREET #19-00
THE OCTAGON SINGAPORE 069534

Attention : Motor Claim Department

Contact : 69896111 Fax No. : 62247175/ 62247478

Estimate : TP17/058

Date : 29/11/2017

Vehicle Num. : GBF 3735M

Make/Model : TOYOTA DYNA 150D

Chassis/Eng# : KDY2318024716

Accident Date : 28/11/2017

Claim No. :

Reference : LYB/GBF3735M/chinataiping/tp/s

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		ON PAINT JOB USING 2K PAINTS.		450 1,000.00
		Labour Total S\$:		2,300.00

E. & O.E.

Total S\$:

4,514.50

=====


for LIM YEW BOO SPRAY PAINT CO.

All cheques should be crossed and made payable to
Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Nov 2017		01 Dec 2017 09:57 Edit Adj Rpt	S\$2,919.75 Edit Estimates	S\$2,919.75 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]		
Insured:	NG SENG LOON, ID: S7602729C					
Main Claimant:	TAI SIN RADIO & ELECTRICAL PTE LTD, Co. Reg. No.: 201523626E					
Vehicle Reg. No.:	GBF3735M	Date of Loss:	28/11/2017 15:00 - :59			
Claim Type:	TP / SNM17D06856C02/8	Policy/Cover Note No.:	DMPCSN3057231700 (Comprehensive)			
Vehicle Reg. No. (Insured):	SLQ6518C	Policy No. (Claimant):	5084301712-01			
		Excess:	S\$0.00			
Repairer:	Lim Yew Boo Spray Paint Co (HQ) Blk 10 Sin Ming Industrial Estate, #01-10, 575645 Sin Ming - Tel: 96852332					
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]					
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 12/12/2017]					
Driver/Custodian (Insured):	NG SENG LOON (41 / Male), NRIC: S7602729C					
Adj Asg. Remarks:	NO ESTIMATES. KENNETH KONG SELECTED AS SJE FOR WP PRS					

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS ☐										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*GBF3735M (SNM17D06856C02/8)
[SLQ6518C]
TP
TAI SIN RADIO & ELECTRICAL PTE LTD
Nov 28 2017 3:00PM
[NG SENG LOON]
Lim Yew Boo Spray Paint Co

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports								1 per page		☒	
No	Finalized On	Sin Ming Autocare BFG Pte Ltd (HQ)						Thumbnail		Print	
1	29/11/17 11:10	Accident Statement						1 Load HTM			
Photos/Images								3 per page		☒	
No	Finalized On	Sin Ming Autocare BFG Pte Ltd (HQ)						Thumbnail		Print	
1	29/11/17 11:03	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
2	29/11/17 11:03	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
3	29/11/17 11:03	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
4	29/11/17 11:03	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
5	29/11/17 11:03	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
6	29/11/17 11:03	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
7	29/11/17 11:03	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
8	29/11/17 11:03	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
9	29/11/17 11:03	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
10	29/11/17 11:04	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	23/12/17 10:54	General View						1 Load JPG		☒	
2	23/12/17 10:54	General View						1 Load JPG		☒	
3	23/12/17 10:54	General View						1 Load JPG		☒	
4	23/12/17 10:54	General View						1 Load JPG		☒	
5	23/12/17 10:54	General View						1 Load JPG		☒	
6	23/12/17 10:54	General View						1 Load JPG		☒	
7	23/12/17 10:54	General View						1 Load JPG		☒	
8	23/12/17 10:54	General View						1 Load JPG		☒	
9	23/12/17 10:54	General View						1 Load JPG		☒	
10	23/12/17 10:54	General View						1 Load JPG		☒	
11	23/12/17 10:54	General View						1 Load JPG		☒	
12	23/12/17 10:54	General View						1 Load JPG		☒	
13	23/12/17 10:54	General View						1 Load JPG		☒	
14	23/12/17 10:58	Reinspection Photo						1 Load JPG		☒	
15	23/12/17 10:58	Reinspection Photo						1 Load JPG		☒	
16	23/12/17 10:58	Reinspection Photo						1 Load JPG		☒	
17	23/12/17 10:58	Reinspection Photo						1 Load JPG		☒	

Documentation			1 per page	☒
No	Finalized On		Thumbnail	Print
1	01/12/17 09:57	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		
		OI GIA REPORT	Load PDF	
No	Finalized On		Thumbnail	Print
1	29/11/17 11:07	Sin Ming Autocare BFG Pte Ltd (HQ)		
		Sketch Plan [Linked Accident Report Documents]	Load JPG	☒
2	29/11/17 11:07	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
1	29/11/17 11:10	Sin Ming Autocare BFG Pte Ltd (HQ)		
		Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On		Thumbnail	Print
1	29/11/17 11:03	Sin Ming Autocare BFG Pte Ltd (HQ)		
		Accident Photo	Load JPG	☒
2	29/11/17 11:03	Accident Photo	Load JPG	☒
3	29/11/17 11:03	Accident Photo	Load JPG	☒
4	29/11/17 11:03	Accident Photo	Load JPG	☒
5	29/11/17 11:03	Accident Photo	Load JPG	☒
6	29/11/17 11:03	Accident Photo	Load JPG	☒
7	29/11/17 11:03	Accident Photo	Load JPG	☒
8	29/11/17 11:03	Accident Photo	Load JPG	☒
9	29/11/17 11:03	Accident Photo	Load JPG	☒
10	29/11/17 11:04	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On		Thumbnail	Print
1	29/11/17 11:07	Sin Ming Autocare BFG Pte Ltd (HQ)		
		Sketch Plan	Load JPG	☒
2	29/11/17 11:07	Sketch Plan #2	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17022847/KVBE2

Date: 15/01/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3057231700

Claimant Vehicle
No : GBF3735MInsured Vehicle
No : SLQ6518C

Date of Loss: 28/11/2017

Nature of Claim: TP

Claim
No: SNM17D06856C02/8

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF3735M**

Make & Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 1KD2612590

Reg. Date: 28/09/2016 (Man. Year: 2016)

Chassis No: KDY2318024716

Colour: Black

Odometer: 26989 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8

Rear Tyre Size: 145 R13X8 (D)

Front Left Side: Bridgestone 9 mm

Rear Left Side: Bridgestone 5/5 mm

Front Right Side: Bridgestone 9 mm

Rear Right Side: Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,214.50	1,949.75	264.75	11.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	970.00	1,330.00	57.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	4,514.50	2,919.75	1,594.75	35.33

INSPECTION

Date of Assignment: 01/12/2017

Date Inspected: 11/12/2017 Inspected At:

Lim Yew Boo Spray Paint Co (HQ)
Blk 10 Sin Ming Industrial Estate, #01-10
Singapore 575645

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 Jan 2018)
Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBF3735M)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,588.00 FL	*1,588.00 FL
2	1		*REAR TAILLAMP (LH)	Cracked	280.00 FL	*280.00 FL
3	1		*REAR TAILGATE BRACKET	O/S Bent	410.00 FL	*205.00 FL
4	1		*REAR NO PLATE}	Dented	28.00 FS	*45.00 FS
5	1		*REAR NO PLATE HOLDER }		28.00 FS	*- FS
6	1		*REAR TAILGATE STICKER	Necessary	450.00 FS	*350.00 FS
					Sub Total (\$\$)	2,784.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	569.50
					Total Parts (\$\$)	2,214.50
						1,949.75

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS	New	120.00	0.00
2	TO CHECK & RECTIFY WIRING SYSTEM	New	60.00	20.00
3	TO REMOVE & REPAIR REAR EXHAUST SILENCER TO HEAT, CUT/WELD REAR PANEL INCLUDING TO HEAT, KNOCK OUT	New	120.00	0.00
4	TO STRAIGHTEN ON AFFECTED AREA & LABOUR TO REPLACE PART	New	1,000.00	500.00
5	TO PUTTY, PRIMER TO SPRAY ON REAR TAILGATE, TO TOUCH UP ON PAINT JOB USING 2K PAINTS	New	1,000.00	450.00
Gross Labour Cost (\$\$)			2,300.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >