

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
 	3		TO REMOVE & REWIRE PARKING SENSOR WIRE.	40	0	0	Reviewing	

Detailed Assessment

Inspection Date *

12/12/2017



Condition of Vehicle at time of survey

General condition

Good



Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

0

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

205/60R16

Rear Tyre Size

205/60R16

POST SURVEY INF ...

CATEGORY	Address type
FNOL INFORMATION...	Personal Correspondence
POST SURVEY INF ...	

CATEGORY	Gender
FNOL INFORMATION...	Male
POST SURVEY INF ...	

CATEGORY	Marital status
FNOL INFORMATION...	Unknown
POST SURVEY INF ...	

CATEGORY	Identification #
FNOL INFORMATION...	S7300809C
POST SURVEY INF...	

POLICY INFORMAT... TPVD AUDI

ASSESSMENT INFO...

AUDI

CATEGORY

Model

POLICY INFORMAT... A4-1.8 TFSI S TRONIC AMBIENTE (A)

ASSESSMENT INFO...

A4 1.4 TFSI S TRONIC

CATEGORY

Type

POLICY INFORMAT...

ASSESSMENT INFO...



CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT...

ASSESSMENT INFO...

WAUZZZF40GA025736

CATEGORY

Date of Birth

FNOL INFORMATI...

January 15, 1973

POST SURVEY INF...

mm/dd/yyyy



CATEGORY

Age

FNOL INFORMATI...

45

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF...

CATEGORY

Driving Experience

Direct settlement

Claim Handler

OH Vale
6568804897
vale.oh@axa.com.sg

Messages Invoices History Documents
Assessment Metrics Notes [Add](#)

Additional Instructions

TP-ARC PLS NOTE OF MINOR DMG OF INSRD
VEH

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
OH Vale	12/1/17 1:36 PM	1989.27	1989.27	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Preliminary Advice.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	December 14, 2017
GA219344- Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	OH Vale	December 1, 2017
GA219344- Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	OH Vale	December 1, 2017
new email.pdf	Letters and Correspondence	Others	PATIL Amol	December 1, 2017
SFE1973M TP GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Amol	November 30, 2017
EMAIL.pdf	Letters and Correspondence	Others	PATIL Amol	November 30, 2017
NEW EMAIL.pdf	Letters and Correspondence	Others	PATIL Amol	November 30, 2017

Direct settlement

Claim Handler

OH Vale
6568804897
vale.oh@axa.com.sg

Messages Invoices History Documents

Assessment Metrics Notes

Document Type

Additional Instructions

TP-ARC PLS NOTE OF MINOR DMG OF INSRD
VEH

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	May 8, 2018
DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	May 8, 2018