

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 01.12.2017

Time: 12:26:57

Page: 1

FWD-4sum

(Fri)

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305093948

REGN NO : SHC 480L

MILEAGE : 0000000000

MAKE : HYUNDAI

MODEL : I-40

DATE OF REGN : 31.10.2013

DATE/TIME IN : 01.12.2017 09:10

ACCIDENT DATE : 01.12.2017

12:45

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0578-G	BUMPER FRT	1	562.30	20.00	449.84	/
0002 04-01-0103-0737-G	BUMPER GRILLE FRT LH	1	40.30	20.00	32.24	/
0003 04-01-0103-0574-G	FENDER FRT LH	1	619.00	20.00	495.20	/
0004 04-01-0103-0572-G	BONNET	1	1,151.80	20.00	921.44	X
0005 04-01-0103-0781-A	HEADLAMP LH	1	1,388.00	20.00	1,110.40	/
0006 04-01-0103-0657-G	FENDER SHIELD FRT LH	1	169.80	20.00	135.84	?
0007 04-01-0103-0658-G	WHEEL CAP FRT LH	1	150.70	20.00	120.56	/
0008 04-01-0103-0600-G	WING MIRROR LH	1	980.50	20.00	784.40	X 1440

SUB-TOTAL : 4,049.92

JOB NATURE

0000 L	PANEL BEATING
0001 23-502	SPRAYPAINT ON AFFECTED AREA
0002 17-01	CHECK ALL LIGHTING

~~860.00~~ 400~~700.00~~ 380~~40.00~~ 20

440

COMFORTDELGRO ENGINEERING PTE LTD

Date: 01.12.2017

REPAIR ESTIMATE

Time: 12:26:57

Page: 2/2

FWD - 4 SUM

(Fri)

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305093948
REGN NO : SHC 480L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 31.10.2013
DATE/TIME IN : 01.12.2017 09:10
ACCIDENT DATE : 01.12.2017

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0003 20-00 TUFF COAT ON AFFECTED PARTS.

~~60.00~~ 20

0004 L WHEEL ALIGNMENT

~~120.00~~ 60

SUB-TOTAL : 1,780.00

TOTAL : 5,829.92

Lmf

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Kalvin 16/11/17
1/12/17 1530 hrs.
3 Days
L/s
After Repair photo.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: