

ASS. REC. BY:

REF: CS/MSG17022874/Tivbo2 Special Instruction:

Survivor
Merimen

Taufich

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSIG

Date/Time:

11/12/17 @ 11:42am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJV 5459T

Insured:

FZ1777C

at Workshop m/s

Cycle & Carriage KIA

Tel:

of

209 Pandan Gardens

Policy No:

MSD/VM7/17-361080

Claim No:

MSC/v/17-001188

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/08/2017

CA / REV / REP. / REV 24 HRS

wp

4/12/17 @

Ham

H.O.D. Endorsement:

Date/Time:

1:58pm @ 11/12/17

Person Contacted:

Andre Chow

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SJV 5459T-NA/INC15012581/d2-D.O.A: 25/07/2015

FZ1777C-x

S/12/17

Send preli. revised by merimen

29/1/18

Final fig \$2304 confirmed by email (Red 1644, 429)

Taufik

MSIG

MSIG

MSIG

Report Date 04/12/2017

Estimated Cost

OD / TP / WS / TP RES / CD RES / EVA / INV / MV

To inspect Vehicle No SJV 5459T
at Workshop No Cycle & Carriage KIA
of 209 Pandan Gardens

Insured

Policy No

Claims No

Sum Insured

Excess

Client's Record


Make of van

Amche

Policy Condition

11:30am

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value

IDAD Accident Report Consistent? : Yes or No

GIA / PF Seen Consistent? : Yes or No

Est. Repairs 3 days Res: Yes or No

Sum Surp % 3 Val: Yes or No

OA / REV / REP : 24 HRS 'up'

Date Person Contacted

Vehicle IN / OUT

Date Time Action Instruction

One Time Fee Passed

☐ : Preli. Report
☐ : Final Report

One Time Fee Returned

29/11- typist

Report Form No

merimen

Auto Surp Fee

2304 / 2

Days Of Repair 3

Resurvey No. of Trip 1

Add Fee

☐ : Site Visit
☐ : ...
☐ : ...
☐ : ...
☐ : ...

Site Visit

Surp Fee

Therapy

200
10
210

SJV 5459T Page 20/0 Jan.

Time M / Day Bus Van Lorry Taxi Prime Mover

Truck Trailer

Make

Kia Cerat EX

1591

Colour

Black

Insured Std N/A

Seating

175671

Radio Insured Std N/A

Eng No

KNAF4411LA5137308

Ch No

Gen Cond Good / Fair / Poor / Burnt

Steering Inorder / Jammed / Leaked / Burnt or

Brake Inorder / Jammed / Leaked / Burnt or

Mod Nil / S/Rim / STD A/Rim or

Tyre Size

195/65R15

R

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

Rear

R.Bal

6

mm

R.Bal

6

mm

L.Bal

6

mm

L.Bal

6

mm

D.O.A.

D.O.A.

Survey reader

AT Pandan

4/12/17 @ 1145

Des of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt 0/5

The U/C / Chassis frame / Body Structure affected due to collision

Survey Department Check List (Case Handler)

Reference No.: CS/MSG 17022874/TIV6

Policy Type: OD/ TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

| (1) Office Assign Form | | Y-Date | N-Date | Y-Date | N-Date |
|------------------------|---------------------------------------|--------|--------|--------|--------|
| C | Reference No. | ✓ | | | |
| C | Customer Code | | | | |
| N | Assign From | | | | |
| C | Assign Date | ✓ | | | |
| C | Veh No (Inspected) | ✓ | | | |
| C | Veh No (Insured) | ✓ | | | |
| C | D.O.A | ✓ | | | |
| C | Policy No | ✓ | | | |
| C | Claim No | ✓ | | | |
| C | Insurance Authorisation (CA /REV/REP) | | | | |
| C | Report Type | ✓ | | | |
| C | Weekend Charges | | | | |
| N | Survey held at/Repairer | ✓ | | | |
| C | Excess | | | | |

Surveyor (): Case handler to make sure the surveyor completed all required information.

| (1) Assignment Form | | Y-Date | N-Date | Y-Date | N-Date |
|---------------------|------------------------|--------|--------|--------|--------|
| C | Vehicle No | ✓ | | | |
| C | Regn Month/Year | ✓ | | | |
| N | Vehicle Type | ✓ | | | |
| N | Make & Model | ✓ | | | |
| C | Engine Capacity. (C.C) | ✓ | | | |
| N | Colour | ✓ | | | |
| C | Odometer. (Sp.Reading) | ✓ | | | |
| C | Chassis No | ✓ | | | |
| N | General Condition | ✓ | | | |
| N | Steering | ✓ | | | |
| N | Brake | ✓ | | | |
| N | Modification (Modi) | ✓ | | | |
| C | Tyre Size | ✓ | | | |
| N | Tyre Make | ✓ | | | |
| C | Tyre Balance | ✓ | | | |
| C | Date of Inspection | ✓ | | | |
| N | Survey held | ✓ | | | |
| N | Des.of Damages | ✓ | | | |

(2) System - (Views/Imerimen)

| | | | | | |
|---|--------------------------------------|---|--|--|--|
| C | Damaged Vehicle Photographs Uploaded | ✓ | | | |
|---|--------------------------------------|---|--|--|--|

(3) Workshop Estimate/Assignment Form

| | | | | | |
|---|---|---|--|--|--|
| N | ALL Parts condition | ✓ | | | |
| C | Market Value for OD cases | | | | |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) | | | | |
| C | Days of repair | ✓ | | | |
| C | Finalised Amount | ✓ | | | |
| C | Re-inspection Cases to Finalize within 5 Days | | | | |

(4) System - (Views/Imerimen)

| | | | | | |
|---|-------------------------|---|--|--|--|
| C | Resurvey photo Uploaded | ✓ | | | |
|---|-------------------------|---|--|--|--|

Check By:

VERON

29/11/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--|---------------------------|---|
| MSIG INSURANCE (SINGAPORE) PTE LTD | | Ref : CS/MSG17022874/T1vb | |
| 16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581 | | Date : 01-12-2017 |  |
| Code : MSG | | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | FZ 1777C | Veh. Inspected | SJV 5459T |
| Policy No. | MSD/VM/17-361080 | Coverage (\$) | 0.00 |
| Claim No. | MSC/V/17-001188 | Excess (\$) | 0.00 |
| Assign From | MERIMEN (CHRISTINA WONG) | Assign Date | 01/12/2017 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | c.c 0 | | |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 01/08/2017 | Inspection Date | |
| Survey held at | CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Created | Est. Submitted | Adj. Assigned | Adj. Rpt | Adj. Submitted | Ins. Auth'd | Status |
|------|-------------|----------------|--|----------|----------------|-------------|---|
| Main | 01 Aug 2017 | | 01 Dec 2017 11:42 Assign | | | | New Assignment Cancel Case |

| | | | | |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|--------------------------|

CLAIM SUBFOLDER DETAILS

Insured: ABDUL WAHID BIN SHARI, ID: S1777712B

Main Claimant: TEH KIM SAN TONI, ID: S7317732D

Vehicle Reg. No.: SJV5459T

Claim Type: TP / MSC/V/17-001188

Vehicle Reg. No. (Insured): FZ1777C

Repairer: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens, 609339 West Coast - Tel:

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]

Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... **[Imm.Advice due 02/12/2017]**

Adj. Asg. Remarks: Pls attend for survey on 04/12/2017 @ 9:30am. Owner is waiting.

[Created by insurer]

Date of Loss: 01/08/2017 06:00 - :59

Policy/Cover Note No.: MSD/VMT/17-361080 (TP, Fire & Theft)
Coverage: 01/03/2017 - 28/02/2018

Policy No. (Claimant):

Excess:

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 05 Dec 2017

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : FZ1777C | | |
| TP Vehicle No | : SJV5459T | Accident Date | : 01/08/2017 |
| Make | : KIA CERATO FORTE | Assignment Date | : 01/12/2017 |
| Date of Inspection | : 04/12/2017 | Est. Duration of Repair | : 3.00 |
| Inspection At | : CYCLE & CARRIAGE KIA PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 3,692.00 |
| Revised Amount | :S\$ | 2,048.00 |
| Check Items (Estimated) | :S\$ | 127.00 |
| Total | :S\$ | 2,175.00 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.



HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

KIA AUTO PROTECTOR

CERTIFICATE NO. 2100189280-07000

(The below excess is subject to GST)

OWN DAMAGE EXCESS S\$600.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes

- 1) **VEHICLE REGISTRATION NO.** SJV5459T
2) **NAME OF INSURED** Teh Kim San Toni
3) **EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT** 29 Jan 2017
4) **DATE OF EXPIRY OF INSURANCE** 28 Jan 2018
5) **PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE***

SUBJECT TO AGE CONDITION / All Age Condition:

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / KIA AUTHORISED REPAIRERS

1. Cycle & Carriage Pandan Gardens Service Centre - 209 Pandan Gardens (Tel: 6568 4555)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 206 Braddell Rd (Tel: 63837116) 3. Ethos - 30 Bukit Batok Cres (Tel: 66547777)

4. Glass-Fix - 52 Ubi Ave 3 (Tel: 62760887) - For windscreen only 5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560)

6. Lai Huet (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110) 7. Maya Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892)

8. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336) 9. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE 15 Days Replacement Car only for repairs at C&C - Refer to policy wordings for details

* **NAMED DRIVER** LIM PECK FUN

HIRE PURCHASE COMPANY DBS BANK LTD
/EMPLOYER'S LOAN

**Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.*

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 18 Jan 2017


AIG Asia Pacific Insurance Pte. Ltd.

500710-050
C&C FULCO-CORP SALES
22 UBI ROAD 4
FULCO BUILDING
SINGAPORE 408617
ANSP - MOTOR


AUTHORISED REPRESENTATIVE

ORIGINAL

SSCFKJ.



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7240512I



Name

CHARLEMAGNE LIM PECK FUN
(LIN BIFEN)

林 碧 芬

Race

CHINESE

Date of birth

06-11-1972

Sex

F

Country of birth


SINGAPORE

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor cars with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles with unladen weight \leq 2500kg 07 Aug 2008

FOR C&C USE ONLY



NP 428A



4654511

NRIC No. S7240512I

Date of issue

30-11-2010

APT BLK 318 UBI AVENUE 1 #10-481
SINGAPORE 400318

NRIC No: S7240512I

Date: 29/01/2016

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------|
| Date Of Report | 01/08/2017 13:14 |
| Date Of Accident | 01/08/2017 06:15 |
| Exact Location Of Accident | 31 HOUGANG AVE 7 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|--|--------------------------------------|
| Vehicle Registration Number | SJV5459T |
| Insured/Policyholder | |
| Name Of Registered Owner | TEH KIM SAN TONI |
| NRIC No | S7317732D |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-92994806 |
| Alternative Phone No | OTHERS-67431007 |
| Vehicle Particulars | |
| Manufacturer | KIA |
| Model | CERATO-1.6 EX (M) |
| Exact Purpose for which vehicle was being used at time of accident | COMMUTE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | AIG ASIA PACIFIC INSURANCE PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 2100189280 |
| Cover Note Number | |
| Driver | |
| Name of Driver | CHARLEMAGNE LIM PECK FUN |
| NRIC No | S7240512I |
| Date Of Birth | 06/11/1972 |
| Occupation | INDOOR |
| Date Of Driving Pass | 07/08/2008 |
| Driving Experience | 8 YEARS AND 11 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-92994806 |
| Fax Number | |
| Contact Number | |
| EEmail Address | VIVIENNECHARLEMAGNE@GMAIL.COM |

Address BLK 318 UBI AVENUE 1 #10-481
Postcode 400318
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured SPOUSE
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FZ1777C
Vehicle Make/Model/Colour BLACK
Details Of Properties MOTORCYCLE
Name of Driver ABDUL NAHID BIN SHARI
NRIC/Passport Number S1777712B
Contact Number 90215864
Address
Postcode
Insurance Company Name
Nature Of Damage STORAGE BOX CAME OUT
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF INJURED PERSON 1

Name ABDUL NAHID BIN SHARI
Approximate Age

| | |
|--|---------------|
| Injuries Sustain | INJURY ON LEG |
| Injured person in which vehicle? | FZ1777C |
| Were seat belts worn? | NO |
| Was injured conveyed to hospital by ambulance? | YES |
| Address | |
| Postcode | |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "**Purposes**")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time




Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan





Describe Circumstances of the Accident


ON 1/8/17 ROAD CONDITION / SURROUNDINGS IS NOT RAINING, & SKY CLEAR, FLOOR IS DRY. I WAS COMING OUT FROM 31 HOUNGATE AVE 7, PREPARING TO TURN RIGHT, & SAW A MOTOR BKE COMING SO THAT I WAS WAITING FOR THE MOTOR BKE TO CLEAR. OPPOSITE THERE WAS A TAXI TRYING TO TURN IN. SUDDENLY THE TAXI MOVED & HIT THE MOTOR CYCLE. THE MOTORCYCLE WAS HIT BY THE TAXI & SKID THUS HITTING MY CAR FROM RIGHT HAND SIDE.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time
1/8/17


Driver's Signature (If driver is not the policyholder) / Date & Time
1/8/17 13:09pm


Witnessed by Reporting Centre Personnel
1/8/17

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|---|
| Mr TEH KIM SAN, TONI Blk 318 Ubi Ave 1 #10-481 Singapore 400318 Contact No Mobile: 98420288 | Cust No/Name /Mr Teh Kim San, Toni Reg No/Reg Date SJV5459T / 29/01/201 Date In/Mileage / 0 Chassis No KNAFU411LA5137308 Engine No G4FC9H304199 Make/Model KIA/CERATO 1.6 M EX (2010) Colour/Trim EB Ebony Black / WK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|------------|-------|-------------------|-----|-----------------|--------|
| CSM00081 | Cash | 01/08/2017/ 11:30 | QUA | 265 / AndreChow | 12721 |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|--|------|------------|-------|----------------|
| E PNT88000 RENEW ACCIDENT DAMAGED PORTION ON FRONT BUMPER AND REALIGN TO THE SAME | | | | ✓ 550. 1100.00 |
| A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM | | | | ✓ 60. 100.00 |
| A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | | | | ✓ ✓ 200.00 |
| E PNT98000 RESPRAY FRONT BUMPER AND OTHER AFFECTED PORTIONS | | | | ✓ 420. 840.00 |
| M SUNDRY SUNDRIES | | | | ✓ 20. 50.00 |
| M COVER-FR BUMPER | 1.00 | 735.00 | 00.00 | de 735.00 ✓ |
| M LIP ASSY-FRONT BUMPER | 1.00 | 63.00 | 00.00 | cut 63.00 ✓ |
| M ABSORBER-FRONT BUMPER ENERGY | 1.00 | 94.00 | 00.00 | 94.00 ✓ |
| M GRILLE-FRONT FOG,RH | 1.00 | 33.00 | 00.00 | 33.00 ✓ |
| M LAMP ASSY-HEAD,RH | 1.00 | 477.00 | 00.00 | 477.00 ✓ |

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME : *Tan Jiah 97493747*

SURVEYOR SIGNATURE : *[Signature]*

DATE : *4/12/17 01:45*

REMARKS : *Resurvey before paint 3 days*

Surv @ lkkauto.com

3948

Confirm & accepted by

| | | |
|----------------------|--------------|-----------------|
| 7% GST on | Nett 3692.00 | 3,692.00 |
| | | 258.44 |
| Total Payable | | 3,950.44 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 29 January 2018 2:24 PM
To: 'Lauro Araos Songcuan Jr'; Taufikh (LKKAUTO); SUR
Subject: RE: SJV5459T (KIA) - FINALISE

Dear Larry,

Confirm finalized amount of \$ **2,304.00** before Gst for SJV5459T.

No of days: 3 days

Final invoice and all supporting documents sent to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lauro Araos Songcuan Jr [mailto:lauro.songcuan@cyclecarriage.com.sg]
Sent: Wednesday, 24 January 2018 12:52 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: SJV5459T (KIA) - FINALISE

Additional photos

From: Lauro Araos Songcuan Jr
Sent: Wednesday, 24 January, 2018 12:49 PM
To: Taufikh (LKKAUTO); 'sur@lkkauto.com'
Cc: 'Veron Chen (LKKAUTO)'; Yusof Bin Hashim; Loi Ai Ting; Andre Chow En De
Subject: SJV5459T (KIA) - FINALISE

Dear Taufikh,

Pls. refer to attached files and photos.

Kindly confirm finalized amount of \$ **2,304.00** before Gst for SJV5459T.

Thank you so much.

Best regards,
Larry Songcuan
Cycle & Carriage
Pandan Gardens

Tel. # 6568 4658

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.



LKK
Taufikh

VEHICLE NO : SJV5459T

MODEL : HA/CERATO 1.6 M EX

WIP : 19076

| | | |
|---|------|-----------------|
| Material | : \$ | <u>1,054.00</u> |
| Labour | : \$ | <u>1,250.00</u> |
| Sub-Total | : \$ | <u>2,304.00</u> |
| Less 2% Disc | : \$ | <u>—</u> |
| Less Excess | : \$ | <u>—</u> |
| Total | : \$ | <u>2,304.00</u> |
| GST 7% | : \$ | <u>161.28</u> |
| Grand Total | : \$ | <u>2,465.28</u> |
| Finalise By/Date : <u>Latmy on 24/01/18</u> | | |

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 3 WORKING DAYS

- * TP vehicle no: FZ1777C (MSIG)
- * GIA search fee \$ 2.00
- * Claim loss of RENTAL.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Cust No/Name | Vehicle Make & Model Info |
|------------------------------|--|---------------------------|
| Mr TEH KIM SAN, TONI | LCV02496/Mr Teh Kim San, Toni | |
| 81k 318 Ubi Ave 1 | Reg No/Reg Date SJV5459T / 29/01/2010 | |
| #10-481 | Date In/Mileage 04/12/2017/ 175671 | |
| Singapore 400318 | Chassis/Package KNAFU411LA513730E /KC1510%(F | |
| Contact No *Mobile: 98420288 | Engine No G4FC9H304199 | |
| 04/12/ | Make/Model KIA/CERATO 1.6 M EX (2010) | |
| | Colour/Trim EB Ebony Black / WK | |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|------------|-------|-------------------|-----|----------------------|--------|
| CTP00080 | Cash | 24/01/2018/ 12:31 | TLA | 884 / Lauro Songcuan | 19076 |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|--|------|------------|-------|----------|
| E PNT98000 | | | | 420.00 ✓ |
| SPRAY PAINT FRONT BUMPER AND OTHER AFFECTED PORTIONS | | | | |
| E PNT88000 | | | | 550.00 ✓ |
| RENEW FRONT BUMPER AND REALIGN TO THE SAME | | | | |
| A 54900099 | | | | 60.00 ✓ |
| CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM | | | | |
| A 10028901 | | | | 200.00 ✓ |
| TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST | | | | |
| USING HI-SCAN PRO TEST | | | | |
| M SUNDRY | | | | 20.00 ✓ |
| SUNDRIES | | | | |
| X COVER-FR BUMPER | 1.00 | 735.00 | 00.00 | 735.00 ✓ |
| X LIP ASSY-FRONT BUMPER | 1.00 | 63.00 | 00.00 | 63.00 ✓ |
| X GUARD ASSY-FRONT WHEEL,RH | 1.00 | 63.00 | 00.00 | 63.00 X |
| X LAMP ASSY-FRONT FOG,RH | 1.00 | 143.00 | 00.00 | 143.00 X |
| X RESERVOIR ASSY-W/SHLD WASHER | 1.00 | 50.00 | 00.00 | 50.00 X |
| Z TEXT | | | | |
| TP MSIG | | | | |
| DOA: 01.08.2017 | | | | |
| SURVEYOR: TAUFIKH 04.12.17 | | | | |
| 3 DAYS | | | | |

"Guarantee your warranty, maintain with Cycle & Carriage."

| | | | |
|-----------------|----------|---------------|----------|
| Parts | 1,054.00 | Nett | 2,304.00 |
| Labour | 1,230.00 | 7% GST on | 161.28 |
| Standard Menu | 0.00 | | |
| Specialist Job | 0.00 | | |
| Diagnostics Job | 0.00 | Total Payable | 2,465.28 |
| Sundry/Others | 20.00 | | |
| Total(w/o GST) | 2,304.00 | | |

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : **MSIG**

Supplementary For Registration No.: **SJV 5459 T**

| <u>Material</u> | | <u>Cost (\$)</u> |
|------------------------|------------------------------|-------------------------|
| 1 | Guard Assy-Front Wheel, RH | 63.00 <i>de</i> ✓ |
| 2 | Lamp Assy-Front Fog, RH | 143.00 <i>ane</i> ✓ |
| 3 | Reservoir Assy-W/Shld Washer | 50.00 <i>de</i> ✓ |
| | | <hr/> 256.00 |
| 7% GST | | 17.92 |
| Total | | <hr/> 273.92 |

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE
TEL: 6568 4658
FAX : 6567 5258

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 01 Aug 2017 | | 01 Dec 2017 11:42 Edit Adj Rpt | S\$2,304.00 Edit Estimates | S\$2,304.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|-----------|--|------------------------|---|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by Insurer] | | | | | | | | | |
| Insured: | | ABDUL WAHID BIN SHARI, ID: S1777712B | | | | | | | |
| Main Claimant: | | TEH KIM SAN TONI, ID: S7317732D | | | | | | | |
| Vehicle Reg. No.: | | SJV5459T | Date of Loss: | 01/08/2017 06:00 - :59 | | | | | |
| Claim Type: | | TP / MSC/V/17-001188 | Policy/Cover Note No.: | MSD/VMT/17-361080 (TP, Fire & Theft) Coverage: 01/03/2017 - 28/02/2018 | | | | | |
| Vehicle Reg. No. (Insured): | | FZ1777C | Policy No. (Claimant): | | | | | | |
| | | | Excess: | | | | | | |
| Repairer: | | Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens, 609339 West Coast - Tel: | | | | | | | |
| Handling Insurer: | | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311] | | | | | | | |
| Adjuster: | | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 31/12/2017] | | | | | | | |
| Adj Asg. Remarks: | | Pls attend for survey on 04/12/2017 @ 9:30am. Owner is waiting. | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

***SJV5459T (MSC/V/17-001188)**

[FZ1777C]

TP

TEH KIM SAN TONI

Aug 1 2017 6:00AM

[ABDUL WAHID BIN SHARI]

Cycle & Carriage KIA Pte Ltd

| | | | | | | | | | | | |
|--------------------|-----------------|-----------------------------------|---------------|--|--|--------------------|--|--|-----------------------------------|----------|-------------------------------------|
| Upload Documents | | | Upload Photos | | | Compose New Letter | | | View View In Browser | | |
| Assessment Reports | | | | | | | | | 1 per page | | <input checked="" type="checkbox"/> |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | Thumbnail | Print | |
| 1 | 05/12/17 13:45 | Adjuster Immediate Advice | | | | | | | 1 | Load HTM | |
| | | | | | | | | | | | |
| Photos/Images | | | | | | | | | 3 per page | | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | Thumbnail | Print | |
| 1 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 2 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 3 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 4 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 5 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 6 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 7 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 8 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 9 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 10 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 11 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 12 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 13 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 14 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 15 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 16 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 17 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 18 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 19 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 20 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 21 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 22 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 23 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 24 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 25 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 26 | 05/12/17 12:56 | General View | | | | | | | 1 | Load JPG | |
| 27 | 24/01/18 15:06 | Reinspection Photo | | | | | | | 1 | Load JPG | |
| 28 | 24/01/18 15:06 | Reinspection Photo | | | | | | | 1 | Load JPG | |
| 29 | 24/01/18 15:06 | Reinspection Photo | | | | | | | 1 | Load JPG | |
| 30 | 24/01/18 15:06 | Reinspection Photo | | | | | | | 1 | Load JPG | |
| 31 | 24/01/18 15:06 | Reinspection Photo | | | | | | | 1 | Load JPG | |
| 32 | 24/01/18 15:06 | Reinspection Photo | | | | | | | 1 | Load JPG | |

| | | | | | |
|----------------------|-----------------|--|---|-------------------------------------|-------------------------------------|
| 33 | 24/01/18 15:06 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 34 | 24/01/18 15:06 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 35 | 24/01/18 15:06 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 36 | 24/01/18 15:06 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 37 | 24/01/18 15:06 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 38 | 24/01/18 15:06 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 39 | 24/01/18 15:06 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 40 | 24/01/18 15:06 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 41 | 24/01/18 15:06 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 42 | 24/01/18 15:06 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 43 | 24/01/18 15:06 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 44 | 24/01/18 15:06 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 45 | 24/01/18 15:06 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 46 | 24/01/18 15:06 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| | | | | | |
| Documentation | | | | 1 per page <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | | Thumbnail | Print |
| 1 | 02/08/17 15:55 | Email frm TP - PRI | 1 | Load PDF | |
| 2 | 02/08/17 15:56 | SJV5459T GIA Rpt | 1 | Load PDF | |
| 3 | 02/08/17 15:57 | Estimate | 1 | Load PDF | |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) | | Thumbnail | Print |
| 1 | 01/12/17 11:16 | Email - Survey appt | 1 | Load PDF | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 01/02/18 12:50 | Supplementary | 1 | Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | | Reset | Save | Print |
|--|--|-------|------|-------|
| There are no document checklists configured. | | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022874/T1VBE2

Date: 01/02/2018

REFERENCE

| | | | | | |
|-----------------------|--------------------------------------|----------------------|------------------|-----------|----------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | MSD/MT/17-361080 | | |
| Claimant Vehicle No : | SJV5459T | Insured Vehicle No : | FZ1777C | | |
| Date of Loss: | 01/08/2017 | Nature of Claim: | TP | Claim No: | MSCV/17-001188 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SJV5459T | Engine No: | G4FC9H304199 |
| Make & Model: | KIA CERATO FORTE, 1.6 EX (A) | Chassis No: | KNAFU411LA5137308 |
| Reg. Date: | 29/01/2010 (Man. Year: 2009) | Odometer: | 175671 km |
| Colour: | Black | | |
| Engine Capacity: | 1591 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 195/65 R15 | Rear Tyre Size: | 195/65 R15 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts | 1,708.00 | 1,074.00 | 634.00 | 37.12 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,240.00 | 1,230.00 | 1,010.00 | 45.09 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (\$\$) | 3,948.00 | 2,304.00 | 1,644.00 | 41.64 |
| + GST 7.00/7.00% (\$\$) | 276.36 | 161.28 | 115.08 | 41.64 |
| Nett Amount (\$\$) | 4,224.36 | 2,465.28 | 1,759.08 | 41.64 |

INSPECTION

| | | | |
|-----------------------------|--------------------------|---|--|
| Date of Assignment: | 01/12/2017 | | |
| Date Inspected: | 04/12/2017 Inspected At: | Cycle & Carriage KIA Pte Ltd (Pandan Gardens) | |
| | | 209 Pandan Gardens | |
| | | Singapore 609339 | |
| Estimated Period of Repair: | 3.0 days | | |

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 01 Feb 2018)
Parts: 143 KIA CERATO FORTE 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJV5459T)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------|---------------|------------|------------|
| 1 | 1 | | *SUNDRIES | Necessary | 50.00 FS | *20.00 FS |
| 2 | 1 | | *COVER-FR BUMPER | Deformed | 735.00 FS | *735.00 FS |
| 3 | 1 | | *LIP ASSY-FRONT BUMPER | Cut | 63.00 FS | *63.00 FS |
| 4 | 1 | | *ABSORBER-FRONT BUMPER ENERGY | Not Necessary | 94.00 FS | *- FS |
| 5 | 1 | | *GRILLE-FRONT FOG, RH | Not Necessary | 33.00 FS | *- FS |
| 6 | 1 | | *LAMP ASSY-HEAD, RH | Not Necessary | 477.00 FS | *- FS |
| 7 | 1 | | *GUARD ASSY-FRONT WHEEL, RH | Deformed | 63.00 FS | *63.00 FS |
| 8 | 1 | | *LAMP ASSY-FRONT FOG, RH | Cracked | 143.00 FS | *143.00 FS |
| 9 | 1 | | *RESERVOIR ASSY-W.SHLD WASHER | Deformed | 50.00 FS | *50.00 FS |

F=Franchise part. S=SpcNett.

Total Parts (S\$) **1,708.00** **1,074.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|---|----------|------------|----------|
| Labour Items | | | | |
| 1 | RENEW ACCIDENT DAMAGED PORTION ON FRONT BUMPER AND REALIGN TO THE SAME | New | 1,100.00 | 550.00 |
| 2 | CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM | New | 100.00 | 60.00 |
| 3 | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | New | 200.00 | 200.00 |
| 4 | RESPRAY FRONT BUMPER AND OTHER AFFECTED PORTIONS | New | 840.00 | 420.00 |
| Gross Labour Cost (\$\$) | | | 2,240.00 | 1,230.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >