

INS. CASE OWNER: Lee Ming Yau CC4 / AIG170 22880, K ea39 LKK: IDAC

Surveyor: Kenneth DOI: ASSIGNMENT 4-12-17 Date / Time: 1-12-17

Registered in Merimen: 1-12-17

Pre-assign / CCU / FTE



Insured Vehicle No.: SLR1001D  
Name of Insured: Singaram Krishnamoorthy  
Insured Tel No.: HP: 96336852  
Excess Sec II :SS D.O.A: 29-11-17

Claim No.: 312756909456  
Policy No.: 1700034978  
Make / Model :  
Place of Accident : Upper Thane Con Rd.

Is driver the owner? ( YES / NO ) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO )

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SKD2342 Z



INSRS: EC Amb  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

Date/ Time

STAGE DATE / PIC

Non-Reporting ltr (1st): 6/12/17

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ ( days) Reduction: %

Email Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email Call

Final Liability: % (Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost: S\$

Loss of Rental (LOR): S\$ ( days)

Loss of Use (LOU): S\$ (\$ x days)

Loss of Income (LOI): S\$ (\$ x days)

LOR only LOR only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search S\$

Medical: S\$

Disbursement: S\$ (e.g. Tow/ Independent)

Legal Cost S\$

Total: S\$ Global Sum S\$:

1) Claim status: Normal/Reject/Private Settle /OP

2) Report Format:

3) Survey fee:

FINAL PAYMENT

Date/Time:

Confirm with:

Email Call

Payee 1: S\$ Name 1:

Payee 2: (Strike if N.A.) S\$ Name 2:


Payee 3: (Strike if N.A.) S\$ Name 3:

## ASSIGNMENT

From: \_\_\_\_\_ Date: **04/12/2017**  
 Estimated Cost: \_\_\_\_\_  
 OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV  
 To inspect Vehicle No: **SKD 23422**  
 at Workshop in: **RC Auto**  
 of **160 Sin Ming Drive # 06-20, 575722**  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record) \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bell or Market Value: \_\_\_\_\_  
 IDAO Accident Report: \_\_\_\_\_ Consistent? Yes or No  
 GIA / FR Seen: \_\_\_\_\_ Consistent? Yes or No  
 Est. Repairs: **02** days Res: Yes or No  
 Lump Sum: **-** % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS **'wp'**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT

Veh No: **SKD 23422** Page **11 11**  
 Type ☒ Car ☐ M/Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **Volkswagen Golf 7B 1390**  
 Colour: **M. Blue** A/C Insured / Std / Nil / NA  
 Seating: **5559** T-Radio Insured / Std / Nil / NA  
 Eng No: \_\_\_\_\_  
 C/Vo: **WVW ZZZIK ZCW 033578**  
 Gen Cond: ☒ Good ☐ Fair ☐ Poor ☐ Burnt  
 Steering: ☒ In order ☐ Jammed / Leaked / Burnt or  
 Brake: ☒ In order ☐ Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD / R/Rim or  
 Tyre Size: **P. B.S 205/55R16**  
**Continental**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: **5** mm R/Bal: **8** mm  
 L/Bal: **5** mm L/Bal: **8** mm  
 D/OA: **29/11/17** D/OI: **4/12/17**  
 Survey held at: \_\_\_\_\_  
 Des. of Damages: ☒ Front ☐ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or  
 The U/C / Chassis/frame / Body Structure affected due to collision

Date Time Action Instruction

**Asher - Handler.**

**5/12 File pass to Customer**

RED: 1,235-50 31/

OneTime File Return? ☐ Prel. Report

☐ Final Report

OneTime File Return? ☐

OneTime File Return? ☐

Report Format: \_\_\_\_\_

Lump Sum / LB / 13

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ Extra Insd: 16

☐ Interim: 9

☐ Tech: 9

☐ U/C: 9

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG17022880/Kea3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 01-12-2017



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |           |                |            |
|--------------|-----------|----------------|------------|
| Insured Veh. | SLR 1001D | Veh. Inspected | SKD 2342Z  |
| Policy No.   |           | Coverage (\$)  | 0.00       |
| Claim No.    |           | Excess (\$)    | 0.00       |
| Assign From  |           | Assign Date    | 01/12/2017 |

## 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |                                                                                   |                 |            |
|----------------|-----------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 29/11/2017                                                                        | Inspection Date | 04/12/2017 |
| Survey held at | R C AUTO<br>BLK 18 SIN MING INDUSTRIAL ESTATE SECTOR A #01-43<br>SINGAPORE 575676 |                 |            |

## 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

# ESTIMATE RC AUTO

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel : 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168K

Not Authored

B ?  
Resurvey After Paint  
2148.50

SKD 2342 Z

Date : 1/12/2017

| Quantity | Description/Particular        | Unit Price | Amount      |
|----------|-------------------------------|------------|-------------|
| 1 pc     | Front Bumper                  | Per \$     | 820 00      |
| 1 pc     | Front GRILLE                  | cm \$      | 390 00      |
| 2 PCS    | Front Headlamp@660            | \$         | 660 1320 00 |
| 1 pc     | Front Bumper beam             | \$         | 420 00      |
| 1 pc     | Front Bumper grille           | \$         | 185 00      |
|          |                               | total \$   | 3135 00     |
|          |                               | less 10    | 2821 50     |
|          | Spray painting                | \$         | 300 00      |
|          | Front Number plate and holder | \$         | 50 00       |
|          | To renew above parts          | \$         | 500 00      |
|          |                               | Total \$   | 3384 00     |

✓  
✓  
X  
✓  
✓  
22d  
45sm  
25d

Received the above goods in good order and condition

for RC AUTO

**RC AUTO**

160, Sin Ming Drive  
#06-20 Sin Ming AutoCity  
Singapore 575722

Email: rcauto5555@gmail.com

Authorised Signature

Received by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

E & O E

Acknowledged by Repairer

Signature:

Date:

Not Noted  
Uly 87  
Penny After Point

Tel : 97619383    Email: rcauto5555@gmail.com

Reg. No. 53199168K

Date : 1/12/2017

✓  
7  
7  
7  
7  
  
250  
✓  
300

for **RC AUTO**

**LKK Auto Consultants** hence notify  
**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- The early survey is on a "Without Prejudice" basis

**E.&O.E.** **Authorised Signatory**

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

- Pre repair inspection request - SKD2342Z VS SLR1001D (OI) DOA: 29/11/2017

From: Chan, Yoke Shi  
To: assignments, Admin A  
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang  
Sent: Friday, 1 December, 2017 4:32:55 PM  
Attachments:  FaxE7EB.TIF

Hi,

Please refer to the enclosed request from **LEGAL OPTIONS LLC**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

*Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.*

Thank you.

Regards,

Yoke Shi @ Ashley  
AIG  
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto  
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)  
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia  
Tel +6 03 2719 6000 | Ext 1012102

[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com) | [www.aig.com](http://www.aig.com)

5pm @ 1/12/2017  
vehicle In  
person @ Mr. Tan  
Arrange on 04/12/2017  
Kenneth

**From:** Tiffany Ling [<mailto:tiffany@legaloptions.biz>]

**Sent:** Friday, December 01, 2017 4:28 PM

**To:** Chan, Yoke Shi

**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang

**Subject:** Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR1001D AND SKD2342Z ON 29/11/2017

Dear Yoke Shi,

Our client propose to use **Kenneth Kong (LKK Auto Consultants Pte Ltd)**.

The said surveyor

may contact Mr Tan at 9761 9383,

M/s RC Auto at

160 Sin Ming Drive #0  
6-20  
, Sin Ming Autocity, Singapore 575722

\*

If we do not hear from you within 2 days of this email, our clients shall deem that you have agree that the surveyor appointed by our clients shall be our single joint expert for this matter.

Thanks n regards,

*Tiffany*

**Secretary**

**LEGAL OPTIONS LLC**

(GST Registration/UEN No. 201203825R)

Tel (65) 6513 2800 DID (65) 6513 2805 Fax (65) 6438 8275

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.

On Fri, Dec 1, 2017 at 3:22 PM, Chan, Yoke Shi <yokeshi.chan@aig.com> wrote:  
Without Prejudice

Your Reference : 17-A18-MISC-187J2.st

Our Reference : SLR1001D

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

| Name of Surveyor         | Company Name                           |
|--------------------------|----------------------------------------|
| Lim Kok Chong            | AIG Asia Pacific Insurance Pte Ltd     |
| Kumar Uthaya             | AIG Asia Pacific Insurance Pte Ltd     |
| Ken Wong                 | AIG Asia Pacific Insurance Pte Ltd     |
| Lawrence Ng Chun Kee     | Priority Services                      |
| Jeffrey Ong Leng Kiat    | Priority Services                      |
| Jimmy Lee                | Priority Services                      |
| EC Looi                  | Automobile Inspection Services Pte Ltd |
| Ricky Teng               | RT Appraisal Pte Ltd                   |
| Elson Teng               | RT Appraisal Pte Ltd                   |
| Michael Cheong           | RT Appraisal Pte Ltd                   |
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd             |
| Ng You Han               | Formteam Adjusters Pte Ltd             |
| Soon Han Xin (Gary)      | Formteam Adjusters Pte Ltd             |
| Chow Bo Xiong            | Formteam Adjusters Pte Ltd             |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd             |
| Kalvin Ang               | LKK Auto Consultants Pte Ltd           |

|                 |                              |
|-----------------|------------------------------|
| Xing Guo Qiang  | LKK Auto Consultants Pte Ltd |
| Marcus Chua     | LKK Auto Consultants Pte Ltd |
| Mohamad Taufikh | LKK Auto Consultants Pte Ltd |
| Adrian Ling     | LKK Auto Consultants Pte Ltd |
| Henry Ng        | LKK Auto Consultants Pte Ltd |
| Mohammed Rasul  | LKK Auto Consultants Pte Ltd |
| Steven Foong    | LKK Auto Consultants Pte Ltd |
| Wei Jie         | LKK Auto Consultants Pte Ltd |
| Ma Chin Fook    | LKK Auto Consultants Pte Ltd |
| Kenneth Kong    | LKK Auto Consultants Pte Ltd |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012102

[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com) | [www.aig.com](http://www.aig.com)

**LEGAL OPTIONS LLC**ADVOCATES & SOLICITORS  
Mediators - Commissioners for Oaths - Notary Public

法商律師事務所

Motor Accident &amp; Personal Injuries

Tel: (65) 6513 2800 Fax: (65) 6438 8275

Commercial, Litigation, Property, Trust &amp; Estate, Family

Tel: (65) 6438 8039 Fax: (65) 6734 8230

We do not accept service of Court Documents by fax

Your Ref : SLR 1001D

Our Ref : 17-A18-MISC-187J2.st

1<sup>st</sup> December 2017

M/S AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way #07-16

AIG Building

Singapore 079120

(Attn: Motor Claims Department)

Dear Sirs,

CLAIMANT : LIAU HUEY CHING

ACCIDENT INVOLVING SKD 2342Z & SLR 1001D ALONG UPPER THOMSON ROAD ON 29.11.2017

We are instructed by MS LIAU HUEY CHING to notify you of a road traffic accident on 29<sup>TH</sup> NOVEMBER 2017 at about 17:00 HOURS ALONG UPPER THOMSON ROAD involving our client's vehicle registration number SKD 2342Z and vehicle registration number SLR 1001D driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully



Cc: Client (SKD 2342Z)

## Directors

Joan Lim Pheok Hoon LL.B (Hons)

Victor Leong Wai Meng LL.B (Hons)

Teo Lip Hua Benedict LL.B (Hons) LL.M

Secretary's DID: 6513 2807

Direct Fax: 6438 8275

(Email: [info@legaleoptions.biz](mailto:info@legaleoptions.biz))

Mailing Address for Accident Claims

Documents Support:

23 Kaki Bukit Avenue 4 #01-01 South Wing,  
Singapore 415933**IMMEDIATE ATTENTION**

By Fax : 6415 3727/Post

## View Received Message

This mail is associated with :

**\*SKD2342Z (31775690945G)**  
**[SLR1001D]**

TP

LIAU HUEY CHING

Nov 29 2017 12:00AM

[SINGARAM KRISHNAMOORTHY]

R C Auto

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 04/12/2017 11:18 AM.  
**To** LKK\_HQ  
**CC** NoorMariesa.AbuKassim@aig.com  
**Subject** NO OI GIA REPORT

Hi

OI has not reported yet. OI details as below :

NAME : SINGARAM KRISHNAMOORTHY

Addresss : 18 Sin Ming Walk, Bishan Park Condominium, #01-01 ,Singapore 575569.

Tel No. : 96336852

Thanks  
Mariesa

### DOCUMENTS SUMMARY

There are no documents.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

| CLAIM SUBFOLDER TRACKING |                                         |               |                                                      |                                                      |                                                |            |                                                                 |
|--------------------------|-----------------------------------------|---------------|------------------------------------------------------|------------------------------------------------------|------------------------------------------------|------------|-----------------------------------------------------------------|
| Case                     | Notified                                | Est Submitted | Adj Assigned                                         | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'd | Status                                                          |
| Main                     | 01 Dec 2017<br><a href="#">Edit Reg</a> |               | 01 Dec 2017<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$2,148.50</b><br><a href="#">Edit Estimates</a> | <b>S\$2,148.50</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|             |                  |                      |                  |                          |
|-------------|------------------|----------------------|------------------|--------------------------|
| <b>Main</b> | <b>Reference</b> | <b>Claim Details</b> | <b>Documents</b> | <a href="#">Show All</a> |
|-------------|------------------|----------------------|------------------|--------------------------|

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

|                             |                                                                                                                          |                        |                            |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------|------------------------|----------------------------|
| Insured:                    | SINGARAM KRISHNAMOORTHY, ID: S0152967F                                                                                   |                        |                            |
| Main Claimant:              | LIAU HUEY CHING, ID: S7608871C                                                                                           |                        |                            |
| Vehicle Reg. No.:           | SKD2342Z                                                                                                                 | Date of Loss:          | 29/11/2017 17:00 - :59     |
| Claim Type:                 | TP / 3177569094SG                                                                                                        | Policy/Cover Note No.: | 1700034978 (Comprehensive) |
| Vehicle Reg. No. (Insured): | SLR1001D                                                                                                                 | Policy No. (Claimant): | P27793039DMV               |
|                             |                                                                                                                          | Excess:                |                            |
| Repairer:                   | R C Auto (HQ) Blk 18 Sin Ming Industrial Estate Sector A #01-43, 575676 Sin Ming - Tel: 64588878                         |                        |                            |
| Handling Insurer:           | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao]<br>MingYao.Lee@aig.com |                        |                            |
| Claimant's Insurer:         | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888                                                           |                        |                            |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 12/12/2017]          |                        |                            |

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG (04/12/2017): NO OI GIA REPORT
- AIG\_SG (04/12/2017): NO TP GIA REPORT

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Claim Documents

\*SKD2342Z (3177569094SG)  
[SLR1001D]  
TP  
LIAU HUEY CHING  
Nov 29 2017 5:00PM  
[SINGARAM KRISHNAMOORTHY]  
R C Auto

| <a href="#">Upload Documents</a> |                 | <a href="#">Upload Photos</a>                                                                               | <a href="#">Compose New Letter</a> | <a href="#">Upload Video</a> | <a href="#">Upload Audio</a>        | View <a href="#">View in Browser</a> |                                     |
|----------------------------------|-----------------|-------------------------------------------------------------------------------------------------------------|------------------------------------|------------------------------|-------------------------------------|--------------------------------------|-------------------------------------|
| <b>Assessment Reports</b>        |                 |                                                                                                             |                                    |                              |                                     | 1 per page                           | <input checked="" type="checkbox"/> |
| No                               | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG)                                                                   | Thumbnail                          |                              | Print                               |                                      |                                     |
| 1                                | 28/12/17 10:50  | <b>Accident Statement</b><br><small>from: SC - Reg. No: SLR1001D, Claimant: SINGARAM KRISHNAMOORTHY</small> | Load HTM                           |                              |                                     |                                      |                                     |
| <b>Photos/Images</b>             |                 |                                                                                                             |                                    |                              |                                     | 3 per page                           | <input checked="" type="checkbox"/> |
| No                               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                                                           | Thumbnail                          |                              | Print                               |                                      |                                     |
| 1                                | 03/01/18 09:52  | General View                                                                                                | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 2                                | 03/01/18 09:52  | General View                                                                                                | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 3                                | 03/01/18 09:52  | General View                                                                                                | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 4                                | 03/01/18 09:52  | General View                                                                                                | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 5                                | 03/01/18 09:52  | General View                                                                                                | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 6                                | 03/01/18 09:52  | General View                                                                                                | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 7                                | 03/01/18 09:52  | General View                                                                                                | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 8                                | 03/01/18 09:52  | Chassis Number                                                                                              | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 9                                | 03/01/18 09:52  | General View                                                                                                | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 10                               | 03/01/18 09:52  | Odometer Reading                                                                                            | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 11                               | 03/01/18 09:52  | General View                                                                                                | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 12                               | 03/01/18 09:53  | Reinspection Photo                                                                                          | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 13                               | 03/01/18 09:53  | Reinspection Photo                                                                                          | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 14                               | 03/01/18 09:53  | Reinspection Photo                                                                                          | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 15                               | 03/01/18 09:53  | Reinspection Photo                                                                                          | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| 16                               | 03/01/18 09:53  | Reinspection Photo                                                                                          | Load JPG                           |                              | <input checked="" type="checkbox"/> |                                      |                                     |
| <b>Documentation</b>             |                 |                                                                                                             |                                    |                              |                                     | 1 per page                           | <input checked="" type="checkbox"/> |
| No                               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                                                           | Thumbnail                          |                              | Print                               |                                      |                                     |
| 1                                | 01/12/17 17:18  | EMAIL FROM AIG DD 01.12.2017                                                                                | Load PDF                           |                              |                                     |                                      |                                     |
| 2                                | 01/12/17 17:18  | NOTIFICATION FROM LAWYER                                                                                    | Load TIF                           |                              |                                     |                                      |                                     |
| 3                                | 04/12/17 09:37  | ACKNOWLEDGEMENT EMAIL TO AIG DD 01.12.2017                                                                  | Load PDF                           |                              |                                     |                                      |                                     |
| 4                                | 05/12/17 18:06  | TP ESTIMATE - MARKED                                                                                        | Load PDF                           |                              |                                     |                                      |                                     |
| 5                                | 05/12/17 18:06  | TP GIA REPORT                                                                                               | Load PDF                           |                              |                                     |                                      |                                     |
| 6                                | 06/12/17 08:17  | Non reporting letter                                                                                        | Load PDF                           |                              |                                     |                                      |                                     |
| 7                                | 10/01/18 07:37  | LETTER TO OI                                                                                                | Load PDF                           |                              |                                     |                                      |                                     |

## Documents Checklist

|                                              |                       |                      |                       |
|----------------------------------------------|-----------------------|----------------------|-----------------------|
| <b>DOCUMENTS CHECKLIST</b>                   | <a href="#">Reset</a> | <a href="#">Save</a> | <a href="#">Print</a> |
| There are no document checklists configured. |                       |                      |                       |

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17022880/KEA3Q2

Date: 10/01/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700034978  
 Claimant Vehicle No: SKD2342Z Insured Vehicle No: SLR1001D  
 Date of Loss: 29/11/2017 Nature of Claim: TP Claim No: 3177569094SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKD2342Z  
 Make & Model: VOLKSWAGEN NEW GOLF 5K13G5, 1.4 (A) Engine No: CAX920064  
 Reg. Date: 09/11/2011 (Man. Year: 2011) Chassis No: WVVZZZ1KZCW033574  
 Colour: Metallic Blue Odometer: 55591 km  
 Engine Capacity: 1390 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Bridgestone 5 mm Rear Left Side: Continental 8 mm  
 Front Right Side: Bridgestone 5 mm Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                     | Repairer's      | Adjuster's      | Difference      | Diff %       |
|------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                              | 2,871.50        | 1,678.50        | 1,193.00        | 41.55        |
| Miscellaneous Items                | 0.00            | 0.00            | 0.00            |              |
| Labour                             | 800.00          | 470.00          | 330.00          | 41.25        |
| Paintwork Labour                   | 0.00            | 0.00            | 0.00            |              |
| Towing                             | 0.00            | 0.00            | 0.00            |              |
| <b>Nett Amount (S\$)</b>           | <b>3,671.50</b> | <b>2,148.50</b> | <b>1,523.00</b> | <b>41.48</b> |
| <b>Global Sum Settlement (S\$)</b> |                 | <b>0.00</b>     |                 |              |

INSPECTION

Date of Assignment: 01/12/2017  
 Date Inspected: 04/12/2017 Inspected At: 160 SIN MING DRIVE #06-20,575722  
 Repairer: R C Auto (HQ)  
 Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                    | Condition   | Repairer's  | Amount     |
|-----|-----|----------|--------------------------------|-------------|-------------|------------|
| 1   | 1   |          | *FRONT BUMPER                  | Buckled     | 820.00 FL   | *820.00 FL |
| 2   | 1   |          | *FRONT GRILLE                  | Mtg Cracked | 390.00 FL   | *390.00 FL |
| 3   | 2   |          | *FRONT HEADLAMP                | Serviceable | 1,320.00 FL | *- FL      |
| 4   | 1   |          | *FRONT BUMPER BEAM             | Bent        | 420.00 FL   | *420.00 FL |
| 5   | 1   |          | *FRONT BUMPER GRILLE           | Dented      | 185.00 FL   | *185.00 FL |
| 6   | 1   |          | *FRONT NUMBER PLATE AND HOLDER | Dented      | 50.00 FS    | *45.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                     |                 |                 |
|-----------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                             | <b>3,185.00</b> | <b>1,860.00</b> |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 313.50          | 181.50          |
| <b>Total Parts (\$\$)</b>                           | <b>2,871.50</b> | <b>1,678.50</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars          | Lab.Type | Repairer's | Amount |
|-------------------------|----------------------|----------|------------|--------|
| <u>Labour Items</u>     |                      |          |            |        |
| 1                       | SPRAY PAINTING       | New      | 300.00     | 220.00 |
| 2                       | TO RENEW ABOVE PARTS | New      | 500.00     | 250.00 |
| Gross Labour Cost (S\$) |                      |          | 800.00     | 470.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >